

APPENDIX AND REFERENCES

POTENTIAL FAILURE MODE ANALYSIS
KOOTENAI DEVELOPMENT IMPOUNDMENT DAM

LINCOLN COUNTY, MONTANA

August 23, 2011

Prepared for:

The Remedium Group


Prepared By:

Billmayer & Hafferman, Inc.
Kalispell, MT

Appendix 1




LRC-06 Flume



LRC-06 Outlet



LRC-06 Inlet




Carney Creek Flow above Flume




CC-02 Flume



CC-02 Outlet



CC-02 Inlet



LRC-02 Flume




LRC-02 Inlet



Rainy Creek Reservoir



LRC-02 Outlet



Flows above Fleetwood Creek Flume




Fleetwood Creek Flume



URC-02 Flume



Fleetwood Creek Outlet



URC-02 Inlet



Reservoir Gauge #1



Reservoir Gauge #2



Steep Slope above Reservoir




Upstream Embankment from Staff Gauge




Reservoir Inlets from Staff Gauge



Principal Spillway Trash Rack



Upstream Toe of Embankment from Road



Principal Spillway Box Culvert Entrance



Box Culvert Inlet



Spillway Channel above Box Culvert



Box Culvert



Upstream Face from P5




Upstream Crest from P5



Downstream Crest from Left Abutment



Spillway Chute below Box Culvert



Downstream Right Abutment



Downstream Face of Dam




Looking across Downstream Embankment to Right Abutment



Downstream Left Abutment



Downstream Face of Embankment




Downstream Right Abutment



Steep Chute



Spillway at top of Steep Chute



Pooling Water at Downstream Left Toe




Drain 1 and Drain 2



Drain 1 Flow



Inside Drain 1



Inside Drain 2




Drain 3



Drain 4




Inside Drain 3




Inside Drain 4




Flume 1-4



Drain 5



Weir 5



Inside Drain 5




Drain 6



Inside Drain 6



Drain 6 Flow



Seepage near Drain 7



Drain 7



Drain 8



Inside Drain 7



Inside Drain 8




Flume 7-8



Decant Line Outlet in Embankment



Seepage near Drain 8



Seepage Near Drain 9




Drain 9



Seepage between Drain 9 and Drain 13



Inside Drain 9




Inside Drain 13




Seepage between Drain 13 and Drain 10



Inside Drain 10



Drain 10 and Drain 11



Inside Drain 11




Weir 12



Drain 12 Flow



Drain 12




Seepage into Drain 12 above Weir




Saturated Area above Drain 12



Sediment in Stream Bed




Water Seepage near Drain 12




Inside Phase 5 Decant Outlet Structure




LRC-01



Seepage along Lower Rainy Creek above Water Level




Lower Rainy Creek below LRC-01



Steep Chute at Stilling Basin




Riprap in Stilling Basin



Trash Rack on Mill Pond



F-Seep Flume




Mill Pond Spillway



Mill Pond



Mill Pond Embankment Crest to Right



Mill Pond Embankment Crest to Left

Appendix 2

TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1216491

SITE NAME: LIBBY ASBESTOS SITE

DOCUMENT DATE: 08/23/2011

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

2 DVDs -

KDID Toe Drain Inspection Drain 1 & Drain 2, March 1, 2, 3, 2010 Volume 1

KDID Toe Drain Inspection II Drain 3, Drain 2 & Drain 6, May 21, 2010

Volume 1

TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1216491

SITE NAME: LIBBY ASBESTOS SITE

DOCUMENT DATE: 08/23/2011

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

3 DVDs -

KDID Toe Drain Inspection Drains 11, 10, 9, 8 & 6, March 1, 2, 3, 2010 Volume 2

KDID Toe Drain Inspection Drains 3, 4, 5 & 12, March 1, 2, 3, 2010 Volume 3

KUID Toe Drain Inspection All Drains Video Condensed March 1, 2, 3, 2010

Volume 4

TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1216491

SITE NAME: LIBBY ASBESTOS SITE

DOCUMENT DATE: 08/23/2011

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

2 DVDs -

KDID PFMA Meeting Video 5/26/2011

KDID Updated PFMA Files with Reference File Locator 5/13/2011

Appendix 3

A3-Reference 1

Koolney

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

15

**RAINY CREEK BASIN
ZONOLITE TAILINGS DAM**

**LIBBY, MONTANA
MT-1470**

PREPARED FOR:
**THE HONORABLE TED SCHWINDEN
GOVERNOR OF THE STATE OF MONTANA**

**W.R. GRACE & COMPANY
CONSTRUCTION PRODUCTS DIVISION
(OWNER AND OPERATOR)**

PREPARED BY:
**MORRISON - MAIERLE, INC.
CONSULTING ENGINEERS**

SEPTEMBER 1981



PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

RAINY CREEK BASIN
ZONOLITE TAILINGS DAM

LIBBY, MONTANA
MT-1470

PREPARED FOR

HONORABLE TED SCHWINDEN
GOVERNOR STATE OF MONTANA

W.R. GRACE & COMPANY
CONSTRUCTION PRODUCTS DIVISION
(OWNER AND OPERATOR)

PREPARED BY

MORRISON-MAIERLE, INC.
CONSULTING ENGINEERS

SEPTEMBER 1981

CONTENTS

| <u>Paragraph</u> | <u>Page</u> |
|--|-------------|
| EXECUTIVE SUMMARY ----- | iv |
| PERTINENT DATA ----- | vii |
| CHAPTER 1 - BACKGROUND | |
| 1.1 INTRODUCTION ----- | 1 |
| 1.1.1. Authority and Scope ----- | 1 |
| 1.1.2 Purpose ----- | 2 |
| 1.1.3 Inspection ----- | 2 |
| 1.2 DESCRIPTION OF PROJECT ----- | 3 |
| 1.2.1 General ----- | 3 |
| 1.2.2 Regional Geology and Seismicity ----- | 4 |
| 1.2.3 Site Geology ----- | 4 |
| 1.2.4 Design and Construction History ----- | 5 |
| CHAPTER 2 - INSPECTION AND RECORDS EVALUATION | |
| 2.1 HYDRAULICS AND STRUCTURES ----- | 7 |
| 2.1.1 Spillway ----- | 7 |
| 2.1.2 Outlet/Decant Tower ----- | 8 |
| 2.1.3 Rainy Creek Diversion ----- | 8 |
| 2.1.4 Freeboard ----- | 8 |
| 2.2 HYDROLOGY, CLIMATOLOGY, AND PHYSIOGRAPHY ----- | 9 |
| 2.2.1 General ----- | 9 |
| 2.2.2 Reservoir Storage ----- | 10 |
| 2.2.3 Estimated Probable Maximum Flood ----- | 10 |
| 2.2.4 Flood Routing ----- | 11 |
| 2.3 GEOTECHNICAL EVALUATION ----- | 11 |
| 2.3.1 Dam ----- | 11 |
| 2.3.2 Foundation Conditions, Seepage, and Drainage ----- | 13 |
| 2.3.3 Stability ----- | 16 |
| 2.4 PROJECT OPERATION AND MAINTENANCE ----- | 17 |
| 2.4.1 Dam ----- | 17 |
| 2.4.2 Reservoir ----- | 17 |
| 2.4.3 Warning Plan ----- | 17 |

CONTENTS - Continued

| <u>Paragraph</u> | <u>Page</u> |
|---|--|
| CHAPTER 3 - FINDINGS AND RECOMMENDATIONS | |
| 3.1 FINDINGS ----- | 18 |
| 3.1.1 Size, Hazard Classification, and Safety Evaluation--- | 18 |
| 3.1.2 Embankment ----- | 18 |
| 3.1.3. Spillway and Reservoir Capacity ----- | 19 |
| 3.1.4 Outlet Works/Decant Tower ----- | 19 |
| 3.1.5 Operation and Maintenance ----- | 19 |
| 3.2 RECOMMENDATIONS ----- | 20 |
| REFERENCES ----- | 21 |
| APPENDIX | |
| Correspondence | |
| LIST OF PLATES | |
| Plate 1 | Vicinity Map |
| Plate 2 | Zonolite Tailings Dam Area Map |
| Plate 3 | Zonolite Tailings Dam Site Plan Phase 5 |
| Plate 4 | Zonolite Tailings Dam - Plan View |
| Plate 5 | Zonolite Tailings Dam Phase 5 Addition |
| Plate 6 | Geology Map |
| Plate 7 | Zonolite Tailings Dam Spillway Design Phase 5 Typical Sections |
| Plate 8 | Zonolite Tailings Dam Combined Decant Line and Spillway Rating Curve |
| LIST OF PHOTOS | |
| Photo 1 | Aerial View of Zonolite Tailings Dam Looking Upstream |
| Photo 2 | Aerial View of Zonolite Dam and Area Immediately Downstream (7-25-80) |
| Photo 3 | Phase 5 - Decant Tower (7-81) |
| Photo 4 | Rainy Creek Diversion Structure Foreground: Entrance to Rainy Creek - Background: Entrance to Diversion Pipeline (8-13-81) |

- Photo 5 Rainy Creek Diversion Pipeline Along Rainy Creek Road (7-81)
- Photo 6 Zonolite Spillway and Downstream Face (8-13-81)
- Photo 7 Spillway Chute and Approach Channel (8-13-81)
- Photo 8 Spillway Approach Channel Looking Downstream (8-13-81)
- Photo 9 Spillway Chute Looking Upstream Near Crest. Note Overlapping Joints (7-81)
- Photo 10 Spillway Foundation Collar (8-13-81)
- Photo 11 Erosion of Backfill and Undermining of Spillway Chute (7-81)
- Photo 12 Bends in Spillway Chute Looking Downstream (7-81)
- Photo 13 Downstream End of Spillway Chute Adjacent to Haul Road (8-13-81)
- Photo 14 East Abutment Drain for Benches on Downstream Face (8-13-81)
- Photo 15 West Abutment Area. Note Rill Erosion (8-13-81)
- Photo 16 Downstream Face Looking Towards the West (8-13-81)
- Photo 17 Upstream Face Looking Towards the West (8-13-81)
- Photo 18 Zonolite Tailings Dam - Phase 5 - Crest (8-13-81)
- Photo 19 Foundation and Spring Drains. Note Wetted Front (8-13-81)
- Photo 20 First Exposed Drain Closest to East (left) Abutment (8-13-81)
- Photo 21 Seepage from Bedding Material Around Spring Drain (8-13-81)
- Photo 22 Foundation and Spring Drains Looking Towards the East (8-13-81)
- Photo 23 Third Exposed Foundation Drain from East Abutment (8-13-81)
- Photo 24 Fourth Exposed Foundation Drain from East Abutment (8-13-81)
- Photo 25 Fifth Exposed Foundation Drain from East Abutment (8-13-81)

EXECUTIVE SUMMARY

Under contract with the State of Montana Department of Natural Resources and Conservation and with representation from Department of Natural Resources and Conservation and the Construction Products Division of W.R. Grace and Company, Morrison-Maierle, Inc. inspected Zonolite Tailings Dam on 25 July 1980 under the authority of Public Law 92-367. At that time the project was undergoing Phase 5 construction to raise the dam 35 feet. A followup inspection was conducted on 13 August 1981 upon construction completion. The dam is located in Lincoln County about 6.5 miles northeast of Libby, Montana in the Rainy Creek Basin.

This report was compiled from information obtained during onsite inspections, review of the construction log and plans, and analysis of available information. Findings were compared with engineering criteria that are currently accepted by most private and public agencies engaged in dam design, construction and operation.

FINDINGS AND EVALUATION

Zonolite Tailings Dam is owned and operated by W.R. Grace and Company and is located on private land. The reservoir is used to contain mine tailings. As tailings are deposited, the dam is raised in phases to provide storage. The dam, designed by Bovay Engineers, Inc. of Spokane, Washington, and Harding-Lawson Associates of Novato, California, will eventually be 200-feet high. Presently, it is 135-feet high (crest elevation 2,925 feet NGVD). The reservoir normally stores only enough water to accomplish tailings settling. A 48-inch diameter corrugated metal pipe intercepts Rainy Creek above the 3,000 foot elevation and diverts flow downstream of the dam. Existing manual controls at the diversion structure do not prevent storm flows from entering the reservoir. This report evaluates the 135-foot high dam assuming a tailings elevation of 2,873.0 feet NGVD (July 1980 inspection) and a dam crest elevation of 2,925 feet NGVD. Under these conditions, the project is capable of impounding about 2,120 acre-feet of water at spillway crest elevation 2,920 feet NGVD and 2,450 acre-feet at dam crest elevation 2,925 feet NGVD. All elevations used in this report are based on owner-supplied design drawings which correspond to the National Geodetic Vertical Datum (NGVD).

On the basis of criteria in U.S. Army Corps of Engineers Recommended Guidelines for Safety Inspection of Dams (Reference 1), the project is large in size. The dam is located such that its failure could endanger more than a few lives and cause excessive economic loss. However, no dam breach analysis or routing of a dam breach flood was made for the downstream area. The conclusions on probable damage are based on brief field visits and engineering judgement.

The project is classified as having a high (Category 1) downstream hazard potential. Inspection criteria (Reference 1) recommend that a large size project with a high downstream hazard potential be capable of safely handling the probable maximum flood (PMF). The PMF is the flood expected from the most severe combination of meteorologic and hydrologic conditions that are reasonably possible in the region.

An estimated thunderstorm PMF was developed for the 9.7-square mile drainage basin during this dam safety study. The PMF resulting from the 6-hour thunderstorm has an estimated volume of 3770 acre-feet and a peak flow of 43,400 cfs. The spillway has a maximum discharge capacity of 200 cfs with the reservoir at assumed top of dam, elevation 2,925 feet. The decant tower with minimum inlet elevation at 2890.1 feet has a maximum discharge capacity of 18 cfs and is used to maintain a steady level on the settling pond so that tailings will settle out and only clear water is discharged downstream. The routing of the PMF was started with the reservoir four feet above the inlet elevation of the decant line, which is the anticipated reservoir elevation prior to the occurrence of a flood of this magnitude. Routing of the PMF indicates that the dam is overtopped when approximately 55 percent of the total flood volume enters the reservoir. A flood with a hydrograph having ordinates corresponding to 45 percent of the PMF hydrograph ordinates is just controlled by the project. Larger floods would overtop the dam. These percentages of the PMF are valid only for conditions immediately after the completion of Phase 5. As tailings are deposited, there will be less storage available for floodwaters and the dam will overtop at PMF percentages smaller than those indicated above. The dam is constructed of materials that could quickly erode and rapidly fail if overtopped by floodwaters. Such failure could endanger lives immediately downstream at the screen plant and cause extensive damage to the highway, property and buildings. Because the project cannot safely handle the recommended spillway design flood (SDF), which is the full PMF, Zonolite Tailings Dam does not conform with inspection guideline hydraulic and hydrologic criteria.


During construction of the various phases of the dam, Bovay Engineering (for the starter dam only) and Harding-Lawson provided engineering services that included observation, consultation, and material testing. Visual inspection of the dam revealed no evidence of cracking, settlement or slope instability. Seepage control measures appeared to be functioning as designed. The structural integrity and support of the spillway is questionable and requires attention to insure flows do not adversely affect embankment safety. There is no riprap or erosion protection on the embankment slopes. Rill erosion is evident but is controlled by seasonal maintenance. Review of the stability analysis on file with the owner indicates the analysis is adequate and that Zonolite Tailings Dam conforms with inspection guideline stability criteria.


RECOMMENDATIONS

Develop and immediately place in action a downstream warning plan for use in the event of possible dam overtopping or structural failure. Periodically test the decant line for possible leaks within the embankment and perform necessary maintenance and repairs. Conduct more detailed hydrologic and hydraulic routing studies to better determine downstream hazard potential.

and to establish the minimum safe flood storage volume and spillway capacity. Studies should take into account the continually decreasing water storage volume as tailings are deposited, the nature of the tailings and their effect of sudden release on the downstream environment and an evaluation of the structural adequacy of the spillway under a full range of possible flow conditions. Modify the operation and/or project as studies indicate. Continue to monitor and evaluate seepage and conduct periodic inspections of the project on at least an annual basis by engineers experienced in dam design and construction.

Prior to performing engineering studies or remedial construction, coordinate with applicable Federal and State agencies to insure compliance with all pertinent laws and regulations.




Rodger C. Foster
Professional Engineer

PERTINENT DATA
ZONOLITE TAILINGS DAM

1. GENERAL

| | |
|-----------------------------|---|
| Federal ID No. | MT-1470 |
| Owner | W.R. Grace & Company |
| Operator | W.R. Grace & Company |
| Date Constructed | Original 1971 Expanded 1973, 1975, 1977, 1980 |
| Location | Section 22, T31N, R30W Longitude 115°24'40" Latitude 48° 26'32" |
| County, State | Lincoln County, Montana |
| Watershed | Rainy Creek |
| Size | Large |
| Downstream Hazard Potential | Category 1, High |
| USGS Quadrangle | Vermiculite Mountain, Montana |

2. RESERVOIR (Phase 5)

| | |
|---|-------------------|
| Surface Area at Spillway Crest | 68.5 acres |
| Drainage Area | 9.7 square-miles |
| *Storage at Spillway Crest (elevation 2920 feet NGVD) | 2120 acre-feet |
| *Storage at Dam Crest (elevation 2925 feet NGVD) | 2450 acre-feet |
| *Storage at Decant Line Inlet (elevation 2890.1 feet NGVD) | 550 acre-feet |
| Surcharge Storage | 330 acre-feet |
| Reservoir Elevation (25 July 80) | 2880.0 feet, NGVD |
| during construction of Phase 5 (13 August 81) | 2893.8 feet, NGVD |

*Water storage only
(Assumed tailings elevation 25 July 80, 2873.0 ft.)

3. SPILLWAY (Phase 5)

| | |
|--------------------------------------|---|
| Type | Uncontrolled chute |
| Shape | Half section, 8-foot diameter round corrugated metal pipe. |
| Crest Elevation | 2920 feet, NGVD |
| Capacity with Reservoir at Dam Crest | 200 cfs |

4. OUTLET WORKS/DECANT TOWER (Phase 5)

| | |
|--|---|
| Decant Tower | 6-foot diameter steel pipe, set vertically with a 1.7-foot wide entrance extending the full height of pipe. Floor elevation at 2890.1 feet. |
| Decant Line | 1600 feet of 16 inch diameter welded steel pipe at 1% slope. |
| Gate | Uncontrolled overflow weir to wet well inlet structure. |
| Capacity with Reservoir at Dam Crest: | 18 cfs |

5. DAM (Phase 5)

| | |
|-------------------------------|--|
| Type | Compacted Tailings |
| Length | 1154 feet at elevation 2925 feet NGVD |
| Crest Width | 40 feet at elevation 2925 feet NGVD |
| Crest Elevation | 2925 feet NGVD |
| Hydraulic Height crest to toe | 135 feet |
| Upstream Slope | 1V on 2H |
| Downstream Slope | 1V on 2H w/Construction Terraces |

Chapter 1

BACKGROUND

1.1 INTRODUCTION

1.1.1 Authority and Scope

This report summarizes the Phase I inspection and evaluation of the Zonolite Tailings Dam, owned by W.R. Grace and Company, Construction Products Division.

The National Dam Inspection Act, Public Law 92-367 dated 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to conduct safety inspections of non-Federal dams throughout the United States. Pursuant to that authority, the Chief of Engineers issued "Recommended Guidelines for Safety Inspection of Dams" in Appendix D, Volume 1 of the U.S. Army Corps of Engineers' report to the United States Congress on "National Program of Inspection of Dams" in May 1975.

The recommended guidelines were prepared with the help of engineers and scientists highly experienced in dam safety from many Federal and State agencies, professional engineering organizations and private engineering consulting firms. Consequently, the evaluation criteria presented in the guidelines represent the comprehensive consensus of the engineering community.

Where necessary, the guidelines recommend a two-phased study procedure for investigation and evaluation of existing dam conditions, so deficiencies and hazardous conditions can be readily identified and corrected. The Phase I study is:

- (1) a limited investigation to assess the general safety condition of the dam.
- (2) based upon an evaluation of the available data and a visual inspection.
- (3) performed to determine if any needed emergency measures and/or if additional studies, investigations, and analyses are necessary or warranted.
- (4) not intended to include extensive explorations and analyses or to provide detailed alternative correction recommendations.

The Phase II investigation includes all additional studies necessary to evaluate the safety of the dam. Included in Phase II, as required, should be additional visual inspections, measurements, foundation exploration and testing, material testing, hydraulic and hydrologic analyses, and structural stability analyses.

The authority for the Corps of Engineers to participate in the inspection of non-federally-owned dams is limited to Phase I investigations with the exception of situations of extreme emergency. In these cases, the Corps may proceed with Phase II studies but only to the extent needed to answer serious questions relating to dam safety that cannot be answered

otherwise. The two phases of investigation outlined above are intended only to evaluate project safety and do not encompass in scope the engineering required to perform design or corrective modification work. Recommendations contained in this report may be for either Phase II safety analyses or detailed design study for corrective work.

The responsibility for implementation of these Phase I recommendations rests with the dam owner and the State of Montana. It should be noted that nothing contained in the National Dam Inspection Act, and no action or failure to act under this Act shall be construed (1) to create liability in the United States or its officers or employees for the recovery of damage caused by such action or failure to act or (2) to relieve an owner or operator of a dam of the legal duties, obligations, or liabilities incident to the ownership or operation of the dam.

1.1.2 Purpose

The purpose of the inspection and evaluation is to identify conditions that threaten public safety, so that they may be corrected in a timely manner by non-Federal interests.

1.1.3 Inspection

The findings and recommendations in this report are based on brief visual inspections of the project and a detailed review of available construction plans, analyses and reports. Inspection procedures and criteria are those established by the Recommended Guidelines for Safety Inspection of Dams (Reference 1).

Personnel present during the 25 July 1980 inspection included:

| | |
|-----------------|---|
| Larry Tegg, | State of Montana, Department of Natural Resources and Conservation |
| Rodger Foster, | Team Leader, Morrison-Maierle, Inc. Water Resource Engineer |
| Mike Kaczmarek, | Engineering Geologist, Morrison-Maierle, Inc. |
| Robert Foss, | Chief Engineer for W. R. Grace and Company, Zonolite Operations at Libby. |

Those present for the 13 August 1981 inspection were:

| | |
|-----------------|--|
| Art Taylor, | State of Montana, Department of Natural Resources and Conservation |
| Harold Eagle, | Chief Engineer, Morrison-Maierle, Inc. |
| Mike Kaczmarek, | Engineering Geologist, Morrison-Maierle, Inc. |
| Phil Porrini, | Water Resources Engineer, Morrison-Maierle, Inc. |
| Michael Ray, | Chief Engineer for W.R. Grace and Company, Zonolite Operations |

Additional Morrison-Maierle personnel who contributed to the evaluation are:

Bill Keith, Structural Engineer

Ken Salo, Hydrologist/Hydraulics Engineer.

Subsequent discussions and coordination were conducted with Mr. Lyle Lewis of Harding-Lawson Associates and Messers William McCaig and Michael Ray of W.R. Grace Company, concerning the completed Phase 5 addition to the dam.

This report was reviewed by W.R. Grace and Company-Construction Products Division, the Montana Department of Natural Resources and Conservation, the Mine Safety and Health Administration and Mr. Lyle Lewis of Harding-Lawson Associates. Mr. Lewis submitted verbal comments only. The written comments received are included in the appendix.

1.2 DESCRIPTION OF PROJECT

1.2.1 General

Zonolite Tailings Dam and Reservoir are located at the site of the W.R. Grace and Company vermiculite mine on Rainy Creek about 6.5 miles northeast of Libby, Montana (Plates 1 and 2) (Photos 1 and 2). Rainy Creek empties into the Kootenai River 5.5 miles upstream of Libby. The project's Federal identification number is MT-1470. The 135-foot high tailings dam creates a reservoir that normally stores only enough water to allow mine tailings to settle out (about 7 feet deep). Normal flow from the Rainy Creek drainage basin is diverted around the reservoir through a 48-inch diameter corrugated metal pipe (CMP) (Photo 5). With the tailings at assumed elevation 2,873.0 feet and the dam crest at elevation 2,925 feet, the dam is capable of impounding about 2,450 acre-feet of water to the dam crest. As tailings accumulate, storage volume decreases. In time, the dam is raised to provide needed storage. The dam is planned to eventually be 200-feet-high. Based on visual reconnaissance and engineering judgement, the screening plant and product storage area at the mouth of Rainy Creek and State Highway 37 could be affected by a sudden breach of the tailings dam. In accordance with the Recommended Guidelines, the project is large in size and the downstream hazard potential is high (Category 1).

Outlets from the reservoir consist of an uncontrolled chute spillway in the left abutment and a decant structure located in the upper reservoir area (Photos 3 and 6). The spillway consists of a trapezoidal approach channel which transitions to a half-section of an 8-foot diameter corrugated metal pipe. The decant structure is a weir-controlled inlet structure to a 16-inch diameter welded steel pipe which extends along the west shoreline in the reservoir, through the dam embankment and discharges into the natural drainage downstream of the dam. The decant tower is designed to skim the cleaner surface water from the tailings pond.

1.2.2 Regional Geology and Seismicity

The Zonolite Tailings Dam is located in the northwest corner of Montana in the Rocky Mountain physiographic province (Reference 2). The area is characterized by high, rugged north-northwest-trending mountain ranges separated by narrow linear valleys that parallel the ranges. The mountain ranges are composed of late Precambrian Belt Series strata consisting of fine-grained clastic and carbonate rocks.

The Belt Series rocks range from 17,000 to 40,000 feet thick (Reference 3) and have undergone regional low-grade metamorphism. The Belt Series strata near Libby and the Zonolite Tailings Dam are deformed into broad, open, north-northwest-trending folds. High angle normal faults of regional proportions parallel the trend of the folds. The narrow linear valleys of the region are fault-bounded structural troughs. Surficial deposits are present on the floor of the Kootenai River valley and its major tributaries and consist primarily of alluvial sand and gravel, glacial lake silts, and alpine glacial deposits.

The Zonolite Tailings Dam is located on an elongate intrusive rock body that intrudes strata of the Precambrian Wallace Formation within the trough of a north-west-trending synclinal fold. The intrusive body is named the Rainy Creek stock and is a complex, composite intrusive which encompasses about 7.5 square miles of outcrop area underlying Vermiculite Mountain and most of the Rainy Creek valley west of Vermiculite Mountain. Vermiculite is mined from this intrusive.

In accordance with the Guidelines' Seismic Zone Map (Reference 1), the Zonolite Tailings Dam is in Seismic Zone 2. The seismic probability of Zone 2 has a potential for moderate earthquake damage and is based on known distribution of damaging earthquakes. Stability analysis performed for the planned 200 foot high embankment indicate that the computed safety factors exceed minimum recommended allowable safety factors for static conditions and also for seismic loadings of 0.1 and 0.2 times gravitational acceleration (Reference 6). Recommended Guidelines indicate that no hazard to embankment dams from earthquakes generally exists in Seismic Zone 2 provided static conditions are satisfactory and conventional safety margins exist.

1.2.3 Site Geology

The geology along the foundation of the Zonolite Tailings Dam was explored by means of 8 test borings 29 to 55 feet deep, 14 test pits 7 to 20 feet deep, 3 seismic velocity survey lines, and 27 soils resistivity soundings all conducted under the supervision of Harding-Lawson Associates in December, 1970 and May, 1971. The seismic velocity lines were used to determine depths to bedrock below the unconsolidated surficial deposits in the foundation area. The resistivity soundings were used to confirm the continuity of unconsolidated deposits between test boring locations. Field techniques and general methodology used are described in Appendix B of Lewis and Lawson (Reference 6).

A summary description of the preconstruction site geology is provided in Appendix A of Lewis and Lawson (Reference 6). Field observations conducted at the time of the dam safety inspection in the area of the abutments

and foundation were in agreement with the 1971 geologic report. The July 25, 1980, field inspection revealed bedrock underlying the dam site in the left abutment consists of the magnetite pyroxenite described by Boettcher (1963). The bedrock in the foundation area and in the right abutment area was covered by alluvium and glacial deposits and was not observed during the inspection. The bedrock exposed on the right abutment above the elevation of the existing dam (elevation 2890 feet) appeared to be the least altered, finer-grained pyroxenite of Boettcher (1953).

The magnetite pyroxenite observed in construction cuts on the downstream side of the left abutment on July 25, 1980, was a highly weathered, friable rock. As described in Appendix A of Lewis and Lawson (Reference 6), the "upper few feet of pyroxenite bedrock has physical characteristics more like those of a dense sand than rock." Discontinuous shear planes 2 to 3 inches thick oriented parallel to the valley wall were observed in the left abutment rocks on about 2 to 3 foot spacing. Lewis and Lawson (Reference 5) interpret the thin shear zones, which contain silt and clay sized rock gouge, to be the result of either glacial ice loading and/or gravity induced rock creep. The left abutment bedrock is discontinuously covered with as much as 10 feet of weathered rock debris. Lewis and Lawson (Reference 6) describe about 4 feet of highly permeable clean sand and gravel present as an outwash terrace remnant at about elevation 2830 feet.

Test pits and borings show the unconsolidated surficial deposits in the right abutment area consist of glacial outwash and till as much as 40 feet thick up to about elevation 2,890 feet (Reference 6). Cuts on the right abutment near elevation 2,870 feet on July 25, 1980, exposed fluviially bedded gravelly coarse sand (outwash). Subsurface investigations (Reference 6) of the unconsolidated foundation materials show as much as six feet of soft silt with lenses of fine sand and sparse gravel stringers over coarse gravel outwash with lenses of silt and fine sand and zones of quartzite boulders 4 to 5 feet in size. The depth to bedrock below the land surface on the alluvial silts and the gravel outwash ranges from 26 to 45 feet in the test boring logs (Reference 6).

1.2.4 Design and Construction History

The Zonolite Tailings Dam was designed in 1971 for W. R. Grace & Company by Bovay Engineers, Inc. of Spokane, Washington and Harding-Lawson Associates of Novato, California. The dam was designed as a tailings impoundment dam to retain fine tails produced in the vermiculite milling process. The staged construction plan called for the construction of a starter dam with provisions for raising the dam in stages as the storage capacity was depleted by tailings. The starter dam was constructed immediately downstream of an older existing dam. This older dam is identified in Reference 6 by crest elevation (2830 feet) and centerline location.

The 50-foot high starter dam was completed in November 1971 to an elevation of 2850 feet. Since that time three additional phases have been completed. Under the phase 1 expansion, completed in June 1973, the dam was raised to elevation 2875 feet. Phase 2 was completed in 1975 and involved raising the dam approximately 5 feet to elevation 2880 feet.

Phase 3 work was begun in late September 1976 and completed in August of 1977. Phase 3 construction brought the dam to elevation 2890 feet, which was the crest elevation at the time of the July 25, 1980 inspection. The Phase 4 addition, was delayed, and later incorporated in the Phase 5 construction. The Phase 5 addition was under construction at the time of the July 25, 1980 inspection, and was completed in October 1980, which raised the dam to elevation 2925 feet. While the phased construction of the dam has added a total of 75 feet to the 50-foot high starter dam's crest, it has also included approximately 10 feet of elevation difference at the downstream toe, making the total hydraulic height of the Phase 5 dam 135 feet.

A log of the planning and construction of the dam including construction drawings is on file with the chief engineer at the W. R. Grace mill site. Drawings showing the "in-place" construction phases are presented on Plates 4 & 5. A stability analysis for the planned 200 foot high embankment is on file with the owner. During construction of the various phases, Bovay Engineering (for the starter dam) and Harding-Lawson provided engineering services that included observation, consultation and material testing. Records indicate embankment construction met or exceeded design criteria.

Information in the Foundation Investigation and Engineering Analysis, (Reference 6) is cited throughout this Phase I - Dam Safety Report as it contains detailed information regarding the design of the starter dam and discussion of the planned 200 foot high embankment.

CHAPTER 2 INSPECTION AND RECORDS EVALUATION

2.1 HYDRAULICS AND STRUCTURES

2.1.1 Spillway

The spillway (Photos 6 to 13) is located in the east abutment and has been built to the same design criteria as described for the Phase 3 spillway in a June 8, 1976, letter to Robert Foss from Lyle Lewis of Harding - Lawson Associates and in a June 29, 1977, letter to Mr. Purnel Whitehead of W.R. Grace & Co. from Lyle Lewis concerning spillway design data (Reference 7). The spillway design criteria is presented on Plate 7. To our knowledge, the spillway has never been operated.

The spillway consists of an unlined trapezoidal shaped approach channel with a concrete transitional inlet structure which leads to half-sections of 8-foot diameter corrugated metal pipe (CMP) that comprise the spillway chute. Two pipes carrying mine tailings cross the unlined trapezoidal channel only slightly above the invert elevation (Photo 8). These pipes would trap floating debris during periods of spillway use and reduce its capacity. Bank sloughing and deposition of material in this unlined approach channel also represents serious capacity reductions and should be prevented. The entrance elevation of spillway is approximately 5 feet below the dam crest. The trapezoidal channel which extends through the east abutment abruptly transitions to the CMP chute (Photos 6 and 7). The CMP chute meanders along the haul road near the left abutment at an eight percent slope for approximately 500 feet and discharges into an unlined roadside ditch. Discharges enter the natural drainage downstream of the embankment toe. No stilling basin or energy dissipater is provided for at the terminus of the spillway chute (Photos 12 and 13). The CMP is anchored to concrete collars at three points along its length (Photo 10) and is also anchored to the concrete trapezoidal section near the crest. Pipe sections are overlapped and bolted to each other but are not sealed to prevent seepage which could produce piping of foundation materials and cause the chute to fail (Photo 9). This assemblage of the spillway raises doubts that the spillway chute will safely handle any high flows. Because of the spillway location, the ability of the half-round pipe to withstand hydraulic forces under all flow conditions, is an important consideration to the safety of the dam.

There was no floating debris noted in the pond, however, the drainage basin and much of the shoreline is heavily timbered and debris could be easily carried into the pond during high flows. There are no apparent provisions to protect the spillway from floating debris.

A spillway rating (Plate 8) was developed using the HEC-2, Water Surface Profiles (Reference 8). Backwater computations determined that critical depth occurs at the spillway crest entrance (elevation 2,920 feet NGVD). A Mannings "n" of 0.022 was used. The maximum discharge capacity of the spillway with the reservoir at the assumed dam crest elevation 2,925 feet NGVD, was estimated to be 200 cfs or about 17 acre-feet per hour. The two slurry pipes which cross the unlined trapezoidal channel were not considered in the capacity analysis.

2.1.2 Outlet/Decant Tower

Flow from the pond under normal operations is controlled by the decant tower. The Phase 5 decant tower is located approximately 1000 feet upstream of the dam (Plate 3) and consists of a 72-inch diameter corrugated metal riser pipe with a 1.7-foot wide rectangular weir entrance with a minimum elevation at 2890.1 feet, NGVD (Photo 3). The maximum weir elevation is the top of the decant tower at approximately 2923.0 feet, NGVD. The purpose of the decant tower is to maintain the level of the settling pond so that solids from the mill tailings are settled out and only the clean surface water is discharged through the decant line. The pond elevation is controlled by stoplogs placed in the decant tower entrance. Stoplogs acting as a weir crest will be installed permanently in stages as tailings accumulate in the pond to maintain several feet of water above the tailings. A log boom (Photo 3) in front of the stoplogs prevents floating debris from clogging the decant tower.

The Phase 5 decant line extends from the tower along the floor of the pond and through the dam embankment discharging approximately 500 feet downstream of the dam. This line consists of 16-inch diameter welded steel pipe. The pipe drains directly from the floor of the decant tower. Mr. Ray stated the portion of the decant line located within the embankment is encased in 1 foot of concrete with two cutoff collars for seepage control. The normal discharge capacity of the decant line was estimated to be 5 cfs and could increase to 18 cfs under unobstructed pressure flow conditions.

2.1.3 Rainy Creek Diversion

Under normal operations Rainy Creek is diverted around the dam. Fleetwood Creek, a tributary to the tailings pond, is not diverted and does enter the reservoir. A 48-inch diameter CMP diversion pipe with an approximate capacity of 100 cfs has been constructed to convey flow from Rainy Creek upstream of the reservoir above the 3,000 foot elevation and divert the flow downstream of the dam (Photo 5). A diversion structure intercepts normal runoff from 60 percent of the drainage basin and discharges it into the diversion pipeline. If inflows were to exceed the diversion pipeline capacity and/or the crest elevation of the flashboard assembly in front of the overflow culvert, then the remaining flow discharges directly into the tailings pond. At the August 13, 1981 inspection, the elevation at the top of the flashboards for the overflow culvert was approximately six inches higher than the water surface in front of the diversion structure, and approximately three feet lower than the structure's crest elevation (Photo 4).

2.1.4. Freeboard

This study indicates the dam overtops during the recommended spillway design flood (SDF) which is the probable maximum flood (see paragraph 2.2.4). Therefore, it has no freeboard. At the time of the July 25, 1980 inspection, the vertical distance from the water level (approximate elevation 2,880 feet) to the dam crest (elevation 2,890 feet) was approximately 10 feet. After the Phase 5 construction, and during the August 13, 1981 inspection, the normal water level was 31 feet below the dam crest. However, the vertical distance between normal water level and the top of the dam will become less

as tailings accumulate in the reservoir. Historically the dam has been raised to provide additional storage when the normal reservoir operating level came to within 10 to 12 feet of the dam crest. The spillway crest on the Phase 5 addition is five feet below the crest of the dam. The dam is located on the southwest end of the pond and the prevailing winds would be directed away from the dam. The effective fetch for wind-generated waves resulting from a north wind is about 2,000 feet and wave run-up on the embankment is estimated to be less than 3 feet. Although the dam will be overtopped by the PMF, the vertical distance between the normal pool elevation and the dam crest is adequate to prevent overtopping of the embankment by wind-generated waves.

2.2 HYDROLOGY, CLIMATOLOGY AND PHYSIOGRAPHY

2.2.1 General

The climate of the area is continental in nature characterized by warm summers and cold winters. Summer temperatures rarely exceed 95°F, and winter temperatures can reach 25 to 30 degrees below 0°F. Winters have few extended extreme cold spells due to periods of warm "chinook" winds.

The Rainy Creek drainage is located between two climatological stations. The Libby 1 N.E. Ranger station site is located 5.5 miles west southwest at an elevation of 2,080 feet NGVD. The Libby station has 74 years of record for temperature and 84 years of record for precipitation. Mean annual precipitation at Libby is 19.4 inches with 37 percent of it occurring in the months November through January and 18 percent falling in the months of May and June. The month having the highest average precipitation is January with 2.42 inches. Temperatures at Libby range from an average of 22.4°F in January to an average of 67°F in July. May and June temperatures average 54°F and 60.3°F, respectively.

A second climatological station is located approximately 5.1 miles east southeast of the basin at Libby Dam. The Libby Dam station is at elevation 2,200 feet NGVD and has 12 years of record for temperature and precipitation.

Average annual precipitation in the Rainy Creek drainage is estimated to be 30 inches per year (Reference 9) and the temperatures would be expected to average 3 to 5 degrees cooler than at Libby.

The Rainy Creek drainage basin above the tailings dam is 9.7 square miles in area and is generally "L" shaped. It is located on a southern exposure of the Purcell Mountains and is primarily forest covered except for the mine area. The basin rises from an elevation of 2,800 feet at the dam to 6,040 feet at Blue Mountain in a stream length of approximately 4.6 miles. There is no gaging station in the basin and the nearest gage downstream is on the Kootenai River at Libby (U.S. Geological Survey Station No. 12303000).

A hydrology report on the Rainy Creek drainage basin was prepared for W.R. Grace and Company in February 1971 by Bovay Engineers, Inc. and indicates the maximum design flow in Rainy Creek at Fleetwood Creek at 200 cfs. The maximum design flow is based on comparisons of maximum discharge of

record, per square mile of drainage area with six nearby and hydrologically similar gaging stations.

2.2.2 Reservoir Storage

In estimating the storage volume of the tailings pond it was assumed that mill tailings deposits had filled the pond to an elevation of 2,873 feet which means the water was approximately 7 feet deep at the time of the inspection. Using the conic method to develop total storage volume for the completed Phase 5 it is estimated that the reservoir would have a surface area of 68.5 acres and a volume of 2,120 acre-feet with the pool at the spillway crest elevation 2,920 feet. Approximately 330 acre-feet of surcharge storage is available in the reservoir between the spillway crest and the dam crest.

Based on estimates of anticipated plant production, tailings fill the reservoir storage at a rate of 135 acre-feet per year. Continued reduction in reservoir floodwater storage by deposition of tailings will seriously affect flood handling potential. Historically the dam has been raised to provide additional storage when the normal reservoir operating level came to within 10 to 12 feet of the dam crest.

2.2.3 Estimated Probable Maximum Flood

The probable maximum flood (PMF) is the flood expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. An estimate of the PMF was made during this dam safety analysis and was routed through the reservoir.

The probable maximum precipitation (PMP) was developed using a procedure contained in the U.S. Weather Bureau's Hydrometeorological Report No. 43 (Reference 10) as updated by U.S. Weather Bureau memorandum dated 9/20/67 (Reference 11). The storm which produces the PMF would be a 6-hour thunderstorm during the period July to August. The July-August thunderstorm PMP produces 6.0 inches of rain in one hour and 8.0 inches of rain in six hours. A minimum loss rate of 0.15 inches per hour was assumed to represent the hydrologic class B soils in the basin and minimum infiltration conditions due to saturated ground. Baseflow was considered to be 110 cfs from Rainy Creek and Fleetwood Creek.

A triangular unit hydrograph for a 10-minute rainfall duration was developed for the 9.7 square mile drainage area using procedures contained in Design of Small Dams (Reference 12). The Soil Conservation Service method of developing a curvilinear fit of the triangular unit hydrograph was used. The hourly increments of the PMP were arranged in a critical time sequence as illustrated in HMR No. 43 page 181 (Reference 10). The 10-minute increments from the greatest two hours were rearranged in the reverse order of the unit hydrograph to produce the greatest possible peak. The PMP was applied to the unit hydrograph by means of the computer program HEC-1 (Reference 13). This estimate of the PMP produced a flood with a peak flow of 43,400 cfs and a volume of 3,770 acre-feet.

2.2.4 Flood Routing

Routing of the probable maximum flood through Zonolite Tailings Pond was performed using the computer program HEC-1 Flood Hydrograph Package (Reference 13). The reservoir routing was started at the minimum elevation of the decant tower (2890.1 feet NGVD) which is the current operating level. This elevation, however, will change as stoplogs are permanently installed to keep water above the tailings. A 100-year 24-hour antecedent storm of 3.4 inches obtained from the National Oceanic and Atmospheric Administration (NOAA) together with Soil Conservation Service (SCS) runoff curve number (CN = 55, forested, class B soil) produced 0.35 inches of runoff. It was assumed that the diversion structure on Rainy Creek had failed allowing the entire runoff from Rainy Creek to join Fleetwood Creek and enter the reservoir. The total volume entering the reservoir would be approximately 180 acre-feet and would raise the reservoir elevation four feet to 2894.0 feet. The decant line discharging at 10 acre-feet per day would leave the reservoir at nearly the same elevation (2894.0 feet NGVD). This elevation was used to start the PMF routing.

Information from the owner regarding reservoir levels indicates that the drainage basin which is not controlled by the Rainy Creek diversion has never seriously contributed to raising the pond elevation. Only the installation of flashboards in the decant tower causes changes in pond elevation. There is no record of either Phase 3 or Phase 5 spillway use.

Routings indicate that the dam overtops during the PMF when approximately 55 percent of the total flood volume enters the reservoir. Routings were made of lesser hypothetical floods than the PMF to determine the magnitude of floods the dam can contain. The hypothetical hydrographs are obtained by applying percentages to the PMF hydrograph ordinates. A flood with a hydrograph having ordinates corresponding to 45 percent of the PMF ordinates is just controlled by the project. Larger floods would overtop the dam. Depletion of water storage volume by adding mill tailings would further reduce project flood handling capabilities.

2.3 GEOTECHNICAL EVALUATION

The following geotechnical evaluation is based on field inspections of the project, examination of the referenced reports, plans, and specifications, and discussion of the construction history with Bob Foss and Mike Ray, Chief Engineers for Zonolite Operations of W.R. Grace and Company, and Lyle Lewis, consulting design engineer, Harding-Lawson Associates.

2.3.1 Dam

The Zonolite Tailings Dam, is a homogenous fill resulting from several phases of incremental construction. The different phases of incremental construction of the embankment are shown on Plate 5. Phases 4 and 5 were constructed simultaneously. The elevation at the base of the dam is about 2,790 feet. The initial starter dam crest elevation was 2,850 feet and successive increments were added at elevations 2,875, 2,880, and 2,890. The phase of construction ongoing at the time of the July 25, 1980 inspection increased the dam height 35 feet to elevation 2,925 feet.

Each of the increments were added to the dam embankment using a downstream method of construction with slopes of 1V on 2H for upstream and downstream faces, and intermediate benches on the downstream face as shown on Plate 5. Table 1 shows a summary of dam height, crest length, and crest width for each successive increment of dam height. The final downstream slope configuration for the structure at elevation 2,925 feet NGVD including erosion benches is shown on Plate 5 and Photos 6, 14, 15 and 16.

Table 1: Summary of general dimensions for incremental structures.^{1/}

| ELEVATION (Feet) | DAM HEIGHT (Feet) | CREST WIDTH (Feet) | CREST LENGTH (Feet) |
|---------------------|----------------------|-----------------------|------------------------|
| 2850 Starter Dam | 50 | 40 | 840 |
| 2875 Phase 1 | 75 | 40 | 975 |
| 2880 Phase 2 | 80 | 35 | 995 |
| 2890 Phase 3 | 95 | 22 | 1002 |
| 2899 Phase 4* | 105 | 80 | 1055 |
| 2925 Phase 5 | 135 | 40 | 1154 |

^{1/} Crest lengths and widths scaled from W.R. Grace & Co. Construction Products Division Drawing No. 40-1009 as revised for each construction phase (Plate 4).

*incorporated in Phase 5 construction.

The materials used to construct the embankment are old mill tailings obtained from a stock pile on the east side of the tailings retention pond area, soils stripped from the abutment areas, and gravel from the location of the old mill pond downstream from the existing structure. Memos and letters in the Harding-Lawson Associates job file indicate that embankment fill was placed in three- to six-inch lifts and compacted to 95 percent relative compaction as determined by laboratory test procedures and periodic field density tests. Relative compaction refers to the in-place dry density of soil expressed as a percentage of the maximum dry density of the same material, as determined by the ASTM D1557-70(C) laboratory test procedures. Records of extensive field density tests during construction phases (thru Phase 3) show relative compaction of 95 percent or more (Reference 7). Discussion with the design consultant indicates that field density tests during Phase 5 construction also conformed with design criteria.

The main bulk of the embankment consists of mill tailings. Preconstruction tests show the mill tailings to consist of greenish gray gravelly sand with a dry density₃ of about 138 pounds per cubic foot (S.G.=3.1), a permeability of 1×10^{-3} feet per day at 95 percent relative compaction, an internal angle of friction (ϕ) of 20° , and cohesion (c) of 4000 psf, (Reference 6 and Reference 14). Strength parameters of ϕ and c are based on consolidated-undrained triaxial tests with pore pressure measurements. Maximum dry density data for mill tailings provided for the field density tests range from 144 to 149 pounds per cubic foot. Tests show surficial materials on the abutments to be gray silty sandy gravel and sandy gravel

that mix to a dry density of 128 pounds per cubic foot and exhibit a permeability of 2×10^{-9} feet per day at 95 percent relative compaction (Reference 6).

Inspection of the embankment did not reveal any sign of cracking, differential settlement, misalignment, or slope failure. A review of the extensive construction inspection records (Reference 7) and discussions with the W.R. Grace Engineer indicate that there have been no stability or consolidation problems with the embankment.

There is no protective shell or riprap on either face of the embankment. However, the coarse-grained mill tailings slurry discharged at the upstream face of the embankment, prohibits serious wave erosion of the embankment face (Photo 17). The downstream face of the dam has been under intermittent construction since 1971. There was evidence on both inspections that rain storms had caused accelerated erosion on the downstream dam slope (Photo 15). Bob Foss stated that rill erosion between benches on the downstream face demands seasonal maintenance by face dressing. A new surface drainage system consisting of half-sections of 42-inch diameter CMP has been constructed in the left abutment (Photo 14). This system drains the bench cuts on the downstream face of the Phase 5 addition. Erosion on the dam face does not pose a hazard to the dam so long as timely maintenance is performed and erosion control measures such as bench cuts or erosion terraces are used. During the PMF, rainfall intensity of 8 inches in 6 hours may cause extensive erosion on the dam's face.

2.3.2 Foundation Conditions, Seepage, and Drainage

The foundation of the Zonolite Tailings Dam, as determined by test borings, test pits, resistivity soundings, and seismic velocity measurements (Reference 6) consists of 20 to 40 feet of sand and gravel outwash with interbedded lenses of fine sand and silt all resting on weathered pyroxenite bedrock. Unsuitable materials were stripped from the foundation. Embankment fill was placed on dense gravelly soils containing abundant cobbles and boulders following foundation stripping. Foundation stripping and preparation was accomplished in phases corresponding to the phases of embankment construction.

Abutment preparation prior to placement of compacted fill consisted of constructing bench cuts 4 to 6 feet wide into the abutments. Bench cuts on the left abutment are in weathered, friable magnetite pyroxenite as observed during the July 25, 1980 inspection and documented in construction inspection memos. Bench cuts on the right abutment required 10 to 15 feet of excavation to remove loose slope debris so that the bench cuts key into the dense glacial soils. Construction inspection memos and as-built drawings for the construction increment bringing the dam crest to elevation 2,890 feet NGVD, describe right abutment bench cuts keyed into glacial soils below elevation 2,860 feet and bedrock above that elevation. At the time of the July 25, 1980 safety inspection, the materials exposed by bench cuts on the right abutment above elevation 2,890 feet consisted of firm glacial soils.

Construction inspection memos and letters (Reference 7) beginning October 24, 1972 describe the presence of an adit in the right abutment in the Rainy Creek ditch cut below elevation 2,875 feet. Discussions with Lyle Lewis of Harding-Lawson Associates revealed the adit was backfilled and drain pipes were installed to control seepage. The absence of seepage in the right abutment contact area and the width of the embankment fill in the reported location of the adit suggest the adit does not pose a threat to the abutment integrity.

Drainage installations employed at the Zonolite Tailings Dam consist of a chimney drain in the original starter dam and foundation drains consisting of perforated concrete pipe bedded in pervious aggregate. The location of foundation drains and the location of the chimney drain, which was not extended beyond the starter dam, are shown on Plates 4 and 5. The foundation drainage system presently consists of two cross drains and essentially seven lateral drains (Photo 12 to 25).

The starter dam was constructed immediately downstream of an older existing dam, which was reported to have a crest elevation of 2830 feet. A foundation cross drain was placed roughly from abutment to abutment and located between the upstream toe of the starter dam and the older existing dam. The cross drain is indicated in the foundation drain pattern on Plate 4 and is composed of a 10 foot wide by one foot thick bed of select drain material. This upstream toe drain is covered by compacted mill tailings used to fill the space between the starter dam and the old existing dam. The so called toe drain discharges into two of the lateral drains under the starter dam embankment.

Construction memos (Reference 7) indicate that toe drains 18 to 24 inches wide and 36 to 48 inches deep were placed at the toe of the starter dam and the first addition to the dam as trench drains to intercept seepage from the natural foundation gravels observed during construction. The toe drains were limited to the abutment portion of the starter dam downstream toe. Foundation stripping for the first addition to the starter dam revealed a spring in the foundation. The spring was excavated and filled with pervious gravel and is drained by the 14 inch steel pipe shown on Plate 4 and Photos 19, 21 and 22.

The foundation drainage system shown on Plate 4 was extended and in some areas expanded as part of the Phase 5 addition. Five perforated concrete drain pipes bedded in gravel were inspected (July 80 and Aug. 81) and each revealed clear water either seeping from the drain pipe or bedding material (Photos 19 to 25). A wetted front along the downstream toe was observed during the August 13, 1981 inspection and extended between all drains at approximate elevation equal to the flow line of the drains. The two 10-inch drain pipes closest to the spillway shown on Plate 4 do not extend to the embankment toe. These two drain pipes are buried but are scheduled to be uncovered by the owner. The 14 inch steel pipe draining the spring in the foundation was discharging flow estimated to be 100 to 200 gpm (Photo 22).

Piezometer monitoring data are available for each phase of dam construction. Five piezometers in the completed Phase 5 addition are shown on

Photo 17 and are located on Plate 5. These piezometers are merely vertical extensions of those that were in place for Phase 3. Only seven readings of the Phase 3 piezometers were recorded in a 29 month period between December 1977 and May 1980. Readings of the water level in the open tube piezometers should be correlated to tailings pond levels but records do not indicate such data is being kept. Although limited information has been obtained since the completion of Phase 5, there continues to be no evidence of significant water levels above the foundation.

Additional piezometer data was collected during the August 13, 1981 follow-up inspection. Measurements included elevations at each piezometer casing top, depths to water from the piezometer casing tops, and total piezometer depths as measured from the casing tops. Table 2 shows elevation and depth measurements conducted on August 13, 1981 and compares measured bottom elevations for each of the piezometers to bottom elevations shown on the as-built drawings (Plate 5).

TABLE 2: Measured piezometer elevations and depths compared to as-built data.

| Piezometer No. (Plate 5) | Measured Top Casing Elev. ^{1/} (Feet) | Measured Piezometer Depth (Feet) | Measured Bottom Elev. (Feet) | As-Built Bottom Elev. (Feet) | Difference From As-Built (Feet) |
|-----------------------------|---|-------------------------------------|---------------------------------|---------------------------------|------------------------------------|
| #1 | 2,920 | 104 | 2,816 | 2,807 | 9 |
| #2 | 2,920 | 121 | 2,799 | 2,790 | 9 |
| #3 | 2,920 | 60 | 2,860 | 2,795 | 65 |
| #4 | 2,921 | 106 | 2,815 | 2,806 | 9 |
| #5 | 2,921 | 104 | 2,817 | 2,811 | 6 |

^{1/} Measured elevations based on assumed crest elevation 2,925 at center-line of dam crest at midpoint between abutments and August 13, 1981 survey. Elevations and depths rounded to nearest foot.

Table 2 shows that measured elevations for the bottoms of the piezometers as of August 13, 1981 are higher than those shown on the as-built (Plate 5). Piezometer #3 in particular is 65 feet shallower than originally constructed. W. R. Grace and Company Chief Engineer for Zonolite Operation, Michael Ray, states that there are indications that vandals have been dropping rocks and loose earth down the piezometers. Measurements in piezometer #3 on August 13, 1981 showed considerable dirt sticking to condensation on the side of the casing beginning at about 34 feet from the top of casing and persisting to the bottom at above 60 feet below the casing top. The foregoing observations suggest that the differences between measured and as-built piezometer depths and bottom hole elevations (Table 2) may possibly be attributed to rocks and earth dropped into the piezometers.

Table 3 shows the depths to water and water surface elevations measured in the piezometers on August 13, 1981. Water surface elevations are compared to the as-built foundation elevation shown on Plate 5. Data on Table 3 show a phreatic surface in the lowermost 22 feet and 15 feet of the dam embankment at piezometers #1 and #2, respectively. Both piezometers #1 and #2 bottom out in the embankment fill without penetrating foundation material. Piezometer #3 is too plugged to yield useful data. Piezometers #4 and #5 both penetrate foundation materials and indicate that the phreatic surface in the foundation at these locations is at a lower elevation than the base of the embankment. The data shown on Table 3 indicate that the foundation drains and the pervious alluvial foundation materials are effectively controlling embankment and foundation seepage within conservatively safe levels.

TABLE 3: Water surface elevations measured in piezometers on August 13, 1981.

| Piezometer No. | Measured Top Casing Elev. ^{1/} (Feet) | Measured Depth to Water ^{2/} (Feet) | Water Surface Elev. ^{3/} (Feet) | As-Built Foundation Elev. (Feet) | Pond ^{3/} Elev. August 13, 1981 (Feet) |
|----------------|---|---|---|-------------------------------------|---|
| #1 | 2,920 | 102.03 | 2,818 | 2,796 | 2,894 |
| #2 | 2,920 | 114.76 | 2,805 | 2,790 | 2,894 |
| #3 | 2,920 | DRY | DRY | 2,796 | 2,894 |
| #4 | 2,921 | DRY | DRY | 2,812 | 2,894 |
| #5 | 2,921 | 103.89 | 2,816 | 2,841 | 2,894 |

- 1/ Measured elevations based on assumed crest elev. 2,925 at centerline of dam crest at midpoint between abutments and August 13, 1981 survey. Elevations and depths rounded to nearest foot.
2/ Water levels measured by steel tape and chalk method to ± 0.01 feet.
3/ Water surface elevation rounded to nearest foot.

2.3.3 Stability

A design stability analysis for the proposed 200-foot high tailings embankment is on file with the owner. Since all lower dams are similar to the planned 200-foot high embankment, consist of homogenous coarse tailings, and have 1V on 2H upstream and downstream slopes and a 20-foot minimum crest width, no stability analyses were performed for individual construction phases. The design stability analysis used an assumed phreatic surface and shear strength data developed from testing of embankment mill-tailing materials.

Results of the field testing through Phase 3 construction were reviewed and are in conformance with the design criteria as established by Harding-Lawson Associates and are in conformance with preconstruction values used in the stability analysis. The recent Phase 5 construction was inspected by a Harding-Lawson engineer and Mr. Lewis reports that field density tests

performed during construction show densities of at least 95% of optimum were achieved. Considering the low phreatic surface (as indicated by piezometers) compared to the phreatic surface used in the stability analysis, it is our judgment that Zonolite Tailings Dam conforms with the Recommended Guidelines stability criteria.

2.4 PROJECT OPERATION AND MAINTENANCE

Information on operations and maintenance was obtained from discussions with Mr. Robert Foss and Mr. Michael Ray, Chief Engineers for W.R. Grace and Company, Zonolite Operations. There is no formal operations and maintenance plan for the project.

2.4.1 Dam

The dam is located at the Zonolite mining operation site and is essentially under constant observation. Mr. Ray is responsible for the on-going maintenance and construction program for the dam and maintains a construction log (Reference 7) of all construction activity and data. Because the dam is being constructed in a phased program under the direction of an engineering design consultant, the embankment is essentially receiving major maintenance attention on a regular basis. Since 1971 when the starter dam was constructed, major construction modifications to the embankment have been performed every 2 to 3 years. Annual maintenance is also performed on the dam which includes dressing the slopes each spring or on an as-needed basis to repair minor erosional problems from surface runoff. Trees and brush are not allowed to become established on the embankment and burrowing animals are not of concern.

2.4.2 Reservoir

Zonolite Tailings Pond is a settling basin for the treatment of slurry mill tailings from the mining operation. The level of the pond is controlled by the decant tower and is maintained at an elevation such that the water from the surface meets necessary discharge quality requirements. As the sediments in the lake build up, storage volume and detention times are decreased and the pond's operating level is raised by placing stoplogs in the decant tower to meet water quality discharge requirements. Historically, the dam is raised when the normal reservoir operating level rises to within 10 to 12 feet of the dam's crest.

2.4.3 Warning Plan

There is no formal warning plan for use in the event of impending dam failure. However, because the project is occupied 24 hours a day early warning of unsafe conditions is probable.

CHAPTER 3 FINDINGS AND RECOMMENDATIONS

3.1 FINDINGS

Visual inspections of the dam, review of construction documents, and analysis of the project in terms of the recommended guidelines' performance standards, resulted in the following findings.

3.1.1 Size, Hazard Classification, and Safety Evaluation

The 135-foot-high Zonolite Tailings Dam could impound a maximum 2450 acre-feet of water with the pond at the crest of the dam and tailings at assumed elevation 2873.0 feet. Water storage decreases as tailings storage increases. In accordance with inspection guidelines, Zonolite Tailings Dam is large in size with a high downstream hazard potential rating. The recommended spillway design flood (SDF) for this project is 100 percent of the PMF. This dam safety study indicates that the project, with maximum water storage of 2450 acre-feet, controls a flood with hydrograph ordinates equal to approximately 45 percent of the PMF hydrograph ordinates. Larger floods will overtop the dam. The steady decrease of flood storage by tailings deposition will lower the flood routing capability. The dam is constructed of materials that would quickly erode and rapidly fail if overtopped by flood waters. Such failure could endanger life and property downstream. Because the project cannot safely handle the recommended SDF which is the full PMF, Zonolite Tailings Dam does not conform with inspection guideline hydrologic and hydraulic criteria.

3.1.2 Embankment

Zonolite Tailings Pond is impounded by an earthfill embankment dam. Since the construction of the starter dam in 1971 the embankment has been raised several times with the most recent being Phase 5. The additions to the embankment have been placed using downstream method of construction, i.e. the additional embankment is placed entirely on the downstream and crest portion of the dam which results in a downstream adjustment of the crest alignment.

The crest on the Phase 5 addition exhibits nearly a 2.0 feet range in elevation along its length. The range in elevation measured along a baseline, offset approximately 13 feet downstream of the centerline. The reason for the range in elevation is unknown as the dam is not equipped with settlement monitors and no "as built" design drawings are available. Annual inspections should monitor this condition. No visual signs of cracking, settlement, or slope instability were observed. Rill erosion on the embankment slopes was evident during both inspections. Seasonal maintenance of the slope erosion is required. Owner records and discussions with project personnel indicates embankment stability has not been a problem. There is no slope protection on the upstream slope of the dam, however, there is also no indication of wave erosion. Prevailing winds would be directed away from the embankment. The vertical distance from the normal reservoir level to the dam crest is adequate to prevent wind-generated waves from overtopping the embankment.

Drains placed in the embankment foundation have been extended to accommodate the additional fill from the phased construction activity. Only clear water has been observed seeping from the drain pipe and bedding material of the five perforated concrete drains. The drain nearest the northwest abutment which was dry in July 1980 was flowing in August 1981. In addition to the foundation drains, a 14-inch diameter steel pipe draining a spring in the foundation was discharging an estimated flow of 100 to 200 gpm. There was no evidence of a wetted front or seepage at the downstream toe of the embankment on July 25, 1980, however, during the August 13, 1981 inspection a wetted front equal in elevation to the flow line in the drains was observed.

A stability analysis for the proposed 200-foot high embankment was prepared in 1971 and is on file with the owner. The analysis was based on preconstruction data that have since been verified by field and laboratory test conducted during all phases of completed construction. Material strength results for all constructed phases of the dam are on file in the office of Harding-Lawson Associates. Piezometers have been installed and monitored with each phased addition to the embankment, however, attention to the changing tailings pond level should be noted with each reading.

Review of design stability analyses indicates that the stability analysis is adequate. In our judgement Zonolite Tailings Dam conforms with the Recommended Guidelines stability criteria.

3.1.3 Spillway and Reservoir Capacity

The reservoir has a surface area of about 68.5 acres and a water storage capacity of 2,120 acre-feet at the spillway crest, elevation 2,920 feet NGVD, assuming tailings to elevation 2873.0 feet. Approximately 330 acre-feet of surcharge storage is available between the elevation of the spillway and the crest of the dam. The discharge capacity of the spillway with the reservoir at the dam crest, is about 200 c.f.s. Because the structural integrity of the spillway is questionable, it is uncertain that the structure can safely contain the design flows without adversely affecting embankment safety.

3.1.4 Outlet Works/Decant Tower

The decant tower provides the normal operational releases from the tailings pond. Inspection of the Phase 5 tower and control facilities shows them to be in good operating condition. A welded steel decant line which rests on the pond floor and extends through the embankment is small and thus inaccessible for inspection without special equipment.

3.1.5 Operations and Maintenance

Zonolite Tailings Pond is operated as a settling basin for the milling operation at the mine site. Flow from Rainy Creek is diverted around the dam so under normal operating conditions the inflow to the pond is from the tailings discharge and from Fleetwood Creek. The pond elevation is regulated in small incremental rises to control the quality of discharges.

The embankment is essentially in a state of constant inspection and maintenance. Equipment necessary for dam maintenance is available at the mine site and maintenance is performed on an as-needed basis. There is no formal downstream warning plan for use in the event of impending dam failure.

3.2 RECOMMENDATIONS

Due to storage between normal pool and dam crest, the present project provides a degree of flood protection to the downstream area. The intent of report recommendations is to maintain or improve project safety, if feasible, without decreasing this flood protection.

The findings suggest that high priority be given the following recommendations:

1. Immediately develop, implement, and periodically test an emergency warning plan for use in the event of impending embankment overtopping or structural failure.
2. Periodically test the decant line in the section which passes through the embankment for possible leaks which could threaten the embankment. Repair if required.
3. Conduct more detailed hydrologic and hydraulic routing studies to better determine the downstream hazard potential and to establish the safe minimum flood storage volume and spillway requirement. Studies should take into account the continually decreasing water storage volume as tailings are deposited and the effect of sudden release on the downstream environment. Monitor tailings accumulation and periodically evaluate the available flood storage volume. Evaluate the structural adequacy of the spillway under a full range of possible flow conditions. Remove the two tailings transfer pipes from the spillway approach section. Modify the project as studies indicate.
4. Continue to conduct inspections of the dam on an annual basis by engineers experienced in dam design and construction, continue to monitor and evaluate piezometers, foundation and toe drains and maintain a construction log of all additions and modifications to the project. Add piezometers during construction as required to define the phreatic surface in the dam. Any changes in the position of the phreatic surface should be fully evaluated with respect to its affect on stability. All existing and future piezometers should be sealed and capped to prevent tampering by vandals. Existing piezometers should be cleaned and unplugged or replaced if reliable and useful data cannot be collected.



Prior to performing engineering studies or remedial construction, coordinate with applicable State and Federal agencies to insure compliance with all pertinent laws and regulations.

REFERENCES


1. U.S. Army Corps of Engineers, Office of the Chief of Engineers Report to the U.S. Congress, National Program of Inspection of Dams, Vol. 1, Appendix D, "Recommended Guidelines for Safety Inspection of Dams," Washington, D.C., Department of the Army, May 1975.
2. Fenneman, N.M., 1931, Physiography of Western United States: New York, McGraw-Hill Book Co., Inc., 534 p.
3. Johns, W.M., 1970 Geology and Mineral Deposits of Lincoln and Flathead Counties, Montana: Montana Bureau of Mines and Geology Bulletin 79, 182 p.
4. Boettcher, A.L., 1966, The Rainy Creek igneous complex near Libby, Montana: Unpub, Ph.D Dissert., Pennsylvania State Univ., 155 p.
5. Boettcher, A.L., 1963, Geology and petrology of the Rainy Creek intrusive near Libby, Montana: Unpub M.S. Thesis, Pennsylvania State Univ., 70 p.
6. Lewis, L.E. and Lawson, R.T., 1971a, Foundation Investigation and Engineering Analysis, Tailings Dam, W.R. Grace & Company, Construction Products Division, near Libby, Montana: Harding, Miller, Lawson & Associates, 55 Mitchell Boulevard, P.O. Box 3030, San Rafael, California; prepared for Bovay Engineers, Inc., Spokane, Washington.
7. Harding - Lawson Associates, 1971 to 1977, Job file office memoranda and letters pertaining to construction inspection and supervision including field density test records; memoranda and letters for period September 15, 1971, to October 13, 1977; logs of Tailings Dam prepared for Construction Products Division, W.R. Grace & Company, Libby, Montana 59923.
8. U.S. Department of Army, Corps of Engineers Hydrologic Engineering Center; "HEC-2 Water Surface Profiles", Generalized Computer Program Users Manual with Supplement; Nov. 76.
9. U.S. Dept. of Agriculture - Soil Conservation Service, Average Annual Precipitation, Montana based on 1941-1970 base period, 13 pp, 1977.
10. U.S. Weather Bureau, Hydrometeorological Report No. 43, "Probable Maximum Precipitation, Northwest States," Washington, D.C., 1966.
11. Hydrometeorological Branch, U.S. Weather Bureau Office of Hydrology, "Memorandum" Probable Maximum Thunderstorm Rain for the Columbia River Basin East of the Cascade Ridge," 20 September 1967.
12. U.S. Department of Interior, "Design of Small Dams", 3rd ed., Bureau of Reclamation, Denver, Colorado, 1977, 816 pp.

References - Continued

13. U.S. Army Corps of Engineers, Hydraulic Engineering Center, "Flood Hydrograph Package (HEC-1) Users Manual for Dam Safety Investigations", Davis, Calif., Department of the Army 1978, 93.
14. Lewis, L.E., 1971, Letter to Gene McKay, Bovay Engineers, Inc., re: Preliminary laboratory data, Tailings Dam, near Libby, Montana: Harding, Miller Lawson & Associates, January 21, 1971.
15. Lewis, L.E., 1971, Letter to Gene McKay, Bovay Engineers, Inc. Subject: Preliminary laboratory data, Tailings Dam, near Libby, Montana; with Particle Size Analysis, Compaction Test Data, Static Triaxial Shear Test Data, and Dynamic Shear Test Data: Harding, Miller, Lawson & Associates, January 21, 1971, 55 Mitchell Boulevard, San Rafael, California 94902.
16. Bovay, Engineers, Inc., 1971, Preliminary dam design and cost estimate for proposed tailings impoundment: for Construction Products Division, W.R. Grace & Co., Libby, Montana.





VICINITY MAP
PLATE 1




Source of Base: USGS Quadrangles-
VERMICULITE MOUNTAIN (1963) ,
LIBBY (1963),
ALEXANDER MOUNTAIN (1963)

ZONOLITE TAILINGS DAM
AREA MAP
PLATE 2






PLAN





TYPICAL DRAIN SECTION
NOT TO SCALE




TYPICAL
FOUNDATION DRAIN PATTERN
NOT TO SCALE

Source: W.R. GRACE & CO. Drawing No. 40-4009/4 (TAILINGS IMPOUNDMENT-PHASE 4)
Drawing Nq. 40-4009/4 (TAILINGS IMPOUNDMENT-PHASE 5)



ZONOLITE TAILINGS DAM
PHASE 5 ADDITION



SEDIMENTARY ROCKS




Striped Peak Formation

Gray and gray-green argillite, quartzite and gray-red-purple argillite. Some ultrabasic gray-green laminated argillite near center. Hiccup marked and mass cracks common. Some cases of salt crystals.




Rhyolite undifferentiated

Medium to light gray quartzite, quartzite, argillite, and argillite, some interbedded and laminated green-gray quartzite argillite weathering gray. In the Flathead Lake region grayish-red-purple, gray-und, and gray-green argillite and local calcareous quartzite greenish-gray argillite. Upper Kalavik marker bed of calcareous argillite mapped as pG.




Holocene Formation

Gray, green-gray, and yellow calcareous and dolomitic sandy argillite. discontinuous dolomite and magnesian limestone beds are common near the middle of the formation. Gray-und chert and minor quartzite locally present near the top. Mud cracks and ripple marks common.



Quaternary glacial deposits


Undifferentiated lacustrine silt, clay, drift, gravel, and alluvial fan material.




Alluvium

Recent gravel, sand, and silt. Some fluvial, some glacial outwash.


IGNEOUS ROCKS



Granite dikes



Syenite stocks




Quartz-lattice porphyry dikes




Basic stock composed of pyroxenite



Metadiorite—dark green-gray and gray-black dikes, sills, and stocks mapped by others as gabbro, hornblende gabbro, amphibolite, and metadiorite.




- Magnetite, pyroxenite
- Biotite
- Kapheline syenite
- Pyroxenite
- Syenite
- Ball Series
- Mine waste and mill tailings




PLAN VIEW-SPILLWAY EAST ABUTMENT

SCALE: 1" = 40'




SECTION A-SPILLWAY PROFILE

SCALE: 1" = 30'




SECTION B

SCALE: 1" = 40'



SECTION C

NO SCALE



ZONOLITE TAILINGS DAM
COMBINED DECANT LINE
&
SPILLWAY RATING CURVE
PLATE 8




Photo 1 Aerial View of Zonolite Tailings Dam Looking Upstream



Photo 2 Aerial View of Zonolite Dam and Area Immediately Downstream (7-25-80)




Photo 3 Phase 5 - Decant Tower
(7-81)



Photo 4
Rainy Creek Diversion Structure
Foreground: Entrance to Rainy Creek -
Background: Entrance to Diversion Pipeline
(8-13-81)



Photo 5 Rainy Creek Diversion Pipeline Along Rainy
Creek Road (7-81)




Photo 6 Zonolite Spillway and Downstream Face (8-13-81)



Photo 7 Spillway Chute and Approach Channel (8-13-81)



Photo 8 Spillway Approach Channel Looking Downstream (8-13-81)



Photo 9 Spillway Chute Looking Upstream Near Crest.
Note Overlapping Joints (7-81)



Photo 10 Spillway Foundation Collar (8-13-81)




Photo 11 Erosion of Backfill and Undermining of Spillway Chute (7-81)



Photo 12 Bends in Spillway Chute Looking
Downstream (7-81)



Photo 13 Downstream End of Spillway Chute Adjacent to
Haul Road (8-13-81)



Photo 14 East Abutment Drain for Benches
on Downstream Face (8-13-81)



Photo 15 West Abutment Area. Note Rill Erosion (8-13-81)




Photo 16 Downstream Face Looking Towards the West (8-13-81)




Photo 17 Upstream Face Looking Towards the West (8-13-81)



Photo 18 Zonolite Tailings Dam - Phase 5 - Crest
(8-13-81)




Photo 19 Foundation and Spring Drains. Note
Wetted Front (8-13-81)



Photo 20 First Exposed Drain Closest to East (left) Abutment (8-13-81)



Photo 21 Seepage from Bedding Material Around Spring Drain (8-13-81)



Photo 22 Foundation and Spring Drains Looking Towards the East (8-13-81)



Photo 23 Third Exposed Foundation Drain from East Abutment (8-13-81)



Photo 24 Fourth Exposed Foundation Drain from East Abutment (8-13-81)



Photo 25 Fifth Exposed Foundation Drain from East Abutment (8-13-81)

APPENDIX
Correspondence

GRACE

Zonolite
Construction Products Division

W.R. Grace & Co.
P.O. Box 609
Libby, MT 59923

14061 293-4131

Sept 4, 1981

Dept. of the Army
Seattle District, Corp. of Engineers
P. O. Box C-3755
Seattle, Washington 98124

Attn: R. P. Sellevold, P.E.
Chief, Engineering Division

Gentlemen:

W. R. GRACE & CO. would like to offer the following as comments to the Phase I inspection report - National Dam Safety Program - Rainy Creek Basin Zonolite Tailings Dam, Libby, Montana MT-1470 Dated July 1981 Revised.

Executive Summary Comments:

1. The location of the dam is stated to endanger lives in the event of a failure. Actually there is no residential area between the dam and the Kootenai River. Danger downstream of the mouth of Rainy Creek would be minimal because the Kootenai River, with a maximum flood stage rating of 95,000 CFS and with Libby Dam acting as flood control, is adequate to handle the flows projected by this report. A dam failure could force evacuation of the W. R. Grace facilities near the mouth of Rainy Creek, but to state that such an event would endanger lives is not justified in fact.
- II. With only 30 days allowed to prepare comments, it is impossible for W. R. GRACE to have a hydrologic and climatologic study prepared. However, the probable maximum flood (PMF) presented in this report must be questioned. In order to judge the rational behind the PMP, we would like to present the following comparisons:
 - a. The PMF generates a 43,400 cfs flow in the 9.7 square mile basin. This is 35.9% of the maximum flood on record in the Kootenai River (121,000 CFS at Libby in 1916)
 - b. Average uncontrolled flow in the Kootenai River for 52 years on record is July 1, 30,000 cfs; Aug. 1, 13,000 cfs and is Sept. 1, 17,000 cfs.

GRACE

Zonolite

Construction Products Division

-2-

c. If in fact this flow rate occurred and if the Zonolite Tailings Dam had spillway capacity to handle it (or if the dam did not exist and Rainy Creek was in it's natural channel), the amount of damage done thru the relatively steep canyon and at the confluence with the Kootenai, would make the integrity of the dam immaterial. Parts of lower Rainy Creek cascade down a 12% grade. Damage in the canyon, at the highway crossing and to the W. R. GRACE facilities near the mouth of the creek, would be extensive if the dam withstood the storm or not.

d. The volume predicted at 3770 acre - feet is 1.78 times the calculated volume retained behind the dam.

III. Spillway capacity is indicated to be 200 cfs. Using standard open channel flow calculation techniques, the capacity of the trapazoidal spillway feeding the 1/2 round lined channel is 760 cfs. The calculations show the 1/2 round discharge channel governs capacity.

IV. The stability analysis has been made available to C of E representatives. The question of the adequacy of the spillway cannot be addressed without correcting the calculated capacity of the existing spillway and without flow requirements from a rational PMF.

V. Comments on the Recommendations.

- a. Any such storm as predicted in the report would provide adequate warnings to anyone down stream and no formal downstream warning plan is needed.
- b. Any decant line leak which would present a problem would be detected by visual inspections and/or show up as an otherwise unexplained rise in the water level in the closest piezometer well.
- c. The Zonolite tailings dam is not intended to provide flood storage or protection.
- d. The question of adequate spillway capacity cannot be answered without reconsideration of design conditions.
- e. W. R. GRACE has and intends to continue using competent engineers to monitor the condition of the dam.

GRACE


Zonolite
Construction Products Division

-3-

W. R. GRACE & CO. appreciates the opportunity to comment on this report prior to publication. The magnitude of the probable maximum flood used in this report is questionable and the conclusions and recommendations based on it must be reconsidered based upon any changes.

Very truly yours,

CONSTRUCTION PRODUCTS DIVISION
W. R. GRACE & CO.


W. J. McCaig
General Manager
Libby Operations

WJM/ns

cc: J. Wolter, M. Ray

DEPARTMENT OF NATURAL RESOURCES
AND CONSERVATION
WATER RESOURCES DIVISION



TED SCHWINDEN GOVERNOR

32 SOUTH WING

STATE OF MONTANA

(406) 449-2072 ADMINISTRATOR
(406) 449-3962 WATER RIGHTS BUREAU
(406) 449-2872 WATER SCIENCES BUREAU
(406) 449-2864 ENGINEERING BUREAU
(406) 449-2872 WATER PLANNING BUREAU

HELENA, MONTANA 59620

September 10, 1981

Department of the Army
Seattle District, Corps of Engineers
P.O. Box C-3755
Seattle, Washington 98124

Attention: Ralph Morrison

Dear Ralph:

Re: Morrison-Maierle, Inc. Dam Safety Inspection Report of
Zonolite Tailings Dam MT-1470.

We have reviewed the above referenced final draft report.
We concur with the findings and recommendations and find
that it satisfies the criteria of Phase I report.

Minor editorial comments have been discussed with your
staff, and we understand these will be incorporated in the
final report.

Thank you for this opportunity to review and comment on
the final draft report on Zonolite Tailings Dam.

Sincerely,


Richard L. Bondy, P.E.
Chief, Engineering Bureau

RB:AT:lz

U. S. Department of Labor

Mine Safety and Health Administration
P O Box 25367
Denver, Colorado 80225



SAFETY AND HEALTH TECHNOLOGY CENTER
Mine Waste and Construction Division

September 1, 1981

Report No. D3674-W1499

File: HLS-5

MEMORANDUM FOR: WILLIAM C. GARDNER
District Manager, Rocky Mountala District
Metal and Nonmetal Mine Safety and Health

FROM: *John L. Odell*
JOHN L. ODELL
Acting Chief, Mine Waste and Construction Division

SUBJECT: Review of Phase I Inspection Report, National Dam
Safety Program by Morrison-Maierle, Inc. for the
Zonolite Tailings Dam, near Libby, Lincoln County,
Montana, Construction Products Division of
W. R. Grace & Company

In response to a request by Wilbur Guthrie, Jr., Supervisory Mine Inspector, Salt Lake City Subdlstrlct Field Office, Helena, Montana, the Phase I Inspection Report, National Dam Safety Program, prepared by Morrison-Maierle, Inc., Consulting Engineers, was reviewed by the Safety and Health Technology Center, Denver, Colorado. The Seattle District Corps of Engineers has requested MSHA critique the report and submit their comments. The report was evaluated for compliance with MSHA's design guidelines for Impounding structures associated with metal/nonmetal mines and MSHA's current regulatory standard, section 57.20-10, title 30, Code of Federal Regulations, which states, "if failure of a water or silt retaining dam will create a hazard. It shall be of substantial construction and Inspected at regular Intervals."

According to the report, the dam is located such that Its failure could endanger many lives and cause excessive economic loss. The report also Indicates that the hydraulic facilities can handle up to 45 percent of the probable maximum flood (PMF). Larger floods would therefore overtop the dam. Since failure can cause loss of life, this office recommends that the facilltes be capable of handling 100 percent of the PMF.

The reservoir routing mentioned in the report was started at the minimum opening elevation of the decant tower. Since stoplogs will be placed in the decant opening as the tailings rise in the Impoundment, it would appear prudent to begin the flood routing at the top elevation of the final stoplog.

Two pipes cross the spillway approach channel at an elevation only slightly above the channel invert. The pipes and any debris trapped by the pipes can significantly reduce flow through the approach channel. Each pipe should be relocated to eliminate any impediment of flow.

it appears that a portion of the approach channel slideslopes is formed by embankment material of the dam. These slopes should be properly lined to prevent erosion of embankment material.

The spillway chute, consisting of a half section of 8-foot diameter corrugated metal pipe and sloped at a relatively steep 8 percent, is only anchored at the dam crest. We concur with the findings stated in the report that the structural integrity of the spillway chute would be questionable when carrying design flows. Since a failure of the chute may affect embankment safety, revisions in design and construction should be made.

Although the report states that the computed safety factors, in regard to embankment stability, exceed minimum recommended allowable safety factors for both static and seismic loading, the safety factors obtained were not stated. Our guidelines require minimum static and seismic factors of safety of 1.5 and 1.2 respectively, under maximum normal anticipated phreatic conditions.

Plate 5 indicates that two piezometers are located on the upstream face of the phase 5 embankment construction. Although the piezometers would have been beneficial in locating the phreatic line during the initial phases of embankment construction, the piezometers during phase 5 will be too close to the water surface in the impoundment to provide any significant data.

It appears that the total stress method was used in determining shear strengths for the stability analysis. For long-term design, an effective stress analysis would have been more appropriate. Also, a dry density of 138 pounds per cubic foot and cohesion of 4000 pounds per square foot seems to be unusually high for gravelly sand material, especially the cohesion in a consolidated-undrained triaxial test. In essence, an embankment with a downstream slope of 2 horizontal to 1 vertical and constructed to the height indicated in the report can be very marginal in regard to obtaining a 1.5 static factor of safety. Therefore, this area of the investigation should be emphasized strongly to verify the designs.

The drawings and most of the report indicate the embankment is ultimately to be 125 feet high. It is assumed that the embankment will be limited to 125 feet rather than the planned 200 feet indicated on pages vii, 10, 11, and 29 of the report.

If we can be of further assistance, please let us know.

cc: T. Shepich
J. Mulhern
F. Delimba
W. Guthrie
R. P. Sellevold



DEPARTMENT OF THE ARMY
SEATTLE DISTRICT, CORPS OF ENGINEERS
P.O. BOX C-3755
SEATTLE, WASHINGTON 98124

NPSIN-FM

10 SEP 1981

Mr. William McCalg
W. R. Grace and Company
P.O. Box 609
Libby, Montana 59923

Dear Mr. McCaig:

Thank you for your comments regarding the Phase I inspection report on Zonolite Tailings Dam. While your comments will be considered in preparation of the final report, we will further address some of your noted concerns.

As the report indicates, the evaluation of the hazard potential is based on engineering judgement and is not supported by a detailed study and/or dam breach analysis. If, as you suggest, the hazard was down-graded from "high" to "significant," the inspection guidelines would still recommend the project (because of its size) be capable of handling the full PMF.

By definition, the PMF is the flood expected from the most severe combination of meteorologic and hydrologic conditions that are reasonably possible in a given region. The probable maximum precipitation for your area was obtained from data published by the U.S. Weather Bureau. We have recommended that more detailed studies be performed to more clearly define the downstream hazard and appropriate spillway design flood along with the recommended minimum water storage volume. The outflow capacity for the spillway is governed by the entrance to the half-round pipe spillway regardless of the approach channel capacity. The control section has a maximum flow capacity of 200 cfs. This outflow was used in the PMF routing.

Thank you for your assistance and cooperation in inspecting Zonolite Tailings Dam.

Sincerely,

R.P. SELLEVOLD, P.E.
Chief, Engineering Division



MORRISON-MAIERLE, INC.
QUALITY ASSURANCE



Robert C. Fortis

Project Manager

Thomas M. Watson

Branch Manager or Department Head

Philip J. Perrine

Peer Reviewer

C.W. Keith

Principal-In-Charge

Chief Engineer No.

81-17

Date Approved

9-18-81

Project No.

1447-09-03 (33)



DEPARTMENT OF THE ARMY
SEATTLE DISTRICT, CORPS OF ENGINEERS
P.O. BOX C-3755
SEATTLE, WASHINGTON 98124

NPSN-FM

Mr. Rick Bondy
Chief, Engineering Bureau
Montana Department of Natural
Resources and Conservation
32 South Ewing
Helena, Montana 59601

Dear Mr. Bondy:

Inclosed are 15 copies of the approved dam safety inspection report on Zonolite Tailings Dam, prepared in accordance with Public Law 92-367, 8 August 1972.

This report presents an executive summary of the project, background information, details of the inspection and records evaluation, findings and recommendations.

Public release of the inspection report and initiation of public statements fall within the Governor's prerogatives. In addition to any public release the Governor might make, the U.S. Army Corps of Engineers will respond to news media and citizen inquiries and make the report accessible on request.

Sincerely,

1 Incl (15 copies)
As stated

LEON K. MORASKI
Colonel, Corps of Engineers
District Engineer

RECEIVED

SEP 01 1981

MONT DEPT OF NATURAL
RESOURCES & CONSERVATION



Schafer & Associates

P.O. Box 6186
Bozeman, MT 59715

(406) 587-3478

Waste Management
Land Reclamation
Resource Inventory
Agricultural Consulting

July 22, 1991

RECEIVED

JUL 28 1992

STATE LANDS

Mr. Pat Flantenberg
Department of State Lands
Hardrock Mining Bureau
1625 Eleventh Avenue
Helena, Montana 59620

Dear Pat:

Enclosed is a copy of our calculations of the rain on snow PMF event related to the proposed flood routing design at the W. R. Grace vermiculite mine. This should help you address this question in your Environmental Assessment report. We used a very conservative approach assuming an unlimited supply of snowpack, snowpack coverage over the entire drainage, and no allowance for infiltration losses. The January storm appears to provide the highest possibility for producing the rain on snow PMF. We calculated a 3-day storm of 11.1 inches producing an additional 2.8 inches of water in snowmelt. This storm was preceded by a 3-day pre-storm melt period which produced a rather substantial runoff of 140 cfs. This volume is successfully routed through the proposed tailings impoundment design without loss of storage capacity.

The PMP produced a peak discharge of 3704 cfs, substantially less than the 11,676 cfs produced in the thunderstorm PMP. However, this comparison is deceiving. Without an emergency spillway, the 4 ft. by 8 ft. box culvert safely passes a 0.50 PMF thunderstorm event while it will pass a 0.53 PMF rain on snow 3-day general storm PMF. Thus, the two storms are really quite comparable in terms of impoundment surge capacity. The proposed emergency spillway will provide additional flood routing capacity in both cases.

The Forest Service inquired about the .5 PMP recorded in the area which was referred to in our report. That event occurred on November 21-22, 1909 and rainfall data was taken at Snowshoe, Montana; 7.0 inches of precipitation was recorded in a 48 hour period. The same storm produced similar events in Rattlesnake Creek, Idaho and Sheep Hill, Idaho. This data is recorded in Hydrometeorological Report No. 43, Probable Maximum Precipitation, Northwest States (Tables 7-2 and 7-3).

If you have any questions or need additional information please call.

Sincerely,

Tom Hudson
Project Manager

**CALCULATION OF RAIN ON SNOW PMF FOR THE
PROPOSED TAILINGS IMPOUNDMENT STREAM ROUTING
AT THE W.R. GRACE MINE, LIBBY MT.**



P.O. Box 618,
Bozeman, MT 59715
(406) 587-3478 Fax: 587-0331

Schafer and Associates

Project: GR R. CAGE
Client Number: 102 Name: TAILINGS CLOSER
Date: 7/17/92 Sheet 1 of 1
By: K14

CALCULATION OF PMP FOR A RAIN OR SNOW PMP EVENT

I PMP

THE PROCEDURE USED FOR CALCULATION OF A WINTER GENERAL STORM PMP IS GIVEN IN CHAPTER II OF HYDRO-METEOROLOGICAL REPORT NO. 43, "PROBABLE MAXIMUM PRECIPITATION, NORTHWEST STATES", U.S. WEATHER BUREAU, NOVEMBER 1966.

CALCULATION WORKSHEETS TO DETERMINE THE 3-DAY GENERAL STORM FOR THE MONTHS OCTOBER THROUGH JUNE ARE ATTACHED. ALTHOUGH PMP'S FOR OCT-DEL AND APR-JUN ARE SOMEWHAT LARGER, THEY ARE PROBABLY NOT SUITABLE CASES BECAUSE SNOWCOVER AT THE 3000-6000 FOOT ELEVATION IS LIKELY TO BE INCOMPLETE OR SNOWPACK MAY BE INADEQUATE. THE INTENT IS TO LOOK AT A SITUATION WHERE FROZEN GROUND OR ICE MAY EFFECTIVELY REDUCE INFILTRATION LOSSES. OF THE MONTHS JAN-MAR, JANUARY APPEARS TO PROVIDE THE BEST OPPORTUNITY FOR PRODUCING A PMP EVENT OF THIS KIND. THE MAXIMUM SUSTAINABLE WIND (WHICH DRIVES THE PMP CALCULATION) IS COMPARABLE TO THAT IN MARCH. THE SUSTAINABLE WINDS WHICH IMPACT SNOWMELT ARE ALSO HIGHEST IN JANUARY. CONSEQUENTLY, A JANUARY 3-DAY GENERAL STORM HAS BE SELECTED FOR ANALYSIS.

II SNOWMELT

"SNOW HYDROLOGY", U.S. CORPS OF ENGINEERS, 1956 PROVIDES METHODOLOGY FOR ESTIMATING SNOWMELT DUE TO CONDUCTIVE HEAT EXCHANGE IN EQUATION G-186, WHICH APPLIES TO FORESTED AREAS.



P.O. Box 618
Bozeman, MT 59715
(406) 587-3478 Fax 587-0331

Project: W.R. LAKE
Client Number: 152 Name: Timothy Cooper
Date: 7/17/93 Sheet 3 of 3
By: TJH

Schafer and Associates

$$M_A = K(0.0084V)(0.22T_a' + 0.78T_d') + 0.029T_a'$$

OTHER FORMULAE APPLY IN HEAVILY FORESTED, PARTLY FORESTED, AND OPEN AREAS. THE VALUE IS IN INCHES/DAY

K = BASIC CONVECTION + CONDENSATION MELT FACTOR
(A CORRECTION FOR RELATIVE WIND EXPOSURE)

V = WIND VELOCITY (mi/hr)

T_a' = TEMPERATURE DIFFERENTIAL BETWEEN AIR @ 10' AND THE SURFACE

T_d' = DIFFERENTIAL DEWPOINT BETWEEN AIR @ 10' AND THE SURFACE


A K VALUE OF 0.6 WILL BE USED WHICH IS INTERMEDIATE BETWEEN AN OPEN AREA (K=1) AND A HEAVILY FORESTED AREA (K=0.2)

V, T_a' and T_d' WILL BE DETERMINED WATER BY METHODS IN HMR 43, CHAPTER VIII.

RAINFALL PRODUCES ADDITIONAL SNOWMELT AS RAIN IS COOLED TO 32° W CONTACT WITH SNOW/ICE. QUANTITY IS GIVEN BY

$$M_R = \frac{P(T_c' - 32)(1014/15 \text{ WATER} - ^\circ\text{F})}{144 \text{ BTU/15 ICE}}$$

M_R = INCHES/INCH OF PRECIPITATION



P.O. Box 618
Bozeman, MT 59715
(406) 587-3478 Fax: 587-0331

Project: W-1. 400 E
Client Number 12 Name: TAMMIS BOGGS
Date: 7/1/92 Sheet 1 of 1
By: JSN

Schafer and Associates

III WEATHER CONDITIONS PRIOR TO & DURING FPM

HMR 43 CHAPTER VII GIVES PROCEDURES FOR ESTIMATING WIND, TEMPERATURE AND DEWPOINTS FROM A DRIED APMC EVENT FOR SNOWMELT COMPUTATIONS. THESE CALCULATIONS FOLLOW:

A. TEMPERATURE & DEWPOINT DURING FPM

- (1) 51°F (12 HR 1000 mb Dewpt)
- (2) 0.88" precipitable water (Wp)
- (3) Percentage ratios (FROM FIG 3-14)

6-HR PERIODS

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|------|------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 1.04 | 1.00 | .97 | .95 | .92 | .90 | .89 | .87 | .85 | .84 | .82 | .81 |

(4) W(p) FOR TIME INCREMENTS

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| .91 | .88 | .85 | .84 | .81 | .79 | .78 | .77 | .75 | .74 | .72 | .71 |

(5) MID-JANUARY 1000 mb TEMPERATURES (FIG 8-2)

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|------|------|------|------|------|------|------|------|------|------|------|------|
| 51.7 | 51.0 | 50.3 | 50.2 | 49.5 | 49.1 | 48.8 | 48.6 | 48.1 | 47.9 | 47.3 | 47.0 |



P.O. Box 618
Bozeman, MT 59715
(406) 587-3478 Fax: 587-0331

Project: 10.1 C.F.R.
Client Number: 102 Name: TAILINGS CLOSURE
Date: 7/1/99 Sheet 4 of 4
By: NH

Schafer and Associates

(6) TEMPERATURE REDUCED TO 4000' AVERAGE
BASIN ELEVATION

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|------|------|------|------|------|------|------|------|------|------|------|------|
| 34.9 | 36.1 | 36.5 | 37.8 | 37.3 | 36.6 | 37.7 | 36.9 | 35.8 | 35.2 | 34.1 | 33.7 |

(7) REARRANGE FOR PMP SEQUENCE

BY TIME: 1 2 3 4 5 6 7 8 9 10 11 12
BY INTENSITY: (9 & 8) 4 2 1 3 (5 & 6) (9 & 10) (11 & 12)

RAINFALL .5 .5 .9 1.7 3.5 1.1 .8 .7 .5 .4 .3 .2
TEMP 35.8 36.1 37.7 38.5 39.3 37.8 36.9 36.5 35.2 34.9 34.1 33.7

B. TEMPERATURES PRIOR TO PMP STORM

(1) 35.8°F

(2) JANUARY TEMPERATURE CHANGES PRIOR
TO STORM (FROM FIG - 8-1)

NO CHANGES REQUIRED

(3) USE 35.8°F FOR 72 HR PRIOR TO STORM

C. DEWPOINTS PRIOR TO PMP STORM (FIG. 8-1)

(1) 6 HR - PERIOD PRIOR TO STORM

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|---------|---|---|---|---|---|---|---|---|----|----|----|
| ADJUST. | 0 | 1 | 1 | 1 | 2 | 2 | 2 | 3 | 3 | 4 | 4 |

(2) 35.8 34.8 34.8 34.8 33.8 33.8 33.8 32.8 32.8 32.8 31.8 31.8



P.O. Box 618,
Bozeman, MT 59715
(406) 587-3478 Fax: 587-0331

Schafer and Associates

Project: W. R. GRACE
Client Number: 102 Name: TAILINGS CURVE
Date: 7/17/92 Sheet 1 of 1
By: NTH

D. WINDS DURING PMP

1) BASIN AOE ELEVATION = 4800'

AOE PRESSURE = 870 mb

2) 6 hr Jan. anemometer winds @ 7700 ft
= 35 kts or 40 mph

3) Jan 6 hr % = 100%

4) 40 mph = MAXIMUM WIND VELOCITY

5) DURATION FACTORS FROM FIG. 4-35

L-HR PERIOD

| | | | | | | | | | | | |
|------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| 1.00 | .92 | .86 | .79 | .73 | .68 | .64 | .61 | .58 | .56 | .53 | .52 |

6) CORRECTED WIND VELOCITIES


| | | | | | | | | | | | |
|----|----|----|----|----|----|----|----|----|----|----|----|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| 40 | 37 | 34 | 32 | 29 | 27 | 26 | 24 | 23 | 22 | 21 | 21 |

7) REARRANGED FOR PMP SEQUENCER

| | | | | | | | | | | | |
|----|----|----|----|----|----|----|----|----|----|----|----|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| 24 | 26 | 32 | 37 | 40 | 34 | 29 | 27 | 23 | 22 | 21 | 21 |

E. WINDS PRIOR TO PMP

USE 24 mph for 72 hours



P.O. Box 6186
Bozeman, MT 59715
(406) 587-3478 Fax: 587-0331

Project: 11.2 - DDC
Client Number 102 Name: TAN INGS (P) SURE
Date: 7/17/92 Sheet 6 of —
By: TJH

Schafer and Associates

IV PMF CALCULATIONS

DATA REGARDING RAINFALL AND WEATHER CONDITIONS WERE ENTERED INTO A SPREADSHEET TO CALCULATE RUN-OFF INTENSITIES. NO ALLOWANCE WAS MADE FOR INFILTRATION LOSSES.

CALCULATION OF THE PMF IS BASED ON THE UNIT HYDROGRAPH METHOD DESCRIBED IN "FLOOD HYDROLOGY MANUAL" U.S. BUREAU OF RECLAMATION, 1989. THIS IS THE SAME METHOD AS USED FOR THE THUNDERSTORM PMF BUT AMENDED TO INCLUDE SNOWMELT AND CALCULATED WITHOUT ALLOWANCE FOR INFILTRATION.

AN INITIAL EVALUATION OF PRE-STORM SNOW MELT SHOWED THAT IN THE PRESENCE OF INFILTRATION A SUBSTANTIAL DISCHARGE COULD BE PRODUCED (~100 GFS). SEE ATTACHED FIGURES. HOWEVER, THIS WILL BE RAPIDLY DISCHARGED BY THE BOX-CULVERT WITHOUT LOSS OF STORAGE CAPACITY.

THE HYDROGRAPH OF THE 3-DAY STORM PRODUCED A PEAK RUNOFF OF 3704 GFS. WHILE THE PEAK FLOW IS MUCH LOWER THAN THE THUNDERSTORM PMF, THE DURATION IS MUCH LONGER. WITHOUT AN EMERGENCY SPILLWAY THE RESERVOIR WILL SAFELY PASS A 0.53 DAY ON SNOW PMF EVENT. THE PROPOSED EMERGENCY SPILLWAY PROVIDE ADDITIONAL FLOOD ROUTING CAPACITY.

ATTACHMENT A
3-DAY GENERAL STORM
PMP WORKSHEETS

Table 6-1

Basin W. D. G. R. T. M. S.Basin Size 9.4 Sq. Mi.

PART I. CONVERGENCE PMP (In.)

LEGEND

- A Stimulation-elevation-barrier factor. Figs. 3-37a to c.
 B 24-hr. 1000-mb. 10-sq. mi. PMP. Figs. 3-23a through 3-31a.
 C Product of A and B.
 O 6/24-hr. ratios. Figs. 3-23b through 3-31b.
 E 6-hr. 10-sq. mi. PMP. (Product of C and O)
 P Incremental percents. Table 3-3. 6-hr. periods through P_4 , 12 hrs. for P_6 , P_8 , P_{10} and P_{12}
 G Basin size reduction. Figs. 3-40a or 3-40b. First four periods only.
 H Product of P and G (each of first four periods). No entry later periods.
 I Accumulated increments. $I_2 = H_1 + H_2$, $I_3 = I_2 + H_3$, $I_4 = I_3 + H_4$, $I_6 = I_4 + P_6$, $I_8 = I_6 + P_8$, etc.
 J Accumulated basin average convergence PMP, $E \times K_1$, I_1 , I_3 , etc.

| A = 0.62 | | | | | | | | | | | | | | | |
|----------|--------------------|----------------|----------------|-----------------|---------------------|--------------------|-----------------|---------------------|-------------------|----------------|--------------------|----------------|----------------|--|--|
| | Through 1st period | | | | | | | | Through 2d period | | | | | | |
| | B | C | D | E | F ₁ | G ₁ | H ₁ | J ₁ | F ₂ | G ₂ | H ₂ | I ₂ | J ₂ | | |
| OCT | 9.8 | 6.1 | .60 | 3.7 | 1.00 | 1.00 | 1.00 | 3.7 | .34 | 1.00 | .34 | 1.34 | 5.0 | | |
| NOV | 8.8 | 5.5 | .59 | 3.2 | 1.00 | 1.00 | 1.00 | 3.2 | .35 | 1.00 | .35 | 1.35 | 4.3 | | |
| DEC | 8.1 | 5.0 | .58 | 2.9 | 1.00 | 1.00 | 1.00 | 2.9 | .36 | 1.00 | .36 | 1.36 | 3.9 | | |
| JAN | 7.8 | 4.8 | .58 | 2.8 | 1.00 | 1.00 | 1.00 | 2.8 | .36 | 1.00 | .36 | 1.36 | 3.8 | | |
| FEB | 7.4 | 4.6 | .58 | 2.7 | 1.00 | 1.00 | 1.00 | 2.7 | .34 | 1.00 | .36 | 1.26 | 3.7 | | |
| MAR | 7.6 | 4.7 | .59 | 2.8 | 1.00 | 1.00 | 1.00 | 2.8 | .35 | 1.00 | .35 | 1.35 | 3.8 | | |
| APR | 9.0 | 5.6 | .61 | 3.4 | 1.00 | 1.00 | 1.00 | 3.4 | .33 | 1.00 | .33 | 1.33 | 4.5 | | |
| MAY | 11.2 | 6.9 | .62 | 4.3 | 1.00 | 1.00 | 1.00 | 4.3 | .21 | 1.00 | .31 | 1.31 | 5.6 | | |
| JUNE | 13.1 | 8.1 | .65 | 5.4 | 1.00 | 1.00 | 1.00 | 5.4 | .26 | 1.00 | .26 | 1.26 | 6.2 | | |
| | Through 3d period | | | | | Through 4th period | | | | | Through 6th period | | | | |
| | F ₃ | C ₃ | H ₃ | I ₃ | J ₃ | F ₄ | G ₄ | H ₄ | I ₄ | J ₄ | F ₆ | I ₆ | J ₆ | | |
| OCT | .20 | 1.00 | .20 | 1.54 | 5.7 | .14 | 1.00 | .14 | 1.68 | 6.2 | .19 | 1.87 | 6.9 | | |
| NOV | .20 | 1.00 | .20 | 1.55 | 5.0 | .15 | 1.00 | .15 | 1.70 | 5.4 | .20 | 1.90 | 6.1 | | |
| DEC | .21 | 1.00 | .21 | 1.57 | 4.6 | .15 | 1.00 | .15 | 1.72 | 5.0 | .21 | 1.93 | 5.6 | | |
| JAN | .21 | 1.00 | .21 | 1.57 | 4.4 | .15 | 1.00 | .15 | 1.72 | 4.8 | .21 | 1.93 | 5.4 | | |
| FEB | .21 | 1.00 | .21 | 1.57 | 4.2 | .15 | 1.00 | .15 | 1.72 | 4.6 | .21 | 1.93 | 5.2 | | |
| MAR | .20 | 1.00 | .20 | 1.55 | 4.3 | .15 | 1.00 | .15 | 1.70 | 4.8 | .20 | 1.90 | 5.3 | | |
| APR | .19 | 1.00 | .19 | 1.52 | 5.2 | .13 | 1.00 | .13 | 1.65 | 5.6 | .18 | 1.83 | 6.2 | | |
| MAY | .18 | 1.00 | .18 | 1.49 | 6.4 | .12 | 1.00 | .12 | 1.61 | 6.9 | .16 | 1.77 | 7.6 | | |
| JUNE | .14 | 1.00 | .14 | 1.48 | 7.6 | .10 | 1.00 | .10 | 1.50 | 8.1 | .13 | 1.63 | 8.8 | | |
| | Through 8th period | | | | Through 10th period | | | Through 12th period | | | | | | | |
| | F ₈ | I ₈ | J ₈ | F ₁₀ | I ₁₀ | J ₁₀ | F ₁₂ | I ₁₂ | J ₁₂ | | | | | | |
| OCT | .13 | 2.00 | 7.4 | .10 | 2.10 | 7.8 | .09 | 2.19 | 8.1 | | | | | | |
| NOV | .14 | 2.04 | 6.5 | .11 | 2.15 | 6.9 | .09 | 2.24 | 7.2 | | | | | | |
| DEC | .15 | 2.08 | 6.0 | .12 | 2.20 | 6.4 | .10 | 2.30 | 6.7 | | | | | | |
| JAN | .15 | 2.08 | 5.8 | .12 | 2.25 | 6.2 | .10 | 2.30 | 6.4 | | | | | | |
| FEB | .15 | 2.08 | 5.6 | .12 | 2.20 | 5.9 | .10 | 2.30 | 6.2 | | | | | | |
| MAR | .14 | 2.04 | 5.7 | .11 | 2.15 | 6.0 | .09 | 2.24 | 6.3 | | | | | | |
| APR | .12 | 1.85 | 6.6 | .10 | 2.05 | 7.0 | .08 | 2.13 | 7.2 | | | | | | |
| MAY | .11 | 1.88 | 8.1 | .10 | 1.98 | 8.5 | .08 | 2.04 | 8.9 | | | | | | |
| JUNE | .09 | 1.72 | 9.3 | .08 | 1.80 | 9.7 | .06 | 1.86 | 10.0 | | | | | | |

PART II. OROGRAPHIC PMP (In.)

LEGEND

- K Basin size factor. Figs. 4-39
 L 6-hr. orographic Index. Grid average over basin. Figs. 4-33a to c.
 M Product of K and L.

| | | |
|---|---|------|
| K | = | 1.00 |
| L | = | .8 |
| M | = | .8 |

Table 6-1 (Cont'd.)

Basin

W.R. COCKEWest of Cascade Divide

Table Q obtained by multiplying M times the accumulated orographic seasonal-durational factors below:

| | | <u>Accumulated factors</u> | | | | | | | |
|------|------|----------------------------|------|------|------|------|------|------|--|
| Per. | 1 | 2 | 3 | 4 | 6 | 8 | 10 | 12 | |
| Mr. | 6 | 12 | 18 | 24 | 36 | 48 | 60 | 72 | |
| OCT | 1.08 | 2.04 | 2.91 | 3.67 | 4.96 | 5.97 | 6.76 | 7.37 | |
| NOV | 1.07 | 2.02 | 2.88 | 3.64 | 4.91 | 5.92 | 6.70 | 7.30 | |
| DEC | 1.04 | 1.97 | 2.80 | 3.54 | 4.77 | 5.75 | 6.51 | 7.09 | |
| JAN | 1.00 | 1.89 | 2.69 | 3.40 | 4.59 | 5.53 | 6.26 | 6.82 | |
| FEB | 1.00 | 1.89 | 2.69 | 3.40 | 4.59 | 5.53 | 6.26 | 6.82 | |
| MAR | .95 | 1.80 | 2.56 | 3.23 | 4.36 | 5.25 | 5.95 | 6.48 | |
| APR | .87 | 1.64 | 2.34 | 2.96 | 3.99 | 4.81 | 5.45 | 5.93 | |
| MAY | .76 | 1.44 | 2.04 | 2.58 | 3.49 | 4.20 | 4.76 | 5.18 | |
| JUNE | .68 | 1.29 | 1.83 | 2.31 | 3.12 | 3.76 | 4.26 | 4.64 | |

East of Cascade Divide

| | | O | N | D | J | F | M | A | M | J |
|------|---|---------------------------------------|------|------|------|------|------|------|------|------|
| N | | .92 | .97 | .94 | .90 | .90 | .90 | .85 | 1.00 | 1.00 |
| | | <u>Accumulated durational factors</u> | | | | | | | | |
| Per. | 1 | 2 | 3 | 4 | 6 | 8 | 10 | 12 | | |
| Ur. | 6 | 12 | 18 | 24 | 36 | 48 | 60 | 72 | | |
| | | 1.00 | 1.89 | 2.69 | 3.40 | 4.59 | 5.48 | 6.09 | 6.46 | |

P* .80 1.51 2.15 2.72 3.47 4.38 4.87 5.17

P* = M x durational factors

Multiply values in line P by percents in line M to get basin orographic PMP. Enter in table Q.

O. Accumulated Orographic PMP (in.)

| | | <u>Duration (hr.)</u> | | | | | | | |
|------|--|-----------------------|-----|-----|-----|-----|-----|-----|-----|
| | | 6 | 12 | 18 | 24 | 36 | 48 | 60 | 72 |
| OCT | | 2.8 | 1.5 | 2.2 | 2.7 | 3.7 | 4.3 | 4.8 | 5.1 |
| NOV | | 2.8 | 1.5 | 2.1 | 2.6 | 3.6 | 4.2 | 4.7 | 5.0 |
| DEC | | 1.8 | 1.4 | 2.0 | 2.6 | 3.4 | 4.1 | 4.6 | 4.9 |
| JAN | | 1.7 | 1.4 | 1.9 | 2.4 | 3.3 | 3.9 | 4.4 | 4.7 |
| FEB | | 1.7 | 1.4 | 1.9 | 2.4 | 3.3 | 3.9 | 4.4 | 4.7 |
| MAR | | 1.7 | 1.4 | 1.9 | 2.4 | 3.3 | 3.9 | 4.4 | 4.7 |
| APR | | 1.8 | 1.4 | 2.0 | 2.6 | 3.5 | 4.2 | 4.6 | 4.9 |
| MAY | | 1.8 | 1.5 | 2.2 | 2.7 | 3.7 | 4.4 | 4.9 | 5.2 |
| JUNE | | 1.8 | 1.5 | 2.2 | 2.7 | 3.7 | 4.4 | 4.9 | 5.2 |

PART III. TOTAL PMP (in.)


| | | <u>Duration (hr.)</u> | | | | | | | |
|------|--|-----------------------|-----|-----|------|------|------|------|------|
| | | 6 | 12 | 18 | 24 | 36 | 48 | 60 | 72 |
| OCT | | 4.5 | 6.5 | 7.9 | 8.9 | 10.6 | 11.7 | 12.6 | 13.2 |
| NOV | | 4.0 | 5.8 | 7.1 | 8.0 | 9.7 | 10.7 | 11.6 | 12.2 |
| DEC | | 3.7 | 5.3 | 6.1 | 7.6 | 9.0 | 10.1 | 11.0 | 11.6 |
| JAN | | 3.5 | 5.2 | 6.3 | 7.2 | 8.7 | 9.7 | 10.6 | 11.1 |
| FEB | | 3.4 | 5.1 | 6.1 | 7.0 | 8.5 | 9.5 | 10.3 | 10.9 |
| MAR | | 3.5 | 5.2 | 6.2 | 7.2 | 8.6 | 9.6 | 10.4 | 11.0 |
| APR | | 4.2 | 5.9 | 7.2 | 8.2 | 9.7 | 10.8 | 11.6 | 12.1 |
| MAY | | 5.1 | 7.1 | 8.6 | 9.6 | 11.3 | 12.5 | 13.4 | 14.1 |
| JUNE | | 6.2 | 8.3 | 9.8 | 11.8 | 13.5 | 13.7 | 14.6 | 15.2 |

ATTACHMENT B

**HYDROGRAPHS FOR
RAIN ON SNOW PMP**


W.R. GRACE PMF FLOOD HYDROGRAPH

3-DAY PRE-STORM RUNOFF




W.R. GRACE HYDROGRAPH

RAIN ON SNOW PMF



W.R. GRACE HYDROGRAPH

MAXIMUM STORM CAPACITY



ATTACHMENT C

**SPREADSHEET OUTPUT FOR
RAIN ON SNOW PMP**

| Time Interval | Air Temp. | Dewpoint | Wind Speed | Increment Convective Snowmelt | Increment Rainfall | Increment Contact Snowmelt | Increment Intn. | Increment Runoff | Rainy Creek Unit Hydrograph | Restwood Creek Unit Hydrograph | Rainy Creek Discharge | Restwood Creek Discharge | Residual Pac-Storm Discharge | Total Discharge |
|------------------|-----------|----------|---------------|-------------------------------------|-----------------------|----------------------------------|--------------------|---------------------|-----------------------------------|--------------------------------------|-----------------------------|--------------------------------|------------------------------------|--------------------|
| (hours) | (F) | (F) | (mph) | (inches) | (inches) | (inches) | (inches) | (inches) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) |
| 0.00 | 35.8 | 35.8 | 24 | 0.0118 | 0.0417 | 0.0011 | | 0.0546 | 0 | 0 | | | 141 | |
| 0.50 | 35.8 | 35.8 | 24 | 0.0119 | 0.0417 | 0.0011 | | 0.0546 | 61 | 76 | 0 | 0 | 141 | 141 |
| 1.00 | 35.8 | 35.8 | 24 | 0.0118 | 0.0417 | 0.0011 | | 0.0546 | 149 | 273 | 3 | 4 | 140 | 146 |
| 1.50 | 38.0 | 35.8 | 24 | 0.0110 | 0.0417 | 0.0011 | | 0.0546 | 319 | 673 | 11 | 19 | 137 | 187 |
| 2.00 | 35.8 | 35.8 | 24 | 0.0110 | 0.0417 | 0.0011 | | 0.0546 | 949 | 640 | 29 | 56 | 126 | 212 |
| 2.50 | 35.8 | 35.8 | 24 | 0.0119 | 0.0417 | 0.0011 | | 0.0546 | 866 | 612 | 89 | 102 | 112 | 273 |
| 3.00 | 35.8 | 35.8 | 24 | 0.0110 | 0.0417 | 0.0011 | | 0.0546 | 967 | 401 | 106 | 139 | 94 | 335 |
| 3.50 | 35.8 | 35.8 | 24 | 0.0119 | 0.0417 | 0.0011 | | 0.0546 | 607 | 202 | 150 | 197 | 76 | 303 |
| 4.00 | 35.8 | 35.8 | 24 | 0.0110 | 0.0417 | 0.0011 | | 0.0546 | 533 | 226 | 203 | 173 | 63 | 439 |
| 4.50 | 35.8 | 35.8 | 24 | 0.0110 | 0.0417 | 0.0011 | | 0.0546 | 442 | 183 | 232 | 189 | 54 | 471 |
| 5.00 | 35.8 | 35.8 | 24 | 0.0119 | 0.0417 | 0.0011 | | 0.0546 | 358 | 144 | 256 | 195 | 46 | 496 |
| 5.50 | 35.8 | 35.8 | 24 | 0.0110 | 0.0417 | 0.0011 | | 0.0546 | 274 | 126 | 276 | 203 | 40 | 516 |
| 6.00 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 299 | 110 | 291 | 210 | 65 | 536 |
| 6.50 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 217 | 04 | 305 | 217 | 31 | 983 |
| 7.00 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 194 | 61 | 317 | 222 | 27 | 567 |
| 7.50 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 171 | 70 | 326 | 226 | 24 | 060 |
| 8.00 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 153 | 57 | 339 | 233 | 21 | 593 |
| 8.50 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 128 | 53 | 349 | 236 | 19 | 605 |
| 9.00 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0505 | 127 | 49 | 356 | 241 | 16 | 615 |
| 9.50 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 114 | 39 | 366 | 244 | 14 | 625 |
| 10.00 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 99 | 33 | 373 | 247 | 13 | 633 |
| 10.50 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 99 | 29 | 380 | 249 | 11 | 639 |
| 11.00 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 85 | 21 | 389 | 251 | 10 | 646 |
| 11.50 | 36.1 | 36.1 | 26 | 0.0137 | 0.0417 | 0.0012 | | 0.0565 | 77 | 16 | 391 | 292 | 8 | 691 |
| 12.00 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0030 | | 0.1006 | 66 | 11 | 395 | 253 | 7 | 656 |
| 12.30 | 37.7 | 37.7 | 32 | 0.0220 | 0.0750 | 0.0080 | | 0.1006 | 64 | 7 | 402 | 286 | 6 | 586 |
| 13.00 | 37.7 | 37.7 | 32 | 0.0226 | 0.0700 | 0.0030 | | 0.1006 | 59 | 0 | 412 | 270 | 5 | 666 |
| 13.50 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0030 | | 0.1006 | 54 | | 430 | 300 | 5 | 734 |
| 14.00 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0030 | | 0.1006 | 46 | | 457 | 337 | 4 | 798 |
| 14.50 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0030 | | 0.1006 | 45 | | 496 | 384 | 3 | 866 |
| 15.00 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0000 | | 0.1006 | 40 | | 544 | 362 | 3 | 928 |
| 15.50 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0030 | | 0.1006 | 34 | | 582 | 395 | 2 | 979 |
| 16.00 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0080 | | 0.1006 | 34 | | 607 | 409 | 2 | 1014 |
| 16.50 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0030 | | 0.1006 | 30 | | 629 | 413 | 2 | 1043 |
| 17.00 | 37.7 | 37.7 | 32 | 0.0226 | 0.0750 | 0.0090 | | 0.1006 | 26 | | 646 | 419 | 1 | 1067 |
| 17.50 | 37.7 | 37.7 | 32 | 0.0326 | 0.0750 | 0.0090 | | 0.1006 | 22 | | 660 | 429 | 1 | 1068 |
| 18.00 | 38.5 | 38.5 | 37 | 0.0292 | 0.1417 | 0.0084 | | 0.1772 | 17 | | 673 | 430 | 1 | 1103 |
| 18.50 | 38.5 | 38.5 | 37 | 0.0292 | 0.1417 | 0.0084 | | 0.1772 | 16 | | 666 | 440 | 0 | 1126 |
| 19.00 | 38.5 | 38.9 | 37 | 0.0292 | 0.1417 | 0.0084 | | 0.1772 | 11 | | 706 | 464 | 0 | 1173 |

| Time Interval | Air Temp. | Gaugpoint | Wind Speed | Increment Convective Snowmelt | Increment Rainfall | Increment Contact Snowmelt | Increment Infiltr. | Increment Runoff | Rainy Creek Unit Hydrograph | Fleetwood Creek Unit Hydrograph | Rainy Creek Discharge | Fleetwood Creek Discharge | Residual Pte-8 Alarm Discharge | Total Discharge |
|------------------|------------|------------|---------------|-------------------------------------|-----------------------|----------------------------------|-----------------------|---------------------|-----------------------------------|---------------------------------------|-----------------------------|---------------------------------|--------------------------------------|--------------------|
| <u>Quarry</u> | <u>(F)</u> | <u>(F)</u> | <u>(mph)</u> | <u>(Inches)</u> | <u>(Inches)</u> | <u>(Inches)</u> | <u>(Inches)</u> | <u>(Inches)</u> | <u>(cfs)</u> | <u>(cfs)</u> | <u>(cfs)</u> | <u>(cfs)</u> | <u>(cfs)</u> | <u>(cfs)</u> |
| 19.90 | 38.5 | 38.8 | 37 | 0.8282 | 0.1417 | 0.0084 | | 0.1772 | 7 | | 741 | 519 | 0 | 1260 |
| 20.00 | 38.8 | 38.8 | 37 | 0.8292 | 0.1417 | 0.0084 | | 0.1772 | 3 | | 790 | 568 | 0 | 1378 |
| 20.50 | 38.5 | 38.8 | 37 | 0.0202 | 0.1417 | 0.0084 | | 0.1772 | 0 | | 883 | 635 | 0 | 1498 |
| 21.00 | 38.5 | 38.8 | 37 | 0.0202 | 0.1417 | 0.0084 | | 0.1772 | | | 043 | 688 | 0 | 1811 |
| 21.50 | 38.8 | 38.5 | 37 | 0.8292 | 0.1417 | 0.0084 | | 0.1772 | | | 1010 | 692 | 0 | 1702 |
| 22.00 | 38.8 | 38.9 | 37 | 0.0292 | 0.1417 | 0.0084 | | 0.1772 | | | 1055 | 711 | 0 | 1788 |
| 22.50 | 38.8 | 38.9 | 37 | 0.8292 | 0.1417 | 0.0084 | | 0.1772 | | | 1093 | 728 | 0 | 1819 |
| 23.00 | 38.5 | 30.5 | 37 | 0.0292 | 0.1417 | 0.0084 | | 0.1772 | | | 1124 | 738 | 0 | 1882 |
| 23.50 | 38.5 | 38.8 | 37 | 0.0292 | 0.1417 | 0.0084 | | 0.1772 | | | 1149 | 749 | 0 | 1897 |
| 24.00 | 39.3 | 38.8 | 40 | 0.0351 | 0.2017 | 0.0148 | | 0.3415 | | | 1172 | 798 | 0 | 1920 |
| 24.50 | 39.3 | 39.8 | 40 | 0.0351 | 0.2917 | 0.0148 | | 0.8419 | | | 1201 | 778 | 0 | 1979 |
| 25.00 | 39.8 | 39.8 | 40 | 0.0351 | 0.2017 | 0.0148 | | 0.8415 | | | 1242 | 829 | 0 | 2071 |
| 25.50 | 39.3 | 39.8 | 40 | 0.0351 | 0.2917 | 0.0148 | | 0.8415 | | | 1310 | 945 | 0 | 2259 |
| 26.00 | 39.8 | 39.3 | 40 | 0.0351 | 0.5917 | 0.0148 | | 0.3415 | | | 1414 | 1067 | 0 | 2502 |
| 26.50 | 39.8 | 30.8 | 40 | 0.0351 | 0.2917 | 0.0148 | | 0.3418 | | | 1589 | 1192 | 0 | 2781 |
| 27.00 | 38.8 | 39.8 | 40 | 0.0351 | 0.5917 | 0.0148 | | 0.8415 | | | 1739 | 1281 | 0 | 3000 |
| 27.50 | 39.3 | 39.8 | 40 | 0.0351 | 0.8917 | 0.0148 | | 0.3419 | | | 1882 | 1312 | 0 | 3194 |
| 28.00 | 39.3 | 39.8 | 40 | 0.0391 | 0.2917 | 0.0148 | | 0.8415 | | | 1979 | 1352 | 0 | 3330 |
| 28.50 | 39.8 | 39.8 | 40 | 0.0351 | 0.8917 | 0.0148 | | 0.8415 | | | 2080 | 1384 | 0 | 3444 |
| 29.00 | 39.8 | 39.8 | 40 | 0.0351 | 0.2017 | 0.0148 | | 0.8415 | | | 2128 | 1409 | 0 | 3538 |
| 29.50 | 39.8 | 39.8 | 40 | 0.0351 | 0.2917 | 0.0148 | | 0.8419 | | | 2178 | 1432 | 0 | 3610 |
| 30.00 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 2228 | 1491 | 0 | 3677 |
| 30.50 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1108 | | | 2254 | 1449 | 0 | 3704 |
| 31.00 | 37.8 | 37.8 | 34 | 0.0242 | 0.0817 | 0.0037 | | 0.1108 | | | 8250 | 1402 | 0 | 3681 |
| 31.50 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 2221 | 1284 | 0 | 3485 |
| 32.00 | 37.8 | 37.8 | 34 | 0.8242 | 0.0917 | 0.0037 | | 0.1188 | | | 2128 | 1087 | 0 | 3215 |
| 32.50 | 37.8 | 37.8 | 34 | 0.0242 | 0.0017 | 0.0087 | | 0.1198 | | | 1859 | 980 | 0 | 2820 |
| 33.00 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 1789 | 078 | 0 | 2847 |
| 33.50 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 1811 | 820 | 0 | 2431 |
| 34.00 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 1512 | 779 | 0 | 2287 |
| 34.50 | 37.8 | 37.8 | 34 | 0.8242 | 0.0917 | 0.0087 | | 0.1198 | | | 1431 | 739 | 0 | 2171 |
| 35.00 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 1388 | 711 | 0 | 2079 |
| 35.50 | 37.8 | 37.8 | 34 | 0.0242 | 0.0917 | 0.0037 | | 0.1198 | | | 1321 | 888 | 0 | 2007 |
| 36.00 | 30.0 | 38.5 | 29 | 0.0179 | 0.0887 | 0.0023 | | 0.0888 | | | 1278 | 883 | 0 | 1839 |
| 36.50 | 38.9 | 38.9 | 29 | 0.0170 | 0.0887 | 0.0023 | | 0.0888 | | | 1238 | 841 | 0 | 1878 |
| 37.00 | 38.8 | 38.8 | 29 | 0.0170 | 0.0887 | 0.0023 | | 0.0888 | | | 1200 | 814 | 0 | 1814 |
| 37.50 | 38.8 | 38.8 | 29 | 0.0179 | 0.0887 | 0.0023 | | 0.0888 | | | 1181 | 978 | 0 | 1737 |
| 38.00 | 38.9 | 38.8 | 29 | 0.0179 | 0.0887 | 0.0023 | | 0.0888 | | | 1117 | 538 | 0 | 1853 |
| 38.50 | 38.8 | 38.8 | 20 | 0.0179 | 0.0887 | 0.0023 | | 0.0888 | | | 1088 | 504 | 0 | 1972 |

| Time | Air Temp. | Dampoint | Wind | Increment | Increment | Increment | Increment | Increment | Rainy | Fleetwood | Rainy | Fleetwood | Residual | Total |
|----------|-----------|----------|-------|------------|-----------|-----------|-----------|-----------|------------|------------|-----------|-----------|-----------|-----------|
| Interval | | | Speed | Convective | Rainfall | Contact | Intilt. | Runoff | Creek UnR | Creek Unit | Creek | Creek | Pro-Storm | Discharge |
| | | | | Snowmelt | | Snowmelt | | | Hydrograph | Hydrograph | Discharge | Discharge | Discharge | |
| (hours) | (F) | (F) | (mph) | (Inches) | (Inches) | (Inches) | (Inches) | (Inches) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) |
| 39.00 | 36.9 | 36.8 | 29 | 0.0179 | 0.0667 | 0.0023 | | 0.0666 | | | 1015 | 461 | 0 | 1496 |
| 39.30 | 36.9 | 36.9 | 29 | 0.0179 | 0.0667 | 0.0023 | | 0.0666 | | | 989 | 463 | 0 | 1431 |
| 40.00 | 36.9 | 36.9 | 29 | 0.0179 | 0.0607 | 0.0023 | | 0.0666 | | | 935 | 448 | 0 | 1303 |
| 40.30 | 36.9 | 36.9 | 29 | 0.0179 | 0.0667 | 0.0023 | | 0.0666 | | | 904 | 438 | 0 | 1340 |
| 41.00 | 36.9 | 36.9 | 29 | 0.0170 | 0.0667 | 0.0023 | | 0.0606 | | | 876 | 426 | 0 | 1304 |
| 41.30 | 36.9 | 36.0 | 29 | 0.0170 | 0.0667 | 0.0023 | | 0.0606 | | | 855 | 418 | 0 | 1273 |
| 42.00 | 36.9 | 36.5 | 27 | 0.0159 | 0.0583 | 0.0018 | | 0.0756 | | | 835 | 412 | 0 | 1247 |
| 42.30 | 36.5 | 36.9 | 27 | 0.0155 | 0.0583 | 0.0018 | | 0.0756 | | | 819 | 407 | 0 | 1222 |
| 43.00 | 36.5 | 36.5 | 27 | 0.0155 | 0.0583 | 0.0018 | | 0.0796 | | | 796 | 401 | 0 | 1197 |
| 43.30 | 36.9 | 36.5 | 27 | 0.0159 | 0.0583 | 0.0018 | | 0.0756 | | | 776 | 391 | 0 | 1167 |
| 44.00 | 36.5 | 36.5 | 27 | 0.0159 | 0.0583 | 0.0018 | | 0.0756 | | | 755 | 380 | 0 | 1139 |
| 44.30 | 36.9 | 36.9 | 27 | 0.0159 | 0.0583 | 0.0018 | | 0.0756 | | | 731 | 371 | 0 | 1102 |
| 49.00 | 36.9 | 36.9 | 27 | 0.0155 | 0.0583 | 0.0018 | | 0.0756 | | | 707 | 365 | 0 | 1072 |
| 49.30 | 36.5 | 30.5 | 27 | 0.0155 | 0.0583 | 0.0018 | | 0.0796 | | | 667 | 361 | 0 | 1046 |
| 46.00 | 36.9 | 36.9 | 27 | 0.0155 | 0.0583 | 0.0018 | | 0.0796 | | | 670 | 357 | 0 | 1027 |
| 46.30 | 36.5 | 36.9 | 27 | 0.0195 | 0.0583 | 0.0018 | | 0.0796 | | | 655 | 354 | 0 | 1009 |
| 47.00 | 36.5 | 36.5 | 27 | 0.0159 | 0.0583 | 0.0018 | | 0.0756 | | | 643 | 392 | 0 | 995 |
| 47.30 | 36.9 | 36.5 | 27 | 0.0159 | 0.0663 | 0.0018 | | 0.0756 | | | 632 | 350 | 0 | 982 |
| 48.00 | 35.9 | 39.2 | 23 | 0.0097 | 0.0417 | 0.0009 | | 0.0923 | | | 624 | 346 | 0 | 972 |
| 48.30 | 35.2 | 35.2 | 23 | 0.0097 | 0.0417 | 0.0005 | | 0.0923 | | | 614 | 345 | 0 | 959 |
| 49.00 | 35.9 | 35.9 | 23 | 0.0007 | 0.0417 | 0.0009 | | 0.0323 | | | 604 | 338 | 0 | 942 |
| 49.30 | 35.9 | 35.2 | 23 | 0.0007 | 0.0417 | 0.0009 | | 0.0529 | | | 592 | 321 | 0 | 913 |
| 50.00 | 35.9 | 35.9 | 23 | 0.0007 | 0.0417 | 0.0009 | | 0.0523 | | | 575 | 301 | 0 | 876 |
| 50.30 | 39.2 | 35.9 | 23 | 0.0007 | 0.0417 | 0.0005 | | 0.0523 | | | 552 | 286 | 0 | 838 |
| 51.00 | 35.2 | 35.2 | 23 | 0.0057 | 0.0417 | 0.0009 | | 0.0323 | | | 926 | 276 | 0 | 603 |
| 51.30 | 35.2 | 39.9 | 23 | 0.0097 | 0.0417 | 0.0009 | | 0.0523 | | | 505 | 269 | 0 | 774 |
| 52.00 | 39.2 | 35.9 | 23 | 0.0057 | 0.0417 | 0.0005 | | 0.0525 | | | 480 | 263 | 0 | 794 |
| 52.30 | 39.2 | 35.2 | 23 | 0.0007 | 0.0417 | 0.0009 | | 0.0923 | | | 476 | 259 | 0 | 737 |
| 53.00 | 35.9 | 35.9 | 23 | 0.0097 | 0.0417 | 0.0009 | | 0.0523 | | | 468 | 255 | 0 | 723 |
| 53.30 | 35.9 | 35.2 | 23 | 0.0097 | 0.0417 | 0.0000 | | 0.0523 | | | 460 | 252 | 0 | 712 |
| 54.00 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 492 | 240 | | 702 |
| 54.30 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 446 | 246 | | 692 |
| 55.00 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 430 | 242 | | 680 |
| 55.30 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0429 | | | 431 | 233 | | 664 |
| 56.00 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 421 | 224 | | 643 |
| 56.30 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0429 | | | 409 | 217 | | 628 |
| 57.00 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0429 | | | 386 | 212 | | 608 |
| 57.30 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0429 | | | 365 | 208 | | 593 |
| 58.00 | 34.9 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 377 | 205 | | 582 |

| Time Interval | Air Temp. | Dewpoint | Wind Speed | Increment Convective Snowmelt | Increment Rainfall | Increment Contact Snowmelt | Increment Infil. | Increment Runoff | Rainy Creek Unit Hydrograph | Fleetwood Creek Unit Hydrograph | Rainy Creek Discharge | Fleetwood Creek Discharge | Residual Pre-Stenn Discharge | Total Discharge |
|------------------|-----------|----------|---------------|-------------------------------------|-----------------------|----------------------------------|---------------------|---------------------|-----------------------------------|---------------------------------------|-----------------------------|---------------------------------|------------------------------------|--------------------|
| (lwars) | (F) | (F) | (mph) | (Inches) | (Inches) | (Inches) | (Inches) | (Inches) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) |
| 08.50 | 34.5 | 34.9 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 370 | 202 | | 973 |
| 09.00 | 34.5 | 34.5 | 22 | 0.0085 | 0.0333 | 0.0007 | | 0.0425 | | | 365 | 200 | | 969 |
| 09.50 | 34.5 | 34.5 | 22 | 0.0089 | 0.0333 | 0.0007 | | 0.0425 | | | 380 | 109 | | 989 |
| 09.00 | 34.1 | 34.1 | 21 | 0.0089 | 0.0250 | 0.0004 | | 0.0313 | | | 356 | 187 | | 953 |
| 09.30 | 34.1 | 34.1 | 21 | 0.0059 | 0.0250 | 0.0004 | | 0.0313 | | | 351 | 105 | | 547 |
| 01.00 | 34.1 | 34.1 | 21 | 0.0050 | 0.0250 | 0.0004 | | 0.0313 | | | 348 | 192 | | 538 |
| 01.30 | 34.1 | 34.1 | 21 | 0.0080 | 0.0250 | 0.0004 | | 0.0313 | | | 340 | 163 | | 523 |
| 02.00 | 34.1 | 34.1 | 21 | 0.0059 | 0.0250 | 0.0004 | | 0.0313 | | | 331 | 173 | | 904 |
| 02.50 | 34.1 | 34.1 | 21 | 0.0058 | 0.0250 | 0.0004 | | 0.0313 | | | 319 | 166 | | 465 |
| 03.00 | 34.1 | 34.1 | 21 | 0.0089 | 0.0290 | 0.0004 | | 0.0313 | | | 306 | 161 | | 467 |
| 03.50 | 34.1 | 34.1 | 21 | 0.0089 | 0.0200 | 0.0004 | | 0.0313 | | | 295 | 156 | | 452 |
| 04.00 | 34.1 | 34.1 | 21 | 0.0089 | 0.0250 | 0.0004 | | 0.0313 | | | 287 | 155 | | 442 |
| 04.50 | 34.1 | 34.1 | 21 | 0.0089 | 0.0250 | 0.0004 | | 0.0313 | | | 280 | 152 | | 433 |
| 05.00 | 34.1 | 34.1 | 21 | 0.0089 | 0.0250 | 0.0004 | | 0.0313 | | | 275 | 151 | | 426 |
| 05.50 | 34.1 | 34.1 | 21 | 0.0059 | 0.0250 | 0.0004 | | 0.0313 | | | 271 | 149 | | 420 |
| 06.00 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 267 | 148 | | 414 |
| 06.50 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0210 | | | 263 | 146 | | 406 |
| 07.00 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 256 | 142 | | 401 |
| 07.50 | 33.7 | 33.7 | 21 | 0.0048 | 0.5167 | 0.0002 | | 0.0216 | | | 253 | 135 | | 386 |
| 08.00 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 245 | 128 | | 371 |
| 08.50 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 235 | 120 | | 355 |
| 09.00 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 224 | 119 | | 339 |
| 09.50 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 214 | 112 | | 326 |
| 10.00 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 208 | 110 | | 317 |
| 10.50 | 33.7 | 33.7 | 21 | 0.0040 | 0.0167 | 0.0002 | | 0.0216 | | | 202 | 107 | | 310 |
| 11.00 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 196 | 106 | | 303 |
| 11.50 | 33.7 | 33.7 | 21 | 0.0048 | 0.0167 | 0.0002 | | 0.0216 | | | 194 | 104 | | 298 |
| 12.00 | | | | | | | | | | | 180 | 103 | | 294 |
| 12.50 | | | | | | | | | | | 166 | 101 | | 287 |
| 13.00 | | | | | | | | | | | 161 | 95 | | 276 |
| 13.50 | | | | | | | | | | | 173 | 62 | | 239 |
| 14.00 | | | | | | | | | | | 160 | 64 | | 224 |
| 14.50 | | | | | | | | | | | 141 | 49 | | 100 |
| 15.00 | | | | | | | | | | | 119 | 39 | | 190 |
| 15.50 | | | | | | | | | | | 99 | 32 | | 131 |
| 16.00 | | | | | | | | | | | 85 | 28 | | 111 |
| 16.50 | | | | | | | | | | | 74 | 22 | | 05 |
| 17.00 | | | | | | | | | | | 64 | 16 | | 63 |
| 17.50 | | | | | | | | | | | 57 | 19 | | 72 |

| Time Interval | Air Temp. | Dewpoint | Wind Speed | Increment Convective Snowmelt | Increment Rainfall | Increment Contact Snowmelt | Increment Infiltr. | Increment Runoff | Rainy Creek Unit Hydrograph | Forestwood Creek Unit Hydrograph | Rainy Creek Discharge | Forestwood Creek Discharge | Residual Pre-Storm Discharge | Total Discharge |
|------------------|-----------|----------|---------------|-------------------------------------|-----------------------|----------------------------------|-----------------------|---------------------|-----------------------------------|--|-----------------------------|----------------------------------|------------------------------------|--------------------|
|------------------|-----------|----------|---------------|-------------------------------------|-----------------------|----------------------------------|-----------------------|---------------------|-----------------------------------|--|-----------------------------|----------------------------------|------------------------------------|--------------------|


| (Hours) | (F) | (F) | (mph) | (Inches) | (Inches) | (Inches) | (Inches) | (Inches) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) | (cfs) |
|---------|-----|-----|-------|----------|----------|----------|----------|----------|-------|-------|-------|-------|-------|-------|
|---------|-----|-----|-------|----------|----------|----------|----------|----------|-------|-------|-------|-------|-------|-------|

| | | | | | | | | | | | | | | |
|-------|--|--|--|--|--|--|--|--|--|--|----|----|--|----|
| 78.00 | | | | | | | | | | | 91 | 13 | | 83 |
| 78.80 | | | | | | | | | | | 45 | 10 | | 55 |
| 79.00 | | | | | | | | | | | 40 | 9 | | 49 |
| 79.80 | | | | | | | | | | | 39 | 7 | | 43 |
| 80.00 | | | | | | | | | | | 32 | 8 | | 37 |
| 80.80 | | | | | | | | | | | 28 | 5 | | 33 |
| 81.00 | | | | | | | | | | | 29 | 4 | | 29 |
| 81.50 | | | | | | | | | | | 22 | 3 | | 25 |
| 82.50 | | | | | | | | | | | 20 | 2 | | 22 |
| 82.50 | | | | | | | | | | | 17 | 1 | | 19 |
| 83.00 | | | | | | | | | | | 15 | 1 | | 18 |
| 83.50 | | | | | | | | | | | 13 | 0 | | 14 |
| 84.00 | | | | | | | | | | | 12 | 0 | | 12 |
| 84.80 | | | | | | | | | | | 10 | 0 | | 10 |
| 85.00 | | | | | | | | | | | 9 | 0 | | 9 |
| 85.50 | | | | | | | | | | | 7 | 0 | | 7 |
| 86.00 | | | | | | | | | | | 8 | 0 | | 8 |
| 86.50 | | | | | | | | | | | 5 | 0 | | 8 |
| 87.00 | | | | | | | | | | | 4 | 0 | | 4 |
| 87.50 | | | | | | | | | | | 4 | 0 | | 4 |
| 88.00 | | | | | | | | | | | 3 | 0 | | 3 |
| 88.80 | | | | | | | | | | | 2 | 0 | | 2 |
| 89.00 | | | | | | | | | | | 2 | 0 | | 2 |
| 89.50 | | | | | | | | | | | 1 | 0 | | 1 |
| 90.00 | | | | | | | | | | | 1 | 0 | | 1 |
| 90.50 | | | | | | | | | | | 1 | 0 | | 1 |
| 91.00 | | | | | | | | | | | 0 | 0 | | 0 |
| 01.50 | | | | | | | | | | | 0 | 0 | | 0 |
| 02.00 | | | | | | | | | | | 0 | 0 | | 0 |

| | | | | | | | | | | | | | | |
|---------|--|--|--|-----|------|-----|-----|------|--|--|--|--|--|--|
| Totals: | | | | 2.4 | 11.1 | 0.4 | 0.0 | 13.0 | | | | | | |
|---------|--|--|--|-----|------|-----|-----|------|--|--|--|--|--|--|

A3-Reference 3

**ENGINEERING ANALYSIS OF
FLOOD ROUTING ALTERNATIVES**
for the
**W.R. GRACE VERMICULITE TAILINGS IMPOUNDMENT
LIBBY, MONTANA**



by:

Bruce K. Parker, P.E.¹

Thomas J. Hudson²

1 - Manager of Engineering Services, Schafer and Associates, Bozeman, MT

2 - Engineering Group Leader, Schafer and Associates, Bozeman, MT

Table of Contents

| Section | Description | Page |
|---------|--|------|
| 1.0 | EXECUTIVE SUMMARY | 1-1 |
| 2.0 | INTRODUCTION | 2-1 |
| 2.1 | OVERVIEW/PROJECT OBJECTIVES | 2-1 |
| 2.2 | PROJECT LOCATION AND DESCRIPTION | 2-2 |
| 2.3 | SITE HISTORY/BACKGROUND | 2-5 |
| 3.0 | HYDROLOGIC EVALUATION | 3-1 |
| 3.1 | HYDROLOGIC PARAMETERS | 3-1 |
| 3.2 | DESIGN STORMS | 3-3 |
| 3.2.1 | 10-Year Event | 3-4 |
| 3.2.2 | 100-Year Event | 3-4 |
| 3.2.3 | Probable Maximum Flood | 3-7 |
| 3.3 | TAILINGS IMPOUNDMENT CAPACITY | 3-9 |
| 3.4 | DAM SAFETY REQUIREMENTS | 3-10 |
| 3.5 | PROPOSED DESIGN FLOWS | 3-12 |
| 4.0 | FLOOD ROUTING | 4-1 |
| 4.1 | OVERVIEW OF ALTERNATIVES | 4-1 |
| 4.2 | FULL DIVERSION ALTERNATIVES | 4-3 |
| 4.2.1 | Description of Design Concepts | 4-3 |
| 4.2.2 | Evaluation of the Full Diversion Alternatives | 4-5 |
| 4.3 | CHANNEL RECONSTRUCTION THROUGH THE IMPOUNDMENT ... | 4-11 |
| 4.3.1 | Description of Design Concepts | 4-11 |
| 4.3.2 | Evaluation of Alternatives for Channel Reconstruction In the Tailings | 4-14 |
| 4.4 | PARTIAL DIVERSION | 4-18 |
| 4.4.1 | Description of Conceptual Designs | 4-18 |
| 4.4.2 | Evaluation of Partial Diversion Alternatives | 4-20 |
| 4.5 | SUMMARY/CONCLUSIONS | 4-22 |
| 5.0 | PROJECT DESIGN - PREFERRED ALTERNATIVE | 5-1 |
| 5.1 | GENERAL DESIGN APPROACH | 5-1 |
| 5.2 | TAILINGS IMPOUNDMENT | 5-2 |

| | | |
|-------|--|-----|
| 5.3 | INLET CHANNEL | 5-2 |
| 5.4 | CONTROL STRUCTURE | 5-3 |
| 5.4.1 | 100-Year Event | 5-3 |
| 5.4.2 | Probable Maximum Flood | 5-4 |
| 5.5 | OUTLET CHANNEL | 5-6 |
| 5.6 | EMERGENCY SPILLWAY | 5-6 |
| 5.7 | REVEGETATION | 5-7 |
| 5.8 | STABIUZATION/EROSION CONTROL | 5-8 |
| 5.9 | OTHER CLOSURE ACTIVITIES | 5-9 |
| 6.0 | POST-CLOSURE CARE | 6-1 |
| 6.1 | POST-CLOSURE MANAGEMENT | 6-1 |
| 6.2 | WATER QUALITY MONITORING PROGRAM | 6-1 |
| 6.3 | MAINTENANCE | 6-1 |
| 7.0 | REFERENCES | 7-1 |

List of Tables

| Number | Description | Page |
|---------------|--|-------------|
| Table 3.1. | Hydrologic parameters for Rainy Creek and Fleetwood Creek drainage areas impounded by the tailings dam. | 3-3 |
| Table 3.2. | Surface water runoff for a 10-year, 24-hour precipitation event using SCS Type II rainfall distribution. | 3-5 |
| Table 3.3. | Surface water runoff for a 100-year, 24-hour precipitation event using SCS Type II rainfall distribution. | 3-6 |
| Table 3.4. | Surface water runoff for a 6-hour PMF event (10.7 in.) using the storm distribution hyetograph of Figure 3.4. | 3-8 |
| Table 3.5. | Storage capacity of the tailings impoundment/reservoir drainage areas impounded by the tailings dam. | 3-10 |
| Table 3.6. | Emergency spillway inflow design flood(s) from Table A of the Montana Dam Safety regulations, Rule 36.14.502. | 3-11 |
| Table 3.7. | Design flood volumes proposed for flood routing alternatives analysis and conceptual design. | 3-13 |
| Table 4.1. | Summary of alternatives considered for flood routing. | 4-2 |
| Table 4.2. | Advantages associated with a full diversion flood routing system. .. | 4-8 |
| Table 4.3. | Disadvantages associated with full diversion flood routing system .. | 4-9 |
| Table 4.4. | Advantages associated with routing floods through the tailings impoundment. | 4-16 |
| Table 4.5. | Disadvantages associated with routing floods through the tailings impoundment. | 4-17 |
| Table 4.6. | Advantages associated with partial diversion flood routing systems. | 4-21 |
| Table 4.7. | Disadvantages associated with partial diversion flood routing systems. | 4-21 |
| Table 5.1. | Flood routing parameters for various routing alternatives. | 5-4 |

List of Figures

| Number | Description | Page |
|------------|---|------|
| Figure 2.1 | Location of the W.R. Grace Project Area | 2-3 |
| Figure 2.2 | W.R. Grace tailings impoundment. USGS Vermiculite Mountain, Mont Quadrangle, Lincoln Co. | 2-4 |
| Figure 3.1 | Drainage areas for Rainy Creek and Fleetwood Creek. | 3-2 |
| Figure 3.2 | Surface water runoff hydrographs and rainfall intensity for a 10-year, 24-hour storm (2.4 in.) in the Rainy Creek and Fleetwood Creek watersheds. | 3-5 |
| Figure 3.3 | Surface water runoff hydrographs and rainfall intensity for a 100-year, 24-hour storm (2.4 in.) in the Rainy Creek and Fleetwood Creek watersheds. | 3-6 |
| Figure 3.4 | Storm hyetograph for a 6-hour PMF event (10.7 in.) in the Rainy Creek and Fleetwood Creek drainage basins. | 3-8 |
| Figure 3.5 | Surface water runoff hydrographs for a 6-hour PMF event (10.7 in.) in the Rainy Creek and Fleetwood Creek watersheds. | 3-9 |

List of Drawing Plates

| Number | Description |
|------------|--|
| Plate 1. | Plan view of project area delineated by base grid system. |
| Plate 2. | Plan view of conceptual full diversion flood routing system employing a single diversion dam below the confluence of Rainy Creek and Fleetwood Creek. |
| Plate 3. | Cross-section A-A' showing typical section of diversion dam for a full diversion flood routing system. |
| Plate 4-A. | Plan view of full diversion dam and channel to deliver Fleetwood Creek to the Rainy Creek diversion dam. |
| Plate 4-B. | Plan view of Rainy Creek diversion system employing a dam upstream of tailings. |
| Plate 5. | Typical cross-section of west diversion channel showing limits of excavation. |
| Plate 6. | Typical section of the east side full diversion channel constructed partially within the fine tailings impoundment. |
| Plate 7. | Typical section of the east side full diversion channel constructed in bedrock, outside of the fine tailings. |
| Plate 8. | Plan view of flood routing through the impoundment in a reconstructed channel (Alternate 1la), showing location of inflow and outflow channels, and control structure. |
| Plate 9. | Plan view of flood routing system through the impoundment with low profile dike (Alternate 1lb) showing the dike and revised inflow channel. |
| Plate 10. | Plan view of the outlet/control structure over the dam face for routing floods through the impoundment (Alternate 1ie). |
| Plate 11. | Typical section for a partial diversion channel at west abutment area. |
| Plate 12. | Section showing centerline of channel for the proposed flood routing system for the vermiculite tailings impoundment. |
| Plate 13. | Typical cross-section of the inflow channel for the proposed flood routing system. |
| Plate 14. | Typical cross-section of the discharge control structure for the proposed flood routing system. |
| Plate 15. | Typical cross-section of the outflow channel for the flood routing system. |
| Plate 16. | Typical cross-section of the emergency relief spillway for the vermiculite tailings impoundment. |

Appendices

| Number | Description |
|---------------|---|
| Appendix A | Hydrologic Modeling Results |
| Appendix B | Probable Maximum Flood Calculations |
| Appendix C | Control Structure and Emergency Spillway Calculations |
| Appendix D | Flood Routing Results |
| Appendix E | Standard Drawing-SCS Drop Structure |

1.0 EXECUTIVE SUMMARY

An engineering analysis of flood routing alternatives was completed at the W.R. Grace vermiculite tailings impoundment, near Libby, Montana, to investigate the various alternatives for routing floods through the tailings impoundment following closure. W.R. Grace has ceased mining and milling operations at the site and wishes to complete closure operations and requirements during 1992 in order to obtain bond release.

Regulatory agencies, including the Department of State Lands (DSL), USDA Forest Service, and others have raised concerns over the mine closure, particularly the closure of the tailings impoundment. These concerns include:

- asbestiform fiber contamination in surface water from the coarse tailings dump and fine tailings impoundment;
- long-term stability and integrity of the dam, primarily with regard to saturation and seepage failure;
- increased sedimentation of downstream areas from the impoundment;
- safety; and finally,
- setting a precedence for other tailings impoundments.

In order to address these issues, an engineering analysis of flood routing alternatives was conducted. The purpose of the engineering analysis was to objectively examine the various alternatives for routing Rainy Creek and Fleetwood Creek flows through the area affected by the vermiculite tailings impoundment, and to present a conceptual plan of the preferred alternative. The analysis addressed the issues of hydrology and flood routing, dam safety, short-term and long-term environmental impact, construction feasibility, costs, long-term stability and erosion control, and proposed reclamation methods and practices.

The impoundment is situated on Rainy Creek, immediately below the confluence with Fleetwood Creek, and impounds approximately 9.4 square miles of the Rainy Creek drainage area. A design flood of 0.5 PMF, calculated at 5838 cfs, was selected as the inflow volume that would be used for flood routing through the impoundment.

The investigation determined that the best method to safely pass a design storm of this magnitude in a stable manner, while assuring the long-term integrity of the dam, is to route the storm through the impoundment using controlled outflow structures. By using the

impoundment to temporarily store peak inflows, outflow volumes can be reduced to a fraction of the 0.5 PMF peak inflow volume.

Routing the floods through the impoundment using controlled outflow structures provided the safest and most cost effective method of flood routing for the tailings impoundment while addressing the majority of the regulatory concerns. Significant advantages include:

- Provides a higher level of public safety than other alternatives while assuring the long-term integrity of the tailings dam and retaining a relatively straightforward design;
- Provides a cost-effective, relatively straightforward method of safely handling storm flows;
- During a 0.5 PMF event this design is geotechnically the most stable of the alternatives;
- System is capable of handling floods larger than the design flood of 0.5 PMF with the addition of an emergency spillway;
- Outflows are considerably less than 0.5 PMF due to flood routing, allowing for a smaller, more cost effective channel, and less downstream disturbance during major events;
- Environmental disturbance is kept to a minimum with the a smaller, more natural outflow channel;
- The remaining impoundment wetland promotes surface water improvement through natural filtration and settlement;
- Least overall maintenance of the alternatives;
- Minimal water loss to infiltration; and,
- Impoundment wetland would provide excellent wildlife habitat.

2.0 INTRODUCTION

2.1 OVERVIEW/PROJECT OBJECTIVES

W.R. Grace and Company, Zonolite Division, Libby, Montana, has retained Schafer and Associates, Bozeman, Montana, to perform an Engineering Analysis of Flood Routing Alternatives for Rainy Creek and Fleetwood Creek, which have been affected by a vermiculite tailings impoundment. The impoundment was constructed to provide process water and settle tailings at W.R. Grace's vermiculite mining/milling operations northeast of Libby. Currently, Rainy Creek is intercepted above the impoundment, and diverted around the tailings impoundment through a culvert constructed of 48 and 52 inch diameter corrugated metal pipe, re-entering the original channel below the tailings dam. Fleetwood Creek enters the impoundment through a constructed diversion channel.

W.R. Grace has ceased operations at the entire mining, milling, and shipping facilities, and has begun implementing reclamation and closure measures at the site. It is the desire of W.R. Grace to complete all reclamation and closure requirements during 1992, and obtain bond release for the entire project area and facilities, including the tailings impoundment.

Regulatory agencies, including the Department of State Lands (DSL), USDA Forest Service, and others have raised concerns over the mine closure, particularly the closure of the tailings impoundment. These concerns include:

- asbestiform fiber contamination in surface water from the coarse tailings dump and fine tailings impoundment;
- long-term stability and integrity of the dam, primarily with regards to saturation and seepage failure;
- increased sedimentation of downstream areas from the impoundment;
- safety; and,
- setting a precedence for other tailings impoundments.

In order to address these issues, an engineering analysis of flood routing alternatives was conducted. The objectives of the engineering analysis are to examine the various alternatives for routing Rainy Creek and Fleetwood Creek through the area affected by the vermiculite tailings impoundment, and to present a conceptual plan of the preferred

alternative. The analysis will address the issues of hydrology and flood routing, dam safety, environmental disturbance, construction feasibility, costs, long-term stability, erosion control, and proposed reclamation methods and practices. (Note: the issues of water quality and tailings dam stability are addressed in separate investigations titled "W.R. Grace Vermiculite Mine Closure Water Quality Monitoring Plan" (Hudson, 1991) and "Geotechnical Evaluation, W.R. Grace Dam, Rainy Creek, Montana" (Vahdani, 1992) respectively.

Various alternatives for collecting and routing Rainy and Fleetwood Creeks around or through the impoundment will be reviewed, with advantages and disadvantages considered and discussed. The ultimate objective is to provide a method of passing storm flows through the impoundment area assuring the integrity of the dam without producing significant environmental impacts in the form of water quality degradation or disturbances to local terrain.

- Our approach to meeting this objective is as follows:
- First, select suitable storm events which will be used as design criteria, determine size, and calculate runoff volumes for these storms (Chapter 3),
- Second, define and compare conceptual approaches and select a preferred alternative for detailed description (Chapter 4),
- Third, define essential elements of design for the preferred alternative and discuss possible alternatives for implementing details of design (Chapter 5),
- Finally, propose maintenance procedures which will be implemented to provide for the perpetual safety of the implemented closure plan (Chapter 6),

2.2 PROJECT LOCATION AND DESCRIPTION

The vermiculite tailings impoundment is part of W.R. Grace's Construction Products Division vermiculite operations. The tailings impoundment encompasses approximately 70 acres within the drainage basin(s) of Rainy and Fleetwood Creeks. The site is located approximately seven miles east northeast of Libby, Montana, within the SW 1/4 of Section 15, and the NW 1/4 of Section 22, Township 31 North, Range 30 West, Lincoln County, Montana. The site is accessed by State Highway 37, and USPS Road No. 401. The impoundment lies entirely within patented mine property owned by W.R. Grace and Company. Surrounding public land is managed by the USDA Forest Service, Libby Ranger District. See Figures 2.1 and 2.2.

The tailings impoundment is located immediately below the confluence of Rainy Creek and Fleetwood Creek. After leaving the mine property, Rainy Creek flows toward the southwest and enters the Kootenai River about 2 1/2 miles downstream of the dam, and about 5 1/2 miles upstream of Libby. The Kootenai River is a tributary of the Clark Fork




Figure 2.1 Location of the W.R. Grace Project Area.

of the Columbia River. The total drainage area impounded by the tailings dam is a 9.4 square miles. The dam is rated as large in size, and is classified as having a high (Category 1) downstream hazard potential (Foster, 1981). The high hazard ranking is attributed to the presence downstream of Highway 37 and the vermiculite product storage and shipping terminal located between the highway and the Kootenai River.

Existing outlets from the impoundment consist of a decant tower and a chute spillway constructed of half-sections of 8 foot diameter corrugated metal pipe (CMP). Normal flows from Rainy Creek are currently diverted around the impoundment through a CMP pipe constructed of 48 and 52 inch diameter sections, re-entering the original channel approximately 800 feet downstream of the dam. All existing outlet and diversion structures will be removed as part of final closure.

The geology of the site consists of late Precambrian Belt Group consisting of fine-grained clastic and carbonate rocks which have undergone various degrees of metamorphism, and are covered with glacial outwash and till (Boettcher, 1963). The tailings impoundment is located on an intrusive rock body called the Rainy Creek stock, of which Vermiculite Mountain and W.R. Grace's mining area is a part. Depths to bedrock range from less than 2 feet to about 25 feet on the valley walls, and from 20 to 45 feet on the valley floor. Portions of the bedrock are weathered with low strength (Lewis, 1971).

The dam is located in Seismic Zone 2, with a potential for moderate earthquake damage. A study completed by Harding Lawson Associates (Vahdani, 1992) indicates "*....the dam is expected to remain stable during and following the design earthquake*", and "*..... results of our stability analysis indicate that the dam is stable during both static and dynamic loading conditions*".

Vegetation at the site consists of grasses, coniferous shrubs, and of mixture of deciduous (primarily cottonwood, alder, and aspen) and evergreen trees (cedar, larch, Douglas fir, ponderosa and lodgepole pine, and spruce). Active logging is taking place within the drainage basin, both on mine property and on adjacent Forest Service land. The tailings impoundment is currently devoid of vegetation.

2.3 SITE HISTORY/BACKGROUND

Vermiculite Mountain has long been the subject of mineral exploration because of the unique geology of the area. However, vermiculite production has been the only economically viable operation there. Mining was done as early 1890 but the first large scale activity was begun by the Zonolite Company beginning in the mid 1920's. W. R. Grace acquired the Zonolite Company in 1963 which continued to operate as the Zonolite Division of W.R. Grace. The first beneficiation process used an air separation method to process ore into a high grade vermiculite product. This process tended to produce high dust levels which took on increased significance with the recognition that asbestiform fibers could lead to certain kinds of lung disease. The ore body has occurrences of tremolite which is classified

as an asbestos-like mineral. The process was converted to a wet process to reduce dust production during processing.

In 1971 W. R. Grace undertook a major expansion to increase capacity and improve the beneficiation process. It was at this time that the tailings impoundment was built to provide for settlement of the fine tails produced by the new process and to recover water for reuse (Foster, 1981; Boettcher, 1963; and Lewis, 1971). The tailings dam was designed by Bovay Engineers, Inc. of Spokane, Washington, and Harding Lawson Associates of Novato, California. The dam was designed and constructed in stages, with the 50 foot high (elevation 2830) starter dam constructed in 1971, immediately downstream of an older, existing dam. Additional construction phases in 1975, 1977, and 1980 have raised the top of dam elevation to 2925, for a total height of 135 feet measured from the downstream toe.

At the peak of operations, ore was processed at the rate of approximately 2,000,000 tons per year. Declining market conditions forced a gradual reduction in plant production from over 200,000 tons per year of product to less than 100,000 tons per year recently. In the fall of 1990 a decision was made to permanently close the facility because of the declining markets. Since 1990, the tailings impoundment has not received fine tails directly from the operations. However, small amounts of tailings from adjacent coarse tailings disposal areas continue to enter the reservoir through natural erosion processes, primarily surface runoff. These processes will be reduced as reclamation and reseeding efforts provide surface cover and stabilize the area.

A reclamation plan was submitted at the time of the expansion. However, the plan was very general and did not define or investigate specific actions in detail. One of the provisions of the permit was to provide for diversion of streams around mining wastes at the time of closure. In the case of the tailings impoundment, the requirements for diversion of a massive storm is calculated to be several thousand cubic feet per second. Our investigation of designs for successfully handling such a large quantity of water has suggested that other alternatives, using the storage capacity of the tailings impoundment might provide a safer and more effective resolution of this problem. The reasons for this conclusion are discussed in the sections which follow.

3.0 HYDROLOGIC EVALUATION

3.1 HYDROLOGIC PARAMETERS

In order to properly assess the requirements of the final closure design for the tailings impoundment it is necessary to evaluate the magnitude of streamflows for various levels of probability. We have analyzed three storm events here. A 10 year thunderstorm event was chosen to represent a condition which might be encountered on a regular basis and which might also be considered as a design parameter for some diversion alternates. A 100 year thunderstorm event was selected principally as the preferred basis for design of a partial diversion alternate, an event which would be exceeded only rarely thereby requiring use of emergency provisions on an infrequent time interval. A runoff equivalent to 0.5 of the probable maximum flood (PMF) event was also selected since the requirements for dam safety are based on the PMF and this value met or exceeded those requirements. There is also a recorded event in the area of a 0.5 PMF event. This event was a three day general storm; our analysis is based on a 6 hour thunderstorm event which produces a more intense runoff in a drainage of this size. The methodology for calculation of these design storms is described in Section 3.2.

The W.R. Grace tailings dam is located on Rainy Creek, approximately 2000 feet below the confluence of Rainy and Fleetwood Creeks. The dam impounds 9.4 square miles (sq. mi.) of the Rainy Creek drainage basin, of which 5.9 sq. mi. is drained by Rainy Creek, and 3.5 sq. mi. is drained by Fleetwood Creek. The two flows enter the impoundment from the north and east, respectively. The drainage basin is generally "L" shaped above the dam (Figure 3.1). Average stream gradients for Rainy and Fleetwood Creeks are 12.2% and 11.1% respectively.

The Rainy Creek drainage basin is located on a southern exposure of the Purcell Mountains, and is primarily forest covered except for the area disturbed by the mining/milling operations and logging operations. The basin rises from an elevation of approximately 2900 at the surface of the tailings impoundment, to 6040 feet at the top of Blue Mountain. The longest length of channel is about 4.9 miles for Rainy Creek, and about 3.1 miles for Fleetwood Creek. Average channel slopes are 5 to 15 percent, with sideslopes ranging from 5 to 45 percent. Rainy Creek enters the Kootenai River approximately 2 1/2 miles downstream of the tailings dam.

Mean annual precipitation at Libby is 19.4 inches, with 37 percent of it occurring in the months of November through January, and 18 percent falling in the months of May and June. The month having the highest average precipitation is January with 2.42 inches.

CREEK
GE AREA




Figure 3.1 Drainage areas for Rainy Creek and F drainage areas indicated by bullseye.

Temperature in Libby ranges from an average of 22.4° Fahrenheit (F) in January to an average of 67°F in July. Average annual precipitation at the site is estimated at 30 inches per year (USDA, 1977), and the temperature would be expected to average 3 to 5 degrees cooler than at Libby. Climatological data was obtained from the Libby 1 N.E. Ranger station.

Soils in the area have been assigned a Hydrologic Soil Classification of "B" by the Soil Conservation Service (SCS). The drainage basin is estimated to have >75% ground cover of mature forest in good condition, with moderate slopes. Antecedent moisture is considered to be average. A "Curve Number" of 60 is estimated for both the Rainy Creek drainage basin and the Fleetwood Creek drainage basin. As discussed in Section 3.2, Curve Numbers are used in the SCS hydrologic model to classify the drainage characteristics of different terrains. To assure a conservative runoff estimate, the curve number was selected slightly higher than normally recommended for forested lands to account for the impact from mining on areas of the Fleetwood Creek drainage and extensive clear cuts in Upper Rainy Creek. A summary of design conditions is shown in Table 3.1.

Table 3.1. Hydrologic parameters for Rainy Creek and Fleetwood Creek drainage areas impounded by the tailings dam.

| WATERSHED NAME | AREA (sq. miles) | SCS CURVE NUMBER | AVE. SLOPE (%) | CHANNEL LENGTH (ft) | SOIL GROUP |
|-----------------------|-------------------------|-------------------------|-----------------------|----------------------------|-------------------|
| Rainy Creek | 5.9 | 60 | 12.2 | 25,870 | B |
| Fleetwood Creek | 3.5 | 60 | 11.1 | 16,370 | B |

3.2 DESIGN STORMS

Runoff from three design storms was used to evaluate flood routing through the tailings impoundment, specifically 1) a 10-year frequency, 24-hour precipitation event; 2) a 100-year frequency, 24-hour precipitation event; and, 3) a 6-hour probable maximum flood (PMF).

A spreadsheet program developed by Schafer and Associates was used to simulate the runoff from the 10 year and 100 year, 24 hour precipitation events. The model uses the calculation procedures outlined in the SCS National Engineering Handbook, Section 4, Hydrology (NEH-4). The SCS method finds a watershed flow hydrograph using the "Curve Number" method. A complete description of the background, methods and procedures is given in NEH-4 (U.S. Dept. of Agriculture, 1985). A brief description is provided below.

The SCS Curve Number Method was developed for areas having little rainfall data, particularly for storm duration and intensity. Runoff does not begin until after some period

of "initial abstraction" (1a) where infiltration, interception, and surface storage occur. The 1a is estimated to be 20 percent of the maximum potential runoff. Rainfall-runoff relations, based on SCS curve numbers, are then developed to estimate the runoff volume and timing from a precipitation event.

Curve numbers are selected based on land use, soil type, cover, hydrologic condition and antecedent moisture (see Section 3.1). Other necessary information includes average slope, drainage area and longest runoff length, and rainfall distributions as a SCS Type II convective thunderstorm event. Lag time, time of concentration, time to peak, etc. are calculated from the curve numbers. A series of elemental hydrographs, based on peak flows and the values of the dimensionless unit hydrograph (SCS), are developed for each duration, which in turn are summed to produce a total hydrograph. See Sections 3.2.1 and 3.2.2.

The PMF was calculated using the method outlined in the Department of Interior, Flood Hydrology Manual (U.S. Dept. of the Interior, 1989). The method is based on development of a "Synthetic Unit Hydrograph" which is used to estimate surface runoff from probable maximum precipitation. A brief description is given in section 3.2.3.

3.2.1 10-Year Event

A 10-year, 24-hour antecedent storm precipitation of 2.4 inches for Rainy Creek drainage basin was obtained from the National Oceanic and Atmospheric Administration (NOAA) Atlas (U.S. Dept. of Commerce, 1973). Using this precipitation value, and the boundary conditions outlined in Sections 3.1, a peak runoff for Rainy Creek (65 cfs) occurred 16.3 hours after the beginning of the storm. Peak runoff for Fleetwood Creek (45 cfs) occurred at 14.9 hours. Model results for the runoff of each drainage area are found in Appendix A. Key parameters for this model are summarized in Table 3.2. Figure 3.2 is a graphical representation of the surface water runoff and rainfall intensity for a 10-year, 24-hour event.

The total runoff hydrograph for the entire watershed area unpounded by the tailings dam was obtained by summing the two individual hydrographs, resulting in a peak flow of about 107 cfs occurring at 15.5 hours after the beginning of the event. The total runoff for the affected drainage area is 74 acre-ft, with 46 acre-ft from Rainy Creek, and 28 acre-ft from Fleetwood Creek.

3.2.2 100-Year Event

A 100-year, 24-hour antecedent storm precipitation of 3.4 inches was obtained from the NOAA Atlas (U.S. Dept. of Commerce, 1973). Using this precipitation value, and the boundary conditions outlined in Sections 3.1, a peak runoff for Rainy Creek (262 cfs) occurred 15.2 hours after the beginning of the storm. Peak runoff for Fleetwood Creek (204 cfs) occurred at 14.4 hours as summarized in Table 3.3. Model results for the runoff of each drainage area are found in Appendix A. Figure 3.3 shows the surface water runoff and rainfall intensity for a 100-year, 24-hour event.

Table 3.2. Surface water runoff for a 10-year, 24-hour precipitation event using SCS Type II rainfall distribution.

| 10-YEAR, 24-HOUR STORM EVENT | | | | |
|------------------------------|------------------------|-----------------|-----------------|---------------------|
| WATERSHED NAME | PRECIPITATION (inches) | RUNOFF (inches) | PEAK FLOW (cfs) | TIME OF PEAK (hrs.) |
| Rainy Creek | 2.4 | 0.147 | 65 | 16.3 |
| Fleetwood Creek | 2.4 | 0.147 | 45 | 14.9 |
| Combined Flows | 2.4 | 0.147 | 107 | 15.5 |




Figure 3.2 Surface water runoff hydrographs and rainfall intensity for a 10-year, 24-hour storm (2.4 in.) in the Rainy Creek and Fleetwood Creek watersheds.

Table 3.3. Surface water runoff for a 100-year, 24-hour precipitation event using SCS Type II rainfall distribution.

| 100-YEAR, 24-HOUR STORM EVENT | | | | |
|-------------------------------|------------------------|-----------------|-----------------|---------------------|
| WATERSHED NAME | PRECIPITATION (inches) | RUNOFF (inches) | PEAK FLOW (cfs) | TIME OF PEAK (hrs.) |
| Rainy Creek | 3.4 | 0.489 | 262 | 15.2 |
| Fleetwood Creek | 3.4 | 0.489 | 204 | 14.4 |
| Combined Flows | 3.4 | 0.489 | 460 | 14.8 |




Figure 3.3 Surface water runoff hydrographs and rainfall intensity for a 100-year, 24-hour storm (3.4 in.) in the Rainy Creek and Fleetwood Creek watersheds.

The total runoff hydrograph for the entire watershed area impounded by the tailings dam was obtained by summing the two individual hydrographs, resulting in a peak flow of 460 cfs occurring at 14.8 hours after the beginning of the event (Fig. 3.3). The total runoff for the drainage area is 245 acre-ft, with 154 acre-ft from Rainy Creek, and 91 acre-ft from Fleetwood Creek.

3.2.3 Probable Maximum Flood

The probable maximum flood (PMF) is the flood expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in a region. Three scenarios are most often considered when estimating the PMF, specifically 1) general seasonal storms (October through June), 2) rain on snow (including snowmelt) and, 3) summer convective thunderstorms. Based on the Hydrometeorological Report No. 43 (HMR 43), "Probable Maximum Precipitation, Northwest States" (U.S. Weather Bureau, 1966), intense local summer thunderstorms of short duration are most likely to produce a PMF event in this region of the United States (east of the Cascade divide and west of the Rocky Mountains).

Using the method outlined in HMR 43 for summer thunderstorms in small drainage basins (<550 square miles), a PMF event is estimated to produce 10.7 inches of precipitation in 6 hours, distributed as shown by the hyetograph in Figure 3.4. Detailed calculations used to determine the PMF hyetograph are located in Appendix B.


Runoff from the PMF is calculated using the method outlined in the Bureau of Reclamation "Flood Hydrology Manual" (U.S. Dept. of the Interior, 1989). This method is similar to the SCS method described in Section 3.1, with the exception of the runoff determined by a synthetic unit hydrograph instead of summing a series of dimensionless unit hydrographs (SCS method). Input data requirements are similar, including drainage area, channel length, average slope, and ultimate infiltration (based on the SCS hydrologic soil group). As in the SCS method, lag time, duration, and incremental runoff are calculated from the input data. Input conditions are similar to those found in Section 3.1, with the exception of antecedent moisture conditions considered to be near or at saturation.

Important runoff parameters for this event are summarized in Table 3.5. The peak runoff for a PMF event in the Rainy Creek drainage area was calculated to be 7330 cfs, occurring 5.5 hours after the beginning of the storm. Peak runoff for Fleetwood Creek was calculated at 5884 cfs occurring at 4.5 hours after the beginning of the storm. Detailed calculations of the PMF runoff are located in Appendix B.

The total PMF runoff hydrograph for the entire watershed area impounded by the tailings dam was obtained by summing the two individual hydrographs (Rainy and Fleetwood Creeks), resulting in a peak flow of 11,676 cfs occurring at 5.0 hours after the beginning of the storm event (Figure 3.5). The total runoff for the drainage area is 4612 acre-ft, with 2895 acre-ft from Rainy Creek, and 1717 acre-ft from Fleetwood Creek.

W.R. GRACE HYETOGRAPH TAILINGS IMPOUNDMENT WATERSHED

PMF STORM EVENT, 6-HOUR AUGUST THUNDERSTORM (10.7 in.)
WEATHER BUREAU METHOD, HMR NO. 43



Schafer and Associates, 1991

Figure 3.4 Storm hyetograph for a 6-hour PMF event (10.7 in.) in the Rainy Creek and Fleetwood Creek drainage basins.

Table 3.4. Surface water runoff for a 6-hour PMF event (10.7 in.) using the storm distribution hyetograph of Figure 3.4.

| PROBABLE MAXIMUM FLOOD (6-HOUR) | | | | |
|---------------------------------|------------------------|-----------------|-----------------|---------------------|
| WATERSHED NAME | PRECIPITATION (inches) | RUNOFF (inches) | PEAK FLOW (cfs) | TIME OF PEAK (hrs.) |
| Rainy Creek | 10.7 | 9.20 | 7330 | 5.5 |
| Fleetwood | 10.7 | 9.20 | 5884 | 4.5 |
| Combined Flows | ---- | ---- | 11676 | 5.0 |




Figure 3.5 Surface water runoff hydrographs for a 6-hour PMF event (10.7 in.) in the Rainy Creek and Fleetwood Creek watersheds.

3.3 TAILINGS IMPOUNDMENT CAPACITY

The top of dam elevation of the vermiculite tailings dam is 2926, with an existing emergency spillway crest elevation of 2920. The top of tailings elevations range from a low of 2895 just north of the decant tower, to a high of 2914 at the southeast corner of the impoundment. Average tailings elevation is estimated to be slightly over 2900.

Using the conic (volume) method to determine the reservoir storage capacity, it is estimated that the reservoir will have a surface area of 68.7 acres and a storage volume of 871 acre-feet measured to the crest of the (existing) emergency spillway. Approximately 431 acre-feet of storage is available between the existing emergency spillway crest and the dam crest, making the total storage capacity (top of dam) 1302 acre feet. A tabulation of impoundment capacities as a function of elevation is given in Table 3.5.

Table 3.5. Storage capacity of the tailings impoundment/reservoir.

| ELEVATION (ft.) | AREA (acres) | INCREMENTAL VOLUME (acre-ft.) | CUMULATIVE VOLUME (acre-ft.) |
|----------------------------|-------------------------|--|---|
| 2895 ¹ | - | - | - |
| 2900 | 10.4 | 26.0 | 26.0 |
| 2905 | 21.0 | 78.5 | 104.5 |
| 2910 | 48.7 | 174.3 | 278.8 |
| 2915 | 59.7 | 271.0 | 549.8 |
| 2920 ² | 68.7 | 321.0 | 870.8 |
| 2926 ³ | 74.9 | 430.8 | 1301.6 |

1 Lower limit of impoundment.

2 Emergency spillway crest elevation.

3 Top of dam elevation.

During the closure work on the impoundment, it is proposed that the existing emergency spillway will be removed, and a new emergency spillway constructed on the west side of the dam. The emergency spillway will work in conjunction with a proposed primary outlet/control structure to route flows through the reservoir. See Section 5.0 for details of the preferred alternative.

3.4 DAM SAFETY REQUIREMENTS

The Rainy Creek Basin Zonolite Tailings Dam, MT-1470 has been rated as large in size and as having a high downstream hazard potential (Category 1), as determined by an inspection and report completed by Morrison-Maierle in 1981 (Foster, 1981). The inspection was conducted in accordance with U.S. Army Corp of Engineers Guidelines for Safety Inspection of Dams, and was completed for the State of Montana Department of Natural Resources and Conservation, under Public Law 92-367. The classification is based on a dam height of 135 feet, and storage capacity of 2120 acre-feet at the spillway crest.

Under State of Montana regulations for Dam Safety, Rule 36.14.206 (State of Montana, 1989):

(1), *".....hazard determination shall be based on the consequences of dam failure--not the condition, probability, or risk of failure. A dam must be classified high-hazard if the impoundment capacity is 50 acre-feet or larger and it is determined that a loss of human life is likely to occur within the breach flooded area as a result of failure of the dam."*

(3) "..... the effects of flood inundation..... will continue downstream until the flood stage is equal to that of the 100 year floodplain.", and

(5) "Loss of life is assumed to occur if the following structures are present: other paved highways....".

Under Rule 36.14.502:

(1) "Spillways (principal and emergency) for high-hazard dams must safely pass the flood calculated from the inflow design flood. The minimum inflow design flood is expressed as a fraction of the probable maximum flood or as otherwise indicated in Table A" (See Table 3.6),

(2) "..... The minimum inflow design flood shall be the 100-year, 24-hour flood",

(3) "..... routing of the inflow design flood through the reservoir shall assume storage contents to be at the emergency crest elevation prior to routing",

(4) "....breach area is designated as Category A if major repair or alteration of the emergency spillway is to be performed, where the downstream hazard contains more than 20 residences and the failure flood wave is less than 4 hours from the dam to the first residence",

(5) ".....breach area is designated as Category B if the dam is an existing dam not meeting the criteria for a Category A dam".

Table 3.6. Emergency spillway inflow design flood(s) from Table A of the Montana Dam Safety regulations, Rule 36.14.502.

| CAPACITY TO THE EMERGENCY CREST/HEIGHT TO DAM CREST | BREACH AREA CATEGORY A | BREACH AREA CATEGORY B |
|--|-------------------------------|-------------------------------|
| Dams less than 100 acre-feet and less than 20 feet in height | 2Q | Q |
| Dams less than 500 acre-feet and less than 35 feet in height | .2 PMF | .1 PMF |
| Dams less than 1000 acre-feet and less than 50 feet in height | .3 PMF | .15 PMF |
| Dams less than 12,500 acre-feet and less than 50 feet in height | .5 PMF | .5 PMF |
| Dams less than 50,000 acre-feet and less than 100 feet in height | .75 PMF | .75 PMF |
| Dams 50,000 acre-feet or greater and 100 feet or greater in height | 1.0 PMF | 1.0 PMF |

We applied the following conditions to select design criteria for the project:

- with the top of tailings elevation of 2900+, the height to the crest of the dam (from the tailings surface) is less than 50 feet;
- the capacity of the reservoir to the existing emergency spillway crest is less than 1000 acre-feet;
- there are no residences between the dam and the Kootenai River, however, a paved highway does exist;
- the impact to the Kootenai River of a dam breach is unknown, but is not expected to exceed the 100-year floodplain at the closest residence downstream;
- the work will be considered to be a major alteration to an existing dam.

Based on these criteria and the provisions in statutes cited above, the tailings dam is considered to be high-hazard, making it applicable to all other criteria for high-hazard dams. The breach area below the dam is unknown, therefore it will be considered as Category A. Based on these guidelines and criteria, the required design flow in Table 3.6 is 0.30 PMF, or 3504 cfs.

The flood routing volume proposed by W.R. Grace is 0.5 PMF, which calculates to a design value of 5838 cfs ($0.5 \times 11,676 = 5838$). This 0.5 PMF value will be used during flood routing analyses.

3.5 PROPOSED DESIGN FLOWS

W.R. Grace proposes to use the flows summarized in Table 3.7 for flood routing through the vermiculite tailings impoundment. Boundary conditions and assumptions follow:

- A 2.4 inch, 24 hour design storm to simulate a 10-year return storm; and 3.4 inch, 24 hour design storm to simulate a 100-year return storm. Both storms are distributed as a SCS Type II convective thunderstorms;
- A 10.7 inch, 6 hour design storm to simulate a probable maximum flood (PMF) event, distributed as a convective thunderstorm according to U.S. Weather Bureau guidelines;
- Soils within the drainage classify as SCS type "B" soil group. The soils contain average in-situ antecedent moisture for the 10 year and 100 year return storms. Soils are considered to be near saturation, with 0.25 inch per hour infiltration for PMF event;

- The drainage basins are dense forest in good condition, with >75% ground cover;
- Curve numbers of 60 are used for both Rainy Creek and Fleetwood Creek drainage basins.
- The tailings dam is classified as a high-hazard dam according to Montana Dam Safety, and U.S. Army Corp of Engineers regulations;
- The required inflow design is 0.30 PMF, based on less than 50 foot dam height (from surface of tailings), less than 1000 acre-feet storage at emergency spillway crest, and a Category A breach area (State of Montana, 1989);
- 0.5 PMF will be used for flood routing analyses and design;
- The existing tailings impoundment decant tower and emergency spillway, and the Rainy Creek diversion and pipeline will be removed during closure.

Table 3.7. Design flood volumes proposed for flood routing alternatives analysis and conceptual design.

| WATERSHED NAME | 10-YEAR, 24-HOUR (cfs) | 100-YEAR, 24-HOUR (cfs) | 0.5 PMF 6-HOUR (cfs) |
|---------------------------|---------------------------------------|--|-------------------------------------|
| Rainy Creek | 65 | 262 | 3665 |
| Fleetwood Creek | 45 | 203 | 2942 |
| Combined Flows | 107 | 460 | 5838 |

4.0 FLOOD ROUTING

4.1 OVERVIEW OF ALTERNATIVES

The project calls for engineering analysis of available alternatives for routing floods through the area affected by the vermiculite tailings impoundment. Concerns that will be addressed by the analysis include safety, potential for water contamination especially from asbestiform fibers, long-term stability of the impoundment including an analysis of tailings dam saturation and seismic events, sedimentation, and others concerns.

Three basic options for flood routing have been considered: Alternate I - diverting all flows, including storms producing PMF events, around the impoundment and dam, Alternate II - routing flows through the impoundment and discharging through an outlet channel constructed in or near the dam and Alternate III - a partial diversion of "normal" stream flows and routing of events exceeding diversion design flows into the impoundment. Flood routings were modeled using a computer program entitled "Hydrograph Develop Program", developed by the SCS in 1990. Routing models were completed by Lew Burton and Ed Juvan, retired SCS engineers.

Within each of the general alternatives are several design variations which have been considered in varying degrees of detail. Table 4.1 provides a summary of the pertinent features of each option considered. A discussion and evaluation of the alternatives follows in Sections 4.2 through 4.4. A description of design details for the preferred alternative is given in Section 5.0.

In the following investigations, each main alternative will begin with a discussion of general parameters, followed by specific routing alternatives, and finally a summary of advantages and disadvantages. Maps, sections, and other design drawings will be provided as necessary. The project area has been set up as a grid, with the north-south (horizontal) axis designated by letters (A - L), and the east-west (vertical) axis designated by numbers (1 - 9). This should provide for a more efficient method of locating sections or more detailed drawings. The base grid system is delineated on Plate 1.

Table 4.1 Summary of alternatives considered for flood routing.

| Alternative | Essential Design Features |
|---|---|
| <p><u>Full Diversion</u></p> <p>Alternate Ia: Partial Isolation of Tailings</p> <p>Alternate Ib: Total Isolation of Tailings</p> <p>Alternate Ic: West Side Diversion Channel</p> <p>Alternate Id: East Side Diversion Channel</p> <p>Alternate Ie: Pipeline</p> | <ul style="list-style-type: none"> • Diversion dam(s) upstream of tailings dam to intercept streams • Flood routing in large channels around dam • Large drop chutes for return of stream flow to Rainy Creek below dam |
| <p><u>Channel Reconstruction in Tailings</u></p> <p>Alternate IIa: Water Level at 2904'</p> <p>Alternate IIb: Water Level at 2910'</p> <p>Alternate IIc: East Abutment Outlet</p> <p>Alternate IId: West Abutment Outlet</p> <p>Alternate IIe: Outlet Over Dam Face</p> | <ul style="list-style-type: none"> • Streams enter impoundment and collect in a pond at the upper end with water level kept away from dam for improved stability • Unused tailings impoundment capacity used for storm surge up to 0.5 PMF • Lined channel (for erosion control) delivers water to outlet structure at the dam • Box culvert outlet control structure reduces stream discharge from impoundment during major storm events • Optional emergency spillway for storms in excess of 0.5 PMF • Armored channel/drop structures return stream flow to Rainy Creek below the dam |
| <p><u>Partial Diversion</u></p> <p>Alternate IIIa: 100-Year Storm Diversion</p> <p>Alternate IIIb: 10-Year Storm Diversion</p> | <ul style="list-style-type: none"> • Diversion dam(s) upstream of tailings dam intercepts Rainy and Fleetwood Creeks • Outlet control structure reduces stream discharge from diversion dams to a design maximum which is routed around the tailings • Drop chutes similar to Alternate I but smaller return diverted stream flow to Rainy Creek below tailings dam • Runoff in excess of design maximum overflows to the tailings impoundment • Secondary outlet and discharge channel similar to that of Alternate II |

4.2 FULL DIVERSION ALTERNATIVES

4.2.1 Description of Design Concepts

Common Diversion Dam (Alternate Ia): Diversion of Rainy and Fleetwood Creeks around the impoundment is one possible method of flood routing following closure. Full diversion will entail intercepting, diverting both creeks around the impoundment, and ultimately returning them to Rainy Creek downstream of the dam.

Construction of a diversion dam across the upper end of the existing impoundment would be required at a location where flows from Rainy Creek and Fleetwood Creek join. The flows would then be diverted around the tailings unboundment through an open channel or pipe constructed adjacent to the impoundment. Once past the dam, a concrete drop chute or other means of elevation reduction would return the diverted flows to Rainy Creek. Plate 2 is a conceptual plan view of this alternate.

A full diversion dam, capable of diverting a 0.5 PMF event while retaining long-term structural integrity, will be very difficult to construct because of the tailings in the impoundment and east abutment. Tailings will not provide a competent foundation for the dam base or abutment, hence significant excavation of the tailings would be required (see Plate 3). Conventional construction methods and equipment often fail when working in tailings, making the project costly and with questionable results.

Separate Diversion Dams (Alternate Ib): An alternative would be to construct a diversion dam at the extreme upper end of the impoundment, beyond the extent of the tailings. A separate diversion dam would be constructed for Fleetwood Creek upstream of the coarse tailings dump. Flows from Fleetwood Creek would be delivered to the Rainy Creek diversion by a constructed channel (Plate 4-A). Both flows would then enter a main diversion channel and be routed around the unboundment as above (Plate 4-B)

West Side Channel (Alternate Ic): Should full diversion be selected, the best method for carrying the diverted flows around the tailings impoundment would be an open channel constructed on the west side of the impoundment. The channel would be constructed in natural material (off the tailings), and connected to a concrete drop chute/plunge pool below the tailings dam. Flows would be diverted into the constructed channel at the diversion dam, carried around the tailings dam and impoundment, and returned to Rainy Creek downstream of the dam. Refer to Plates 2, 4-A, and 4-B.

A conceptual design was completed for a 0.5 PMF channel on the west side of the tailings using a beginning channel elevation of 2900.0, and a gradient of 0.005 ft/ft (0.5%). The structure would be a rock-lined, trapezoidal open channel with 20 ft wide (flat) bottom and 2:1 sideslopes. With a design flow of 0.5 PMF (5838 cfs) and applying Manning's Equation:

$$Q = A \frac{1.486}{n} R^{2/3} S^{1/2}$$

in which:

- Q = volume of flow, cfs
- A = cross-sectional area of flow in ft²
- S = slope, ft/ft
- R = hydraulic radius, ft
- n = coefficient of roughness (0.04 for rock lined channels)

a peak flow depth of about 12 feet is calculated with a velocity of approximately 11 feet per second. With the beginning channel elevation of 2900 and 0.005 ft/ft gradient, the bottom elevation of the channel opposite the dam will be about 2888. Recommended maximum cut slopes are 2:1, with spaced 10 ft safety benches where possible. The channel would be armored with a minimum of 24 inches of D₅₀ = 18 inch-rock lining to handle the velocities associated with peak flows corresponding to the predicted peak water level. Plate 5 shows a typical cross-section of the west side diversion channel (relative location shown on Plate 2).

East Side Channel (Alternate Id): An alternate full diversion channel would be to construct an open channel on the east side of the impoundment. The channel would be similar to the west side with a concrete drop chute/plunge pool. Flows would be diverted into the channel at the diversion dam, carried around the impoundment, and returned to Rainy Creek downstream of the tailings dam.

This alternate is not practical due to the proximity of the coarse tailings dump, and presence of shallow bedrock and steep slopes. The beginning section of the channel would be located entirely within the coarse tailings dump which is unconsolidated and geotechnically unstable. Significant design and engineering would be necessary to construct a channel in this material. Further, lining would be required to prevent rapid infiltration and increased foundation instability. Excavation to natural material would be virtually impossible.

On the lower sections of the channel, the depth to bedrock is generally less than 10 feet (Lewis, 1971) and portions of the drainage sideslopes are very steep. These restrictions, coupled with the required channel size for 0.5 PMF, would require that the channel be constructed partially within the fine tailings (see Plate 6). An alternative would be to construct the channel entirely in bedrock (see Plate 7), requiring extensive drilling and blasting. Either channel location has drawbacks.

Pipeline (Alternate Ie): A pipeline, or other closed conduit, was explored as an alternate for carrying full diversion flows around the tailings impoundment. As with the open channels, the entire flow from both Rainy and Fleetwood Creeks would be diverted into the pipeline which would carry this flow around the impoundment and return it to Rainy Creek downstream of the tailings dam. The pipeline would most likely be located on the west abutment, and would eliminate the need for a drop structure.

The primary advantage to a pipeline is the elimination of water loss through infiltration, and associated tailings dam saturation problems. Another advantage is the reduction in public accessibility, with the exception of the pipe entrance.

Disadvantages include size, geotechnical stability, maintenance, and cost. A pipeline greater than 20 ft (diameter) is required to carry 5838 cfs, the exact size depending on shape and material type. To properly install a pipe of this size requires extensive excavation, and specialized construction methods and equipment. Pre-stressed concrete pipe would be the best choice, but with considerable cost. Even with pre-stressed concrete, geotechnical stability may remain a problem, due primarily to the geology and topographic relief of the area.

A safety concern is the entrance into the pipeline, and the closed system preventing quick escape. Installation of a grate, or other barrier would prevent this, but would greatly increase maintenance and the possibility of plugging with subsequent system failure during major events.

4.2.2 Evaluation of the Full Diversion Alternatives

Safety: Safety and long-term integrity of any system are directly related, and should be the primary considerations when selecting a flood routing system. The full diversion alternate increases the potential for failure, and decreases the safety of the system. The drop chute and plunge pool, constructed of reinforced concrete, would be difficult to build on steep slopes such as these. Stability of the structure in a massive flood condition would be problematic.

The channels carrying the diverted flows would be very large, and inherently less stable than smaller channels, particularly when constructed into the side of a hill as they would be in this case. From a hydrologic and geotechnical standpoint, any channel, natural or constructed, located above the low point in a drainage is generally not considered to provide good long-term service, particularly when considering flows of this magnitude.

For the east side diversion channel, the combination of construction difficulties and doubtful foundation/geotechnical factors make this alternative a poor choice for a long-term diversion channel. For both east and west side channels, construction of the drop chute will be costly, and plugging during high flows a primary concern.

The drop chute below the tailings dam would be a large, concrete structure to handle the volume and velocity of the peak flows. Construction on the steep terrain of the west abutment area will be very expensive, and long-term geotechnical stability may be difficult to obtain. Other safety considerations include public accessibility to the large, fast moving flows in the channels and drop chute, and the difficulty in "escaping" from such.

The diversion dams are designed to only collect water prior to routing around the impoundment and would have little useful storage capacity. Should the diversion

channels become plugged, or the system fail for some other reason, the flood flows would quickly breach the diversion dams and enter the impoundment. The breach could be rapid, in turn causing a large surge of water to strike the tailing dam. If the tailings dam did not fail from impact, the impoundment would begin to fill and could cut a new channel from the tailings impoundment into the diversion channel, or in an improbable event, could block the diversion channel with debris so badly that overtopping of the impoundment might occur. Either event would bring the potential for extensive uncontrolled erosion of the tailings material. Overtopping the dam could cause catastrophic failure of the dam unless additional precautions are taken. Dams in a series are not considered to be good engineering practice.

Full diversion of a 0.5 PMF event (producing 5838 cfs) requires a complex system of very large diversion dams, channels, and drop chute to route the entire peak flow of a storm of this magnitude around the impoundment, and return it to Rainy Creek downstream of the tailings dam. This alternate ignores the potential for flood control in the unused storage capacity of the impoundment. By allowing the reservoir to surge and temporarily store the peak flood flows, outflow peaks can be reduced to roughly 15 percent of the peak inflow (5838 cfs) and still contain a 0.5 PMF event.

Water Quality Impacts: While water contamination, particularly from tremolite fibers may be reduced by diversion, it will not be eliminated. Constructing a diversion dam to collect both flows simultaneously will include a section of the tailings impoundment. In addition, Fleetwood Creek will be flowing through the coarse tailings.

Asbestiform fiber contamination from the tailings impoundment and coarse tailings dump could be eliminated by the second diversion alternative shown in Plate 4-A and 4-B. This alternative would prevent streamflows from contacting the tailings, however, these fibers would continue to enter Fleetwood Creek from the natural vermiculite intrusive from which Fleetwood Creek originates. Further, Carney Creek, which enters Rainy Creek downstream of the impoundment, will continue to contribute tremolite fibers to Rainy Creek, regardless of the routing alternative selected.

Environmental Impacts: Environmental disturbance would be significant for a full diversion flood routing system, primarily from the massive excavations required to construct the diversion channels and drop chute. Environmental disturbance would be less for the east side channel than the west channel, but still significant. Channel lining with an impermeable material is recommended to prevent the complete loss of the smaller summer flows, and reduce potential for dam saturation. In order to construct an engineered channel that would have a reasonable longevity and acceptable maintenance, a large portion of either abutment would be removed, which creates an additional problem, namely, where to spoil the waste.

Additional concerns include relocation of the Forest Service access road at several locations, and the continued downstream flooding and erosion from the full 0.5 PMF flows.

Tailings/Dam Saturation: Saturation of the tailings dam and subsequent seepage and instability in the event of toe drain failure has been identified as a major regulatory concern. This subject has been addressed in detail by a study completed by Harding Lawson Associates (HLA) of San Francisco, California (Vahdani, 1992).

HLA completed a drilling program in the tailings and in the dam foundation materials as part of a study to assess the stability of the dam and impounded tailings during static and seismic loading conditions. The study concludes that the dam is currently safe under seismic load, even with the water at the face of the dam, and will not fail. The study encountered two types of tailings materials which appear to be interbedded and sloping away from the dam face. Elastic silts comprise about 60 percent of the tailings while loose, poorly graded sands and silty sands comprise about 40 percent. The elastic silts were not expected to liquify in a seismic event; however the sands could liquify if they remain saturated. If a section of the dam were to be removed the tailings could be expected to fail, but would maintain a 4:1 angle of repose. HLA judges the potential for material run-off in the event of a failure to be very low on the basis of its findings.

The drilling also indicated that the tailings consolidated with depth and gained significant strength. If the tailings are left without standing surface water, up to 5 feet of surface subsidence is projected in areas of deeper tailings as excess pore water pressure is relieved. HLA sees the major threat to dam stability to be the eventual failure of the toe drain piping. It will then be possible for the phreatic surface to increase in the dam and possibly begin seeping from the dam face. Should this occur there will be the likelihood of erosion of the toe and eventual weakening of the dam. Installation of additional piezometers is recommended to provide better monitoring and a conceptual design for a permanent drain structure to be retrofitted as required is proposed. HLA has indicated that based on the probable hydraulic conductivity of the tailings material, it may be possible to reduce the phreatic surface in the dam permanently by maintaining the pond surface approximately 500 feet upstream from the crest of the dam.

Diverting flows around the tailings impoundment will ~~not~~ eliminate saturation of a portion of the tailings dam adjacent to the channel, unless an impermeable liner is installed. The material covering the bedrock on the abutments is glacial outwash and till with moderate to very high permeability (Lewis, 1971). Significant loss of water through infiltration would be expected. The area of influence from the lost water is unknown but is likely to impact a portion of the tailings dam.

Infiltration could be eliminated by lining the channel with an impervious liner material, possibly HDPE or clay. Depending on the life of the selected material, infiltration would be significantly reduced or eliminated, at least through the life of the liner. Channel lining is an option with each alternative, hence no advantage or disadvantage to a particular alternative.

Sedimentation: Reduction of downstream sedimentation associated with the tailings would be expected with a full diversion, particularly if the second (full diversion) option were exercised. The surface of the impoundment is currently devoid of vegetation and subject to potential erosion in major storm events despite its relatively low angle of repose because of the small particle size of the fine tailings. Over the next three to five years, it is anticipated that vegetation will become firmly established on the both the fine and coarse tailings and the potential for erosion will be greatly decreased. Sediment contribution from the tailings should become relatively insignificant.

Disadvantages associated with diversion include the loss of settling and natural filtration associated with some of the other options which provide a wetland in the upper portion of the tailings impoundment. While the impact of sedimentation from tailings materials may be lessened, there is a great potential for increased sedimentation from other sources associated with the massive excavations which would be required for the channels, drop chute, and other diversion structures.

In summary the full diversion alternates greatly reduce safety, increase the possibility of system failure, increase environmental disturbance, and increase construction and maintenance costs. Concerns over geotechnical stability, asbestiform fibers, and tailings dam saturation are not eliminated.

Advantages (Table 4.2) and disadvantages (Table 4.3) of the full diversion alternates are summarized below:

Table 4.2. Advantages associated with a full diversion flood routing system.

| ALTERNATE | FULL DIVERSION - ADVANTAGES |
|--|---|
| All Alternates | <ul style="list-style-type: none"> • Possible reduction in downstream tremolite fiber concentration in surface water; • Probable reduction in short-term sedimentation from the tailings impoundment. |
| Common Diversion Dam (Alternate Ia) | <ul style="list-style-type: none"> • Provides the least complex design for intercepting flows from both Rainy Creek and Fleetwood Creek. |
| Separate Diversion Dams (Alternate Ib) | <ul style="list-style-type: none"> • Intercepts water from both Rainy Creek and Fleetwood Creek before contact with any portion of the tailings impoundment area. |
| West Channel (Alternate Ic) | <ul style="list-style-type: none"> • Best overall alternate of full diversion channels; • Most stable geotechnically of the full diversion alternates. |

| ALTERNATE | FULL DIVERSION - ADVANTAGES |
|--------------------------------|--|
| East channel (Alternate Id) | <ul style="list-style-type: none"> • Less environmental disturbance than west channel; • Bedrock channel reduces infiltration and subsequent potential for saturation of tailings dam. |
| Pipeline (Alternate Ie) | <ul style="list-style-type: none"> • Eliminates infiltration and subsequent saturation of tailings dam; • Least (long-term) environmental disturbance of diversion alternates; • Least public accessibility to flood flows, excluding inlet; Eliminates need for separate drop chute. |

Table 4.3. Disadvantages associated with full diversion flood routing system.

| ALTERNATE | FULL DIVERSION - DISADVANTAGES |
|----------------|--|
| All Alternates | <ul style="list-style-type: none"> • Does not use the reservoir capacity to temporarily store peak flows resulting in higher peak flows downstream in Rainy Creek; • Will not eliminate tremolite fiber contamination of downstream surface water; • Construction of diversion dams in tailings is very difficult, and the long-term stability of such dams is questionable; • Significant environmental disturbance to construct channels/pipeline to carry diverted flows around the tailings impoundment. Massive cut slopes would be required; • Diversion dam(s), channels, and other structures will be required to handle 0.5 PMF flows, making them large and very costly; • Dam safety is inferior. Dams in series are more prone to catastrophic failure; • No backup flood routing system; • The diversion channels will not eliminate the possibility of tailings dam saturation and resultant stability concerns, unless impermeable lining is installed; • Does not take advantage of the wetland within the tailings facility for settling and natural surface water filtration; • Increased maintenance; • Tailings will be dry, thereby increasing the possibility of blowing dust and raising air quality risks; • Limited opportunity for wetland habitat construction. |

| ALTERNATE | FULL DIVERSION - DISADVANTAGES |
|--|--|
| Common Diversion Dam (Alternate Ia) | <ul style="list-style-type: none"> Does not achieve complete isolation of streamflows from tailings materials. |
| Separate Diversion Dams (Alternate Ib) | <ul style="list-style-type: none"> More complex design; Greater environmental disturbance resulting from construction. |
| West channel (Alternate Ic) | <ul style="list-style-type: none"> Significant environmental impact from the massive excavations required to properly construct a long-term channel; Channels are prone to plugging with debris, particularly during flood events, resulting in greatly increased risk of channel/system failure and associated safety risks; Channel would require lining to prevent infiltration into underlying material, particularly during low flows; Major relocation of the Forest Service access road would be required. |
| East channel (Alternate Id) | <ul style="list-style-type: none"> Upper reach of channel in geotechnically unstable coarse tailings material; Lower portion partially within fine tailings, or would require drilling and blasting of bedrock to construct channel; Channel would be prone to plugging with associated safety risks; Construction difficulties; Channel lining would be required in coarse tailings section to prevent water loss and foundation problems; Significant environmental impact, although less than west channel. |
| Pipeline (Alternate Ie) | <ul style="list-style-type: none"> Very large (>20 ft diameter) pipe required to carry the full 0.5 PMF design flows; Very expensive construction and material costs; Geotechnical stability questionable; Considerable maintenance required; Prone to plugging, and once plugged, very difficult to clean; Safety concern (no escape) from a closed system. |

4.3 CHANNEL RECONSTRUCTION THROUGH THE IMPOUNDMENT

Initial studies of this concept were approached from the standpoint that a 0.5 PMF event could be safely routed through the impoundment and discharged through the dam into a channel or drop structure constructed to withstand such a massive flood event. Large, armored channels similar to those required for a full diversion were the result. These concepts suffered from many of the same stability problems that were cited for the full diversion alternatives. A study of the flood surges and the damping effect caused by the unfilled volume of the tailings impoundment suggested that the most useful feature of this concept is the potential for storing much of the runoff from events comparable to a PMF and releasing it downstream at a much reduced and more manageable volume. Our investigation centered on designs which would take advantage of this as it provided the safest method of passing a flood event equal to or exceeding a 0.5 PMF event, while adequately addressing the majority of the engineering, environmental and geotechnical concerns.

A general concept employed in these alternatives is to hold water away from the dam during all but very large runoff events. This principal of design results from the work of Harding Lawson Associates on geotechnical stability of the dam. The study showed that although the dam would not fail with water at the face even during an earthquake, additional stability and a reduced risk of foundation saturation could be obtained by keeping water back some distance thereby lowering the phreatic surface at the dam. We considered two concepts for providing this increased level of stability and several options for passing water through the dam face. These alternatives are described in Section 4.3.1 below.

4.3.1 Description of Conceptual Designs

Water Level at 2904' (Alternate IIa): This alternate would allow inflows from Rainy and Fleetwood Creeks to enter the impoundment unimpeded. Once in the reservoir, the flows would be temporarily stored, or passed directly through the impoundment with a constructed channel, depending on the volume received. This alternative provides for a water elevation in the impoundment of 2904 feet which is the minimum practical elevation that can currently be obtained through control at the decant tower. Tailings materials have accumulated to this level at the decant tower.

Discharge from the impoundment would be controlled at the tailings dam by a control structure, preferably a single concrete box culvert. The control structure would limit outflows to a maximum design flow (about 15 percent of 0.5 PMF). At this design rate the impoundment can receive a 0.5 PMF event without overtopping the dam.

An extensive study of outlet control structures was made before selecting the box culvert design. The control structure must necessarily have a small cross-sectional area if it is to reduce the volume of discharge and fully utilize the impoundment storage capacity. More natural control structures such as open channels were considered but these could only be utilized by sacrificing a large portion of the impoundment's potential storage capacity. Pipelines were also considered as an

inexpensive alternative but these presented safety hazards and were judged to be more subject to failure in long-term service.

Outflows from the control structure would be returned to Rainy Creek by an engineered channel armored with a rock rip-rap lining, integrating a series of reinforced concrete drop structures. The channel would be considerably smaller than a full diversion channel, and would be designed to incorporate natural terrain where possible to promote aesthetics and decrease environmental disturbance. Plate 8 shows a plan view of this routing alternate.

An emergency spillway, designed to safely pass flows exceeding the 0.5 PMF without overtopping or causing damage to the dam, could be constructed with this system. The spillway would be located opposite the control structure and outflow channel to prevent interference during use. A conceptual plan of a spillway located at the west abutment is shown on the plan. The spillway would be constructed such that flows are carried past the toe of the dam before release in order to prevent damage to the dam.

Water Level at 2910' (Alternate IIh): The fine tailings in the impoundment are saturated, unconsolidated, and have little bearing capacity making standard construction methods and equipment difficult to use. Due to the expected difficulties associated with constructing the inflow channel in the fine tailings, a variation of this alternate was investigated. To reduce the problems of construction in the tailings materials, a low level dike of cohesive (low permeability) material would be constructed across the tailings impoundment, approximately 500 feet from the face of the tailings dam as recommended in the Harding Lawson Associates dam stability report. Located at this distance from the dam the potential impact of standing water on dam foundations is minimal in the judgement of engineers at Harding Lawson Associates. Top of dike elevation would be approximately 2912.0, with the water level in the impoundment maintained at 2910.0, which has been selected as the maximum practical elevation at which water can be maintained in the impoundment without significant loss of storage capacity or increasing the risks associated with saturated tailings dam foundations and sudden failure or breaching of the dike. By raising the water level in the impoundment, the length of inflow channel and subsequent tailings excavation would be reduced and this would reduce construction costs. This alternate provides water cover for much of the tailings and thereby reduces the potential for dust production and also reduces the areal extent of required revegetation. Plate 9 shows a plan view of this alternate.

There are some additional risks with this alternative, however. Should the dike leak, which it may very well do because of the difficulty in getting good compaction of the dike materials on top of tailings and the potential for seepage through the tailings material itself, a drainage channel would probably be needed below the dike. Also, in the event of a major runoff event, one slightly greater than a 100-year storm, the dike would be overtopped resulting in damage to it and to the drainage channel below the dike.

East Abutment Outlet (Alternate IIc): Placing the control structure and outflow channel on the east abutment, and the emergency overflow channel on the west abutment, as shown in Plate 8, is judged to be the best overall alternate for routing floods through the vermiculite tailings impoundment while maintaining structural integrity. Placing the outflow on the east abutment provides the most aesthetically pleasing alternate for returning the flows to Rainy Creek, with the least environmental disturbance of considered alternatives.

The east abutment area can easily be modified to construct the outflow channel without significantly disturbing the area. The outflow channel would be armored with a rock rip-rap lining and integrate a series of drop structures placed to take maximum advantage of the terrain. A natural drainage would be incorporated into the final design to increase aesthetics, and decrease excavation and construction costs.

The emergency spillway, if provided, would be constructed in natural material adjacent to the tailings dam on the west abutment to the extent that it did not interfere with the existing Forest Service road. The area is presently disturbed from mining activities. To protect the toe of the dam, the spillway will carry the flows past the toe before release. The excavated material would be placed in the groin of the dam for additional protection.

The primary disadvantage of this alternate is the longer inflow channel in the tailings, resulting in higher construction costs to excavate and construct the channel. Some drilling and blasting may be required to construct portions of the outflow channel as well.

West Abutment Outlet (Alternate IIId): Locating the outflow control structure and channel on the west abutment, and the emergency spillway on the east abutment was investigated as an alternate for returning flows to Rainy Creek downstream of the tailings dam. No plans are provided for this alternate.

The primary advantage of this alternate would be to shorten the inflow channel through the tailings, reducing the extent of specialized construction to build the channel. Because the tailings are not as deep on this side of the impoundment, both the length of the channel excavation and the quantity of material to be removed would be reduced.

The primary disadvantage is the steeper sideslopes making construction of the outflow channel more difficult, and with questionable long-term geotechnical stability. A concrete drop chute (at considerable cost) or significant excavation of the abutment area may be required. Placing the emergency spillway on the east abutment would require relatively more excavation, partially in undisturbed forest, to get the flow past the toe of the dam before releasing it, reducing visual aesthetics as well. A partial relocation of the Forest Service access road would be required. Due to these engineering and aesthetic draw-backs, and lack of discernable advantages, this alternate was eliminated.

Outlet Over Dam Face (Alternate IIe): Constructing an outlet through the center of the dam and down the face was investigated as an alternate for returning flows to Rainy Creek. This alternate would consist of a straight inflow channel through the fine tailings connected to a reinforced concrete control structure and drop chute. Plate 10 provides a plan view of this alternative.

Placing an outlet in the dam face eliminates the need for excavation of either abutment, unless an emergency spillway is desired. The outlet control structure and drop chute would be built as one structure, and tied directly into the existing channel below the dam, eliminating the need for extensive downstream work. Overall, environmental disturbance is negligible.

There is an increased possibility of tailings dam saturation and seepage with this option. The zone of influence from the channel will affect a larger area than if it were located adjacent to an abutment. As with the other alternates, lining the channel would eliminate the problem. Long-term geotechnical stability of this system may be questionable, and construction would be moderately difficult on the steep slope.

Other disadvantages are reduced aesthetics, higher construction costs (reinforced concrete) and public safety (straight-walled drop chute and high velocities eliminate any chance of escape).

4.3.2 Evaluation of Alternatives for Channel Reconstruction in the Tailings

Safety: Routing floods through the tailings impoundment provides the best method to safely pass storm events of 0.5 PMF or larger while assuring the integrity of the dam. This concept takes advantage of the temporary storage capacity of the impoundment to reduce outflows while providing safe, effective flood routing.

The existing tailings dam is geotechnically very stable, having been designed to withstand earthquakes of a recommended magnitude with no loss of integrity. Temporarily storing peak flows provides a way of assuring minimum risk to the dam. Elimination of upstream diversion dams associated with the other main alternatives reduces risks associated with diversion dam failure.

Because of the storage capacity in the reservoir, and the emergency spillway, risk from debris/plugging is minimal for this alternative. In addition, several low maintenance structures would be installed to prevent debris from entering the control structure. During peak events, the entrance into the control structure will be submerged to prevent debris from entering into the control structure.

Reduced peak outflows will result in a considerably smaller outflow channel, making escape from the channel easier, hence better for public safety. In addition, the reduced outflows result in less flood damage to downstream structures, such as the highway.

Water Quality Impacts: With this alternate, tremolite fibers from the coarse tailings dump, and fine tailings impoundment will continue to impact surface water. However, during normal flow conditions the low gradient of the reconstructed channel and the placement of protective cover in the reconstructed channel will greatly reduce the risk of tremolite entrainment. Also it is anticipated that entrainment will continually decrease as vegetation becomes established and stabilizes the dump, impoundment, and other disturbed areas. Preliminary data from water monitoring programs indicate that water quality degradation from other mineral constituents is minimal at this site.

As discussed in Section 4.2, tremolite fibers will not be eliminated from Rainy Creek, regardless of the alternative selected. Fibers from the headwaters of Fleetwood Creek, from Carney Creek, and in the Rainy Creek streambed downstream of the impoundment, will continue to contribute to fiber counts in Rainy Creek.

Environmental Impacts: Environmental disturbance will be minimized with this alternate, especially when compared with full diversion. Some disturbance will occur during construction of the outflow channel. By reducing outflow volumes, erosion and other flood-related problems will be diminished.

Tailings/Dam Saturation: Saturation of the tailings dam in the immediate vicinity of the inflow channel, and resulting embankment stability should the toe-drains become inoperable, is a primary regulatory concern. Because of the low permeability of the fine tailings relative to the dam material, major water loss through infiltration is not expected to be as severe of a problem as with the diversion channels. Further, the rate of water movement through the fine tailings is significantly slower than the dam, as demonstrated by the piezometers installed in the dam face. Water entering the dam from the tailings or channel is expected to drain relatively quickly, hence reducing the possibility of saturation and subsequent seepage.

As discussed earlier, diverting flows to the side of the impoundment will not eliminate the possibility of tailings dam saturation. The only sure method of eliminating the risk, from any alternate, is with an impermeable channel or pipeline. Should tailings dam saturation become a problem, construction of an engineered toe drain will be completed by W.R. Grace.

Sedimentation: Increased sedimentation from the tailings impoundment is expected for a short period of time (estimated at 2 to 5 years) following closure. After that, vegetation will become established and provide slope stabilization, reduced erosion, utilization of excess water, and wildlife forage. A detailed description of re-vegetation is provided in Section 5.7. Sedimentation associated with channel excavations and other construction activities may also occur for a short time period, but will be negligible compared with a full diversion alternate.

Routing the surface water flows through the impoundment will take advantage of the remaining wetland to improve water quality through natural filtration and settlement.

In summary, routing floods through the existing tailings impoundment with a controlled outflow system provides the best method to safely control flood events meeting or exceeding the required 0.5 PMF design. This general concept provides a feasible method to safely route floods while minimizing environmental disturbance and maintenance, and improving aesthetics.

Advantages (Table 4.4) and disadvantages (Table 4.5) of routing the flood flows in a reconstructed channel through the tailings impoundment follow:

Table 4.4. Advantages associated with routing floods through the tailings impoundment.

| ALTERNATE | ROUTING THROUGH IMPOUNDMENT - ADVANTAGES |
|--------------------------------------|---|
| All Alternatives | <ul style="list-style-type: none"> ● Provides a higher level of public safety than other alternatives while retaining a relatively simple design; ● Provides a safe, cost effective method to handle storm flows while maintaining long-term integrity of the dam; ● Geotechnically the most stable alternative; ● Plugging/debris problems less critical or likely; ● The system is capable of handling floods larger than 0.5 PMF with the addition of a relatively simple emergency spillway; ● Outflow channel relatively small, making construction feasible and cost effective; ● Limited environmental disturbance; ● More natural/aesthetic outflow channel; ● Remaining wetland provides improves surface water quality through natural filtration and settling; ● Water loss to infiltration expected to be minimal; ● Less overall maintenance; ● Reduced potential for airborne particulate; ● Reduced outflows will reduce downstream impact from flooding. |
| Water Level at 2904' (Alternate IIa) | <ul style="list-style-type: none"> ● Maintains water away from the dam face as much as possible for maximum safety. |
| Water Level at 2910' (Alternate IIb) | <ul style="list-style-type: none"> ● Maintains water away from the dam face provided seepage through or under the dike is minimal; ● Reduces the requirements for construction in mucky material; ● Reduces requirements for revegetation; ● Maximum potential for reduction of airborne particulate from the impoundment. |

| ALTERNATE | ROUTING THROUGH IMPOUNDMENT - ADVANTAGES |
|--|---|
| East abutment outflow (Alternate IIc) | <ul style="list-style-type: none"> • Less overall environmental disturbance than west side outflow channel; • Existing terrain can be easily modified for outflow channel thereby reducing environmental disturbance; • Emergency spillway on west abutment can be constructed with a minimum of excavation and disturbance; • Highest public safety of all alternates. |
| West abutment outflow (Alternate IId) | <ul style="list-style-type: none"> • Shorter inflow channel; • Bedrock does not affect construction. |
| Outflow over dam face (Alternate IIe) | <ul style="list-style-type: none"> • Eliminates excavation of abutments for outflow channels; • Negligible environmental disturbance; • Control structure and drop structure are one structure; • Minimal downstream work required. |

Table 4.5. Disadvantages associated with routing floods through the tailings impoundment.

| ALTERNATE | ROUTING THROUGH IMPOUNDMENT - DISADVANTAGES |
|---|--|
| All Alternates | <ul style="list-style-type: none"> • Inflow channel difficult to construct in fine tailings, requiring specialized construction methods and equipment and increased costs; • Does not address tremolite fiber issue actively; • Possible saturation of a portion of the tailings dam; • Probable increased short-term sedimentation; • Slight risk of control structure becoming plugged. |
| Water Level at 2904' (Alternate IIa) | <ul style="list-style-type: none"> • Potentially difficult construction of a long channel through soft mucky tailings. |
| Water Level at 2910' (Alternate IIb) | <ul style="list-style-type: none"> • Dike and foundation materials may seep at a significant rate creating saturated tailings downstream of the dike, thereby defeating its intended purpose; • A major runoff event will cause the dike to be breached and repair will be required; • Reduces slightly the total storage capacity of the impoundment. |

| ALTERNATE | ROUTING THROUGH IMPOUNDMENT - DISADVANTAGES |
|---|---|
| East abutment outlet (Alternate IIc) | <ul style="list-style-type: none"> ● Excavation of bedrock may be necessary to construct outflow channel; ● Longer inflow channel required, unless variation is selected. |
| West abutment outlet (Alternate IId) | <ul style="list-style-type: none"> ● Outflow channel difficult to construct on steep side slopes; ● May require concrete drop chute; ● Emergency spillway difficult to construct on east abutment; ● Portion of the Forest Service access road requires relocation or reconstruction; ● Increase environmental disturbance. |
| Outlet over dam face (Alternate IIe) | <ul style="list-style-type: none"> ● Long-term geotechnical stability may be questionable; ● Saturation of tailings dam more likely than with other (no diversion) alternatives; ● Concrete structures increase cost; ● Safety concern with vertical side walls and high velocity flows; ● Most unnatural of impoundment routing alternatives. |

4.4 PARTIAL DIVERSION

A partial diversion of flood flows would entail diversion dam(s) and channels designed to intercept and divert flows up to and including a selected design flow, i.e. 10-year or 100-year events, which are described in Section 4.4.1 below. Flows exceeding the design capacity of the diversion dams would be allowed to by-pass the diversion dam through a "blow-out" plug of uncompacted fill placed in an engineered spillway and be routed through the reservoir using a system similar to those in Section 4.3. The concept behind this alternative would be to provide a system that would combine the advantages of a full diversion system with the advantages of flood routing through the reservoir. A full engineering analysis of these alternates is not detailed below, as many of the issues are covered in previous sections.

4.4.1 Description of Conceptual Designs

100-Year Flood Diversion (Alternate IIIa): A partial diversion system would require one or more dams similar to the full diversion dams, but designed to allow higher flows to by-pass them during larger events. The smaller design flows would be diverted around the impoundment in an open channel or pipeline, returning to Rainy Creek below the tailings dam. The larger flows would be routed through the reservoir using a system similar to those in Section 4.3, which includes a constructed

inflow channel and outflow channel, control structure, and emergency spillway. This alternative would virtually "double" the costs for the project, by requiring both flood routing systems to be constructed.

Designing and constructing a structurally competent diversion dam capable of diverting smaller flows while by-passing larger flows will be difficult to accomplish. As stated earlier, the tailings do not provide adequate foundation for structures, making long-term structural integrity and durability questionable. A single by-pass flood event would likely cause irreparable damage to the diversion structure due to scouring of the foundation layer. Constructing separate dams for Fleetwood and Rainy Creeks above the tailings is again an option. Regardless of the diversion dam site selection, continual maintenance would be required.

Due to the adverse conditions associated with the east side (coarse tailings, bedrock, etc.), the partial diversion channel would be constructed on the west side of the impoundment. Assuming a 10 ft. flat-bottomed channel, 2:1 maximum cut slopes, and 0.005 ft/ft gradient produces the channel section shown in Plate 11. The bottom of channel elevation would be approximately 2888 at the tailings dam. As with a full diversion channel, massive cuts would be required to construct a channel that would provide long-term service. Complete relocation of the Forest Service access road would again be required.

During a 0.5 PMF event, assuming the impoundment routing system was constructed similar to those in Section 4.3, the water level in the impoundment would rise to at least 2922, making the water level in the partial diversion channel 34 feet in depth (refer to Plate 11). Obviously, this volume of flow would be impossible to control without a structure, further increasing the cost of this system while providing limited added benefit. Lining the channel would also be recommended to prevent infiltration, geotechnical instability, and possible tailings dam saturation.

An option would be to install a pipeline to carry the partial flows around the impoundment, making the system similar to the existing Rainy Creek diversion pipeline. Continual maintenance could be expected based on W.R. Grace's experience with the current pipeline, and plugging would be a problem. A pipeline system of any kind is not recommended.

A partial diversion system would require separate outflow channels for the diversion channel, and the "backup" impoundment routing system. The outflow channel for the impoundment would be constructed as described in Section 4.3, while the partial diversion would require a drop chute or some other method of returning outflows to the elevation of Rainy Creek downstream of the tailings dam.

10-Year Flood Diversion: The partial diversion of stream flows exceeding a 10-year storm event would be virtually identical to the 100-year event. The restrictions of construction equipment dictate that the diversion channel would assume basically the same dimensions. The only significant design variation is in the outlet control structure from the diversion dam(s) which needs to be more restrictive in order to

limit flow. The smaller outlet, is a potential source of problems in that will be more subject to plugging by debris and will likely require more frequent cleanout.

One perceived advantage of this alternate is the periodic wetting of the tailings which might be beneficial for maintenance of vegetation and reduction of potential dust production. However, this wetting would be incomplete at best and its benefits would be questionable on such an infrequent and unpredictable basis.

4.4.2 Evaluation of Partial Diversion Alternatives

Safety: From a safety standpoint, partial diversion does not improve safety over the "no diversion" alternate, however, it is significantly better than a full diversion system. The reasons are covered in previous sections. Plugging or failure of smaller partial diversion dams would be less critical.

Water Quality Impacts: Asbestiform fiber contamination of surface water from the tailings impoundment would be reduced by diverting the "day-to-day" smaller flows around the impoundment, but would not be eliminated as discussed in Section 4.2.

Environmental Impacts: The environmental disturbance would be the most significant of any option. Massive excavations would be required for the diversion channel and drop chute. All excavation required for the outflow channel associated with routing through the impoundment would remain as well. Downstream impact would be reduced when compared to full diversion, but would be greater than the alternates routing floods through the impoundment.

Tailings/Dam Saturation: The possibility of saturating a portion of the tailings dam due to continuous flow through the impoundment will be eliminated, however, saturation from the diversion channel remains a possibility unless channel lining is installed.

Sediment: Short-term sedimentation from the tailings impoundment would be reduced with this alternative, but may increase from the major excavations associated with the diversion channel. The advantage of using the impoundment wetland for improving surface water quality through natural filtration and settling would be eliminated.

in summary, using a partial diversion system in conjunction with an impoundment routing system does not increase safety over the impoundment routing system. This alternate greatly increases costs. Maintenance and environmental disturbance increase, and geotechnical stability, construction feasibility, tailings dam saturation, and sedimentation remain as issues.

Advantages (Table 4.6) and disadvantages (Table 4.7) of the partial diversion alternate are summarized below:

Table 4.6 Advantages associated with partial diversion flood routing systems.

| ALTERNATE | PARTIAL DIVERSION - ADVANTAGES |
|--|--|
| All Alternates | <ul style="list-style-type: none"> • Will provides a higher level of public safety than a full diversion; • Geotechnically more stable than full diversion; • Plugging of channel from flood debris less critical than full diversion; • Possible reduction in downstream tremolite fiber concentration in surface water; • Possible reduction in short-term sedimentation from the tailings impoundment. |
| 100-Year Flood Design Basis (Alternate IIIa) | <ul style="list-style-type: none"> • Diversion dam outlet structures will be less prone to plugging than those for a 10-year flood. |
| 10-Year Flood Design Basis (Alternate IIIb) | <ul style="list-style-type: none"> • Periodic wetting of tailings <u>may</u> enhance growth of vegetation and provide for some degree of dust control; • Marginally lower costs for channel lining materials. |

Table 4.7 Disadvantages associated with partial diversion flood routing systems.

| ALTERNATE | PARTIAL DIVERSION - DISADVANTAGES |
|----------------|---|
| All Alternates | <ul style="list-style-type: none"> • Adds no safety benefit to impoundment routing (no diversion) alternative; • Partial diversion dams difficult to construct in fine tailings, requiring specialized construction methods and equipment and increased costs; • Long-term stability and integrity of partial diversion dams questionable; • Increases overall cost of the project significantly due to combination of systems; • Increased maintenance, particularly with partial diversion dams; • Saturation of tailings dam remains a possibility without diversion channel lining; • Possible increased short-term sedimentation from excavation; • Does not take advantage of impoundment wetland; • Plugging of smaller partial diversion channels; • Largest environmental disturbance of all alternatives. |

| ALTERNATE | PARTIAL DIVERSION - DISADVANTAGES |
|--|--|
| 100-Year Flood Design Basis (Alternate IIIa) | <ul style="list-style-type: none"> • Tailings will not receive a thorough wetting on any reasonably short time frame. |
| 10-Year Flood Design Basis (Alternate IIIb) | <ul style="list-style-type: none"> • More prone to plugging than a system designed for larger flows. |

4.4 SUMMARY/CONCLUSIONS


Based on findings of the engineering analysis of the various flood routing alternatives, routing the flood through the tailings impoundment using a designed structure to control discharges to an east abutment outflow channel appears to be the best, most feasible, and safest method for flood routing Rainy Creek through the vermiculite tailings impoundment area. In our judgement, safety should be the overriding factor in selection of a permanent reclamation plan. This alternate provides sufficient storage capacity within the impoundment to receive a 0.5 PMF event without utilizing an emergency spillway which is provided in the event of an even larger storm.


The recommended alternative does violate a provision of the permit requiring diversion of water around mine wastes at closure. This could be a matter of concern from the standpoint of water quality issues. It should be understood that this mine is not a base metal mine and does not produce acid mine drainage typically containing high levels of metals. One significant area of potential concern is tremolite fiber entrainment. However, Rainy Creek is not utilized directly as a drinking water source. Other alternatives will not totally eliminate this concern since Fleetwood Creek and Carney Creek originate in areas where natural outcropping of tremolite occurs or which have been subject to disturbance by mining activity.


In order to reduce these concerns, disturbed areas will be stabilized to reduce erosion through the establishment of vegetative cover. Similar measures are proposed for the tailings impoundment to reduce the level of suspended particulate in surface waters discharged through the dam. Included in these measures will be revegetation of tailings beach areas and installation of channel linings to stabilize the channel and prevent direct contact with underlying tailings material. A program to establish current water quality levels is underway and will continue on a regular basis as reclamation proceeds. Overall entrainment of asbestiform fibers from the tailings should be minimal due to these design measures.


Another area of concern may be the establishment of a precedent for reclamation by allowing surface waters to be routed through mine waste facilities. Had this facility


presented a significant risk to water quality, our recommendations would have been entirely different. As it is, the resolution of the safety and long-term stability aspects of the existing situation appear to take precedence over the relatively minor water quality issues, which are not life threatening or environmentally damaging. In summary, site-specific considerations make channel re-establishment a sound decision where at other facilities diversion may be more technically sound.


















Plate 5. Typical cross-section of west diversion channel showing limits of excavation.









LEGEND




Plate 10. Plan view of outlet/control structure over dam face for routing floods through the tailings impoundment (Alternate IIe).

5.0 PROJECT DESIGN - PREFERRED ALTERNATIVE

5.1 GENERAL DESIGN APPROACH

The general design approach of the preferred alternative entails routing all flood flows from both Rainy Creek and Fleetwood Creek into the tailings impoundment, controlling discharge with a control structure, and returning water to Rainy Creek (downstream of the tailings dam) by means of an outflow channel. No diversion structures will be employed. Flows in excess of 0.5 PMF will be handled with an armored emergency spillway. Routing flows through the unboundment provides the safest method of passing major flood events through the impoundment area, while maintaining the long-term integrity of the tailings dam. The advantages of such a system have been demonstrated in Section 4.0.

Flood flows enter the impoundment unrestricted and, depending on the discharge rate, are passed directly through the impoundment and discharged, or temporarily stored in the existing reservoir until discharged. Discharges from the unboundment are restricted to a design peak outflow by means of a concrete box culvert. Discharges from the control structure enter a constructed outflow consisting of a rock-lined, trapezoidal channel connecting a series of concrete drop structures. Flows are returned to Rainy Creek approximately 800 feet below the tailings dam. An inflow channel will be constructed in the tailings in order to connect the impoundment wetland with the control structure. This system will allow W.R. Grace to maintain a relatively constant water surface elevation (in the wetland) to aid in revegetation, and prevent saturation of the tailings dam.

Other work proposed during closure includes removal of the existing water control structures (Rainy Creek diversion, emergency spillway, and decant tower); providing a stabilized Fleetwood Creek channel through the coarse tailings dump; revegetation and other erosion control and surface stabilization measures; and, general reclamation efforts to improve natural aesthetics of the impoundment area.

Plate 8 shows a plan view of the tailings impoundment with the preferred flood routing alternate overlain. Following sections provide greater detail of the proposed closure plan for the vermiculite tailings unboundment.

5.2 TAILINGS IMPOUNDMENT

The tallings impoundment will basically remain as it currently exists with a pond and associated fringe of emergent vegetation (wetland), "beach" area, dam, and inflow from Rainy and Fleetwood Creeks. The flood routing system will be constructed, the existing water control structures removed, and revegetation/reclamation work completed during closure.

Following closure, the pond will be retained as a natural wetland. The wetland will have a water surface elevation of $2904 \pm$ and will encompass approximately 20 acres in the middle to upper portion of the impoundment. Water depths will range from 0 ft at the water's edge to a maximum of about 7 ft, with an average depth estimated at 2 to 4 feet. The water's edge will remain approximately 700 to 800 feet from the dam creating a "beach" area (between the water's edge and the upstream face of the dam) of slightly less than 20 acres. Revegetation will take place on the entire impoundment area (see Section 5.7). The estimated boundaries of the wetland, following closure, are represented by blue lines on Plate 8.

Inflow from Rainy Creek will continue to enter the impoundment from the north. The (Rainy Creek) diversion structure, located approximately 1 mile upstream of the impoundment, and associated pipeline together with the present emergency spillway and decant tower/pipeline will be removed. Fleetwood Creek will be restored to a stabilized channel located adjacent to the toe of the coarse tailings dump, and enter the impoundment from the east. Neither flow will be restricted or diverted.

A flood routing control system for the impoundment will be constructed on the lower (dam) end. Details are located in following sections.

5.3 INLET CHANNEL

An inlet or inflow channel, from the edge of the wetland to the control structure, will be constructed as part of the preferred flood routing system. In addition to flood routing, the inflow channel will provide passage for low flows through the impoundment to prevent the water surface elevation in the pond from rising, inundating the beach area, and eventually saturating the tailings dam. The inlet channel is shown on Plate 8.

The inflow channel will connect the wetland with the control structure. The channel crest elevation (at the edge of the wetland) will be set at $2904.0 \pm$, and the crest elevation of the control structure will be set at 2900.0, making a channel gradient of approximately 0.0038 ft/ft or 0.38%. Maximum calculated flow velocity in the inflow channel will be 5.5 feet per second. Plate 12 represents a section following the centerline of channel, identifying elevations, grades, etc. for the inflow channel, control structure, and outflow channel.

The inflow channel will be a trapezoidal construction with 10 ft wide bottom, and a combination of 2:1 and 3:1 sideslopes. Plate 13 shows a typical inlet channel cross-section. The bottom and sides of the channel (to 7 ft elevation) will be covered with a non-woven

geo-textile, followed by a 6 inch bedding layer of "dirty" gravel, and overlain by a 12 inch (minimum) layer of well graded $D_{50} = 4"$ cobbles with fines (dirty) and seeded. In addition to providing bedding for the cobble channel lining, the dirty gravel will improve revegetation success in the channel, and substantially reduce the contribution of tremolite fibers from that portion of the channel. The dirty cobble lining should also improve reclamation success, further stabilizing the channel against storm events. The channel lining will be keyed into the sides of the channel as shown.

The lined portion of the channel will be excavated at a 2:1 slope, with the upper portions excavated at a 3:1 (refer to Plate 13). The concept behind this design is that the upper, unlined portions of the slope will have less potential for erosion prior to vegetation becoming established with a flatter slope. Also, vegetation will have a better success rate, and will become established quicker. Armoring the 2:1 slopes will prevent erosion and flood scour from occurring until vegetation becomes established. Should slope stability or other problems become evident during actual construction, the slopes will be flattened at that time.

5.4 CONTROL STRUCTURE

A control structure will be constructed through the tailings dam to control discharges from the reservoir, and into the outlet channel below the dam. The control structure will provide a method for safely reducing peak flows during major events while preserving the integrity of the dam and reducing the downstream impact. Our study of various control structures including open channels, concrete box culverts and metal pipe culverts suggests that the concrete box culvert provides the best method for controlling outflow while preserving the surge capacity of the impoundment for major storm events.

For the purpose of the conceptual study, we investigated two configurations for the box culvert control structure. These were twin 4 ft. by 6 ft. concrete box culverts (total open area 46.6 square feet), and a single 4 ft. by 8 ft. concrete box culvert (total open area 31.4 square feet). Both structures have an inflow elevation of 2900.0, and a 2% grade. Entrance construction will match adjacent contours.

Calculated peak outflow (26 feet elevation head) from the twin box culverts is 1080 cfs, and 744 cfs from the single box culvert. Design calculations for peak outflow are located in Appendix C. We then looked at the performance of these outlet structures under several flow conditions including the 100-year storm event and the 0.5 PMF event. A discussion of the performance of the systems under these conditions follows in Sections 5.4.1 and 5.4.2. Pertinent findings of this analysis are summarized in Table 5.1.

5.4.1 100-Year Event

Routing the 100-year, 24-hour event peak inflow of 460 cfs (Section 3.2.2) through the reservoir using a crest elevation (beginning of the inflow channel) of 2904.0, and the single 4' x 8' box culvert for outlet control, produced a peak discharge of 243 cfs and a maximum water surface elevation of 2905.4 at the outlet control structure. With this system,

Table 5.1 Flood routing parameters for various routing alternatives.

| DESIGN FLOOD | PEAK FLOW (cfs) | CONTROL STRUCTURE | PEAK DISCHARGE ¹ (cfs) | PEAK WATER ELEVATION (ft) |
|--------------|-----------------|-------------------|-----------------------------------|---------------------------|
| 100-Year | 460 | twin 4' x 6' | 228 | 2904.0 |
| 0.5 PMF | 5838 | as above | 983 | 2922.6 |
| 0.5 PMF | 5838 | single 4' x 8' | 731 | 2925.1 |
| 0.55 PMF | 6320 | twin 4' x 6' | 1078 | 2925.9 |
| 0.66 PMF | 7750 | as above | 2071 ² | 2925.9 |
| 0.66 PMF | 7700 | single 5' x 9' | 1860 ³ | 2925.9 |

1 Peak discharge from the proposed control structure.

2 Includes outflow from a 50 foot wide emergency spillway.

3 Includes outflow from a 35 foot wide emergency spillway.

virtually all of the impounded flows from a 100-year event would drain in less than 24 hours. This demonstrates that the surface water elevation of the impoundment will not rise significantly above the elevation of 2904.0 during a 100-year event if the twin box culverts are used to control outflow.

This is an important point. Should a 100-year event occur immediately before a 0.5 PMF event, the surface water elevation in the impoundment will remain at the proposed static water elevation of 2904.0. Because of this, routing/storage will begin at elevation 2904.0 rather than the existing emergency crest elevation of 2920.0 as outlined by the Montana Dam Safety regulations (State of Montana, 1989).

5.4.2 Probable Maximum Flood

Various percentages of the PMF event, beginning with a minimum of 0.5 PMF, were routed through the impoundment using representative outlet control scenarios, including with and without an emergency spillway. The results of the flood routing models are located in Appendix C.

Routing 0.5 PMF using the twin box culvert control (no emergency spillway) produced a peak discharge of 983 cfs, and a maximum water surface elevation of 2921.95, or slightly over 4 feet of freeboard remaining at the worst case. This routing was modeled using an initial water surface elevation of 2900, rather than the expected elevation of 2904. Final water surface elevations are estimated to be about 0.6 feet higher than the model results, or approximately 2922.55.

Routing 0.5 PMF using the single box culvert control (no emergency spillway) produced a peak discharge of 731 cfs at a maximum water surface elevation of 2925.1, or slightly less than 0.9 feet of freeboard. Again, a beginning elevation of 2900 was used, making the peak elevation slightly higher.

An event with a peak flow of 6320 cfs (approximately 0.55 PMF) was routed through the reservoir using the twin box culverts, and no emergency spillway. This event produced a peak outflow discharge of 1078 cfs, and a peak water surface elevation of 2925.9, or approximately 0.1 feet of freeboard.

A fourth model was completed to determine what peak flow the reservoir would safely handle with a 50 foot wide (2:1 sides) emergency spillway channel in conjunction with the twin box culverts. Setting the crest of the emergency spillway at elevation 2922.0 would allow an event of approximately 7750 cfs (0.66 PMF) through the impoundment without overtopping the dam. Maximum water elevation would be 2925.9.

The proposed location of the emergency spillway imposes constraints on the amount of available space to construct the spillway without affecting the existing USPS road. In order to avoid impacting the USPS road, the emergency spillway will be about 35 feet in width. A model was completed using a single box culvert and a 35 foot wide emergency spillway with a crest elevation of 2922.0. This system will allow an event of approximately 7700 cfs (0.66 PMF) through the impoundment with a peak discharge (combined culvert and emergency spillway) of approximately 1860 cfs, and a maximum water elevation of 2925.9.

The preferred control structure for this conceptual design is a single concrete box culvert with dimensions 4 ft by 8 ft, and an estimated total length of 120 feet (inlet to outlet). This structure will be less prone to blockage by debris and easier to maintain because of its large open area. The control structure will be placed in the east abutment of the tailings dam adjacent to the bedrock, and graded at 0.02 ft/ft, or 2%. Inlet (crest) elevation will be 2900.0 and outlet elevation approximately 2897.6. The control structure will outflow directly into the outflow channel (Section 5.5). Plate 14 shows a typical cross-section of the control structure at the centerline of the tailings dam.

Peak inflows from large events will enter the reservoir and be temporarily stored until discharged through the control structure at a greatly reduced rate. With a peak inflow of 5838 cfs at 0.5 PMF, and a maximum control structure discharge of 744 cfs at 26 feet elevation head (distance from free water surface to control structure crest elevation), outflows are reduced by greater than 85%.

Every precaution will be taken during final design and construction of the box culvert in the tailings dam to insure against failure and maintain the integrity of the dam. The box culvert will be bedded, backfilled, and compacted following strict specifications. Rip-rap in the apron approach to the inlet of the culvert will be upgraded to compensate for the acceleration of flow as it converges on the opening of the culvert. Provisions will be made for collection of debris before the culvert entry which could be substantial in a major flood. Constant on-site supervision will be provided by a Registered Professional Engineer.

With the reduction in peak discharge, the outflow channel will be considerably smaller and more stable, and flood impact to downstream areas will be greatly reduced as well.

5.5 OUTLET CHANNEL

The outlet or outflow channel will be constructed as part of the flood routing system, and will carry discharges from the reservoir control structure and return them to the natural Rainy Creek channel downstream of the tailings dam. The outflow channel, constructed on the east abutment, will consist of a heavily armored channel in conjunction with a series of concrete grade control or drop structures. This type of construction will be both functional and aesthetically pleasing, and will quickly return the flows to Rainy Creek. Environmental disturbance will be kept to a minimum. Plate 8 shows the outflow channel in plan view.

The channel will begin at the outlet of the control structure (elevation 2897.6) and tie into the Rainy Creek channel at approximate elevation 2780, with a total length of about 1300 feet. Maximum gradient will be slightly over 0.04 ft/ft (4%), and will be adjusted to "fit" the existing terrain. Maximum drop height of the drop structures will be 12 feet. A section following the centerline of channel is found on Plate 12.

A typical cross-section of the of the channel will be trapezoidal construction with a 10 foot wide bottom and 2:1 sideslopes, heavily armored with a minimum of 42 inches of rock rip-rap and underlain with a sand/gravel layer or a non-woven geotextile filter cloth. The rip-rap will be well graded with a minimum size of 3 inches and a maximum size of 36 inches. A 12-foot wide access road will be constructed on the inside berm. Plate 15 shows a typical outflow section.

The grade control structures proposed will be straight reinforced concrete drop structures similar to the SCS Type C structures, with a maximum drop height of 12 feet. The drop structures will be placed to utilize existing terrain, and depending on foundation conditions encountered during final design field investigations, some modifications may be required. Approximate drop structure locations are shown on Plate 8. Appendix D contains a standard drawing for a Type C drop spillway.

Construction of the outlet will require a moderate amount of excavation in the hillside adjacent to the east abutment of the tailings dam. With the close proximity of bedrock, portions of the channel will be in weathered or unweathered bedrock, requiring drilling and blasting. Some modification of the designed sideslopes of the outflow channel may be made should final design field investigations indicate the presence of durable bedrock. The intent of the project is to align the channel to maximize the use of the existing terrain and minimize environmental disturbance.

5.6 EMERGENCY SPILLWAY

An emergency relief spillway will be constructed on the west abutment of the tailings dam, and work in conjunction with the main flood routing system to assure safe passage of

storm events exceeding 0.5 PMF. It will be sized to provide additional flood routing capacity within the constraints of maintaining construction within the abutment area of the dam but without necessitating a relocation of the Forest Service road. The spillway is designed to prevent overtopping of the tailings dam for storms with peak inflows of approximately 7700 cfs or 0.66 PMF (35 ft.). Construction of this emergency spillway is not required by regulation, but as a method of improving public safety. Plate 8 shows the general location of the spillway.

The emergency relief spillway will be constructed adjacent to the west abutment of the tailings dam, and will terminate 300+ feet downstream of the centerline of the dam. The design will prevent damage to the dam by delaying release of the overflows until past the toe of the tailings dam.

A typical cross-section of the of the emergency relief spillway will be trapezoidal construction with a 30 to 35 foot wide bottom and 2:1 sideslopes, armored with a minimum of 36 inches of well graded rock rip-rap. Plate 16 shows a typical cross-section of the relief spillway.

5.7 REVEGETATION

Revegetation of the tailings impoundment area will stress the re-establishment of plant species for slope stabilization, reduced erosion, utilization of excess water, aesthetic enhancement and self perpetuating vegetation for wildlife. The re-vegetation plan includes grasses, forbes, shrubs, and trees.

A specific grass mix will be used for reseeding, with each specie selected for a particular advantage that will include fixing nitrogen, production of organic matter, early emergence for soil cover and species with deep root penetration to stabilize the soil and recover water from a greater soil thickness. The tailings impoundment area will be hydroseeded at approximately 24 lbs PLS/acre and 2000 lbs/acre organic mulch where soil conditions permit. The mulch will aid in erosion control, soil aeration, seed germination, seedling establishment, and organic material. Broadcast seeding will be done on the soft tailings materials which provide poor bearing capacity for hydromulching equipment. An 18-46-0 fertilizer will be applied concurrently to improve plant growth, color and vigor. All seeding will take place in the spring or early fall.

The lower, wetter portions of the tailings impoundment area are characteristic of riparian sites which naturally promote fast growing native species such as willow, aspen, alder, chokecherry, dogwood, current, serviceberry and rose wood. These species will be planted to utilize excess water on the area surrounding the tailings pond and the beach area. Larger-sized trees are subject to wind-throw and are not recommended for this specific location.

Smaller trees and shrubs will be planted along the side slopes of the tailings dam and excavated channels. Certain provisions of the dam safety law prohibit trees on the face of dams. However, since the impoundment will normally not be holding water at capacity, the

use of trees to stabilize the dam face, particularly at the lower elevations, would appear to offer more benefits both aesthetically and structurally than leaving the face of the dam entirely barren. Shrubs will quickly establish a denser cover to protect tree seedlings and new grass. Roots, especially those of woody vegetation, help stabilize banks by holding soil, reduce sediment flow and increase hydraulic resistance flow.

The coarse tailings dump has already been reclaimed and revegetated. Dozer basins were installed as catchments for runoff in order to reduce the potential for erosion. The entire coarse tailings area was seeded with a mixture of grasses and clovers. Several thousand trees and native plant species have been planted randomly along the face of the coarse tailings dump and in the dozer basins.

The tailings impoundment is currently used by moose which forage for aquatic vegetation near its edges. The reestablishment of vegetation on other areas of the impoundment will encourage use by deer and elk which are also commonly seen in the area. The use of specific cultural treatments, proper seed selection and a diversity of woody plant material will aid in the re-establishment of vegetation which will have probable long-term soil stabilization and assist in the natural regeneration of a productive forest habitat.

5.8 STABILIZATION/EROSION CONTROL

An important constituent of the flood routing system, and other (tailings impoundment) closure activities will be reduction of erosion and long-term stabilization. This is particularly important at this site as the tailings impoundment and coarse tailings dump are basically devoid of vegetation at the present, making them prone to erosion and other problems. W.R. Grace will exercise best management practices to reduce these concerns.

As described in the above sections, armoring of channels, revegetation, grade reduction (drop) structures, and other methods will be employed to reduce erosion in the flood routing systems. Cut slopes will be a maximum of 2:1 for long slopes, and 1 1/2:1 with spaced benches for road relocation and other lesser cuts. The emergency spillway will be constructed to release flows past the toe of the dam, and the groin of the dam will be reinforced as necessary.


Fleetwood Creek, now located in a sideslope constructed drainage channel, will be returned to a more natural channel adjacent to the toe of the coarse tailings dump. The channel will be stabilized with natural materials where possible including vegetation, log structures, and other methods to improve geomorphic stability.

The remaining impoundment wetland will improve surface water quality through natural filtration and settling.

5.9 OTHER CLOSURE ACTIVITIES

Other work that will be completed as part of the impoundment closure will be to remove the Rainy Creek diversion pipeline, remove and reclaim roads, regrade portions of the coarse tailings dump, and plant trees on the downstream face of the tailings dam (below the level of the tailings).

The final construction activity for the impoundment will be to demolish the decant tower and plug its outflow piping with concrete.






Plate 13. Typical cross-section of the inflow channel for the proposed flood routing system.





Plate 14. Typical cross-section of the discharge control structure for the proposed flood routing system. Section taken from centerline of dam.



6.0 POST-CLOSURE CARE

6.1 POST-CLOSURE MANAGEMENT

W.R. Grace & Company is committed to proper management of the reclaimed mine property as long as it retains ownership of the property. Arrangements would be made for a fulltime custodian to look after the property. Part of the custodian's responsibilities will include periodic inspection of stream routing structures to assure proper operation and structural integrity.

W.R. Grace will close access to the upper mine property. However, situated next to the Forest Service access road, the tailings pond area will be accessible to the public. These areas will be posted for no trespassing. The custodian will provide security for this area to prevent unauthorized access to the property which will assure that initial revegetation efforts are not disturbed by recreational use. The custodian will also be responsible for coordination with regulatory agencies for ongoing monitoring activities.

6.2 WATER QUALITY MONITORING PROGRAM

A program of water quality monitoring was begun in the fall of 1991 by W.R. Grace to develop data regarding current water quality and to monitor the effects of closure activities on future water quality. This program is described in a document submitted to the Montana Department of State Lands, Water Quality Bureau (Hudson, 1991). The program calls for sampling and analysis of Rainy Creek, Fleetwood Creek, Carney Creek and discharges from the tailings impoundment. Monitoring will include heavy metals, although this should not be a problem for this particular mine, and asbestiform fibers. The monitoring will continue for a minimum of three years with provisions for additional monitoring depending on the results of the previous sampling.

6.3 MAINTENANCE

The construction of channels for flood routing is not expected to be a solution without maintenance requirements. The recommended alternative is what we believe will offer the lowest maintenance requirements and least potential for catastrophic failures. The success of the closure in meeting these goals for the long-term depends on good maintenance practices. W.R. Grace is committed to this maintenance throughout its ownership of the

property and will require that it be continued as a condition of any future sale of the property.

Areas which will require periodic inspection, on at least an annual basis, are the toe drain piping, box culvert outlet structure, and the constructed channels. Should the toe drains begin to fail and remedial action be indicated to prevent saturation and subsequent erosion of the dam foundations, W.R. Grace will implement appropriate corrective measures. A conceptual design for such remedial action has already been prepared by Harding Lawson Associates. Other structures may also require maintenance or reconstruction from time to time to assure continued functionality according to intended design.

7.0 REFERENCES

- Hudson, T.J., 1991, "W.R. Grace Vermiculite Mine Closure Water Quality Monitoring Plan"; Schafer and Associates, Bozeman, Montana; prepared for Montana Department of Health and Environmental Sciences, Water Quality Bureau, Helena, Montana.
- Shahriar Vahdani, Ph.D., et al, 1992, "Geotechnical Evaluation, W.R. Grace Dam, Rainy Creek, Montana"; Harding Lawson Associates, San Francisco, California; prepared for W.R. Grace & Company, Construction Products Division, Libby, Montana.
- Foster, R.C. et al, 1981, "Rainy Creek Basin Zonolite Tailings Dam, Libby, Montana, MT-1470, Phase I Inspection Report, National Dam Safety Program"; Morrison-Maierle, Inc. Consulting Engineers, Helena, Montana; prepared for The Honorable Ted Schwinden, Governor of the State of Montana.
- Boettcher, A.L., 1963, "Geology and petrology of the Rainy Creek intrusive near Libby, Montana", Unpublished M.S. Thesis, Pennsylvania State University., 70 p.
- Lewis, L.E. and Lawson, R.T., 1971, "Foundation Investigation and Engineering Analysis, Tailings Dam, W.R. Grace and Company, Construction Products Division, near Libby, Montana"; Harding, Milier, Lawson and Associates, San Rafael, California; prepared for Bovay Engineers, Inc. of Spokane, Washington.
- U.S. Dept. of Agriculture, 1977, Soil Conservation Service, Average Annual Precipitation, Montana based on 1941-1970 base period, 13 pp.
- U.S. Dept. of Agriculture, 1985, Soil Conservation Service, National Engineering Handbook, Section 4, "Hydrology", 6th amend.
- U.S. Dept. of the Interior, 1989, "Flood Hydrology Manual", A Water Resources Technical Publication, 1st ed., Bureau of Reclamation, Denver, Colorado, 243 pp.
- U.S. Dept. of Commerce, 1973, National Oceanic and Atmospheric Administration, National Weather Service, "Precipitation-Frequency Atlas of the Western U.S.", Volume 1 - Montana.
- U.S. Weather Bureau, 1966, Hydrometeorological Report No. 43, "Probable Maximum Precipitation, Northwest States", Washington, D.C.
- State of Montana, January 1989, Department of Natural Resources and Conservation, "Dam Safety", Chapter 14.

APPENDIX A

HYDROLOGIC MODELING RESULTS

**W.R. GRACE HYDROGRAPH
FLEETWOOD CREEK
10-YEAR, 24-HOUR STORM (2.4 in.)**

| | INPUT DATA | TIME STEP (Hrs) | TIME (Hrs) | CUMULATIVE PRECIP (Inches) | CUMULATIVE RUNOFF (Inches) | INCREMENTAL RUNOFF (Inches) | TOTAL FLOW (cfs) |
|--------------------------|---------------|-----------------------|---------------|----------------------------------|----------------------------------|-----------------------------------|------------------------|
| Total Precip (Inches) | 2.400 | 1.000 | 0.515 | 0.012 | 0.000 | 0.000 | 0.000 |
| Total Duration (Hrs) | 24.000 | 2.000 | 1.030 | 0.026 | 0.000 | 0.000 | 0.000 |
| | | 3.000 | 1.545 | 0.041 | 0.000 | 0.000 | 0.000 |
| Area (Sq. miles) | 3.900 | 4.000 | 2.061 | 0.035 | 0.000 | 0.000 | 0.000 |
| Longest Run (Feet) | 16370.000 | 5.000 | 2.579 | 0.070 | 0.000 | 0.000 | 0.000 |
| Ave. Slope (%) | 11.100 | 6.000 | 3.001 | 0.084 | 0.000 | 0.000 | 0.000 |
| SCS Curve # | 60.000 | 7.000 | 3.006 | 0.088 | 0.000 | 0.000 | 0.000 |
| | | 8.000 | 4.121 | 0.115 | 0.000 | 0.000 | 0.000 |
| Stonige 3 (Inches) | 6.667 | 0.000 | 4.636 | 0.134 | 0.000 | 0.000 | 0.000 |
| Initial Abstr. (Inches) | 1.333 | 10.000 | 5.151 | 0.154 | 0.000 | 0.000 | 0.000 |
| Time-concentration (Hrs) | 2.576 | 11.000 | 6.657 | 0.173 | 0.000 | 0.000 | 0.000 |
| Time-peak (Hrs) | 1.803 | 12.000 | 6.182 | 0.192 | 0.000 | 0.000 | 0.000 |
| Time-base (Hrs) | 4.814 | 13.000 | 6.607 | 0.218 | 0.000 | 0.000 | 0.000 |
| Duration (Hrs) | 0.515 | 14.000 | 7.212 | 0.240 | 0.000 | 0.000 | 0.000 |
| Incr. Precip. (Inches) | 0.052 | 15.000 | 7.727 | 0.284 | 0.000 | 0.000 | 0.000 |
| | | 16.000 | 8.242 | 0.288 | 0.000 | 0.000 | 0.000 |
| | | 17.000 | 0.757 | 0.336 | 0.000 | 0.000 | 0.000 |
| | | 18.000 | 9.273 | 0.372 | 0.000 | 0.000 | 0.000 |
| | | 10.000 | 0.788 | 0.413 | 0.000 | 0.000 | 0.000 |
| | | 20.000 | 10.303 | 0.458 | 0.000 | 0.000 | 0.000 |
| | | 21.000 | 10.818 | 0.523 | 0.000 | 0.000 | 0.000 |
| | | 22.000 | 11.333 | 0.617 | 0.000 | 0.000 | 0.000 |
| | | 23.000 | 11.848 | 0.929 | 0.000 | 0.010 | 0.883 |
| | | 24.000 | 12.363 | 1.097 | 0.019 | 0.014 | 4.287 |
| | | 23.000 | 12.879 | 1.819 | 0.033 | 0.011 | 11.824 |
| | | 26.000 | 13.394 | 1.808 | 0.044 | 0.009 | 23.084 |
| | | 27.000 | 13.909 | 1.958 | 0.093 | 0.008 | 34.836 |
| | | 28.000 | 14.424 | 2.002 | 0.061 | 0.005 | 42.210 |
| | | 20.000 | 14.938 | 2.038 | 0.087 | 0.006 | 40.137 |
| | | 30.000 | 15.454 | 2.071 | 0.074 | 0.006 | 44.611 |
| | | 31.000 | 15.969 | 2.100 | 0.078 | 0.006 | 42.476 |
| | | 32.000 | 16.485 | 2.129 | 0.065 | 0.005 | 39.069 |
| | | 33.000 | 17.000 | 2.155 | 0.080 | 0.008 | 37.712 |
| | | 34.000 | 17.515 | 2.191 | 0.098 | 0.009 | 35.028 |
| | | 35.000 | 18.030 | 2.213 | 0.102 | 0.004 | 34.688 |
| | | 36.000 | 18.540 | 2.232 | 0.107 | 0.004 | 33.616 |
| | | 37.000 | 19.060 | 2.251 | 0.111 | 0.004 | 32.287 |
| | | 38.000 | 19.576 | 2.270 | 0.115 | 0.004 | 30.372 |
| | | 38.000 | 20.091 | 2.287 | 0.110 | 0.003 | 28.474 |
| | | 40.000 | 20.600 | 2.302 | 0.123 | 0.003 | 26.701 |
| | | 41.000 | 21.121 | 2.316 | 0.126 | 0.003 | 25.088 |
| | | 42.000 | 21.636 | 2.330 | 0.130 | 0.004 | 23.585 |
| | | 43.000 | 22.181 | 2.345 | 0.133 | 0.004 | 22.301 |
| | | 44.000 | 22.666 | 2.358 | 0.137 | 0.004 | 21.310 |
| | | 45.000 | 23.181 | 2.374 | 0.140 | 0.004 | 20.625 |
| | | 46.000 | 23.697 | 2.308 | 0.144 | 0.003 | 20.132 |
| | | 47.000 | 24.212 | 2.400 | 0.147 | 0.000 | 19.609 |
| | | 48.000 | 24.727 | 2.400 | 0.147 | 0.000 | 18.607 |
| | | 48.000 | 25.242 | 2.400 | 0.147 | 0.000 | 18.688 |
| | | 50.000 | 25.757 | 2.400 | 0.147 | 0.000 | 13.836 |
| | | 51.000 | 20.272 | 2.400 | 0.147 | 0.000 | 10.961 |
| | | 52.000 | 26.787 | 2.400 | 0.147 | 0.000 | 7.712 |
| | | 53.000 | 27.309 | 2.400 | 0.147 | 0.000 | 5.510 |
| | | 54.000 | 27.818 | 2.400 | 0.147 | 0.000 | 3.946 |
| | | 55.000 | 28.333 | 2.400 | 0.147 | 0.000 | 2.842 |
| | | 56.000 | 28.848 | 2.400 | 0.147 | 0.000 | 2.036 |
| | | 57.000 | 29.363 | 2.400 | 0.147 | 0.000 | 1.466 |
| | | 58.000 | 29.878 | 2.400 | 0.147 | 0.000 | 1.040 |
| | | 59.000 | 30.393 | 2.400 | 0.147 | 0.000 | 0.740 |
| | | 60.000 | 30.900 | 2.400 | 0.147 | 0.000 | 0.924 |
| | | 61.000 | 31.424 | 2.400 | 0.147 | 0.000 | 0.370 |
| | | 62.000 | 31.038 | 2.400 | 0.147 | 0.000 | 0.259 |
| | | 60.000 | 38.484 | 2.400 | 0.147 | 0.000 | 0.176 |
| | | 64.000 | 32.969 | 2.400 | 0.147 | 0.000 | 0.120 |
| | | 65.000 | 33.484 | 2.400 | 0.147 | 0.000 | 0.078 |
| | | 66.000 | 33.999 | 2.400 | 0.147 | 0.000 | 0.047 |
| | | 67.000 | 34.519 | 2.400 | 0.147 | 0.000 | 0.025 |
| | | 68.000 | 35.030 | 2.400 | 0.147 | 0.000 | 0.009 |
| | | 69.000 | 35.545 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 70.000 | 36.060 | 2.400 | 0.147 | 0.000 | 0.000 |

**W.R. GRACE HYDROGRAPH
RAINY CREEK
10-YEAR, 24-HOUR STORM (2.4 in.)**

| | INPUT DATA | TIME STEP (Hrs) | TIME (Hrs) | CUMULATIVE PRECIP (Inches) | CUMULATIVE RUNOFF (Inches) | INCREMENTAL RUNOFF (Inches) | TOTAL FLOW (cfs) |
|--------------------------|---------------|-----------------------|---------------|----------------------------------|----------------------------------|-----------------------------------|------------------------|
| Total Precip (Inches) | 2.400 | 1.000 | 0.709 | 0.012 | 0.000 | 0.000 | 0.000 |
| Total Duration (Hrs) | 24.000 | 2.000 | 1.417 | 0.034 | 0.000 | 0.000 | 0.000 |
| | | 3.000 | 2.128 | 0.055 | 0.000 | 0.000 | 0.000 |
| Area (Sq. miles) | 5.900 | 4.000 | 2.834 | 0.077 | 0.000 | 0.000 | 0.000 |
| Longest Run (Feet) | 25870.000 | 8.000 | 3.543 | 0.098 | 0.000 | 0.000 | 0.000 |
| Ave. Slope (%) | 12.200 | 0.000 | 4.252 | 0.125 | 0.000 | 0.000 | 0.000 |
| SCS Curve # | 60.000 | 7.000 | 4.980 | 0.144 | 0.000 | 0.000 | 0.000 |
| | | 0.000 | 5.609 | 0.173 | 0.000 | 0.000 | 0.000 |
| Storage S (Inches) | 0.667 | 8.000 | 0.377 | 0.204 | 0.000 | 0.000 | 0.000 |
| Initial Abstr. (Inches) | 1.333 | 10.000 | 7.086 | 0.240 | 0.000 | 0.000 | 0.000 |
| Time-concentration (Hrs) | 3.543 | 11.000 | 7.789 | 0.276 | 0.000 | 0.000 | 0.000 |
| Time-peak (Hrs) | 2.400 | 12.000 | 0.503 | 0.319 | 0.000 | 0.000 | 0.000 |
| Time-base (Hrs) | 6.622 | 13.000 | 8.212 | 0.353 | 0.000 | 0.000 | 0.000 |
| Duration (Hrs) | 0.700 | 14.000 | 9.821 | 0.413 | 0.000 | 0.000 | 0.000 |
| Incr. Precip. (Inches) | 0.071 | 15.000 | 10.629 | 0.487 | 0.000 | 0.000 | 0.000 |
| | | 16.000 | 11.338 | 0.617 | 0.000 | 0.010 | 0.533 |
| | | 17.000 | 12.848 | 1.581 | 0.010 | 0.023 | 3.614 |
| | | 18.000 | 12.755 | 1.619 | 0.033 | 0.011 | 11.528 |
| | | 19.000 | 13.484 | 1.808 | 0.044 | 0.013 | 25.239 |
| | | 20.000 | 14.172 | 1.880 | 0.057 | 0.010 | 41.973 |
| | | 21.000 | 14.881 | 2.038 | 0.067 | 0.000 | 58.838 |
| | | 22.000 | 15.589 | 2.086 | 0.076 | 0.009 | 60.014 |
| | | 23.000 | 16.288 | 2.129 | 0.085 | 0.008 | 69.484 |
| | | 24.000 | 17.007 | 2.167 | 0.093 | 0.009 | 64.309 |
| | | 25.000 | 17.715 | 2.181 | 0.098 | 0.007 | 61.614 |
| | | 26.000 | 18.424 | 2.222 | 0.105 | 0.000 | 58.121 |
| | | 27.000 | 19.132 | 2.251 | 0.111 | 0.007 | 54.338 |
| | | 28.000 | 19.841 | 2.280 | 0.118 | 0.009 | 50.903 |
| | | 29.000 | 20.580 | 2.302 | 0.123 | 0.009 | 48.280 |
| | | 30.000 | 21.258 | 2.323 | 0.128 | 0.004 | 45.735 |
| | | 31.000 | 21.967 | 2.338 | 0.131 | 0.005 | 43.082 |
| | | 32.000 | 22.676 | 2.359 | 0.137 | 0.000 | 40.268 |
| | | 33.000 | 23.384 | 2.381 | 0.142 | 0.005 | 37.818 |
| | | 34.000 | 24.083 | 2.400 | 0.147 | 0.000 | 35.807 |
| | | 35.000 | 24.801 | 2.400 | 0.147 | 0.000 | 33.788 |
| | | 36.000 | 25.510 | 2.400 | 0.147 | 0.000 | 30.448 |
| | | 37.000 | 26.219 | 2.400 | 0.147 | 0.000 | 25.439 |
| | | 38.000 | 26.927 | 2.400 | 0.147 | 0.000 | 19.500 |
| | | 39.000 | 27.636 | 2.400 | 0.147 | 0.000 | 14.248 |
| | | 40.000 | 28.344 | 2.400 | 0.147 | 0.000 | 10.133 |
| | | 41.000 | 29.053 | 2.400 | 0.147 | 0.000 | 7.251 |
| | | 42.000 | 29.762 | 2.400 | 0.147 | 0.000 | 5.200 |
| | | 43.000 | 30.470 | 2.400 | 0.147 | 0.000 | 3.733 |
| | | 44.000 | 31.170 | 2.400 | 0.147 | 0.000 | 2.684 |
| | | 45.000 | 31.887 | 2.400 | 0.147 | 0.000 | 1.897 |
| | | 46.000 | 32.596 | 2.400 | 0.147 | 0.000 | 1.340 |
| | | 47.000 | 33.305 | 2.400 | 0.147 | 0.000 | 0.897 |
| | | 48.000 | 34.013 | 2.400 | 0.147 | 0.000 | 0.672 |
| | | 49.000 | 34.722 | 2.400 | 0.147 | 0.000 | 0.465 |
| | | 50.000 | 35.430 | 2.400 | 0.147 | 0.000 | 0.317 |
| | | 51.000 | 36.139 | 2.400 | 0.147 | 0.000 | 0.214 |
| | | 52.000 | 36.848 | 2.400 | 0.147 | 0.000 | 0.140 |
| | | 53.000 | 37.558 | 2.400 | 0.147 | 0.000 | 0.080 |
| | | 54.000 | 38.265 | 2.400 | 0.147 | 0.000 | 0.047 |
| | | 55.000 | 38.974 | 2.400 | 0.147 | 0.000 | 0.017 |
| | | 56.000 | 39.682 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 57.000 | 40.391 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 58.000 | 41.099 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 59.000 | 41.808 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 60.000 | 42.617 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 61.000 | 43.228 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 62.000 | 43.834 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 63.000 | 44.642 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 64.000 | 45.451 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 65.000 | 46.060 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 66.000 | 46.768 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 67.000 | 47.477 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 68.000 | 48.189 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 69.000 | 48.094 | 2.400 | 0.147 | 0.000 | 0.000 |
| | | 70.000 | 48.603 | 2.400 | 0.147 | 0.000 | 0.000 |

**W.R. GRACE HYDROGRAPH
RAINY CREEK
100-YEAR, 24-HOUR STORM (3.4 in.)**

| | INPUT DATA | TIME STEP (Hrs) | TIME (Hrs) | CUMULATIVE PRECIP (Inches) | CUMULATIVE RUNOFF (Inches) | INCREMENTAL RUNOFF (Inches) | TOTAL FLOW (cfs) |
|--------------------------|---------------|-----------------------|---------------|----------------------------------|----------------------------------|-----------------------------------|------------------------|
| Total Precip (Inches) | 3.400 | 1.000 | 0.700 | 0.017 | 0.000 | 0.000 | 0.000 |
| Total Duration (Hrs) | 24.000 | 2.000 | 1.417 | 0.048 | 0.000 | 0.000 | 0.000 |
| | | 3.000 | 2.128 | 0.078 | 0.000 | 0.000 | 0.000 |
| Area (Sq. miles) | 5.900 | 4.000 | 2.834 | 0.109 | 0.000 | 0.000 | 0.000 |
| Longest Run (Feet) | 25870.000 | 5.000 | 0.943 | 0.139 | 0.000 | 0.000 | 0.000 |
| Ave. Slope (%) | 12.200 | 0.000 | 4.282 | 0.177 | 0.000 | 0.000 | 0.000 |
| SCS Curve # | 60.000 | 7.000 | 4.960 | 0.204 | 0.000 | 0.000 | 0.000 |
| | | 0.000 | 0.669 | 0.249 | 0.000 | 0.000 | 0.000 |
| Storage S (Inches) | 6.007 | 0.000 | 0.377 | 0.289 | 0.000 | 0.000 | 0.000 |
| Initial Abstr. (Inches) | 1.333 | 10.000 | 7.086 | 0.340 | 0.000 | 0.000 | 0.000 |
| Time-concentration (Hrs) | 3.543 | 11.000 | 7.799 | 0.001 | 0.000 | 0.000 | 0.000 |
| Time-peak (Hrs) | 2.460 | 12.000 | 0.503 | 0.492 | 0.000 | 0.000 | 0.000 |
| Time-base (Hrs) | 0.622 | 10.000 | 9.212 | 0.000 | 0.000 | 0.000 | 0.000 |
| Duration (Hrs) | 0.709 | 14.000 | 9.921 | 0.585 | 0.000 | 0.000 | 0.000 |
| Incr. Precip. (Inches) | 0.100 | 15.000 | 10.629 | 0.690 | 0.000 | 0.000 | 0.000 |
| | | 16.000 | 11.338 | 0.874 | 0.000 | 0.112 | 6.434 |
| | | 17.000 | 12.046 | 2.254 | 0.112 | 0.084 | 31.209 |
| | | 18.000 | 12.789 | 2.577 | 0.106 | 0.034 | 84.132 |
| | | 19.000 | 13.464 | 2.689 | 0.220 | 0.037 | 159.174 |
| | | 20.000 | 14.172 | 2.809 | 0.266 | 0.027 | 229.974 |
| | | 21.000 | 14.881 | 2.887 | 0.284 | 0.024 | 262.377 |
| | | 22.000 | 19.980 | 2.955 | 0.317 | 0.022 | 282.018 |
| | | 23.000 | 10.298 | 0.016 | 0.339 | 0.020 | 244.487 |
| | | 24.000 | 17.007 | 3.070 | 0.359 | 0.013 | 220.858 |
| | | 29.000 | 17.719 | 3.104 | 0.372 | 0.017 | 190.888 |
| | | 20.000 | 10.424 | 0.148 | 0.388 | 0.016 | 170.352 |
| | | 27.000 | 18.132 | 0.180 | 0.404 | 0.010 | 159.606 |
| | | 28.000 | 19.841 | 3.230 | 0.420 | 0.012 | 140.976 |
| | | 29.000 | 20.950 | 0.261 | 0.432 | 0.012 | 131.924 |
| | | 30.000 | 21.258 | 3.291 | 0.444 | 0.008 | 121.475 |
| | | 31.000 | 21.967 | 0.312 | 0.483 | 0.012 | 111.794 |
| | | 32.000 | 22.676 | 0.342 | 0.445 | 0.013 | 102.432 |
| | | 30.000 | 23.384 | 3.373 | 0.478 | 0.011 | 94.523 |
| | | 34.000 | 24.093 | 3.400 | 0.489 | 0.000 | 88.118 |
| | | 00.000 | 24.601 | 3.400 | 0.489 | 0.000 | 82.102 |
| | | 36.000 | 25.910 | 0.400 | 0.489 | 0.000 | 70.338 |
| | | 37.000 | 20.219 | 0.400 | 0.489 | 0.000 | 60.938 |
| | | 00.000 | 20.927 | 0.400 | 0.489 | 0.000 | 48.571 |
| | | 39.000 | 27.636 | 0.400 | 0.489 | 0.000 | 33.759 |
| | | 40.000 | 28.344 | 2.400 | 0.489 | 0.000 | 20.939 |
| | | 41.000 | 20.053 | 0.400 | 0.489 | 0.000 | 17.109 |
| | | 42.000 | 29.762 | 0.400 | 0.489 | 0.000 | 12.273 |
| | | 43.000 | 30.470 | 0.400 | 0.480 | 0.000 | 2.786 |
| | | 44.000 | 31.179 | 0.400 | 0.489 | 0.000 | 6.262 |
| | | 48.000 | 31.887 | 0.400 | 0.489 | 0.000 | 4.459 |
| | | 46.000 | 32.596 | 2.400 | 0.409 | 0.000 | 0.167 |
| | | 47.000 | 30.808 | 0.400 | 0.480 | 0.000 | 2.241 |
| | | 40.000 | 34.013 | 0.400 | 0.488 | 0.000 | 1.971 |
| | | 40.000 | 34.722 | 0.400 | 0.489 | 0.000 | 1.087 |
| | | 50.000 | 30.430 | 3.400 | 0.489 | 0.000 | 0.738 |
| | | 91.000 | 30.139 | 3.400 | 0.489 | 0.000 | 0.407 |
| | | 92.000 | 30.848 | 3.400 | 0.489 | 0.000 | 0.329 |
| | | 53.000 | 37.556 | 0.400 | 0.489 | 0.000 | 0.207 |
| | | 64.000 | 30.265 | 0.400 | 0.489 | 0.000 | 0.109 |
| | | 95.000 | 38.974 | 0.400 | 0.489 | 0.000 | 0.039 |
| | | 96.000 | 30.682 | 2.400 | 0.489 | 0.000 | 0.000 |
| | | 67.000 | 40.391 | 0.400 | 0.489 | 0.000 | 0.000 |
| | | 98.000 | 41.099 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 99.000 | 41.808 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 80.000 | 42.517 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 61.000 | 43.229 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 62.000 | 43.934 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 80.000 | 44.642 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 04.000 | 40.391 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 08.000 | 40.080 | 0.400 | 0.489 | 0.000 | 0.000 |
| | | 00.000 | 46.768 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 67.000 | 47.477 | 2.400 | 0.488 | 0.000 | 0.000 |
| | | 68.000 | 48.189 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 69.000 | 48.894 | 2.400 | 0.489 | 0.000 | 0.000 |
| | | 70.000 | 49.603 | 2.400 | 0.489 | 0.000 | 0.000 |

**W.R. GRACE HYDROGRAPH
FLEETWOOD CREEK
100-YEAR, 24-HOUR STORM (3.4 in.)**

| | INPUT DATA | TIME STEP (Hrs) | TIME (Hrs) | CUMULATIVE PRECIP (Inches) | CUMULATIVE RUNOFF (Inches) | INCREMENTAL RUNOFF (Inches) | TOTAL FLOW (cfs) |
|--------------------------|---------------|-----------------------|---------------|----------------------------------|----------------------------------|-----------------------------------|------------------------|
| Total Precip (Inches) | 3.400 | 1.000 | 0.818 | 0.017 | 0.000 | 0.000 | 0.000 |
| Total Duration (Hrs) | 24.000 | 3.000 | 1.030 | 0.037 | 0.000 | 0.000 | 0.000 |
| | | 3.000 | 1.545 | 0.058 | 0.000 | 0.000 | 0.000 |
| Area (Sq. miles) | 3.900 | 4.000 | 3.061 | 0.078 | 0.000 | 0.000 | 0.000 |
| Longest Run (Feet) | 16370.000 | 9.000 | 3.576 | 0.090 | 0.000 | 0.000 | 0.000 |
| Ave. Slope (%) | 11.100 | 6.000 | 3.001 | 0.119 | 0.000 | 0.000 | 0.000 |
| SCS Curve # | 60.000 | 7.000 | 3.606 | 0.139 | 0.000 | 0.000 | 0.000 |
| | | 8.000 | 4.121 | 0.163 | 0.000 | 0.000 | 0.000 |
| Storage S (Inches) | 0.067 | 9.000 | 4.636 | 0.100 | 0.000 | 0.000 | 0.000 |
| Initial Abstr. (Inches) | 1.333 | 10.000 | 5.151 | 0.218 | 0.000 | 0.000 | 0.000 |
| Time-concentration (Hrs) | 3.576 | 11.000 | 3.687 | 0.249 | 0.000 | 0.000 | 0.000 |
| Time-peak (Hrs) | 1.803 | 13.000 | 0.182 | 0.272 | 0.000 | 0.000 | 0.000 |
| Time-base (Hrs) | 4.814 | 10.000 | 8.697 | 0.306 | 0.000 | 0.000 | 0.000 |
| Duration (Hrs) | 0.919 | 14.000 | 7.212 | 0.340 | 0.000 | 0.000 | 0.000 |
| Incr. Precip. (Inches) | 0.073 | 15.000 | 7.727 | 0.374 | 0.000 | 0.000 | 0.000 |
| | | 16.000 | 0.242 | 0.408 | 0.000 | 0.000 | 0.000 |
| | | 17.000 | 0.757 | 0.476 | 0.000 | 0.000 | 0.000 |
| | | 18.000 | 3.273 | 0.527 | 0.000 | 0.000 | 0.000 |
| | | 19.000 | 9.788 | 0.589 | 0.000 | 0.000 | 0.000 |
| | | 20.000 | 10.303 | 0.640 | 0.000 | 0.000 | 0.000 |
| | | 21.000 | 10.818 | 0.741 | 0.000 | 0.000 | 0.000 |
| | | 23.000 | 11.333 | 0.874 | 0.000 | 0.000 | 3.000 |
| | | 20.000 | 11.848 | 1.316 | 0.000 | 0.148 | 8.958 |
| | | 24.000 | 13.363 | 3.404 | 0.148 | 0.047 | 30.756 |
| | | 23.000 | 13.879 | 3.977 | 0.196 | 0.034 | 70.213 |
| | | 20.000 | 13.394 | 3.689 | 0.229 | 0.026 | 139.932 |
| | | 27.000 | 13.909 | 3.771 | 0.299 | 0.021 | 191.041 |
| | | 28.000 | 14.424 | 3.836 | 0.276 | 0.017 | 200.807 |
| | | 29.000 | 14.939 | 3.887 | 0.294 | 0.016 | 194.918 |
| | | 30.000 | 10.454 | 3.934 | 0.310 | 0.014 | 173.976 |
| | | 31.000 | 15.969 | 3.979 | 3.324 | 0.015 | 183.814 |
| | | 33.000 | 10.465 | 3.016 | 0.339 | 0.014 | 130.109 |
| | | 33.000 | 17.000 | 3.083 | 0.363 | 0.019 | 120.709 |
| | | 34.000 | 17.515 | 0.104 | 0.372 | 0.012 | 109.377 |
| | | 39.000 | 10.060 | 3.139 | 0.383 | 0.010 | 101.139 |
| | | 38.000 | 18.545 | 3.162 | 0.394 | 0.011 | 94.390 |
| | | 37.000 | 19.060 | 3.189 | 0.404 | 0.011 | 87.029 |
| | | 30.000 | 19.979 | 3.216 | 0.415 | 0.009 | 80.838 |
| | | 39.000 | 20.091 | 3.240 | 0.424 | 0.000 | 74.278 |
| | | 40.000 | 20.000 | 3.261 | 3.432 | 0.008 | 68.438 |
| | | 41.000 | 21.121 | 3.281 | 0.440 | 0.008 | 63.338 |
| | | 43.000 | 21.636 | 3.301 | 0.449 | 0.008 | 60.801 |
| | | 40.000 | 23.151 | 3.332 | 0.457 | 0.008 | 54.047 |
| | | 44.000 | 23.666 | 3.342 | 0.465 | 0.000 | 51.090 |
| | | 49.000 | 23.181 | 3.363 | 0.474 | 0.008 | 49.740 |
| | | 46.000 | 23.697 | 3.383 | 0.482 | 0.007 | 47.939 |
| | | 47.000 | 24.212 | 3.400 | 0.489 | 0.000 | 46.378 |
| | | 40.000 | 24.727 | 3.400 | 0.489 | 0.000 | 43.786 |
| | | 49.000 | 28.242 | 3.400 | 3.489 | 0.000 | 39.153 |
| | | 50.000 | 29.757 | 3.400 | 0.489 | 0.000 | 32.371 |
| | | 81.000 | 20.272 | 3.400 | 3.489 | 0.000 | 24.684 |
| | | 83.000 | 20.787 | 3.400 | 3.489 | 0.000 | 10.018 |
| | | 80.000 | 27.303 | 3.400 | 3.489 | 0.000 | 13.869 |
| | | 84.000 | 27.818 | 3.400 | 0.489 | 0.000 | 9.219 |
| | | 99.000 | 20.333 | 3.400 | 0.489 | 0.000 | 3.633 |
| | | 56.000 | 20.848 | 3.400 | 0.489 | 0.000 | 4.747 |
| | | 57.000 | 29.363 | 0.400 | 3.489 | 0.000 | 3.394 |
| | | 80.000 | 29.878 | 3.400 | 0.489 | 0.000 | 3.429 |
| | | 59.000 | 30.393 | 3.400 | 0.489 | 0.000 | 1.723 |
| | | 60.000 | 30.009 | 3.400 | 0.489 | 0.000 | 1.219 |
| | | 61.000 | 31.424 | 3.400 | 3.489 | 0.000 | 3.860 |
| | | 63.000 | 31.939 | 3.400 | 0.489 | 0.000 | 3.601 |
| | | 80.000 | 33.454 | 3.400 | 0.489 | 0.000 | 3.414 |
| | | 64.000 | 33.969 | 3.400 | 3.489 | 0.000 | 3.279 |
| | | 65.000 | 30.484 | 3.400 | 0.489 | 0.000 | 3.181 |
| | | 66.000 | 33.993 | 3.400 | 3.489 | 0.000 | 0.110 |
| | | 67.000 | 34.519 | 3.400 | 0.489 | 0.000 | 0.057 |
| | | 68.000 | 30.030 | 3.400 | 0.489 | 0.000 | 0.020 |
| | | 69.000 | 35.545 | 3.400 | 0.489 | 0.000 | 0.000 |
| | | 70.000 | 36.060 | 3.400 | 0.489 | 0.000 | 0.000 |

W.R. GRACE HYDROGRAPH
TAILINGS IMPOUNDMENT WATERSHED
PMF STORM EVENT, 6-HOUR AUGUST THUNDERSTORM (10.7 in.)

| Time | Incremental Rainfall | Rainfall Rate | Rainy Creek Flow | Fleetwood Creek Flow | Comblwd Flow |
|--------|-------------------------|------------------|------------------------|----------------------------|-----------------|
| (Hrs) | (Inches) | (In/Hr) | (cfs) | (cfs) | (cfs) |
| 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 |
| 0.500 | 0.200 | 0.400 | 0.000 | 0.000 | 0.000 |
| 1.000 | 0.300 | 0.600 | 5.000 | 6.000 | 11.000 |
| 1.500 | 0.500 | 1.000 | 22.000 | 35.000 | 57.000 |
| 2.000 | 2.200 | 4.400 | 73.000 | 169.000 | 238.000 |
| 2.500 | 4.500 | 9.000 | 280.000 | 447.000 | 727.000 |
| 3.000 | 1.000 | 2.000 | 1131.000 | 1394.000 | 2485.000 |
| 3.500 | 0.500 | 1.000 | 1782.000 | 3112.000 | 4894.000 |
| 4.000 | 0.500 | 1.000 | 3242.000 | 5276.000 | 8520.000 |
| 4.500 | 0.300 | 0.600 | 5582.000 | 5884.000 | 11466.000 |
| 5.000 | 0.300 | 0.600 | 6900.000 | 4776.000 | 11676.000 |
| 5.500 | 0.200 | 0.400 | 7330.000 | 3652.000 | 10982.000 |
| 6.000 | 0.200 | 0.400 | 6390.000 | 2917.000 | 9267.000 |
| 6.500 | 0.000 | 0.000 | 5012.000 | 2380.000 | 7392.000 |
| 7.000 | 0.000 | 0.000 | 4256.000 | 1956.000 | 6212.000 |
| 7.500 | 0.000 | 0.000 | 3580.000 | 1604.000 | 5184.000 |
| 8.000 | 0.000 | 0.000 | 2960.000 | 1350.000 | 4310.000 |
| 8.500 | 0.000 | 0.000 | 2606.000 | 1123.000 | 3729.000 |
| 9.000 | 0.000 | 0.000 | 2218.000 | 940.000 | 3198.000 |
| 9.500 | 0.000 | 0.000 | 1921.000 | 800.000 | 2721.000 |
| 10.000 | 0.000 | 0.000 | 1675.000 | 680.000 | 2389.000 |
| 10.500 | 0.000 | 0.000 | 1466.000 | 578.000 | 2044.000 |
| 11.000 | 0.000 | 0.000 | 1291.000 | 510.000 | 1801.000 |
| 11.500 | 0.000 | 0.000 | 1197.000 | 439.000 | 1636.000 |
| 12.000 | 0.000 | 0.000 | 1076.000 | 377.000 | 1453.000 |
| 12.500 | 0.000 | 0.000 | 963.000 | 322.000 | 1285.000 |
| 13.000 | 0.000 | 0.000 | 890.000 | 270.000 | 1160.000 |
| 13.500 | 0.000 | 0.000 | 804.000 | 213.000 | 1017.000 |
| 14.000 | 0.000 | 0.000 | 722.000 | 169.000 | 891.000 |
| 14.500 | 0.000 | 0.000 | 648.000 | 117.000 | 765.000 |
| 15.000 | 0.000 | 0.000 | 604.000 | 72.000 | 676.000 |
| 15.500 | 0.000 | 0.000 | 556.000 | 31.000 | 587.000 |
| 16.000 | 0.000 | 0.000 | 909.000 | 16.000 | 523.000 |
| 16.500 | 0.000 | 0.000 | 459.000 | 11.000 | 470.000 |
| 17.000 | 0.000 | 0.000 | 420.000 | 6.000 | 426.000 |
| 17.500 | 0.000 | 0.000 | 375.000 | 3.000 | 378.000 |
| 18.000 | 0.000 | 0.000 | 336.000 | | 336.000 |
| 18.500 | 0.000 | 0.000 | 314.000 | | 314.000 |
| 19.000 | 0.000 | 0.000 | 280.000 | | 280.000 |
| 19.500 | 0.000 | 0.000 | 243.000 | | 243.000 |
| 20.000 | 0.000 | 0.000 | 204.000 | | 204.000 |
| 20.500 | 0.000 | 0.000 | 164.000 | | 164.000 |
| 21.000 | 0.000 | 0.000 | 119.000 | | 115.000 |
| 21.500 | 0.000 | 0.000 | 43.000 | | 43.000 |
| 22.000 | 0.000 | 0.000 | 25.000 | | 25.000 |
| 22.500 | 0.000 | 0.000 | 17.000 | | 17.000 |
| 23.000 | 0.000 | 0.000 | 9.000 | | 9.000 |
| 23.500 | 0.000 | 0.000 | 9.000 | | 9.000 |
| 24.000 | 0.000 | 0.000 | 2.000 | | 2.000 |

APPENDIX B

PROBABLE MAXIMUM FLOOD CALCULATIONS

→ USE METHOD FOR THUNDERSTORM PMP - pg 180-184 OF HMR 43 ←

1) DISTANCE FROM S.E. BORDER : ~ 455 miles

2) MAY : 71.5 %

JUNE : 79.1 %

JULY : 84.4 %

AUG : 88.6 %

SEPT : 74.9 %

← Use

NOTE: THIS METHOD IS TAKEN
DIRECTLY FROM HMR 43: "PROBABLE
MAXIMUM PRECIPITATION, NORTHWEST
STATES", U.S. WEATHER BUREAU, 1966

3) 2900' ELEVATION → ≤ 5000'

4) 1/2 HR : 6.0 in

1 HR : 8.0 in

2 HR : 9.5 in

3 HR : 10.3 in

4 HR : 10.8 in

5 HR : 11.25 in

6 HR : 11.6 in

5) 1 HR : 84 %

3 HR : 87 %

6 HR : 92 %

6) 1 HR : (8.0) (0.84) = 6.7 "

3 HR : (10.3) (0.87) = 9.0 "

6 HR : (11.6) (0.92) = 10.7 "

7) 1/2 HR : 4.5 "

4 HR : 9.7 "


1 HR : 6.7 "

5 HR : 10.2 "

2 HR : 8.2 "


6 HR : 10.7 "

3 HR : 9.0 "




7) CONT.

| | | | | | | |
|---------------|-----|-----|-----|-----|------|------|
| $\frac{1}{2}$ | 1 | 2 | 3 | 4 | 5 | 6 |
| 4.5 | 6.7 | 8.2 | 9.0 | 9.7 | 10.2 | 10.7 |
| 6.7 | 1.5 | .8 | .7 | .5 | .5 | |

EXPAND FOR $\frac{1}{2}$ HR DURATION: (USING RATIO $1.5/6.7 = 67\%$)8) SEQUENCE ($\frac{1}{2}$ HR DURATION)

0.2 0.3 0.5 2.2 4.5 1.0 0.5 0.5 0.3 0.3 0.2 0.2

NOTE: THESE VALUES WILL BE USED TO CALCULATE RUNOFF BY BUREAU OF RECLAMATION METHOD OUTLINED IN CHPT 4 OF "FLOOD HYDROLOGY MANUAL", BUREAU OF RECLAMATION, 1989.



→ CALCULATE RUNOFF FOR RAINY CREEK: ← *

RAINY CREEK: 5.9 sq mi
25872 FT (4.9 mi) LONGEST REACH
12.2% (637'/mi) SLOPE

$$Lag = Lq = 26 K_n \left(\frac{L L_{ca}}{S^{0.5}} \right)^{0.33}$$

where $L = 4.9$ mi

$L_{ca} = \sim 2.8$ mi

$S = 637'/mi$

$K_n = 0.17$ (estimated from Table 4.5)

$$\therefore Lq = 26(0.17) \left(\frac{(4.9)(2.8)}{\sqrt{637}} \right)^{0.33}$$

$$= 3.61 \text{ HRS}$$

$$\text{DURATION} \sim Lq / 5.5 = 3.61 / 5.5 = 0.65 \text{ HR} = \sim 39 \text{ minutes}$$

$$\text{CHECKING } 15 \text{ TO } 20\% \text{ OF } LAG \quad 0.15(3.61)60 = 32.5 \text{ minutes } \checkmark$$

→ USE 30 MINUTE DURATION ←

INFILTRATION LOSSES: SOIL TYPE 'B' 0.15 TO 0.30 "/HR ULT. INFILTRATION

RMP METHOD REQUIRES SATURATED SOILS W/ ULT. INFILTRATION → THIS AREA IS FOREST W/ EXC. GROUND COVER: USE 0.25 "/HR

CALCULATE "S-graph"

$$q_{ult.} (\text{ultimate discharge}) = \frac{645.3 \times 5.9}{0.5} = 7615 \text{ hrs-cfs}$$

— NOTE: USE TABLE 4-16 (CASCADE AREA) FOR S-graph data.

* NOTE: THIS METHOD IS TAKEN FROM CHPT 4, "FLOOD HYDROLOGY MANUAL" BUREAU OF REC, 1989.

| TIME HRS | ACCUM RAINFALL | ACCUM. RUNOFF | INCREM RUNOFF | REVERSED INCREM. RUNOFF |
|-------------|-------------------|------------------|------------------|-------------------------------|
| 0 | 0 | 0 | 0 | .07 |
| 0.5 | 0.2 | .08 | .08 | .08 |
| 1.0 | 0.5 | .25 | .17 | .17 |
| 1.5 | 1.0 | .63 | .38 | .18 |
| 2.0 | 3.2 | 2.70 | 2.07 | .37 |
| 2.5 | 7.7 | 7.08 | 4.38 | .38 |
| 3.0 | 8.7 | 7.95 | .87 | .87 |
| 3.5 | 9.2 | 8.33 | .38 | 4.38 |
| 4.0 | 9.7 | 8.70 | .37 | 2.07 |
| 4.5 | 10.0 | 8.88 | .18 | .38 |
| 5.0 | 10.3 | 9.05 | .17 | .17 |
| 5.5 | 10.5 | 9.13 | .08 | .08 |
| 6.0 | 10.7 | 9.20 | .07 | 0 |

RAINY CREEK

| TIME HRS | TIME (% L ₉) | DISCHARGE (% U.S.) | E HYDROGRAPH ORDINATES (cfs) | UNIT HYDROGRAPH (cfs) | FLOOD HYDROGRAPH (cfs) |
|-------------|-----------------------------|-----------------------|------------------------------------|-----------------------------|------------------------------|
| 0 | 0 | 0 | 0 | 0 | 0 |
| 0.5 | 14 | 0.8 | 61 | 61 | 0 |
| 1.0 | 28 | 2.7 | 206 | 145 | 5 |
| 1.5 | 42 | 6.9 | 525 | 319 | 22 |
| 2.0 | 55 | 14.1 | 1074 | 549 | 73 |
| 2.5 | 69 | 25.5 | 1942 | 565 | 250 |
| 3.0 | 83 | 38.2 | 2909 | 967 | 1131 |
| 3.5 | 97 | 48.8 | 3716 | 807 | 1782 |
| 4.0 | 111 | 55.8 | 4249 | 533 | 3242 |
| 4.5 | 125 | 61.6 | 4691 | 442 | 5552 |
| 5.0 | 139 | 66.3 | 5049 | 358 | 6900 |
| 5.5 | 152 | 69.9 | 5323 | 274 | 7330 |
| 6.0 | 166 | 75.3 | 5582 | 259 | 6350 |
| 6.5 | 180 | 76.15 | 5799 | 217 | 5012 |
| 7.0 | 194 | 78.7 | 5993 | 194 | 4256 |
| 7.5 | 208 | 80.95 | 6164 | 171 | 3560 |
| 8.0 | 222 | 82.95 | 6317 | 153 | 2960 |
| 8.5 | 235 | 84.63 | 6445 | 128 | 2606 |
| 9.0 | 249 | 86.3 | 6572 | 127 | 2218 |
| 9.5 | 263 | 87.8 | 6686 | 114 | 1921 |
| 10.0 | 277 | 89.1 | 6785 | 59 | 1675 |
| 10.5 | 291 | 90.35 | 6880 | 93 | 1466 |
| 11.0 | 305 | 91.47 | 6965 | 85 | 1291 |

| | | | | | |
|------|-----|-------|------|----|------|
| 11.5 | 319 | 92.48 | 7042 | 77 | 1197 |
| 12.0 | 332 | 93.3 | 7108 | 66 | 1076 |
| 12.5 | 346 | 94.2 | 7172 | 64 | 963 |
| 13.0 | 360 | 94.96 | 7231 | 59 | 890 |
| 13.5 | 374 | 95.66 | 7285 | 54 | 804 |
| 14.0 | 388 | 96.3 | 7333 | 48 | 722 |
| 14.5 | 402 | 96.9 | 7378 | 43 | 648 |
| 15.0 | 416 | 97.4 | 7418 | 40 | 604 |
| 15.5 | 429 | 97.9 | 7452 | 34 | 556 |
| 16.0 | 443 | 98.3 | 7486 | 34 | 505 |
| 16.5 | 457 | 98.7 | 7516 | 30 | 459 |
| 17.0 | 471 | 99.0 | 7542 | 26 | 420 |
| 17.5 | 485 | 99.33 | 7564 | 22 | 375 |
| 18.0 | 498 | 99.56 | 7581 | 17 | 336 |
| 18.5 | 512 | 99.75 | 7596 | 15 | 314 |
| 19.0 | | | | | 280 |
| 19.5 | | | | | 243 |
| 20.0 | | | | | 204 |
| | | | | | 164 |
| | | | | | 115 |
| | | | | | 43 |
| | | | | | 25 |
| | | | | | 17 |
| | | | | | 9 |
| | | | | | 5 |
| | | | | | 2 |

DISCHARGE (% OF ULTIMATE) \longrightarrow

71

100
80
60
40
20
0

"S-graph"

RAINY CREEK

TIME (% OF LAG) \longrightarrow

0

50

100

150

200

250

300

350

400

450

500

→ RUNOFF FOR FLEETWOOD CREEK →

FLEETWOOD CREEK: AREA = 3.5 mi²
 L = 3.1 mi
 Lca = 1.2 mi
 S = 5104 - 2900 / 3.1 = 711'/mi

$$Lag = 2.6 K_n \left(\frac{L L_{ca}}{S^{0.5}} \right)^{0.33}$$

$$= 2.6 (0.17) \left(\frac{(3.1)(1.2)}{711} \right)^{0.33} = 2.29 \text{ HRS}$$

$$DURATION = L_1 / S = (2.29)(60) / 5.5 = 25 \text{ min} \rightarrow \text{USE 30 min (TO BE CONS. W/ RAINY)}$$

INFILTRATION: 0.25"/HR

$$Q_{ULF} = \frac{645.3 \times 3.5}{0.5} = 4517 \text{ hrs-cfs}$$

→ USE TABLE 4-16 (CASCADING)

FLEETWOOD CREEK

| TIME HRS | TIME (% LG) | DISCHARGE (% ULT) | Σ HYDROGRAPH ORDINATES (cfs) | UNIT HYDROGRAPH (cfs) | FLOOD HYDROGRAPH (cfs) |
|-------------|----------------|----------------------|------------------------------------|-----------------------------|------------------------------|
| 0 | 0 | 0 | 0 | 0 | 0 |
| 0.5 | 22 | 1.7 | 78 | 78 | 0 |
| 1.0 | 44 | 7.8 | 351 | 273 | 6 |
| 1.5 | 66 | 22.7 | 1024 | 673 | 35 |
| 2.0 | 87 | 41.3 | 1864 | 840 | 165 |
| 2.5 | 109 | 54.8 | 2476 | 612 | 447 |
| 3.0 | 131 | 63.7 | 2877 | 401 | 1354 |
| 3.5 | 153 | 70.2 | 3169 | 292 | 3112 |
| 4.0 | 175 | 75.2 | 3345 | 226 | 5278 |
| 4.5 | 197 | 79.2 | 3578 | 183 | 5889 |
| 5.0 | 218 | 82.4 | 3722 | 144 | 4776 |
| 5.5 | 240 | 85.2 | 3850 | 128 | 3652 |
| 6.0 | 262 | 87.7 | 3960 | 110 | 2917 |
| 6.5 | 284 | 89.8 | 4054 | 99 | 2380 |
| 7.0 | 306 | 91.5 | 4135 | 81 | 1956 |
| 7.5 | 328 | 93.1 | 4208 | 70 | 1604 |
| 8.0 | 349 | 94.35 | 4262 | 57 | 1350 |
| 8.5 | 371 | 95.8 | 4315 | 53 | 1123 |
| 9.0 | 393 | 96.5 | 4360 | 43 | 990 |
| 9.5 | 415 | 97.4 | 4399 | 39 | 800 |
| 10.0 | 437 | 98.1 | 4432 | 33 | 680 |
| 10.5 | 459 | 98.8 | 4461 | 29 | 578 |
| 11.0 | 480 | 99.2 | 4482 | 21 | 510 |


| | | | | | |
|------|-----|-------|------|----|-----|
| 11.5 | 502 | 99.6 | 4500 | 18 | 439 |
| 12.0 | 524 | 99.9 | 4511 | 11 | 377 |
| 12.5 | 546 | 100.0 | 4517 | 7 | 322 |
| 13.0 | | | | 0 | 270 |
| 13.5 | | | | | 213 |
| 14.0 | | | | | 169 |
| 14.5 | | | | | 117 |
| 15.0 | | | | | 72 |
| | | | | | 31 |
| | | | | | 18 |
| | | | | | 11 |
| | | | | | 6 |
| | | | | | 3 |

11/

DISCHARGE (% ULTIMATE) →

"S-graph" - FLEETWOOD CREEK

Time (% of L_g) →



| TIME (HRS) | RAINY CREEK (cfs) | FLEETWOOD CREEK (cfs) | COMBINED (cfs) |
|---------------|----------------------|--------------------------|-------------------|
| 0 | 0 | 0 | 0 |
| 0.5 | 0 | 0 | 0 |
| 1.0 | 5 | 6 | 11 |
| 1.5 | 22 | 35 | 57 |
| 2.0 | 73 | 165 | 238 |
| 2.5 | 280 | 447 | 727 |
| 3.0 | 1131 | 1354 | 2485 |
| 3.3 | 1782 | 3112 | 4894 |
| 4.0 | 3242 | 5278 | 8520 |
| 4.5 | 5582 | 5884 | 11,466 |
| 5.0 | 6900 | 4776 | 11,676 |
| 5.5 | 7330 | 3652 | 10,982 |
| 6.0 | 6350 | 2917 | 9267 |
| 6.5 | 5012 | 2380 | 7392 |
| 7.0 | 4256 | 1956 | 6212 |
| 7.5 | 3560 | 1604 | 5164 |
| 8.0 | 2960 | 1350 | 4310 |
| 8.5 | 2606 | 1123 | 3729 |
| 9.0 | 2218 | 940 | 3158 |
| 9.5 | 1921 | 800 | 2721 |
| 10.0 | 1675 | 680 | 2355 |
| 10.5 | 1466 | 578 | 2044 |
| 11.0 | 1291 | 510 | 1801 |

| TIME | RAINY CREEK | FLEETWOOD CK | COMBINED |
|------|-------------|--------------|----------|
| 11.5 | 1197 | 439 | 1636 |
| 12.0 | 1076 | 377 | 1453 |
| 12.5 | 963 | 322 | 1235 |
| 13.0 | 890 | 270 | 1160 |
| 13.5 | 804 | 213 | 1017 |
| 14.0 | 722 | 169 | 891 |
| 14.5 | 648 | 117 | 765 |
| 15.0 | 604 | 72 | 676 |
| 15.5 | 556 | 31 | 587 |
| 16.0 | 505 | 18 | 523 |
| 16.5 | 459 | 11 | 470 |
| 17.0 | 420 | 6 | 426 |
| 17.5 | 375 | 3 | 378 |
| 18.0 | 336 | 0 | 336 |
| 18.5 | 314 | | 314 |
| 19.0 | 280 | | 280 |
| 19.5 | 243 | | 243 |
| 20.0 | 204 | | 204 |
| 20.5 | 164 | | 164 |
| 21.0 | 115 | | 115 |
| 21.5 | 43 | | 43 |
| 22.0 | 25 | | 25 |
| 22.5 | 17 | | 17 |
| 23.0 | 9 | | 9 |

14/

DISCHARGE (cfs)

12000

10000

8000

6

4

2000

0

2

4

6

8

10

12

14

16

18

20

TIME (HRS)


PEAK @ 11,676 cfs

NOTE: DOES NOT INCLUDE
BASE FLOW(s)

COMBINED
FLOWS

RAINY
CREEK

FLEETWOOD
CREEK



APPENDIX C

**CONTROL STRUCTURE and EMERGENCY SPILLWAY
CALCULATIONS**

CONTROL STRUCTURE
CULVERT RATING CURVE

SINGLE 4' X 8' CONCRETE BOX CULVERT

| ELEVATION | INLET CONTROL | | | |
|------------------|----------------------|-------------|----------------------|--------------------|
| | HW (ft) | HW/D | Q/B (cfs) | Q (cfs) |
| 2900 | 0 | 0 | 0 | 0 |
| 2901 | 1.0 | 0.25 | 3.5 | 28 |
| 2902 | 2.0 | 0.50 | 7.2 | 58 |
| 2905 | 5.0 | 1.25 | 28 | 224 |
| 2907 | 7.0 | 1.75 | 40 | 320 |
| 2910 | 10.0 | 2.5 | 52 | 416 |
| 2915 | 15.0 | 3.75 | 68 | 544 |
| 2920 | 20.0 | 5.0 | 82 | 656 |
| 2926 | 26.0 | 6.5 | 93 | 744 |

CONTROL STRUCTURE
CULVERT RATING CURVE

TWIN 4' X 6' CONCRETE BOX CULVERTS

| ELEVATION | INLET CONTROL | | | | |
|------------------|----------------------|-------------|----------------------|------------------------|------------------------------------|
| | HW (ft) | HW/D | Q/B (cfs) | Q/Box (cfs) | Q_{Total} (cfs) |
| 2900 | 0 | 0 | 0 | 0 | 0 |
| 2901 | 1.0 | 0.25 | 3.5 | 21 | 42 |
| 2902 | 2.0 | 0.50 | 7 | 42 | 84 |
| 2905 | 5.0 | 1.25 | 27 | 162 | 324 |
| 2907 | 7.0 | 1.75 | 38 | 228 | 456 |
| 2910 | 10.0 | 2.5 | 48 | 288 | 576 |
| 2915 | 15.0 | 3.75 | 65 | 390 | 780 |
| 2920 | 20.0 | 5.0 | 78 | 468 | 936 |
| 2926 | 26.0 | 6.5 | 90 | 540 | 1080 |

CONTROL STRUCTURE

CULVERT RATING CURVE

SINGLE 5' X 9' CONCRETE BOX CULVERT

| ELEVATION | INLET CONTROL | | | |
|-----------|---------------|------|--------------|------------|
| | HW (ft) | HW/D | Q/B (cfs) | Q (cfs) |
| 2900 | 0 | 0 | 0 | 0 |
| 2901 | 1.0 | 0.25 | 3.5 | 31.5 |
| 2902 | 2.0 | 0.50 | 7 | 63 |
| 2905 | 5.0 | 1.25 | 28 | 252 |
| 2907 | 7.0 | 1.75 | 45 | 405 |
| 2910 | 10.0 | 2.5 | 52 | 468 |
| 2915 | 15.0 | 3.75 | 68 | 612 |
| 2920 | 20.0 | 5.0 | 82 | 738 |
| 2926 | 26.0 | 6.5 | 93 | 837 |

EMERGENCY SPILLWAY

STAGE-DISCHARGE

50 FT EMERGENCY SPILLWAY, CREST ELEVATION 2922.0

| STAGE-DISCHARGE FOR EMERGENCY SPILLWAY | | | |
|--|----------------|------------------------|--------------------|
| ELEVATION | H _p | Q _{High Flow} | Q _{Total} |
| 2922 | --- | --- | 990 |
| 2923 | 1.0 | 200 | 1223 |
| 2924 | 2.0 | 350 | 1386 |
| 2925 | 3.0 | 650 | 1709 |
| 2926 | 4.0 | 1000 | 2080 |

EMERGENCY SPILLWAY

STAGE-DISCHARGE

35 FT EMERGENCY SPILLWAY, CREST ELEVATION 2922.0

| STAGE-DISCHARGE FOR EMERGENCY SPILLWAY | | | |
|--|----------------|------------------------|--------------------|
| ELEVATION | H _p | Q _{High Flow} | Q _{Total} |
| 2922 | --- | --- | 1057 |
| 2923 | 1.0 | 140 | 1225 |
| 2924 | 2.0 | 245 | 1359 |
| 2925 | 3.0 | 455 | 1597 |
| 2926 | 4.0 | 700 | 1870 |

APPENDIX D

FLOOD ROUTING RESULTS

FLOOD ROUTING: 100-YEAR, 24-HOUR EVENT

TWIN 4' X 6' BOX CULVERTS

ESERVOIR ROUTING PROG. (RES.BAS) SMH.3-06-87

WR GRACE DAM
100 YR 24 HR
LLB
12-15-1991

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 . DELTA T= .2

CASE I EMERG. SPLWY. CURVE, CREST LENGTH = 500 FT
EARTH EMERG. SPILLWAY: CREST EL.= 2900 . WIDTH= 12 .
SIDE SLOPE= .001 . EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW.2=HSO.3=BO.4=FB.10=LSW.20=LSO.100=ES.1000=CS
500=ES CURVE IS EXCEEDED. O'S ARE EXTRAPOLATED

| ELEV | PRIN. Q | CHUTE Q | O/FT | FFF. W. | TOT. Q | CTR |
|---------|---------|---------|-------|---------|---------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 12.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 12.00 | 21.00 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 12.00 | 42.00 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.00 | 12.00 | 84.01 | 100 |
| 2904.00 | 0.00 | 0.00 | 20.33 | 12.00 | 244.05 | 100 |
| 2906.00 | 0.00 | 0.00 | 32.50 | 12.00 | 390.10 | 100 |
| 2907.00 | 0.00 | 0.00 | 38.00 | 12.00 | 458.14 | 100 |
| 2910.00 | 0.00 | 0.00 | 48.00 | 12.00 | 576.20 | 100 |
| 2915.00 | 0.00 | 0.00 | 65.00 | 12.01 | 780.33 | 100 |
| 2920.00 | 0.00 | 0.00 | 78.00 | 12.01 | 936.45 | 100 |
| 2926.00 | 0.00 | 0.00 | 90.00 | 12.01 | 1080.57 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40
ACTUAL DELTA T ROUTING INTERVAL= .2 HRS.. PRINTOUT INTERVAL= 1 HRS.
INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: HYD100.

| TIME INT..HRS | INFLOW, CFS | S/T+0/2 | OUTFLOW, CFS | EXIT VEL |
|---------------|-------------|---------|--------------|----------|
| INITIAL | | 1597.20 | 0.00 | |

PEAK

| | | | | |
|------------------|----------|----------------|---------|------------------|
| ELEV= 2900.00 | STORAGE= | 26.37 | | |
| TIME= 0.00 | -0.20 | INFLOW= | -1.73 | S/T 0/2= 1595.47 |
| TOTAL SPLWY DIS= | 0.00 | CTR= | 0 | |
| PRIN Q= | 0.00 | CHUTE Q= | 0.00 | |
| EMRG Q= | 0.00 | EMRG EXIT VEL= | 0.00 | |
| 0.80 | -1.00 | 3.92 | 1599.91 | 0.24 0.69 |
| 1.80 | -2.00 | 5.86 | 1621.99 | 2.17 1.68 |
| 2.80 | -3.00 | 5.99 | 1637.91 | 3.57 2.05 |
| 3.80 | -4.00 | 6.00 | 1648.11 | 4.46 2.24 |
| 4.80 | -5.00 | 6.00 | 1654.56 | 5.03 2.35 |
| 5.80 | -6.00 | 6.00 | 1658.65 | 5.38 2.42 |
| 6.80 | -7.00 | 6.00 | 1661.23 | 5.61 2.46 |
| 7.80 | -8.00 | 6.00 | 1662.86 | 5.75 2.48 |
| 8.80 | -9.00 | 6.00 | 1663.89 | 5.84 2.50 |
| 9.80 | -10.00 | 6.06 | 1664.60 | 5.91 2.51 |
| | | | 1727.51 | 12.30 3.36 |

| | | | | | |
|-------|--------|--------|---------|--------|-------|
| 11.80 | -12.00 | 316.56 | 3483.72 | 140.53 | 8.91 |
| 12.80 | -13.00 | 286.64 | 4159.90 | 194.24 | 10.14 |
| 13.80 | -14.00 | 258.97 | 4477.29 | 219.45 | 10.65 |
| 14.80 | -15.00 | 234.42 | 4577.95 | 227.45 | 10.81 |

****PEAK****

ELEV= 2903.80 STORAGE= 73.84
 TIME= 16.00 -16.20 INFLOW= 230.43 S/T 0/2= 4580.93
 TOTAL SPLWY DIS= 227.69 CTR= 100
 PRIN Q= 0.00 CHUTE Q= 0.00
 EMRG Q= 227.69 EMRG EXIT VEL= 10.81

| | | | | | |
|-------|--------|--------|---------|--------|-------|
| 16.80 | -17.00 | 219.14 | 4562.80 | 226.25 | 10.78 |
| 17.80 | -18.00 | 207.91 | 4503.14 | 221.51 | 10.69 |
| 18.80 | -19.00 | 195.51 | 4411.02 | 214.19 | 10.55 |
| 19.80 | -20.00 | 183.75 | 4298.89 | 205.28 | 10.37 |
| 20.80 | -21.00 | 176.84 | 4188.19 | 196.49 | 10.19 |
| 21.80 | -22.00 | 167.59 | 4078.97 | 187.81 | 10.01 |
| 22.80 | -23.00 | 162.72 | 3978.78 | 179.86 | 9.84 |
| 23.80 | -24.00 | 156.54 | 3889.10 | 172.73 | 9.68 |
| 24.80 | -25.00 | 151.36 | 3807.64 | 166.26 | 9.53 |
| 25.80 | -26.00 | 104.43 | 3639.89 | 152.94 | 9.22 |
| 26.80 | -27.00 | 40.20 | 3247.26 | 121.75 | 8.42 |
| 27.80 | -28.00 | 15.30 | 2822.50 | 88.01 | 7.39 |
| 28.80 | -29.00 | 8.32 | 2482.82 | 65.67 | 6.57 |
| 29.80 | -30.00 | 6.46 | 2224.24 | 49.29 | 5.86 |
| 30.80 | -31.00 | 6.06 | 2034.84 | 36.26 | 5.18 |
| 31.80 | -32.00 | 6.06 | 1905.39 | 26.29 | 4.56 |
| 32.80 | -33.00 | 6.06 | 1818.75 | 19.42 | 4.04 |
| 33.80 | -34.00 | 6.06 | 1762.71 | 14.50 | 3.59 |
| 34.80 | -35.00 | 6.06 | 1727.28 | 11.40 | 3.26 |
| 35.80 | -36.00 | 6.06 | 1704.88 | 9.44 | 3.03 |
| 36.80 | -37.00 | 6.06 | 1690.72 | 8.20 | 2.86 |
| 37.80 | -38.00 | 6.06 | 1681.77 | 7.41 | 2.75 |
| 38.80 | -39.00 | 6.06 | 1676.11 | 6.92 | 2.67 |
| 39.80 | -40.00 | 6.06 | 1672.54 | 6.80 | 2.62 |
| 40.80 | -41.00 | 6.06 | 1670.27 | 6.40 | 2.59 |
| 41.80 | -42.00 | 6.06 | 1668.84 | 6.28 | 2.57 |

TOTAL VOLUME EMERG SPLWY FLOW= 273.43 AF
 TOTAL VOLUME OF HYD ROUTED= 274.50 AF

FLOOD ROUTING: 100-YEAR, 24-HOUR EVENT

SINGLE 4' X 8' BOX CULVERT

RESERVOIR ROUTING PROG. (RES.BAS) SMH.3-06-87

WR GRACE DAM
100 YR 24 HR
LLB
03-17-1992

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 DELTA T= .25

CASE I EMERG. SPLWY. CURVE. CREST LENGTH = 20 FT

EARTH EMERG. SPILLWAY: CREST EL.= 2900 WIDTH= 8
SIDE SLOPE= .001 EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW.2=HSO.3=BO.4=FB.10=LSW.20=LSO.100=ES.1000=CS
500=ES CURVE IS EXCEEDED. O'S ARE EXTRAPOLATED

EMERG. SPLWY. VALUES

| ELEV | PRIN. Q | CHUTE Q | O/FT | EFF. W. | TOT. Q | CTR |
|---------|---------|---------|-------|---------|--------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 8.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 8.00 | 14.00 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 8.00 | 28.00 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.50 | 8.00 | 60.01 | 100 |
| 2904.00 | 0.00 | 0.00 | 21.17 | 8.00 | 169.38 | 100 |
| 2906.00 | 0.00 | 0.00 | 34.00 | 8.00 | 272.11 | 100 |
| 2907.00 | 0.00 | 0.00 | 40.00 | 3.00 | 320.15 | 100 |
| 2910.00 | 0.00 | 0.00 | 52.00 | 8.00 | 416.23 | 100 |
| 2915.00 | 0.00 | 0.00 | 68.00 | 8.01 | 544.36 | 100 |
| 2920.00 | 0.00 | 0.00 | 82.00 | 8.01 | 656.49 | 100 |
| 2926.00 | 0.00 | 0.00 | 93.00 | 8.01 | 744.60 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

STORAGE INDICATION CURVE:

| ELEV. | STORAGE | S/T+0/2 | TOT. DIS. | CTR. |
|---------|---------|----------|-----------|------|
| 2900.00 | 26.40 | 1277.76 | 0.00 | 100 |
| 2900.50 | 30.19* | 1468.07 | 14.00 | 100 |
| 2901.00 | 34.52* | 1684.63 | 28.00 | 100 |
| 2902.00 | 45.13* | 2214.09 | 60.01 | 100 |
| 2904.00 | 77.11* | 3816.60 | 169.38 | 100 |
| 2906.00 | 131.70 | 6510.34 | 272.11 | 100 |
| 2907.00 | 158.86* | 7848.92 | 320.15 | 100 |
| 2910.00 | 278.70 | 13697.20 | 416.23 | 100 |
| 2915.00 | 549.70 | 26877.66 | 544.36 | 100 |
| 2920.00 | 870.70 | 42470.13 | 656.49 | 100 |
| 2926.00 | 1301.50 | 63364.90 | 744.60 | 100 |

*--VALUE INSERTED BY LOG-LOG INTERP BY PROG.

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40
ACTUAL DELTA T ROUTING INTERVAL= .25 HRS., PRINTOUT INTERVAL= 1 HRS.
INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: HYD100

| TIME INT., HRS | INFLOW, CFS | S/T+0/2 | OUTFLOW, CFS | EXIT VEL |
|----------------|-------------|---------|--------------|----------|
| INITIAL | | 1277.76 | 0.00 | |
| 0.75 -1.00 | 3.71 | 1281.88 | 0.30 | 0.90 |
| 1.50 -2.00 | 5.78 | 1300.05 | 1.64 | 1.77 |

| | | | | | |
|-------|--------|--------|---------|--------|-------|
| 3.75 | -4.00 | 6.00 | 1326.88 | 3.62 | 2.43 |
| 4.75 | -5.00 | 6.00 | 1335.49 | 1.25 | 2.59 |
| 5.75 | -6.00 | 6.00 | 1341.77 | 4.71 | 2.63 |
| 6.75 | -7.00 | 6.00 | 1346.39 | 5.05 | 2.77 |
| 7.75 | -8.00 | 6.00 | 1349.79 | 5.30 | 2.83 |
| 8.75 | -9.00 | 6.00 | 1352.30 | 5.48 | 2.86 |
| 9.75 | -10.00 | 6.16 | 1354.30 | 5.63 | 2.89 |
| 10.75 | -11.00 | 75.36 | 1460.52 | 13.45 | 4.10 |
| 11.75 | -12.00 | 360.15 | 2349.24 | 69.23 | 7.90 |
| 12.75 | -13.00 | 435.14 | 3648.53 | 157.91 | 10.98 |
| 13.75 | -14.00 | 378.10 | 4548.77 | 197.31 | 12.00 |
| 14.75 | -15.00 | 331.31 | 5114.21 | 218.87 | 12.51 |
| 15.75 | -16.00 | 294.81 | 5448.27 | 231.61 | 12.80 |
| 16.75 | -17.00 | 271.94 | 5627.55 | 238.45 | 12.95 |
| 17.75 | -18.00 | 255.95 | 5716.03 | 241.82 | 13.02 |

****PEAK****

ELEV= 2905.42 STORAGE= 115.92
 TIME= 18.50 -18.75 INFLOW= 243.31 S/T 0/2= 5731.91
 TOTAL SPLWY DIS= 242.43 CTR= 100
 PRIN Q= 0.00 CHUTE Q= 0.00
 EMRG Q= 242.43 EMRG EXIT VEL= 13.04

| | | | | | |
|-------|--------|--------|---------|--------|-------|
| 18.75 | -19.00 | 239.40 | 5728.89 | 242.31 | 13.04 |
| 19.75 | -20.00 | 221.04 | 5580.19 | 240.15 | 12.99 |
| 20.75 | -21.00 | 211.46 | 5594.64 | 237.19 | 12.92 |
| 21.75 | -22.00 | 202.78 | 5480.32 | 232.83 | 12.83 |
| 22.75 | -23.00 | 196.00 | 5349.53 | 227.84 | 12.72 |
| 23.75 | -24.00 | 188.19 | 5210.61 | 222.55 | 12.60 |
| 24.75 | -25.00 | 181.49 | 5066.15 | 217.04 | 12.47 |
| 25.75 | -26.00 | 128.38 | 4827.25 | 207.93 | 12.26 |
| 26.75 | -27.00 | 51.33 | 4330.29 | 188.97 | 11.80 |
| 27.75 | -28.00 | 18.92 | 3721.97 | 162.93 | 11.12 |
| 28.75 | -29.00 | 9.32 | 3176.62 | 125.70 | 10.02 |
| 29.75 | -30.00 | 6.71 | 2749.61 | 96.56 | 9.02 |
| 30.75 | -31.00 | 6.11 | 2423.63 | 74.31 | 8.12 |
| 31.75 | -32.00 | 6.11 | 2177.51 | 57.80 | 7.35 |
| 32.75 | -33.00 | 6.11 | 1988.76 | 46.39 | 6.73 |
| 33.75 | -34.00 | 6.11 | 1841.68 | 37.50 | 6.18 |
| 34.75 | -35.00 | 6.11 | 1727.07 | 30.57 | 5.69 |
| 35.75 | -36.00 | 6.11 | 1637.89 | 24.98 | 5.25 |
| 36.75 | -37.00 | 6.11 | 1569.42 | 20.55 | 4.86 |
| 37.75 | -38.00 | 6.11 | 1517.01 | 17.17 | 4.52 |
| 38.75 | -39.00 | 6.11 | 1476.90 | 14.57 | 4.23 |
| 39.75 | -40.00 | 6.11 | 1446.39 | 12.41 | 3.97 |
| 40.75 | -41.00 | 6.11 | 1423.85 | 10.75 | 3.75 |
| 41.75 | -42.00 | 6.11 | 1407.25 | 9.53 | 3.57 |
| 42.75 | -43.00 | 0.00 | 1388.91 | 8.18 | 3.36 |

TOTAL VOLUME EMERG SPLWY FLOW= 344.68 AF
 TOTAL VOLUME OF HYD ROUTED= 346.80 AF

FLOOD ROUTING: 0.5 PMF EVENT

TWIN 4' X 6' BOX CULVERTS

RESERVOIR ROUTING PROG. (RES.BAS) SMH.3-06-87

WR GRACE DAM

.5PMP

LLB

12-14-1991

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 . DELTA T= .2

CASE I EMERG. SPLWY. CURVE. CREST LENGTH = 500 FT
EARTH EMERG. SPILLWAY: CREST EL.= 2900 . WIDTH= 12 '
SIDE SLOPE= .001 . EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW.2=HSO.3=BO.4=FB.10=LSW.20=LSO.100=ES.1000=CS

500=ES CURVE IS EXCEEDED, Q'S ARE EXTRAPOLATED

EMERG. SPLWY. VALUES

| ELEV | PRIN. Q | CHUTE Q | O/FT | EFF. W. | TOT. Q | CTR |
|---------|---------|---------|-------|---------|---------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 12.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 12.00 | 21.00 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 12.00 | 42.00 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.00 | 12.00 | 84.01 | 100 |
| 2904.00 | 0.00 | 0.00 | 20.33 | 12.00 | 244.05 | 100 |
| 2906.00 | 0.00 | 0.00 | 32.50 | 12.00 | 390.10 | 100 |
| 2907.00 | 0.00 | 0.00 | 38.00 | 12.00 | 456.14 | 100 |
| 2910.00 | 0.00 | 0.00 | 48.00 | 12.00 | 576.20 | 100 |
| 2915.00 | 0.00 | 0.00 | 65.00 | 12.01 | 780.33 | 100 |
| 2920.00 | 0.00 | 0.00 | 78.00 | 12.01 | 936.45 | 100 |
| 2926.00 | 0.00 | 0.00 | 90.00 | 12.01 | 1080.57 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40

ACTUAL DELTA T ROUTING INTERVAL= .2 HRS., PRINTOUT INTERVAL= .1 HRS.

INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: HYD55.PMP

| TIME INT..HRS | INFLOW. CFS | S/T+O/2 | OUTFLOW. CFS | EXIT VEL |
|---------------|-------------|---------|--------------|----------|
| INITIAL | | 1597.20 | 0.00 | |
| 0.40 -0.60 | 3.41 | 1598.88 | 0.15 | 0.57 |
| 0.60 -0.80 | 5.89 | 1604.62 | 0.65 | 1.04 |
| 0.80 -1.00 | 7.02 | 1610.99 | 1.21 | 1.33 |
| 1.00 -1.20 | 7.55 | 1617.33 | 1.76 | 1.55 |
| 1.20 -1.40 | 7.79 | 1623.36 | 2.29 | 1.72 |
| 1.40 -1.60 | 7.90 | 1628.97 | 2.78 | 1.86 |
| 1.60 -1.80 | 7.96 | 1634.14 | 3.24 | 1.97 |
| 1.80 -2.00 | 7.98 | 1638.89 | 3.65 | 2.07 |
| 2.00 -2.20 | 7.99 | 1643.22 | 4.03 | 2.15 |
| 2.20 -2.40 | 8.00 | 1647.18 | 4.38 | 2.23 |
| 2.40 -2.60 | 8.00 | 1650.80 | 4.70 | 2.29 |
| 2.60 -2.80 | 8.00 | 1654.10 | 4.99 | 2.34 |
| 2.80 -3.00 | 8.00 | 1657.12 | 5.25 | 2.39 |
| 3.00 -3.20 | 8.00 | 1659.87 | 5.49 | 2.44 |
| 3.20 -3.40 | 8.00 | 1662.37 | 5.71 | 2.48 |
| 3.40 -3.60 | 8.00 | 1664.66 | 5.91 | 2.51 |
| 3.60 -3.80 | 8.00 | 1666.75 | 6.10 | 2.54 |

| | | | | | |
|-------|--------|---------|----------|--------|-------|
| 4.20 | -4.40 | 8.00 | 1671.98 | 6.55 | 2.62 |
| 4.40 | -4.60 | 8.00 | 1673.42 | 6.68 | 2.64 |
| 4.60 | -4.80 | 8.00 | 1674.74 | 6.80 | 2.65 |
| 4.80 | -5.00 | 8.00 | 1675.95 | 6.90 | 2.67 |
| 5.00 | -5.20 | 8.00 | 1677.05 | 7.00 | 2.68 |
| 5.20 | -5.40 | 8.00 | 1678.05 | 7.09 | 2.70 |
| 5.40 | -5.60 | 8.00 | 1678.96 | 7.17 | 2.71 |
| 5.60 | -5.80 | 8.00 | 1679.80 | 7.24 | 2.72 |
| 5.80 | -6.00 | 8.00 | 1680.56 | 7.31 | 2.73 |
| 6.00 | -6.20 | 8.01 | 1681.26 | 7.37 | 2.74 |
| 6.20 | -6.40 | 8.04 | 1531.94 | 7.43 | 2.75 |
| 6.40 | -6.60 | 8.19 | 1682.70 | 7.49 | 2.76 |
| 6.60 | -6.80 | 8.77 | 1683.98 | 7.60 | 2.78 |
| 6.80 | -7.00 | 10.35 | 1686.72 | 7.85 | 2.81 |
| 7.00 | -7.20 | 13.74 | 1692.61 | 8.36 | 2.88 |
| 7.20 | -7.40 | 19.77 | 1704.02 | 9.36 | 3.02 |
| 7.40 | -7.60 | 29.09 | 1723.75 | 11.09 | 3.23 |
| 7.60 | -7.80 | 42.21 | 1754.87 | 13.82 | 3.52 |
| 7.80 | -8.00 | 59.39 | 1800.44 | 17.81 | 3.90 |
| 8.00 | -8.20 | 80.74 | 1863.38 | 23.05 | 4.32 |
| 8.20 | -8.40 | 106.27 | 1946.60 | 29.46 | 4.77 |
| 8.40 | -8.60 | 135.87 | 2053.01 | 37.66 | 5.26 |
| 8.60 | -8.80 | 169.87 | 2185.22 | 46.81 | 5.74 |
| 8.80 | -9.00 | 209.31 | 2347.72 | 57.11 | 6.22 |
| 9.00 | -9.20 | 256.38 | 2546.98 | 89.74 | 6.73 |
| 9.20 | -9.40 | 313.96 | 2791.20 | 85.52 | 7.31 |
| 9.40 | -9.60 | 385.43 | 3091.11 | 109.35 | 8.06 |
| 9.60 | -9.80 | 475.67 | 3457.43 | 138.44 | 8.86 |
| 9.80 | -10.00 | 597.13 | 3916.11 | 174.88 | 9.73 |
| 10.00 | -10.20 | 790.91 | 4532.14 | 223.81 | 10.74 |
| 10.20 | -10.40 | 1140.91 | 5440.24 | 272.70 | 11.62 |
| 10.40 | -10.60 | 1738.37 | 6914.91 | 336.11 | 12.63 |
| 10.60 | -10.80 | 2589.74 | 9168.53 | 429.72 | 13.94 |
| 10.80 | -11.00 | 3554.47 | 12293.28 | 496.44 | 14.78 |
| 11.00 | -11.20 | 4403.85 | 16200.69 | 560.62 | 15.50 |
| 11.20 | -11.40 | 4954.91 | 20594.98 | 618.83 | 16.12 |
| 11.40 | -11.60 | 5144.53 | 25120.68 | 674.83 | 16.69 |
| 11.60 | -11.80 | 5015.65 | 29461.50 | 728.54 | 17.21 |
| 11.80 | -12.00 | 4678.04 | 33411.00 | 777.41 | 17.66 |
| 12.00 | -12.20 | 4253.34 | 36886.93 | 806.27 | 17.92 |
| 12.20 | -12.40 | 3824.35 | 39905.00 | 830.44 | 18.14 |
| 12.40 | -12.60 | 3429.79 | 42504.36 | 851.25 | 18.32 |
| 12.60 | -12.80 | 3084.40 | 44737.51 | 869.13 | 18.47 |
| 12.80 | -13.00 | 2790.65 | 46659.04 | 884.51 | 18.60 |
| 13.00 | -13.20 | 2544.68 | 48319.20 | 897.80 | 18.71 |
| 13.20 | -13.40 | 2340.83 | 49762.23 | 909.36 | 18.81 |
| 13.40 | -13.60 | 2174.31 | 51027.18 | 919.49 | 18.89 |
| 13.60 | -13.80 | 2039.95 | 52147.64 | 928.46 | 18.96 |
| 13.80 | -14.00 | 1931.21 | 53150.40 | 936.47 | 19.03 |
| 14.00 | -14.20 | 1840.70 | 54054.62 | 941.46 | 19.07 |
| 14.20 | -14.40 | 1761.56 | 54874.71 | 945.98 | 19.11 |
| 14.40 | -14.60 | 1688.89 | 55617.63 | 950.08 | 19.14 |
| 14.60 | -14.80 | 1620.32 | 56287.87 | 953.78 | 19.17 |
| 14.80 | -15.00 | 1555.92 | 56890.01 | 957.10 | 19.20 |
| 15.00 | -15.20 | 1496.93 | 57429.84 | 960.07 | 19.22 |
| 15.20 | -15.40 | 1444.30 | 57914.07 | 962.74 | 19.24 |
| 15.40 | -15.60 | 1398.18 | 58349.51 | 965.14 | 19.26 |
| 15.60 | -15.80 | 1358.21 | 58742.58 | 967.31 | 19.28 |
| 15.80 | -16.00 | 1324.07 | 59099.34 | 969.28 | 19.29 |
| 16.00 | -16.20 | 1295.51 | 59425.57 | 971.08 | 19.31 |
| 16.20 | -16.40 | 1271.71 | 59726.20 | 972.74 | 19.32 |
| 16.40 | -16.60 | 1251.14 | 60004.61 | 974.27 | 19.33 |
| 16.60 | -16.80 | 1232.01 | 60262.35 | 975.69 | 19.34 |
| 16.80 | -17.00 | 1212.81 | 60499.46 | 977.00 | 19.36 |

| | | | | | |
|-------|--------|---------|----------|--------|-------|
| 17.40 | -17.60 | 1147.33 | 61075.36 | 980.18 | 19.38 |
| 17.60 | -17.80 | 1123.65 | 61218.84 | 980.97 | 19.39 |
| 17.80 | -18.00 | 1100.68 | 61338.55 | 981.63 | 19.39 |
| 18.00 | -18.20 | 1079.50 | 61436.43 | 982.17 | 19.40 |
| 18.20 | -18.40 | 1060.39 | 61514.66 | 982.50 | 19.40 |
| 18.40 | -18.60 | 1042.60 | 61574.66 | 982.93 | 19.40 |
| 18.60 | -18.80 | 1024.93 | 61616.66 | 983.16 | 19.40 |
| 18.80 | -19.00 | 1006.36 | 61639.86 | 983.29 | 19.40 |
| 19.00 | -19.20 | 986.79 | 61643.37 | 983.31 | 19.40 |

****PEAK****

ELEV= 2921.95 STORAGE= 1010.77
 TIME= 19.00 -19.20 INFLOW= 986.79 S/T 0/2= 61643.37
 TOTAL SPLWY DIS= 983.31 CTR= 100
 PRIN Q= 0.00 CRUTE Q= 0.00
 EMRG 0= 983.31 EMRG EXIT VEL= 19.40

| | | | | | |
|-------|--------|--------|----------|--------|-------|
| 19.20 | -19.40 | 967.55 | 61627.61 | 983.22 | 19.40 |
| 19.40 | -19.60 | 950.95 | 61595.34 | 983.04 | 19.40 |
| 19.60 | -19.80 | 938.53 | 61550.83 | 982.80 | 19.40 |
| 19.80 | -20.00 | 929.77 | 61497.80 | 982.51 | 19.40 |
| 20.00 | -20.20 | 922.51 | 61437.80 | 982.17 | 19.40 |
| 20.20 | -20.40 | 914.23 | 61369.86 | 981.80 | 19.39 |
| 20.40 | -20.60 | 903.26 | 61291.32 | 981.37 | 19.39 |
| 20.60 | -20.80 | 889.28 | 61199.23 | 980.86 | 19.39 |
| 20.80 | -21.00 | 873.44 | 61091.82 | 980.27 | 19.38 |
| 21.00 | -21.20 | 857.66 | 60969.21 | 979.59 | 19.38 |
| 21.20 | -21.40 | 843.50 | 60833.12 | 978.84 | 19.37 |
| 21.40 | -21.60 | 831.80 | 60686.08 | 978.03 | 19.36 |
| 21.60 | -21.80 | 822.81 | 60530.86 | 977.17 | 19.36 |
| 21.80 | -22.00 | 816.20 | 60369.89 | 976.29 | 19.35 |
| 22.00 | -22.20 | 811.15 | 60204.75 | 975.37 | 19.34 |
| 22.20 | -22.40 | 806.37 | 60035.74 | 974.44 | 19.33 |
| 22.40 | -22.60 | 800.46 | 59861.76 | 973.48 | 19.33 |
| 22.60 | -22.80 | 792.52 | 59680.80 | 972.49 | 19.32 |
| 22.80 | -23.00 | 782.76 | 59491.08 | 971.44 | 19.31 |
| 23.00 | -23.20 | 772.23 | 59291.86 | 970.34 | 19.30 |
| 23.20 | -23.40 | 762.14 | 59083.66 | 969.19 | 19.29 |
| 23.40 | -23.60 | 753.46 | 58867.93 | 968.00 | 19.28 |
| 23.60 | -23.80 | 746.63 | 58646.56 | 966.78 | 19.27 |
| 23.80 | -24.00 | 741.53 | 58421.30 | 965.54 | 19.26 |
| 24.00 | -24.20 | 737.48 | 58193.24 | 964.28 | 19.25 |
| 24.20 | -24.40 | 733.22 | 57962.18 | 963.01 | 19.24 |
| 24.40 | -24.60 | 726.14 | 57725.30 | 961.70 | 19.23 |
| 24.60 | -24.80 | 710.90 | 57474.50 | 960.32 | 19.22 |
| 24.80 | -25.00 | 679.79 | 57193.98 | 958.77 | 19.21 |
| 25.00 | -25.20 | 626.10 | 56861.30 | 956.94 | 19.20 |
| 25.20 | -25.40 | 549.84 | 56454.20 | 954.69 | 19.18 |
| 25.40 | -25.60 | 459.46 | 55958.97 | 951.96 | 19.16 |
| 25.60 | -25.80 | 366.79 | 55373.80 | 948.74 | 19.13 |
| 25.80 | -26.00 | 282.04 | 54707.11 | 945.06 | 19.10 |
| 26.00 | -26.20 | 211.59 | 53973.64 | 941.01 | 19.07 |
| 26.20 | -26.40 | 157.00 | 53189.62 | 936.69 | 19.03 |
| 26.40 | -26.60 | 116.15 | 52369.08 | 930.23 | 18.98 |
| 26.60 | -26.80 | 86.02 | 51524.87 | 923.47 | 18.92 |
| 26.80 | -27.00 | 64.01 | 50665.41 | 916.59 | 18.87 |
| 27.00 | -27.20 | 48.07 | 49796.89 | 909.64 | 18.81 |
| 27.20 | -27.40 | 36.56 | 48923.81 | 902.65 | 18.75 |
| 27.40 | -27.60 | 28.28 | 48049.44 | 895.65 | 18.69 |
| 27.60 | -27.80 | 22.33 | 47176.13 | 888.65 | 18.64 |
| 27.80 | -28.00 | 18.06 | 46305.53 | 881.68 | 18.58 |
| 28.00 | -28.20 | 14.98 | 45438.83 | 874.74 | 18.52 |
| 28.20 | -28.40 | 12.76 | 44576.85 | 867.84 | 18.46 |
| 28.40 | -28.60 | 11.17 | 43720.17 | 860.98 | 18.40 |
| 28.60 | -28.80 | 10.01 | 42869.20 | 854.17 | 18.34 |
| 28.80 | -29.00 | 9.20 | 42021.22 | 847.40 | 18.28 |

| | | | | | |
|-------|--------|------|----------|--------|-------|
| 29.20 | -29.40 | 8.38 | 40353.19 | 834.02 | 18.17 |
| 29.40 | -29.60 | 8.24 | 39527.41 | 827.41 | 18.11 |
| 29.60 | -29.80 | 8.20 | 38708.20 | 820.85 | 18.05 |
| 29.80 | -30.00 | 8.20 | 37895.54 | 814.35 | 18.00 |
| 30.00 | -30.20 | 8.20 | 37089.40 | 807.89 | 17.94 |
| 30.20 | -30.40 | 8.20 | 36289.71 | 801.49 | 17.88 |
| 30.40 | -30.60 | 8.20 | 35496.42 | 795.14 | 17.82 |
| 30.60 | -30.80 | 8.20 | 34709.48 | 788.84 | 17.77 |
| 30.80 | -31.00 | 8.20 | 33928.84 | 782.59 | 17.71 |
| 31.00 | -31.20 | 8.20 | 33154.46 | 774.24 | 17.64 |
| 31.20 | -31.40 | 8.20 | 32388.42 | 764.76 | 17.55 |
| 31.40 | -31.60 | 8.20 | 31631.87 | 755.40 | 17.46 |
| 31.60 | -31.80 | 8.20 | 30884.67 | 746.15 | 17.38 |
| 31.80 | -32.00 | 8.20 | 30146.72 | 737.02 | 17.29 |
| 32.00 | -32.20 | 8.20 | 29417.91 | 728.00 | 17.21 |
| 32.20 | -32.40 | 8.20 | 28698.11 | 719.10 | 17.12 |
| 32.40 | -32.60 | 8.20 | 27987.21 | 710.30 | 17.04 |
| 32.60 | -32.80 | 8.20 | 27285.11 | 701.61 | 16.95 |
| 32.80 | -33.00 | 8.20 | 26591.70 | 693.03 | 16.87 |
| 33.00 | -33.20 | 8.20 | 25906.87 | 684.56 | 16.79 |
| 33.20 | -33.40 | 8.20 | 25230.52 | 676.19 | 16.71 |
| 33.40 | -33.60 | 8.20 | 21582.53 | 667.92 | 16.62 |
| 33.60 | -33.80 | 8.20 | 23902.80 | 659.76 | 16.54 |
| 33.80 | -34.00 | 8.20 | 23251.24 | 651.70 | 16.46 |
| 34.00 | -34.20 | 8.20 | 22607.73 | 643.74 | 16.38 |
| 34.20 | -34.40 | 8.20 | 21972.21 | 635.87 | 16.30 |
| 34.40 | -34.60 | 8.20 | 21344.54 | 628.11 | 16.22 |
| 34.60 | -34.80 | 3.20 | 20724.63 | 620.44 | 16.14 |
| 34.80 | -35.00 | 8.20 | 20112.40 | 612.86 | 16.06 |
| 35.00 | -35.20 | 8.20 | 19507.74 | 605.38 | 15.98 |
| 35.20 | -35.40 | 8.20 | 18910.56 | 597.99 | 15.91 |
| 35.40 | -35.60 | 8.20 | 18320.77 | 590.69 | 15.83 |
| 35.60 | -35.80 | 8.20 | 17738.28 | 583.49 | 15.75 |
| 35.80 | -36.00 | 8.20 | 17163.00 | 576.37 | 15.67 |
| 36.00 | -36.20 | 8.20 | 16594.83 | 567.09 | 15.57 |
| 36.20 | -36.40 | 8.20 | 16035.95 | 557.91 | 15.47 |
| 36.40 | -36.60 | 8.20 | 15486.24 | 548.88 | 15.37 |
| 36.60 | -36.80 | 8.20 | 14945.56 | 540.00 | 15.27 |
| 36.80 | -37.00 | 8.20 | 14413.75 | 531.27 | 15.17 |
| 37.00 | -37.20 | 8.20 | 13890.69 | 522.68 | 15.07 |
| 37.20 | -37.40 | 8.20 | 13376.21 | 514.23 | 14.97 |
| 37.40 | -37.60 | 8.20 | 12870.19 | 505.92 | 14.83 |
| 37.60 | -37.80 | 8.20 | 12372.47 | 497.74 | 14.78 |
| 37.80 | -38.00 | 8.20 | 11882.93 | 489.70 | 14.68 |
| 38.00 | -38.20 | 8.20 | 11401.43 | 481.79 | 14.59 |
| 38.20 | -38.40 | 8.20 | 10927.84 | 474.02 | 14.49 |
| 38.40 | -38.50 | 8.20 | 10462.02 | 466.37 | 14.40 |
| 38.60 | -38.30 | 8.20 | 10003.86 | 458.84 | 14.31 |
| 38.80 | -39.00 | 8.20 | 9553.22 | 444.87 | 14.13 |
| 39.00 | -39.20 | 8.20 | 9116.55 | 427.67 | 13.91 |
| 39.20 | -39.40 | 8.20 | 8697.08 | 411.15 | 13.69 |
| 39.40 | -39.60 | 8.20 | 8294.13 | 395.27 | 13.48 |
| 39.60 | -39.80 | 8.20 | 7907.06 | 379.04 | 13.25 |
| 39.80 | -40.00 | 8.20 | 7536.23 | 362.99 | 13.03 |
| 40.00 | -40.20 | 8.20 | 7181.44 | 347.64 | 12.80 |
| 40.20 | -40.40 | 8.20 | 6842.00 | 332.96 | 12.58 |
| 40.40 | -40.60 | 8.20 | 6517.24 | 318.91 | 12.37 |
| 40.60 | -40.80 | 8.20 | 6206.54 | 305.47 | 12.16 |
| 40.80 | -41.00 | 8.20 | 5909.27 | 292.60 | 11.95 |
| 41.00 | -41.20 | 8.20 | 5624.87 | 280.30 | 11.75 |
| 41.20 | -41.40 | 6.64 | 5351.21 | 268.46 | 11.55 |
| 41.40 | -41.60 | 5.09 | 5087.84 | 257.07 | 11.35 |

TOTAL VOLUME EMERG SPLWY FLOW=

2041.08 AF

FLOOD ROUTING: 0.5 PMF EVENT

SINGLE 4' X 8' BOX CULVERTS

RESERVOIR ROUTING PROG. (RES.BAS) SMH.3-06-87

WR GRACE DAM

.5PMP

LLB

01-01-1992

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 . DELTA T= .2

CASE I EMERG. SPLWY. CURVE. CREST LENGTH = 500 FT

EARTH EMERG. SPILLWAY: CREST EL.= 2900 . WIDTH= 3 .

SIDE SLOPE= .001 . EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW.2=HSO.3=BO.4=FB.10=LSW.20=LSO.100=ES.1000=CS

500=ES CURVE IS EXCEEDED. Q'S ARE EXTRAPOLATED

EMERG. SPLWY. VALUES

| ELEV | PRIN. Q | CHUTE Q | Q/FT | EFF. W. | TOT. Q | CTP |
|---------|---------|---------|-------|---------|--------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 8.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 8.00 | 14.00 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 8.00 | 28.00 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.50 | 8.00 | 60.01 | 100 |
| 2904.00 | 0.00 | 0.00 | 21.17 | 3.00 | 169.38 | 100 |
| 2906.00 | 0.00 | 0.00 | 34.00 | 8.00 | 272.11 | 100 |
| 2907.00 | 0.00 | 0.00 | 40.00 | 8.00 | 320.15 | 100 |
| 2910.00 | 0.00 | 0.00 | 52.00 | 8.00 | 416.23 | 100 |
| 2915.00 | 0.00 | 0.00 | 68.00 | 8.01 | 544.36 | 100 |
| 2920.00 | 0.00 | 0.00 | 82.00 | 8.01 | 656.49 | 100 |
| 2926.00 | 0.00 | 0.00 | 93.00 | 8.01 | 744.60 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

STORAGE INDICATION CURVE:

| ELEV. | STORAGE | S/T+O/2 | TOT. DIS. | CTR. |
|---------|---------|----------|-----------|------|
| 2900.00 | 26.40 | 1597.20 | 0.00 | 100 |
| 2900.50 | 30.19* | 1833.33 | 14.00 | 100 |
| 2901.00 | 34.52* | 2102.29 | 28.00 | 100 |
| 2902.00 | 45.13* | 2760.12 | 60.01 | 100 |
| 2904.00 | 77.11* | 4749.58 | 169.38 | 100 |
| 2906.00 | 131.70 | 8103.91 | 272.11 | 100 |
| 2907.00 | 158.86* | 9771.13 | 320.15 | 100 |
| 2910.00 | 278.70 | 17069.46 | 416.23 | 100 |
| 2915.00 | 549.70 | 33529.03 | 544.36 | 100 |
| 2920.00 | 870.70 | 53005.59 | 656.49 | 100 |
| 2926.00 | 1301.50 | 79113.05 | 744.60 | 100 |

*--VALUE INSERTED BY LOG-LOG INTERP BY PROG.

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40

ACTUAL DELTA T ROUTING INTERVAL= .2 HRS.. PRINTOUT INTERVAL= 1 HRS.

INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: HYD55.PMP

| TIME INT..HRS | INFLOW. CFS | S/T+O/2 | OUTFLOW. CFS | EXIT VEL |
|---------------|-------------|---------|--------------|----------|
| INITIAL | | 1597.20 | 0.00 | |
| 0.80 -1.00 | 7.02 | 1611.25 | 0.83 | 1.35 |
| 1.80 -2.00 | 7.98 | 1642.41 | 2.68 | 2.15 |

| | | | | | |
|-------|--------|---------|----------|--------|-------|
| 3.80 | -4.00 | 8.00 | 1683.42 | 5.11 | 2.78 |
| 4.80 | -5.00 | 8.00 | 1696.25 | 5.87 | 2.94 |
| 5.80 | -6.00 | 8.00 | 1705.70 | 6.43 | 3.05 |
| 6.80 | -7.00 | 10.35 | 1715.93 | 7.04 | 3.17 |
| 7.80 | -8.00 | 59.39 | 1836.73 | 14.18 | 4.19 |
| 8.80 | -9.00 | 209.31 | 2421.51 | 43.53 | 6.56 |
| 9.80 | -10.00 | 597.13 | 4094.01 | 133.34 | 10.26 |
| 10.80 | -11.00 | 3554.47 | 12844.70 | 360.61 | 15.28 |
| 11.80 | -12.00 | 4678.04 | 34808.40 | 551.72 | 18.11 |
| 12.80 | -13.00 | 2790.65 | 49244.00 | 634.83 | 19.16 |
| 13.80 | -14.00 | 1931.21 | 57011.92 | 670.01 | 19.57 |
| 14.80 | -15.00 | 1555.92 | 62092.45 | 687.16 | 19.77 |
| 15.80 | -16.00 | 1324.07 | 65652.80 | 699.17 | 19.91 |
| 16.80 | -17.00 | 1212.81 | 68400.82 | 708.45 | 20.01 |
| 17.80 | -18.00 | 1100.68 | 70577.73 | 715.79 | 20.10 |
| 18.80 | -19.00 | 1006.36 | 72200.94 | 721.27 | 20.16 |
| 19.80 | -20.00 | 929.77 | 73359.84 | 725.18 | 20.20 |
| 20.80 | -21.00 | 873.44 | 74230.32 | 728.12 | 20.23 |
| 21.80 | -22.00 | 816.20 | 74757.77 | 729.90 | 20.25 |
| 22.80 | -23.00 | 782.76 | 75098.97 | 731.05 | 20.27 |
| 23.80 | -24.00 | 741.53 | 75218.61 | 731.46 | 20.27 |

****PEAK****

ELEV= 2925.11 STORAGE= 1237.37
 TIME= 24.20 -24.40 INFLOW= 733.22 S/T 0/2= 75226.38
 TOTAL SPLWY DIS= 731.48 CTR= 100
 PRIN Q= 0.00 CHUTE Q= 0.00
 EMRG Q= 731.48 EMRG EXIT VEL= 20.27

| | | | | | |
|-------|--------|--------|----------|--------|-------|
| 24.80 | -25.00 | 679.79 | 75148.87 | 731.22 | 20.27 |
| 25.80 | -26.00 | 282.04 | 73783.30 | 726.61 | 20.22 |
| 26.80 | -27.00 | 64.01 | 70803.95 | 716.56 | 20.11 |
| 27.80 | -28.00 | 18.06 | 67397.27 | 705.06 | 19.98 |
| 28.80 | -29.00 | 9.20 | 63953.38 | 693.44 | 19.84 |
| 29.80 | -30.00 | 8.20 | 60550.93 | 681.95 | 19.71 |
| 30.80 | -31.00 | 8.20 | 57204.84 | 670.66 | 19.58 |
| 31.80 | -32.00 | 8.20 | 53914.84 | 659.56 | 19.45 |
| 32.80 | -33.00 | 8.20 | 50687.37 | 643.14 | 19.26 |
| 33.80 | -34.00 | 8.20 | 47549.02 | 625.07 | 19.04 |
| 34.80 | -35.00 | 8.20 | 44499.98 | 607.52 | 18.82 |
| 35.80 | -36.00 | 8.20 | 41537.71 | 590.45 | 18.61 |
| 36.80 | -37.00 | 8.20 | 38659.73 | 573.89 | 18.40 |
| 37.80 | -38.00 | 8.20 | 35863.64 | 557.80 | 18.19 |
| 38.80 | -39.00 | 8.20 | 33147.13 | 541.38 | 17.97 |
| 39.80 | -40.00 | 8.20 | 30522.41 | 520.95 | 17.70 |
| 40.80 | -41.00 | 8.20 | 27998.26 | 501.30 | 17.43 |

TOTAL VOLUME EMERG SPLWY FLOW= 1690.60 AF
 TOTAL VOLUME OF HYD ROUTED= 2094.52 AF

FLOOD ROUTING: 0.55 PMF, NO EMERGENCY SPILLWAY

TWIN 4' X 6' BOX CULVERTS

ESERVOIR ROUTING PROG. (RES.BAS) SMH,3-06-87

WR GRACE DAM

FBD

LLB

12-14-1991

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 , DELTA T= .2

CASE I EMERG. SPLWY. CURVE. CREST LENGTH = 500 FT
EARTH EMERG. SPILLWAY: CREST EL.= 2900 , WIDTH= 12 '
SIDE SLOPE= .001 , EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW,2=HSO,3=BO,4=FB,10=LSW,20=LSO,100=ES,1000=CS

500=ES CURVE IS EXCEEDED, Q'S ARE EXTRAPOLATED

EMERG. SPLWY. VALUES

| ELEV | PRIN. Q | CHUTE Q | Q/FT | EFF. W. | TOT. Q | CTR |
|---------|---------|---------|-------|---------|---------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 12.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 12.00 | 21.00 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 12.00 | 42.00 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.00 | 12.00 | 84.01 | 100 |
| 2904.00 | 0.00 | 0.00 | 20.33 | 12.00 | 244.05 | 100 |
| 2906.00 | 0.00 | 0.00 | 32.50 | 12.00 | 390.10 | 100 |
| 2907.00 | 0.00 | 0.00 | 38.00 | 12.00 | 456.14 | 100 |
| 2910.00 | 0.00 | 0.00 | 48.00 | 12.00 | 576.20 | 100 |
| 2915.00 | 0.00 | 0.00 | 65.00 | 12.01 | 780.33 | 100 |
| 2920.00 | 0.00 | 0.00 | 78.00 | 12.01 | 936.45 | 100 |
| 2926.00 | 0.00 | 0.00 | 90.00 | 12.01 | 1080.57 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

STORAGE INDICATION CURVE:

| ELEV. | STORAGE | S/T+0/2 | TOT. DIS. | CTR. |
|---------|---------|----------|-----------|------|
| 2900.00 | 26.40 | 1597.20 | 0.00 | 100 |
| 2900.50 | 30.19* | 1836.83 | 21.00 | 100 |
| 2901.00 | 34.52* | 2109.29 | 42.00 | 100 |
| 2902.00 | 45.13* | 2772.11 | 84.01 | 100 |
| 2904.00 | 77.11* | 4786.91 | 244.05 | 100 |
| 2906.00 | 131.70 | 8162.90 | 390.10 | 100 |
| 2907.00 | 158.86* | 9839.12 | 456.14 | 100 |
| 2910.00 | 278.70 | 17149.45 | 576.20 | 100 |
| 2915.00 | 549.70 | 33647.02 | 780.33 | 100 |
| 2920.00 | 870.70 | 53145.57 | 936.45 | 100 |
| 2926.00 | 1301.50 | 79281.03 | 1080.57 | 100 |

*--VALUE INSERTED BY LOG-LOG INTERP BY PROG.

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40
ACTUAL DELTA T ROUTING INTERVAL= .2 HRS., PRINTOUT INTERVAL= 1 HRS.
INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: HYD5.PMP

| TIME INT..HRS | INFLOW, CFS | S/T+0/2 | OUTFLOW, CFS | EXIT VEL |
|---------------|-------------|---------|--------------|----------|
| INITIAL | | 1597.20 | 0.00 | |
| 0.80 -1.00 | 7.90 | 1612.89 | 1.37 | 1.40 |

| | | | | | |
|-------|--------|---------|----------|---------|-------|
| 3.80 | -4.00 | 9.00 | 1677.63 | 7.05 | 2.69 |
| 4.80 | -5.00 | 9.00 | 1685.82 | 7.77 | 2.80 |
| 5.80 | -6.00 | 9.10 | 1691.12 | 8.23 | 2.86 |
| 6.80 | -7.00 | 27.25 | 1726.99 | 11.37 | 3.26 |
| 7.80 | -8.00 | 127.39 | 2030.68 | 35.94 | 5.17 |
| 8.80 | -9.00 | 331.99 | 2953.57 | 98.42 | 7.73 |
| 9.80 | -10.00 | 823.78 | 5092.35 | 257.26 | 11.35 |
| 10.80 | -11.00 | 4434.61 | 15773.85 | 553.61 | 15.42 |
| 11.80 | -12.00 | 5695.06 | 42049.00 | 847.60 | 18.29 |
| 12.80 | -13.00 | 3341.43 | 58474.15 | 965.83 | 19.27 |
| 13.80 | -14.00 | 2287.57 | 66664.52 | 1011.00 | 19.62 |
| 14.80 | -15.00 | 1832.04 | 71542.82 | 1037.90 | 19.83 |
| 15.80 | -16.00 | 1553.62 | 74566.58 | 1054.57 | 19.96 |
| 16.80 | -17.00 | 1419.73 | 76608.12 | 1065.83 | 20.04 |
| 17.80 | -18.00 | 1286.09 | 77967.94 | 1073.33 | 20.10 |
| 18.80 | -19.00 | 1174.05 | 78678.52 | 1077.25 | 20.13 |
| 19.80 | -20.00 | 1083.26 | 78853.98 | 1078.21 | 20.13 |

****PEAK****

ELEV= 2925.90 STORAGE= 1294.46
 TIME= 19.80 -20.00 INFLOW= 1083.26 S/T 0/2= 78853.98
 TOTAL SPLWY DIS= 1078.21 CTR= 100
 PRIN Q= 0.00 CHUTE Q= 0.00
 EMRG Q= 1078.21 EMRG EXIT VEL= 20.13

| | | | | | |
|-------|--------|---------|----------|---------|-------|
| 20.80 | -21.00 | 1016.47 | 78706.13 | 1077.40 | 20.13 |
| 21.80 | -22.00 | 948.88 | 78176.46 | 1074.48 | 20.11 |
| 22.80 | -23.00 | 909.18 | 77451.48 | 1070.48 | 20.08 |
| 23.80 | -24.00 | 860.57 | 76492.83 | 1065.19 | 20.04 |
| 24.80 | -25.00 | 788.35 | 75340.38 | 1058.84 | 19.99 |
| 25.80 | -26.00 | 326.83 | 72717.78 | 1044.38 | 19.88 |
| 26.80 | -27.00 | 73.96 | 68277.61 | 1019.89 | 19.69 |
| 27.80 | -28.00 | 20.66 | 63408.07 | 993.04 | 19.48 |
| 28.80 | -29.00 | 10.39 | 58562.54 | 966.32 | 19.27 |
| 29.80 | -30.00 | 9.23 | 53830.38 | 940.22 | 19.06 |
| 30.80 | -31.00 | 9.23 | 49242.63 | 905.20 | 18.77 |
| 31.80 | -32.00 | 9.23 | 44833.97 | 869.90 | 18.48 |
| 32.80 | -33.00 | 9.23 | 40599.00 | 835.99 | 18.19 |
| 33.80 | -34.00 | 9.23 | 36530.88 | 803.42 | 17.90 |
| 34.80 | -35.00 | 9.23 | 32624.14 | 767.67 | 17.58 |
| 35.80 | -36.00 | 9.23 | 28924.63 | 721.90 | 17.15 |
| 36.80 | -37.00 | 9.23 | 25448.40 | 678.89 | 16.73 |
| 37.80 | -38.00 | 9.23 | 22181.99 | 638.47 | 16.33 |
| 38.80 | -39.00 | 9.23 | 19112.71 | 600.49 | 15.93 |
| 39.80 | -40.00 | 9.23 | 16230.13 | 561.10 | 15.51 |
| 40.80 | -41.00 | 9.23 | 13559.96 | 517.25 | 15.01 |

TOTAL VOLUME EMERG SPLWY FLOW= 2356.07 AF
 TOTAL VOLUME OF HYD ROUTED= 2520.77 AF

FLOOD ROUTING: 0.66 PMF W/ EMERGENCY SPILLWAY

TWIN 4' X 6' BOX CULVERTS

ESERVOIR ROUTING PROG. (RES.BAS) SMH.3-06-87

WR GRACE DAM

.66PMP

LLB

12-14-1991

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 . DELTA T= .2

CASE I EMERG. SPLWY. CURVE. CREST LENGTH = 100 FT

EARTH EMERG. SPILLWAY: CREST EL.= 2900 . WIDTH= 12

SIDE SLOPE= .01 . EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW.2=HSO.3=BO.4=FB.10=LSW.20=LSO.100=ES.1000=CS

500=ES CURVE IS EXCEEDED. Q'S ARE EXTRAPOLATED

EMERG. SPLWY. VALUES

| ELEV | PRIN. O | CHUTE O | Q/FT | EFF. W. | TOT. Q | CTR |
|---------|---------|---------|--------|---------|---------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 12.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 12.00 | 21.01 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 12.01 | 42.03 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.00 | 12.01 | 84.08 | 100 |
| 2904.00 | 0.00 | 0.00 | 20.33 | 12.02 | 244.48 | 100 |
| 2906.00 | 0.00 | 0.00 | 32.50 | 12.03 | 391.04 | 100 |
| 2907.00 | 0.00 | 0.00 | 38.00 | 12.04 | 457.35 | 100 |
| 2910.00 | 0.00 | 0.00 | 48.00 | 12.04 | 577.99 | 100 |
| 2915.00 | 0.00 | 0.00 | 65.00 | 12.05 | 783.30 | 100 |
| 2920.00 | 0.00 | 0.00 | 78.00 | 12.06 | 940.48 | 100 |
| 2926.00 | 0.00 | 0.00 | 173.30 | 12.10 | 2096.54 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

STORAGE INDICATION CURVE:

| ELEV. | STORAGE | S/T+O/2 | TOT. DIS. | CTR. |
|---------|---------|----------|-----------|------|
| 2900.00 | 26.40 | 1597.20 | 0.00 | 100 |
| 2900.50 | 30.19* | 1836.84 | 21.01 | 100 |
| 2901.00 | 34.52* | 2109.30 | 42.03 | 100 |
| 2902.00 | 45.13* | 2772.15 | 84.08 | 100 |
| 2904.00 | 77.11* | 4787.12 | 244.48 | 100 |
| 2906.00 | 131.70 | 8163.37 | 391.04 | 100 |
| 2907.00 | 158.86* | 9839.73 | 457.35 | 100 |
| 2910.00 | 278.70 | 17150.35 | 577.99 | 100 |
| 2915.00 | 549.70 | 33648.50 | 783.30 | 100 |
| 2920.00 | 870.70 | 53147.59 | 940.48 | 100 |
| 2926.00 | 1301.50 | 79789.02 | 2096.54 | 100 |

*--VALUE INSERTED BY LOG-LOG INTERP BY PROG.

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40

ACTUAL DELTA T ROUTING INTERVAL= .2 HRS.. PRINTOUT INTERVAL= .1 HRS.

INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: HYD75.PMP

| TIME INT..HRS | INFLOW, CFS | S/T+O/2 | OUTFLOW, CFS | EXIT VEL |
|---------------|-------------|---------|--------------|----------|
| INITIAL | | 1597.20 | 0.00 | |
| 0.40 -0.60 | 3.89 | 1599.28 | 0.18 | 0.62 |
| 0.80 -1.00 | 0.00 | 1605.72 | 0.75 | 1.10 |

| | | | | | |
|-------|--------|---------|----------|---------|-------|
| 1.00 | -1.20 | 8.49 | 1620.00 | 2.00 | 1.63 |
| 1.20 | -1.40 | 8.76 | 1628.77 | 2.59 | 1.80 |
| 1.40 | -1.60 | 8.89 | 1633.07 | 3.14 | 1.95 |
| 1.60 | -1.80 | 8.95 | 1638.87 | 3.65 | 2.07 |
| 1.80 | -2.00 | 8.98 | 1644.19 | 4.12 | 2.17 |
| 2.00 | -2.20 | 8.99 | 1649.06 | 4.55 | 2.26 |
| 2.20 | -2.40 | 8.99 | 1653.51 | 4.94 | 2.33 |
| 2.40 | -2.60 | 9.00 | 1657.57 | 5.29 | 2.40 |
| 2.60 | -2.80 | 9.00 | 1661.28 | 5.62 | 2.46 |
| 2.80 | -3.00 | 9.00 | 1664.66 | 5.91 | 2.51 |
| 3.00 | -3.20 | 9.00 | 1667.75 | 6.18 | 2.56 |
| 3.20 | -3.40 | 9.00 | 1670.56 | 6.43 | 2.60 |
| 3.40 | -3.60 | 9.00 | 1673.13 | 6.66 | 2.63 |
| 3.60 | -3.80 | 9.00 | 1675.47 | 6.86 | 2.56 |
| 3.80 | -4.00 | 9.00 | 1677.61 | 7.05 | 2.69 |
| 4.00 | -4.20 | 9.00 | 1679.55 | 7.22 | 2.72 |
| 4.20 | -4.40 | 9.00 | 1681.34 | 7.38 | 2.74 |
| 4.40 | -4.60 | 9.00 | 1682.97 | 7.52 | 2.76 |
| 4.60 | -4.80 | 9.00 | 1684.45 | 7.65 | 2.78 |
| 4.80 | -5.00 | 9.01 | 1685.80 | 7.77 | 2.80 |
| 5.00 | -5.20 | 9.04 | 1687.08 | 7.88 | 2.82 |
| 5.20 | -5.40 | 9.18 | 1683.33 | 7.99 | 2.83 |
| 5.40 | -5.60 | 9.63 | 1690.01 | 8.14 | 2.85 |
| 5.60 | -5.80 | 10.89 | 1692.77 | 8.38 | 2.89 |
| 5.80 | -6.00 | 13.87 | 1698.26 | 8.86 | 2.95 |
| 6.00 | -6.20 | 19.71 | 1709.11 | 9.81 | 3.07 |
| 6.20 | -6.40 | 29.40 | 1728.70 | 11.53 | 3.28 |
| 6.40 | -6.60 | 43.39 | 1760.56 | 14.32 | 3.57 |
| 6.60 | -6.80 | 61.69 | 1807.93 | 18.47 | 3.96 |
| 6.80 | -7.00 | 83.93 | 1873.39 | 23.83 | 4.38 |
| 7.00 | -7.20 | 109.61 | 1959.17 | 30.44 | 4.83 |
| 7.20 | -7.40 | 138.44 | 2067.17 | 33.78 | 5.32 |
| 7.40 | -7.60 | 170.41 | 2198.80 | 47.70 | 5.78 |
| 7.60 | -7.80 | 205.78 | 2356.88 | 57.73 | 6.24 |
| 7.80 | -8.00 | 244.94 | 2544.09 | 69.61 | 6.73 |
| 8.00 | -8.20 | 288.29 | 2762.77 | 83.49 | 7.23 |
| 8.20 | -8.40 | 336.09 | 3015.37 | 103.44 | 7.88 |
| 8.40 | -8.60 | 388.47 | 3300.40 | 126.13 | 8.53 |
| 8.60 | -8.80 | 446.26 | 3620.53 | 151.61 | 9.18 |
| 8.80 | -9.00 | 511.57 | 3980.49 | 180.27 | 9.84 |
| 9.00 | -9.20 | 588.27 | 4388.48 | 212.74 | 10.51 |
| 9.20 | -9.40 | 681.31 | 4857.05 | 247.51 | 11.17 |
| 9.40 | -9.60 | 796.21 | 5405.75 | 271.33 | 11.59 |
| 9.60 | -9.80 | 940.31 | 6074.74 | 300.37 | 12.07 |
| 9.80 | -10.00 | 1131.76 | 6906.12 | 336.46 | 12.63 |
| 10.00 | -10.20 | 1430.46 | 8000.12 | 383.95 | 13.31 |
| 10.20 | -10.40 | 1959.12 | 9575.28 | 446.89 | 14.14 |
| 10.40 | -10.60 | 2850.23 | 11978.63 | 492.65 | 14.70 |
| 10.60 | -10.80 | 4108.81 | 15594.78 | 552.32 | 15.39 |
| 10.80 | -11.00 | 5520.77 | 20563.23 | 620.47 | 16.12 |
| 11.00 | -11.20 | 6742.67 | 26685.44 | 696.65 | 16.88 |
| 11.20 | -11.40 | 7504.32 | 33493.10 | 781.37 | 17.67 |
| 11.40 | -11.60 | 7719.71 | 40431.44 | 837.98 | 18.17 |
| 11.60 | -11.80 | 7462.33 | 47055.80 | 891.37 | 18.63 |
| 11.80 | -12.00 | 6902.97 | 53067.39 | 939.83 | 19.02 |
| 12.00 | -12.20 | 6226.64 | 58354.21 | 1166.41 | 20.74 |
| 12.20 | -12.40 | 5556.76 | 62744.56 | 1356.92 | 22.02 |
| 12.40 | -12.60 | 4948.50 | 66336.14 | 1512.77 | 23.00 |
| 12.60 | -12.80 | 4420.90 | 69244.27 | 1638.97 | 23.74 |
| 12.80 | -13.00 | 3975.42 | 71580.72 | 1740.35 | 24.32 |
| 13.00 | -13.20 | 3604.71 | 73445.08 | 1821.25 | 24.76 |
| 13.20 | -13.40 | 3299.09 | 74922.91 | 1385.38 | 25.11 |
| 13.40 | -13.60 | 3050.34 | 76087.87 | 1935.93 | 25.37 |
| 13.60 | -13.80 | 2850.06 | 77001.99 | 1975.60 | 25.58 |

| | | | | | |
|-------|--------|---------|----------|---------|-------|
| 14.20 | -14.40 | 2437.31 | 78668.18 | 2047.95 | 25.95 |
| 14.40 | -14.60 | 2330.93 | 78952.16 | 2060.23 | 26.01 |
| 14.60 | -14.80 | 2231.27 | 79123.20 | 2067.65 | 26.04 |
| 14.80 | -15.00 | 2138.20 | 79193.75 | 2070.71 | 26.06 |

****PEAK****

| | | | | | |
|--------------------------|--------|----------------------|----------|-------------------|-------|
| ELEV= 2925.87 | | STORAGE= 1291.87 | | | |
| TIME= 14.80 -15.00 | | INFLOW= 2138.20 | | S/T 0/2= 79193.75 | |
| TOTAL SPLWY DIS= 2070.71 | | CTR= 100 | | | |
| PRIN Q= 0.00 | | CHUTE Q= 0.00 | | | |
| EMRG Q= 2070.71 | | EMRG EXIT VEL= 26.06 | | | |
| 15.00 | -15.20 | 2053.33 | 79176.37 | 2069.95 | 26.06 |
| 15.20 | -15.40 | 1977.85 | 79084.26 | 2065.96 | 26.04 |
| 15.40 | -15.60 | 1911.89 | 78930.19 | 2059.27 | 26.00 |
| 15.60 | -15.80 | 1854.78 | 78725.70 | 2050.40 | 25.96 |
| 15.80 | -16.00 | 1805.97 | 78481.27 | 2039.79 | 25.90 |
| 16.00 | -16.20 | 1765.03 | 78206.51 | 2027.87 | 25.84 |
| 16.20 | -16.40 | 1730.77 | 77909.41 | 2014.98 | 25.78 |
| 16.40 | -16.60 | 1701.07 | 77595.50 | 2001.38 | 25.71 |
| 16.60 | -16.80 | 1673.48 | 77267.63 | 1987.13 | 25.64 |
| 16.80 | -17.00 | 1645.91 | 76926.41 | 1972.32 | 25.56 |
| 17.00 | -17.20 | 1616.91 | 76571.01 | 1956.90 | 25.43 |
| 17.20 | -17.40 | 1585.88 | 76199.99 | 1940.80 | 25.40 |
| 17.40 | -17.60 | 1553.21 | 75312.40 | 1923.98 | 25.31 |
| 17.60 | -17.80 | 1519.99 | 75408.41 | 1906.45 | 25.22 |
| 17.80 | -18.00 | 1487.82 | 74989.78 | 1888.28 | 25.12 |
| 18.00 | -18.20 | 1458.14 | 74559.64 | 1869.62 | 25.02 |
| 18.20 | -18.40 | 1431.32 | 74121.34 | 1850.60 | 24.92 |
| 18.40 | -18.60 | 1406.37 | 73677.12 | 1831.32 | 24.82 |
| 18.60 | -18.80 | 1381.63 | 73227.43 | 1811.81 | 24.71 |
| 18.80 | -19.00 | 1355.76 | 72771.38 | 1792.02 | 24.60 |
| 19.00 | -19.20 | 1328.60 | 72307.95 | 1771.91 | 24.49 |
| 19.20 | -19.40 | 1301.93 | 71837.97 | 1751.52 | 24.38 |
| 19.40 | -19.60 | 1278.85 | 71365.30 | 1731.01 | 24.27 |
| 19.60 | -19.80 | 1261.43 | 70895.72 | 1710.63 | 24.15 |
| 19.80 | -20.00 | 1248.97 | 70434.06 | 1690.60 | 24.04 |
| 20.00 | -20.20 | 1238.56 | 69982.03 | 1670.98 | 23.93 |
| 20.20 | -20.40 | 1226.83 | 69537.88 | 1651.71 | 23.82 |
| 20.40 | -20.60 | 1211.51 | 69097.68 | 1632.61 | 23.71 |
| 20.60 | -20.80 | 1192.18 | 68657.26 | 1513.49 | 23.60 |
| 20.80 | -21.00 | 1170.41 | 68214.17 | 1594.27 | 23.48 |
| 21.00 | -21.20 | 1148.72 | 67768.63 | 1574.93 | 23.37 |
| 21.20 | -21.40 | 1129.24 | 67322.93 | 1555.59 | 23.26 |
| 21.40 | -21.60 | 1113.08 | 66880.42 | 1536.39 | 23.14 |
| 21.60 | -21.80 | 1100.57 | 66444.60 | 1517.48 | 23.03 |
| 21.80 | -22.00 | 1091.27 | 66018.39 | 1498.99 | 22.92 |
| 22.00 | -22.20 | 1084.06 | 65603.47 | 1480.98 | 22.81 |
| 22.20 | -22.40 | 1077.25 | 65199.74 | 1463.46 | 22.70 |
| 22.40 | -22.60 | 1068.94 | 64805.22 | 1446.34 | 22.59 |
| 22.60 | -22.80 | 1057.94 | 64416.81 | 1429.49 | 22.49 |
| 22.80 | -23.00 | 1044.51 | 64031.84 | 1412.78 | 22.38 |
| 23.00 | -23.20 | 1030.07 | 63649.13 | 1396.17 | 22.28 |
| 23.20 | -23.40 | 1016.24 | 63269.19 | 1379.69 | 22.17 |
| 23.40 | -23.60 | 1004.30 | 62893.80 | 1363.40 | 22.07 |
| 23.60 | -23.80 | 994.85 | 62525.25 | 1347.41 | 21.96 |
| 23.80 | -24.00 | 987.71 | 62165.55 | 1331.80 | 21.86 |
| 24.00 | -24.20 | 981.98 | 61815.74 | 1316.62 | 21.76 |
| 24.20 | -24.40 | 975.99 | 61475.11 | 1301.84 | 21.66 |
| 24.40 | -24.60 | 966.25 | 61139.53 | 1287.28 | 21.57 |
| 24.60 | -24.80 | 945.68 | 60797.93 | 1272.45 | 21.47 |
| 24.80 | -25.00 | 904.01 | 60429.49 | 1256.46 | 21.38 |
| 25.00 | -25.20 | 832.32 | 60005.34 | 1238.06 | 21.23 |
| 25.20 | -25.40 | 730.63 | 59497.91 | 1216.04 | 21.08 |
| 25.40 | -25.60 | 610.20 | 58892.08 | 1189.75 | 20.90 |
| 25.60 | -25.80 | 488.77 | 58189.10 | 1159.25 | 20.68 |

| | | | | | |
|-------|--------|--------|----------|---------|-------|
| 26.00 | -26.20 | 280.09 | 56558.67 | 1088.50 | 20.17 |
| 26.20 | -26.40 | 297.39 | 55677.57 | 1050.26 | 19.89 |
| 26.40 | -26.60 | 153.00 | 54780.21 | 1011.33 | 19.59 |
| 26.60 | -26.80 | 112.88 | 53881.86 | 972.34 | 19.28 |
| 26.80 | -27.00 | 83.58 | 52993.10 | 939.23 | 19.02 |
| 27.00 | -27.20 | 62.34 | 52116.21 | 932.16 | 18.96 |
| 27.20 | -27.40 | 47.02 | 51231.07 | 925.03 | 18.90 |
| 27.40 | -27.60 | 36.00 | 50342.04 | 917.86 | 18.85 |
| 27.60 | -27.80 | 28.08 | 49452.25 | 910.69 | 18.79 |
| 27.80 | -28.00 | 22.39 | 48563.95 | 903.53 | 18.73 |
| 28.00 | -28.20 | 18.29 | 47678.71 | 896.40 | 18.67 |
| 28.20 | -28.40 | 15.34 | 46797.66 | 889.29 | 18.61 |
| 28.40 | -28.60 | 13.22 | 45921.58 | 882.23 | 18.55 |
| 28.60 | -28.80 | 11.68 | 45051.03 | 875.22 | 18.49 |
| 28.80 | -29.00 | 10.60 | 44186.41 | 868.25 | 13.43 |
| 29.00 | -29.20 | 9.89 | 43328.06 | 861.33 | 18.37 |
| 29.20 | -29.40 | 9.50 | 42476.23 | 854.46 | 18.32 |
| 29.40 | -29.60 | 9.32 | 41631.09 | 847.65 | 18.26 |
| 29.60 | -29.80 | 9.27 | 40792.71 | 840.89 | 18.20 |
| 29.80 | -30.00 | 9.27 | 39961.09 | 834.19 | 13.14 |
| 30.00 | -30.20 | 9.27 | 39136.17 | 827.54 | 18.08 |
| 30.20 | -30.40 | 9.27 | 38317.90 | 820.94 | 18.03 |
| 30.40 | -30.60 | 9.27 | 37506.23 | 814.40 | 17.97 |
| 30.60 | -30.80 | 9.27 | 36701.09 | 807.91 | 17.91 |
| 30.80 | -31.00 | 9.27 | 35902.45 | 801.47 | 17.85 |
| 31.00 | -31.20 | 9.27 | 35110.25 | 795.09 | 17.80 |
| 31.20 | -31.40 | 9.27 | 34324.43 | 788.75 | 17.74 |
| 31.40 | -31.60 | 9.27 | 33544.95 | 782.02 | 17.68 |
| 31.60 | -31.80 | 9.27 | 32772.20 | 772.40 | 17.59 |
| 31.80 | -32.00 | 9.27 | 32009.07 | 762.90 | 17.51 |
| 32.00 | -32.20 | 9.27 | 31255.43 | 753.52 | 17.42 |
| 32.20 | -32.40 | 9.27 | 30511.13 | 744.26 | 17.33 |
| 32.40 | -32.60 | 9.27 | 29776.18 | 735.12 | 17.25 |
| 32.60 | -32.80 | 9.27 | 29050.34 | 726.08 | 17.16 |
| 32.80 | -33.00 | 9.27 | 28333.52 | 717.16 | 17.08 |
| 33.00 | -33.20 | 9.27 | 27625.63 | 708.35 | 17.00 |
| 33.20 | -33.40 | 9.27 | 26926.54 | 699.65 | 16.91 |
| 33.40 | -33.60 | 9.27 | 26236.16 | 691.06 | 16.83 |
| 33.60 | -33.80 | 9.27 | 25554.37 | 682.58 | 16.75 |
| 33.80 | -34.00 | 9.27 | 24881.06 | 674.20 | 16.66 |
| 34.00 | -34.20 | 9.27 | 24216.13 | 665.92 | 16.58 |
| 34.20 | -34.40 | 9.27 | 23559.47 | 657.75 | 16.50 |
| 34.40 | -34.60 | 9.27 | 22910.99 | 649.68 | 16.42 |
| 34.60 | -34.80 | 9.27 | 22270.58 | 641.71 | 16.34 |
| 34.80 | -35.00 | 9.27 | 21638.13 | 633.84 | 16.26 |
| 35.00 | -35.20 | 9.27 | 21013.56 | 626.07 | 16.18 |
| 35.20 | -35.40 | 9.27 | 20396.76 | 618.39 | 16.10 |
| 35.40 | -35.60 | 9.27 | 19787.63 | 610.81 | 16.02 |
| 35.60 | -35.80 | 9.27 | 19186.09 | 603.33 | 15.94 |
| 35.80 | -36.00 | 9.27 | 18592.03 | 595.93 | 15.86 |
| 36.00 | -36.20 | 9.27 | 18005.36 | 588.63 | 15.79 |
| 36.20 | -36.40 | 9.27 | 17426.00 | 581.42 | 15.71 |
| 36.40 | -36.60 | 9.27 | 16853.84 | 573.10 | 15.62 |
| 36.60 | -36.80 | 9.27 | 16290.01 | 563.80 | 15.52 |
| 36.80 | -37.00 | 9.27 | 15735.48 | 554.64 | 15.42 |
| 37.00 | -37.20 | 9.27 | 15190.11 | 545.64 | 15.31 |
| 37.20 | -37.40 | 9.27 | 14653.73 | 536.79 | 15.22 |
| 37.40 | -37.60 | 9.27 | 14126.21 | 528.09 | 15.12 |
| 37.60 | -37.80 | 9.27 | 13607.39 | 519.53 | 15.02 |
| 37.80 | -38.00 | 9.27 | 13097.13 | 511.11 | 14.92 |
| 38.00 | -38.20 | 9.27 | 12595.29 | 502.82 | 14.82 |
| 38.20 | -38.40 | 9.27 | 12101.74 | 494.68 | 14.73 |
| 38.40 | -38.60 | 9.27 | 11616.33 | 486.67 | 14.63 |
| 38.60 | -38.80 | 9.27 | 11138.92 | 478.79 | 14.54 |
| 38.80 | -39.00 | 9.27 | 10669.44 | 471.04 | 14.44 |

| | | | | | |
|-------|--------|------|---------|--------|-------|
| 39.20 | -39.40 | 9.27 | 9753.48 | 153.94 | 14.23 |
| 39.40 | -39.60 | 9.27 | 9308.81 | 436.35 | 14.01 |
| 39.60 | -39.80 | 9.27 | 8831.72 | 419.46 | 13.79 |
| 39.80 | -40.00 | 9.27 | 8471.54 | 403.23 | 13.57 |
| 40.00 | -40.20 | 9.27 | 8077.58 | 387.32 | 13.36 |
| 40.20 | -40.40 | 9.27 | 7699.53 | 370.91 | 13.13 |
| 40.40 | -40.60 | 9.27 | 7337.89 | 355.21 | 12.90 |
| 40.60 | -40.80 | 9.27 | 6991.95 | 340.19 | 12.68 |
| 40.80 | -41.00 | 9.27 | 6661.03 | 325.82 | 12.47 |
| 41.00 | -41.20 | 9.26 | 6344.47 | 312.08 | 12.25 |

| | |
|--------------------------------|------------|
| TOTAL VOLUME EMERG SPLWY FLOW= | 2947.67 AF |
| TOTAL VOLUME OF HYD ROUTED= | 3020.96 AF |

FLOOD ROUTING: 0.66 PMF W/ EMERGENCY SPILLWAY

SINGLE 5' X 9' BOX CULVERT

RESERVOIR ROUTING PROG. (RES.BAS) SMH.3-06-87

WR GRACE DAM

.75PMP

LLB

03-19-1992

INPUT CONTROLS:

NO OF STORAGE CURVE POINTS= 7 . DELTA T= .2

CASE I EMERG. SPLWY. CURVE. CREST LENGTH = 500 FT
EARTH EMERG. SPILLWAY: CREST EL.= 2900 , WIDTH= 9 '
SIDE SLOPE= .001 . EXIT SLOPE= .04

SPILLWAY DISCHARGE CURVES:

CTR: 1=HSW, 2=HSO, 3=BO, 4=FB, 10=LSW, 20=LSO, 100=ES, 1000=CS

500=ES CURVE IS EXCEEDED. Q'S ARE EXTRAPOLATED

EMERG. SPLWY. VALUES

| ELEV | PRIN. Q | CHUTE Q | Q/FT | EFF. W. | TOT. Q | CTR |
|---------|---------|---------|--------|---------|---------|-----|
| 2900.00 | 0.00 | 0.00 | 0.00 | 9.00 | 0.00 | 100 |
| 2900.50 | 0.00 | 0.00 | 1.75 | 9.00 | 15.75 | 100 |
| 2901.00 | 0.00 | 0.00 | 3.50 | 9.00 | 31.50 | 100 |
| 2902.00 | 0.00 | 0.00 | 7.50 | 9.00 | 67.51 | 100 |
| 2904.00 | 0.00 | 0.00 | 21.17 | 9.00 | 190.55 | 100 |
| 2906.00 | 0.00 | 0.00 | 36.50 | 9.00 | 328.63 | 100 |
| 2907.00 | 0.00 | 0.00 | 45.00 | 9.00 | 405.18 | 100 |
| 2910.00 | 0.00 | 0.00 | 62.00 | 9.00 | 558.31 | 100 |
| 2915.00 | 0.00 | 0.00 | 90.00 | 9.01 | 810.57 | 100 |
| 2920.00 | 0.00 | 0.00 | 100.00 | 9.01 | 900.68 | 100 |
| 2926.00 | 0.00 | 0.00 | 195.00 | 9.01 | 1757.06 | 100 |

**** WARNING: DELTA T MAY BE TOO LARGE FOR PROPER ROUTING ****

INITIAL ROUTING ELEV= 2900.00 STORAGE= 26.40

ACTUAL DELTA T ROUTING INTERVAL= .2 HRS.. PRINTOUT INTERVAL= 1 HRS.

INFLOW Q INTEGRATED FROM TIME-Q DATA IN FILE: RYD75.PMP

| TIME INT., HRS | INFLOW, CFS | S/T+0/2 | OUTFLOW, CFS | EXIT VEL |
|----------------|-------------|----------|--------------|----------|
| INITIAL | | 1597.20 | 0.00 | |
| 0.80 -1.00 | 7.90 | 1613.11 | 1.06 | 1.41 |
| 1.80 -2.00 | 8.98 | 1647.14 | 3.32 | 2.24 |
| 2.80 -3.00 | 9.00 | 1671.99 | 4.97 | 2.63 |
| 3.80 -4.00 | 9.00 | 1689.64 | 6.14 | 2.86 |
| 4.80 -5.00 | 9.01 | 1702.15 | 6.97 | 3.01 |
| 5.80 -6.00 | 13.87 | 1718.38 | 8.05 | 3.19 |
| 6.80 -7.00 | 83.93 | 1901.35 | 19.67 | 4.55 |
| 7.80 -8.00 | 244.94 | 2607.06 | 58.95 | 7.06 |
| 8.80 -9.00 | 511.57 | 4124.10 | 151.35 | 10.30 |
| 9.80 -10.00 | 1131.76 | 7245.58 | 292.32 | 13.40 |
| 10.80 -11.00 | 5520.77 | 21076.87 | 618.41 | 18.08 |
| 11.80 -12.00 | 6902.97 | 53547.65 | 914.25 | 21.14 |
| 12.80 -13.00 | 3975.42 | 72644.48 | 1531.59 | 25.99 |
| 13.80 -14.00 | 2688.27 | 79918.49 | 1766.73 | 27.51 |
| 14.80 -15.00 | 2138.20 | 82565.72 | 1852.31 | 28.04 |

PEAK

TOTAL SPLWY DIS= 1864.25 CTR= 100
 PRIN Q= 0.00 CHUTE Q= 0.00
 EMRG Q= 1864.25 EMRG EXIT VEL= 28.11

| | | | | | |
|-------|--------|---------|----------|---------|-------|
| 15.80 | -16.00 | 1805.97 | 82867.57 | 1862.07 | 28.10 |
| 16.80 | -17.00 | 1615.91 | 82114.12 | 1837.71 | 27.95 |
| 17.80 | -18.00 | 1487.82 | 80768.58 | 1794.21 | 27.68 |
| 18.80 | -19.00 | 1355.76 | 78944.20 | 1735.24 | 27.32 |
| 19.80 | -20.00 | 1248.97 | 76822.88 | 1666.66 | 26.88 |
| 20.80 | -21.00 | 1170.41 | 74667.37 | 1596.98 | 26.43 |
| 21.80 | -22.00 | 1091.27 | 72411.28 | 1524.05 | 25.94 |
| 22.80 | -23.00 | 1044.51 | 70263.88 | 1454.63 | 25.46 |
| 23.80 | -24.00 | 987.71 | 68160.83 | 1386.65 | 24.98 |
| 24.80 | -25.00 | 904.01 | 66130.89 | 1321.03 | 24.50 |
| 25.80 | -26.00 | 373.90 | 62747.38 | 1211.65 | 23.66 |
| 26.80 | -27.00 | 83.58 | 57837.95 | 1052.94 | 22.37 |
| 27.80 | -28.00 | 22.39 | 53083.33 | 900.47 | 21.02 |
| 28.80 | -29.00 | 10.60 | 48690.87 | 880.14 | 20.83 |
| 29.80 | -30.00 | 9.27 | 44377.54 | 860.17 | 20.63 |
| 30.80 | -31.00 | 9.27 | 40162.23 | 840.66 | 20.45 |
| 31.80 | -32.00 | 9.27 | 36043.58 | 821.59 | 20.26 |
| 32.80 | -33.00 | 9.27 | 32028.85 | 785.63 | 19.90 |
| 33.80 | -34.00 | 9.27 | 28263.79 | 728.14 | 19.31 |
| 34.80 | -35.00 | 9.27 | 24777.51 | 674.91 | 18.73 |
| 35.80 | -36.00 | 9.27 | 21549.33 | 625.62 | 18.17 |
| 36.80 | -37.00 | 9.27 | 18560.29 | 579.98 | 17.63 |
| 37.80 | -38.00 | 9.27 | 15798.58 | 530.26 | 17.01 |
| 38.80 | -39.00 | 9.27 | 13300.25 | 478.05 | 16.32 |
| 39.80 | -40.00 | 9.27 | 11052.30 | 431.07 | 15.65 |
| 40.80 | -41.00 | 9.27 | 9039.42 | 369.93 | 14.73 |

TOTAL VOLUME EMERG SPLWY FLOW= 2909.77 AF
 TOTAL VOLUME OF HYD ROUTED= 3020.96 AF

INLET CHANNEL HYDRAULICS

COOPERATOR OR PROJECT= WR GRACE

DESCRIPTION= INLET CHANNEL

CALCULATED BY LLB

12-14-1991

DITCH HYDRAULICS PROGRAM

| DEPTH FT. | AREA SQ. FT. | B.W. FT. | AVE. S.S. | CHAN. GRADE | MAN. N | VEL. F.P.S. | FLOW CFS |
|--------------|-----------------|-------------|--------------|----------------|-----------|----------------|-------------|
| 1.0 | 12.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.05 | 24.60 |
| 1.1 | 13.42 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.17 | 29.12 |
| 1.2 | 14.88 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.28 | 33.93 |
| 1.3 | 16.38 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.39 | 39.15 |
| 1.4 | 17.92 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.48 | 44.44 |
| 1.5 | 19.50 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.58 | 50.31 |
| 1.6 | 21.12 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.67 | 56.39 |
| 1.7 | 22.78 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.76 | 62.87 |
| 1.8 | 24.48 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.85 | 59.77 |
| 1.9 | 26.22 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 2.94 | 77.09 |
| 2.0 | 28.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.02 | 84.56 |
| 2.1 | 29.82 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.10 | 92.44 |
| 2.2 | 31.68 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.18 | 100.74 |
| 2.3 | 33.58 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.26 | 109.47 |
| 2.4 | 35.52 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.33 | 118.28 |
| 2.5 | 37.50 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.40 | 127.50 |
| 2.6 | 39.52 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.48 | 137.53 |
| 2.7 | 41.58 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.54 | 147.19 |
| 2.8 | 43.68 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.62 | 158.12 |
| 2.9 | 45.82 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.68 | 168.62 |
| 3.0 | 48.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.75 | 180.00 |
| 3.1 | 50.22 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.81 | 191.34 |
| 3.2 | 52.48 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.89 | 204.15 |
| 3.3 | 54.78 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 3.95 | 218.22 |

DITCH HYDRAULICS PROGRAM

| DEPTH FT. | AREA SQ. FT. | B.W. FT. | AVE. S.S. | CHAN. GRADE | MAN. N | VEL. F.P.S. | FLOW CFS |
|--------------|-----------------|-------------|--------------|----------------|-----------|----------------|-------------|
| 3.4 | 57.12 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.02 | 229.52 |
| 3.5 | 59.50 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.08 | 242.76 |
| 3.6 | 61.92 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.13 | 255.73 |
| 3.7 | 64.38 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.19 | 269.75 |
| 3.8 | 66.88 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.25 | 284.91 |
| 3.9 | 69.42 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.32 | 299.89 |
| 4.0 | 72.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.38 | 315.36 |
| 4.1 | 74.62 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.43 | 330.57 |
| 4.2 | 77.28 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.50 | 347.76 |
| 4.3 | 79.98 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.56 | 364.71 |
| 4.4 | 82.72 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.61 | 381.34 |
| 4.5 | 85.50 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.67 | 399.29 |
| 4.6 | 88.32 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.72 | 416.87 |
| 4.7 | 91.18 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.77 | 434.93 |
| 4.8 | 94.08 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.83 | 454.41 |
| 4.9 | 97.02 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.88 | 473.46 |
| 5.0 | 100.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.94 | 494.00 |
| 5.1 | 103.02 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 4.99 | 514.07 |
| 5.2 | 106.08 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.04 | 534.64 |
| 5.3 | 109.18 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.09 | 555.73 |
| 5.4 | 112.32 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.15 | 578.45 |
| 5.5 | 115.50 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.20 | 600.60 |
| 5.6 | 118.72 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.25 | 623.28 |
| 5.7 | 121.98 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.30 | 646.49 |

DITCH HYDRAULICS PROGRAM

| DEPTH FT. | AREA SQ. FT. | B.W. FT. | AVE. S.S. | CHAN. GRADE | MAN. N | VEL. F.P.S. | FLOW CFS |
|--------------|-----------------|-------------|--------------|----------------|-----------|----------------|-------------|
| 5.8 | 125.28 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.35 | 670.25 |
| 5.9 | 128.62 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.39 | 693.26 |
| 6.0 | 132.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.44 | 718.08 |
| 6.1 | 135.42 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.50 | 744.81 |
| 6.2 | 138.88 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.55 | 770.78 |
| 6.3 | 142.38 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.60 | 797.33 |
| 6.4 | 145.92 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.65 | 824.45 |
| 6.5 | 149.50 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.70 | 852.15 |
| 6.6 | 153.12 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.73 | 877.38 |
| 6.7 | 156.78 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.78 | 906.19 |
| 6.8 | 160.48 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.83 | 935.60 |
| 6.9 | 164.22 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.88 | 965.51 |
| 7.0 | 168.00 | 10.0 | 2.0 TO 1 | .00300 | .0350 | 5.93 | 996.24 |

OUTLET CHANNEL HYDRAULICS

COOPERATOR OR PROJECT= WR GRACE DAM

DESCRIPTION= OUTLET CHANNEL

CALCULATED BY LLB

12-13-1991

DITCH HYDRAULICS PROGRAM

| DEPTH FT. | AREA SQ. FT. | B.W. FT. | AVE. S.S. | CHAN. GRADE | MAN. N | VEL. F.P.S. | FLOW CFS |
|--------------|-----------------|-------------|--------------|----------------|-----------|----------------|-------------|
| 1.0 | 11.50 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 6.61 | 76.01 |
| 1.1 | 12.82 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 7.03 | 90.12 |
| 1.2 | 14.16 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 7.38 | 104.50 |
| 1.3 | 15.54 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 7.72 | 119.97 |
| 1.4 | 16.94 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 8.06 | 136.54 |
| 1.5 | 18.38 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 8.34 | 153.29 |
| 1.6 | 19.84 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 8.67 | 172.01 |
| 1.7 | 21.34 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 8.94 | 190.78 |
| 1.8 | 22.86 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 9.26 | 211.68 |
| 1.9 | 24.42 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 9.52 | 232.48 |
| 2.0 | 26.00 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 9.78 | 254.28 |
| 2.1 | 27.62 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 10.04 | 277.30 |
| 2.2 | 29.26 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 10.29 | 301.09 |
| 2.3 | 30.93 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 10.54 | 326.00 |
| 2.4 | 32.64 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 10.79 | 352.19 |
| 2.5 | 34.37 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 11.04 | 379.44 |
| 2.6 | 36.14 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 11.28 | 407.66 |
| 2.7 | 37.93 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 11.48 | 435.44 |
| 2.8 | 39.76 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 11.72 | 465.99 |
| 2.9 | 41.61 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 11.91 | 495.58 |


DITCH HYDRAULICS PROGRAM

| DEPTH FT. | AREA SQ. FT. | B.W. FT. | AVE. S.S. | CHAN. GRADE | MAN. N | VEL. F.P.S. | FLOW CFS |
|--------------|-----------------|-------------|--------------|----------------|-----------|----------------|-------------|
| 3.0 | 43.50 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 12.15 | 528.52 |
| 3.1 | 45.41 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 12.34 | 560.36 |
| 3.2 | 47.36 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 12.57 | 595.32 |
| 3.3 | 49.33 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 12.76 | 629.45 |
| 3.4 | 51.34 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 12.99 | 666.91 |
| 3.5 | 53.37 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 13.17 | 702.88 |
| 3.6 | 55.44 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 13.36 | 740.63 |
| 3.7 | 57.53 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 13.54 | 778.96 |
| 3.8 | 59.66 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 13.76 | 820.92 |
| 3.9 | 61.81 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 13.94 | 861.63 |
| 4.0 | 64.00 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 14.13 | 904.32 |
| 4.1 | 66.21 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 14.30 | 946.80 |
| 4.2 | 68.45 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 14.48 | 991.30 |
| 4.3 | 70.73 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 14.66 | 1036.90 |
| 4.4 | 73.04 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 14.84 | 1083.91 |
| 4.5 | 75.37 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 15.01 | 1131.30 |
| 4.6 | 77.74 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 15.18 | 1180.09 |
| 4.7 | 80.13 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 15.36 | 1230.80 |
| 4.8 | 82.56 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 15.53 | 1282.16 |
| 4.9 | 85.01 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 15.70 | 1334.66 |
| 5.0 | 87.50 | 10.0 | 1.5 TO 1 | .04000 | .0400 | 15.87 | 1338.63 |


APPENDIX E

STANDARD DRAWING - SCS DROP STRUCTURE


DROP SPILLWAYS: NOMENCLATURE AND SYMBOLS OF DROP SPILLWAY



DOWNSTREAM ELEVATION




PLAN



SECTION ON CENTER LINE

SYMBOLS

- L = Length of weir.
- h = Depth of weir.
- F = Drop through spillway from crest of weir to top of transverse sill.
- s = Height of transverse sill.
- L_s = Length of apron.
- T = Depth of toewall below top of apron.
- C = Depth of cutoff wall below top of apron.
- d_c = Critical depth of weir.
- E = Length of headwall extension.
- J = Height of wingwall and sidewall at junction.



PERSPECTIVE VIEW

REFERENCE

Rev. 12-14-53

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

ENGINEERING STANDARDS UNIT

STANDARD DWG. NO.

ES-63

SHEET 1 OF 1

DATE 1-26-52

Harding Lawson Associates

Engineering and Environmental Services



**GEOTECHNICAL EVALUATION
W.R. GRACE DAM
RAINY CREEK, MONTANA**

HLA Job No. 5891,053.03

by

A Report Prepared for

W. R. Grace & Company
Construction Products Division
P.O. Box 609
Libby, Montana 59923

GEOTECHNICAL EVALUATION
W.R. GRACE DAM
RAINY CREEK, MONTANA

HLA Job No. 5891,053.03

by

Shahriar Vahdani


Shahriar Vahdani, Ph.D.
Civil Engineer

Hugo Hanson

Hugo Hanson
Geotechnical Engineer

Robert T. Lawson

Robert T. Lawson
Civil Engineer



Harding Lawson Associates
303 Second Street, 630 North
San Francisco, California 94107
415/543-8422

February 3, 1992

TABLE OF CONTENTS

| | |
|--|-----|
| LIST OF ILLUSTRATIONS..... | iii |
| I INTRODUCTION | I |
| II PROJECT DESCRIPTION..... | 3 |
| III FIELD INVESTIGATION AND LABORATORY TESTING | 5 |
| IV DISCUSSION | 7 |
| A. Material Characterization | 7 |
| 1. Tailings | 7 |
| 2. Embankment Soils | 7 |
| 3. Natural Foundation Soils | 8 |
| B. Seismic Design Criteria | 8 |
| 1. Regional and Site Geology | 8 |
| 2. Seismicity | 11 |
| 3. Design Ground Motion | 12 |
| C. Groundwater Considerations | 13 |
| D. Static and Dynamic Design Considerations | 14 |
| 1. Consolidation Settlement | 14 |
| 2. Liquefaction Potential | 14 |
| 3. Stability of Slopes | 15 |
| 4. Deformation Analysis | 18 |
| V CONCLUSIONS AND RECOMMENDATIONS | 19 |
| VI REFERENCES | 21 |
| VII ILLUSTRATIONS | 22 |

DISTRIBUTION

LIST OF ILLUSTRATIONS

| | |
|-------------------------|--|
| Plate 1 | Site Plan |
| Plates 2 through 11 | Logs of Borings A-1 through A-10 |
| Plate 12 | Soil Classification Chart |
| Plate 13 | Physical Properties Criteria for Soil Classifications |
| Plate 14 | Physical Properties Criteria for Rock Classification |
| Plates 15 through 25 | Particle Size Analysis Data |
| Plate 26 | Plasticity Chart |
| Plates 27 through 30 | Unconsolidated-Undrained Triaxial Compression Test Reports |
| Plate 31 | Consolidation Test Data |
| Plate 32 | Compaction Test Data |
| Plate 33 | Geologic Map of Site and Vicinity |
| Plate 34 | Stability Analysis for Water Approximately 500 feet from Embankment |
| Plate 35 | Stability Analysis for Water at Face of Embankment |
| Plate 36 | Schematic Section of Proposed Drainage/Monitoring Schemes |

I INTRODUCTION

This report presents the results of a geotechnical investigation and assessment performed by Harding Lawson Associates (HLA) of the long-term stability of the W. R. Grace Zonolite tailings retention dam in Libby, Montana. Our study was conducted for W. R. Grace Company, Construction Products Division, as part of the closure plans for the mining facility.

In the early 1970s, we performed a preliminary exploration and a detailed foundation investigation for the construction of the tailings retention dam. The results were presented in reports dated January 8, 1971 and August 18, 1971, respectively. We subsequently performed construction observation services for the project. In 1974, we conducted waste disposal studies for the mine tailings and presented the results in reports dated July 19, 1974 and September 30, 1974. Finally, we presented the results of a processing study in a report dated February 29, 1980.

The purpose of the current investigation was to determine whether the long-term stability of the dam conforms to the State of Montana requirements for closure. Primary concerns regarding performance of the dam included: 1) strength of the tailings and the potential for a significant downstream flow of tailings in a postulated dam failure, 2) potential for liquefaction of the tailings during the maximum credible earthquake (MCE)* and its potential effects on the stability of the dam, and 3) reliability and adequacy of the existing surface and internal drainage systems for a permanent embankment.

* The maximum credible earthquake is the maximum event which, consistent with current knowledge, may ever be expected at the building site within the known geological framework.

The scope of work for this phase of the study, as outlined in our revised proposal dated April 10, 1991, was to review pertinent literature and reports, explore subsurface conditions of the tailings, embankment, and foundation materials, and perform engineering analyses to develop conclusions and, as appropriate, recommendations regarding the following:

1. Seismic design criteria
2. Geotechnical characteristics of the tailings material.
3. Liquefaction potential of the tailings and foundation soil based on current standards of practice.
4. Long-term static and dynamic stability of the dam.
5. Adequacy of the existing internal drainage system of the dam.

II PROJECT DESCRIPTION

W.R. Grace dam is located on Rainy Creek, approximately 3 miles northeast of the Kootenai River and northwest of Vermiculite Mountain on which the mine and mill were formerly situated. Construction of the tailings retention dam began with a 50-foot-high starter embankment, which was completed in November 1971. Since that time, the storage has been incrementally increased using a downstream, staged method of construction to raise the embankment as the tailings accumulated. The embankment is now 127 feet high with the crest at approximate Elevation +2927 feet.* The tailings surface elevation adjacent to the dam varies between +2913 and +2908 feet and slopes down to about Elevation +2903 feet where it intersects the surface of a pond upstream of the dam, as shown on the Site Plan, Plate I. At the time of our field investigation (June 1991), the pond was about 750 feet from the dam. The maximum depth, surface elevation, and distance of the pond from the dam vary seasonally; however, it is important to note that presently water is not impounded directly behind the dam and that the excess water from the drainage basin and Rainy Creek is diverted around the reservoir through a 48-inch diameter corrugated metal pipe culvert and an intake structure near the tailings-water interface upstream of the dam.

To restore Rainy Creek to its natural state, two alternatives are being considered by the design team: 1) to maintain the water upstream of the dam at approximately Elevation +2510 feet by constructing a shallow diversion levee about 500 feet upstream of the dam and by replacing the existing culvert with a channel starting at the proposed levee location to discharge excess water through a new spillway to be constructed in the left abutment, and 2) to allow water to flood the existing tailings reservoir and be

* National Geodetic Vertical Datum, NGVD.

impounded directly behind the dam. The impounded water would be discharged through a new spillway to be constructed in the left abutment.

III FIELD INVESTIGATION AND LABORATORY TESTING

We explored the subsurface conditions at the dam site by drilling 10 test borings at the locations shown on Plate 1. Borings A-1 through A-5 were drilled in the tailings to obtain soil samples for classification and laboratory testing. To augment available subsurface information and to obtain data needed for determining liquefaction potential and evaluating the natural foundation material (based on today's standards), Borings A-6 through A-10 were drilled on the downstream side, near the left abutment. The borings were drilled to depths between 21-1/2 and 77 feet using a truck-mounted rotary drilling rig. An open well piezometer was installed in Boring A-8. Boulders encountered during drilling of Borings A-6 through A-10 were cored using NX coring equipment. Our field engineer logged the borings and obtained samples for visual classification and laboratory testing. The soil types encountered were classified in accordance with ASTM D2487-85 based on visual-manual procedures as outlined in ASTM D2488-84. The boring logs are presented on Plates 2 through 11. The soil classification system that was used is presented on Plate 12. Physical properties criteria for soil and rock classifications are presented on Plates 13 and 14, respectively.

Soil samples were obtained using a Sprague and Henwood (S&H) split-barrel sampler (3.0-inch-outside diameter, 2.45-inch-inside diameter), a standard penetration test (SPT) sampler, and thin-walled Shelby tubes (3.0-inch outside diameter, 2.87-inch inside diameter). Both S&H and SPT samplers were driven by a 140-pound, automatic-trip hammer falling 30 inches. The number of blows required

to drive the sampler the final 12 inches of an 18-inch drive were recorded. The S&H blows were converted to pseudo SPT N-values* to aid in comparison with published data. This conversion is only approximate and its reliability varies with soil type and sampling procedures. The pseudo SPT N-values obtained with the S&H sampler and N-values obtained with the SPT sampler are shown on the boring logs. Shelby tubes were used to obtain relatively undisturbed samples of silty material.

The soil samples were reexamined in our laboratory to confirm field classifications and to select representative samples for testing. Laboratory tests determined moisture content, dry density, Atterberg limits, gradation, percent passing the No. 200 sieve, unconsolidated-undrained triaxial shear strength, consolidation characteristics, and compaction characteristics. The laboratory test results are summarized on the boring logs in the manner described in the Key to Test Data shown on Plate 12.

Particle size (gradation) data are presented on Plates 15 through 25. Atterberg limits test data are presented on Plate 26. Shear strength test data are presented on Plates 27 through 30. Consolidation test data are presented on Plate 31, and compaction test data are presented on Plate 32.

* The SPT N-value is defined as the number of blows of a 140-pound hammer, falling freely through the height of 30 inches, required to drive a standard penetration test sampler (2-inch outside diameter, 1-3/8-inch shoe inside diameter, and 1-1/2-inch tube inside diameter) the last 12 inches of an 18-inch drive. For SPT procedures, see ASTM D1586-84.

IV DISCUSSION

A. Material Characterization

1. Tailings

Borings A-1 through A-5 were drilled in the tailings material. The tailings consist of interbedded layers of soft to stiff elastic silt (60%) and loose to medium dense poorly graded sands and silty sands (40%) with mica and pyrite flakes. Silt and sand layers generally slope down and away from the embankment, reflecting the fact that tailings were discharged at the five discharge locations shown on Plate 1.

On the basis of laboratory tests performed on elastic silt samples, we assigned a static undrained shear strength to this material which varies linearly from 50 pounds per square foot (psf) at the surface to 1900 psf at the foundation level (Elevation +2800 feet). Based on our experience with similar material (San Francisco Bay Mud and other plastic silts), we judge that during the design earthquake the shear strength of silts encountered will be temporarily reduced by about 30 percent due to pore water pressure build-up caused by earthquake-induced cyclic loading conditions. We assigned an average friction angle of 30 degrees to the sands and silty sands for static loading conditions. Based on an empirical method suggested by Seed and Harder (1990), we assigned a post-liquefaction residual undrained shear strength of 100 psf to this material (see Section IV.D.2 for discussion on liquefaction potential).

2. Embankment Soils

Embankment soils were encountered near the bottoms of borings A-1, A-2 and A-4. These soils consist of dense to very dense, well graded silty sands. On the basis of 1) data obtained during this investigation, 2) laboratory tests performed on representative samples during the 1971 study, and 3) correlation with published data, we

assigned the embankment soils an effective friction angle of 37 degrees and cohesion values ranging between 50 and 500 psf. The upper bound effective cohesion value of 500 psf was obtained from unconsolidated undrained triaxial tests. Due to strain rate/creep effects, however, the field cohesion value could be somewhat lower. Therefore, consideration of a range in the cohesion value (as stated above) was deemed appropriate.

3. Natural Foundation Soils

Natural foundation soils encountered during both the 1971 and present explorations consist mainly of dense to very dense poorly graded gravels, dense to very dense poorly graded sands and moderately hard, friable pyroxenite bedrock, with abundant magnetite and pyrite.

B. Seismic Design Criteria

1. Regional And Site Geology*

The project site on Rainy Creek is in a region exposing pre-Cambrian age bedrock. The rocks, chiefly argillite and quartzite of the Belt Series, are folded in a series of broad open northwest-trending folds. In Rainy Creek, the rocks are intruded by basic plutonic igneous rocks consisting of pyroxenite and syenite. A geologic map of the site and vicinity is shown on Plate 33.

The terrain within the region is relatively flat, and is the result of long continued erosion until mid-Tertiary geologic time. During the Pliocene through mid-Pleistocene epochs, the area was subjected to faulting and uplift which resulted in renewed stream

* Harding, Miller, Lawson & Associates. 1971. "Foundation Investigation and Engineering Analyses, Tailings Dam, W. R. Grace & Company, Construction Products Division, near Libby, Montana," dated August 18, 1971.

downcutting. This formed the basic existing drainage pattern. During the Pleistocene epoch, glacial action widened and deepened the valleys, including Rainy Creek valley. The valley of the Kootenai River was dammed by a glacier and a lake was formed which reached a surface elevation of about 2500 feet.

Intermittent active displacement of the faults developed during the Pliocene and early Pleistocene epochs. These displacements continue at a few locations in western Montana. However, there is no indication of active faulting at or near the site either in the geologic literature or from visible terrain features.

Bedrock underlying the dam and tailings pond areas consists of predominantly dark green to black pyroxenite which is generally fine grained and highly friable. The upper few feet of pyroxenite bedrock has physical characteristics not unlike those of a dense sand. In trench exposures on the canyon slopes, the pyroxenite contains thin, discontinuous, crushed zones. These crushed zones are planar and oriented approximately parallel to the canyon slope surface, suggesting that they are the result of glacial movement and/or gravity creep.

Syenite dikes, generally 6 inches or less in thickness, locally intrude into the pyroxenite. The syenite is generally quite hard and coarse-grained. Quartz-tremolite veins also cut the pyroxenite. The tremolite alteration is also accompanied by varying amounts of iron sulphides and oxides.

During the Pleistocene glaciation, the Rainy Creek valley was occupied by a glacier that produced a somewhat flattened valley bottom with rounded sides, in contrast to the typical V-shaped canyon that would result from stream erosion alone. As the glacier retreated upstream (possibly more than once), outwash alluvium was deposited in the valley bottom. The alluvium consisted of mixed silts, sands, and gravels, within which are zones with many large boulders of hard quartzite. Occasionally, the boulders

reach a diameter of 4 to 5 feet. Where viewed in trench walls, the glacial outwash consists predominantly of fine- to coarse-grained gravels with about 10 percent or less of fine sands and silts. The gravels contain zones of very high porosity and permeability.

Zones of finer-grained alluvium consisting of clayey gravels to thinly laminated silts are found in the valley bottom near the right abutment. These sediments appear to be largely rock flour deposited in a lake formed during glaciation.

The right abutment slope is underlain by a thick blanket of glacial outwash and till, probably a lateral moraine, to approximately Elevation +2890 feet. The thickness of this zone varies from a few feet to about 40 feet. Near the top of the abutment slope, the alluvium consists of nearly horizontally bedded silty and sandy gravels overlain by approximately 6 feet of thinly laminated fine silt, possibly of lacustrine origin.

The left abutment slope, in contrast, is blanketed by a relatively thin (10 feet and less) mantle of slope debris and remnants of a lateral moraine near the base of the canyon slope. At about Elevation +2830 feet, there is a remnant of an outwash terrace capped by a horizontal, 4-foot-thick bed of highly permeable, relatively clean sand and gravel.

A 1- to 2-inch-thick bed of nearly white silt overlies the top of the glacial outwash gravels in the valley bottom, suggesting that there was a temporary lake in Rainy Creek at the close of the Pleistocene glaciation.

Recent unconsolidated alluvium in the valley bottom consists of a blanket of soft silt up to about 6 feet thick. This flood plain deposit locally contains fine sand and gravel streaks with occasional large boulders near the present stream course. These materials are reworked glacial outwash.

2. Seismicity

The project site is within a seismically active zone that forms an arc through western Montana, northwestern Wyoming, southeastern Idaho, and Utah. Earthquakes of both large and small intensities have an epicentral concentration within this seismic zone. In Montana, six earthquakes with intensities of VIII (Modified Mercalli Scale) or greater have occurred within this zone since 1868. Most of the strong historic earthquakes in Montana, including the Hebgen Lake earthquake which occurred in 1959, have occurred between Yellowstone National Park and Helena. The 1959 Hebgen Lake earthquake had no significant effect on the Libby area. There is no record of moderate to large earthquakes locally. However, smaller "random" events (events that are not related to known active or potentially active faults) with a maximum magnitude of 5 have occurred in the region.

There are several potentially active faults in the region that may affect the project site. These are the Lenia, Bull Lake, Savage Lake, O'Brien Creek, Snowshoe, Rock Lake, and Hope faults. The closest, the O'Brien Creek fault, is about 13 km west of the site (see Plate 33).

The Lenia fault has been traced continuously for 16 km within the Libby quadrangle. It almost certainly continues southward, either under the Bull Lake, or less probably, through the Trio prospect. Evidence suggests that movement along the fault is vertical.

The Bull Lake fault is a normal fault with younger beds exposed in the relatively downthrown block on the west. It has been traced for 21 km along a curving course, concave to the east. The fault is not observed north of Madge Creek, and is joined by the Savage Lake fault south of Crowell Creek. From this junction, the Bull Lake fault trends southward and then curves to the southeast.

The Savage Lake fault is largely inferred from physiographic and structural evidence. The fault, seen at the Carter prospect about 2 km east of Savage Lake, trends first, southwestward, then southward along the east side of the Libby Formation.

The O'Brien Creek fault is a normal fault thought to pass through the "island" of Wallace Formation just north of Savage Lake in a north-northwesterly fashion and cross beneath the Great Northern tracks. The fault is concealed under alluvium north of the Kootenai River. It then passes very close to the mountain front on the east side of O'Brien Creek.

The Snowshoe fault strikes north and is nearly vertical for most of its trace of 26 km. It cuts the crest of the northward-plunging Snowshoe anticline and is cut off at the north by a small fault along Horse Creek. The fault terminates at the Snowshoe anticline east of Elephant Peak.

The Rock Lake fault, approximately 19 km long, extends from Dad Peak southeastward past Wanless Lake. Displacement along this fault has been irregular in magnitude and direction, but movement has been essentially vertical. The Hope fault, a normal fault with the downthrow on the southwest, was traced from Hope, Idaho, to Heron, Montana.

On the basis of fault length and published relationships correlating fault rupture length and earthquake magnitude, we have conservatively assigned a maximum credible magnitude of 7 to these faults.

3. Design Ground Motion

Based on a postulated magnitude 7 earthquake on the nearby O'Brien Creek fault (about 13 km from the site) and using published attenuation relationships (Idriss, 1987), we estimate the peak bedrock acceleration (PBA) at the site to be about 0.30 gravity (g). The estimated PBA corresponding to a "random" magnitude 5 event at

a close distance (less than 1 km) is less than 0.30g. The Uniform Building Code (UBC, 1991) maps the project site in the Seismic Zone 2B with the expected PBA of 0.20g. We believe that a 0.30g acceleration conservatively envelopes expected long-term seismic activities in the region.

C. Groundwater Considerations

Because we used a rotary wash drilling system, the groundwater level could not be measured during our field investigation. However, stabilized groundwater table was measured about 10 feet below ground surface from the piezometer installed in Boring A-8. In addition, groundwater level data are available from five piezometers installed following the construction of the starter dam in 1971 (see Plate 1 for piezometer locations). Since then, groundwater level has been monitored by W. R. Grace staff on a monthly basis. Water levels observed in piezometers indicate that water flows mainly in the highly previous natural gravelly foundation material and that the phreatic surface rises only occasionally above the foundation level (one of the six piezometers indicates temporary water levels that were about 3 feet above the dam foundation).

During the construction of the starter embankment, a series of 20-foot-wide, 2-foot-high drainage blankets consisting of native gravel material was placed at the embankment foundation level. Eight-inch-diameter perforated pipes were embedded within the drainage blankets to collect the water and transport it to the downstream side. These pipes were connected to a single 14-inch-diameter pipe which was extended at each subsequent stages of construction and presently emerges from the downstream face near Boring A-8. The volume of discharged water was roughly estimated to be 300 gallons per minute (gpm) at the time of this investigation.

D. Static and Dynamic Design Considerations

1. Consolidation Settlements

As described above, two scenarios are being considered for the restoration of Rainy Creek. If water is kept near the proposed levee, consolidation settlements will continue to occur in the tailings as water drains from the tailings material. The magnitude of settlement will vary with the thickness of the tailings. Where the tailings are 100 feet thick, we anticipate a total settlement of approximately 5 feet would occur over a 30-year period based on the consolidation characteristics of the tailings. We estimate that half of this settlement will occur during the next few years. On the other hand, if water is allowed to rise and pond against the embankment, the pore pressure would be unchanged, and therefore no additional settlement of the surface of tailings would occur.

2. Liquefaction Potential

Using field and laboratory test data to evaluate the potential for liquefaction of the tailings material, we determined that if the tailings remain saturated, the discontinuous loose sand and silty sand layers encountered in the tailings material will likely liquefy during the design earthquake (MCE). We further determined that settlements of up to several inches could result from liquefaction and/or densification of loose sands in the tailings. These settlements would likely be nonuniform because of the variable thicknesses and depths of the sand layers.

Due to their high plasticity indices, saturated silts encountered in the tailings are not susceptible to liquefaction. However, we believe that a build-up of pore water pressure (if the tailings reservoir remain saturated) during the design earthquake could result in a decrease of up to 30 percent in the static undrained shear strength of these soils. If the silts are drained, there would be no reduction in undrained shear strength due to cyclic loading conditions.

3. Stability of Slopes

Stability analyses of the embankment and tailings were performed for four different cases, using the Bishop's Modified Method of Slices. The method analyzes circular slip surfaces using conventional limit equilibrium theory to compute factors of safety for the slope geometry and soil parameters being considered.

The cases analyzed were:

- Case I - Static analysis with the water about 500 feet upstream of the dam (Plate 34).
- Case II - Dynamic (pseudo-static) analysis with the water about 500 feet upstream of the dam and with seismic coefficients k_x , of 0.10g, 0.15g and 0.20g. For this case a yield seismic coefficient k_y was also determined. (This coefficient yields a factor of safety, F.S., of 1.0) (Plate 34).
- Case III - Static analysis with the water at the upstream face of the dam, at the tailings elevation (Plate 35).
- Case IV - Dynamic (pseudo-static) analysis with the water at the upstream face of the dam, at the tailings elevation. Seismic coefficients of 0.10g, 0.15g and 0.20g were used and a yield coefficient k_y was also determined (Plate 35).

On the basis of engineering analysis and measured groundwater levels in the piezometers, we believe that the groundwater level immediately upstream of the embankment does not rise above the foundation level. Therefore, for our stability analyses, we have assumed that the water level is at the base of the embankment (Plates 34a and 34b). If water is allowed to come in contact with the embankment, it could become partially saturated, as shown by the phreatic surface on Plates 35a and 35b, with water emerging from the downstream face of the embankment. As a worst-case condition, we assumed that the pervious natural gravel layer will be clogged at some time in the future and would no longer be effective in providing drainage as presently observed. In reality, the relatively high permeability of the foundation material likely

will cause the phreatic surface to drop, and water may never emerge from the downstream face of the embankment.

Without a permanent monitoring system in place, however, it would be inadvisable to assume a long-term phreatic surface lower than that shown on Plate 35a and 35b. As indicated in our 1971 reports, the material used in construction of the dam is highly susceptible to erosion. Therefore, water emerging from the downstream face of the embankment and running parallel to surface would be unacceptable for both stability and erosion considerations. The problem could be mitigated either by 1) providing a permanent monitoring program, such as installing piezometers in the downstream face to monitor the actual location of the phreatic surface within the embankment, or 2) providing a new internal drainage system, such as a chimney drain constructed near the downstream toe to collect water which otherwise could cause erosion of the downstream face. Assuming one of these alternatives will be put in place to mitigate the potential for a "localized" instability and/or erosion, we evaluated the overall global static and dynamic stability of the two alternatives shown on Plates 34 and 35.

The analyses were performed considering a range of shear strength values appropriate for static and dynamic loading conditions. The shear strength values are summarized below:

i) Embankment Material

$c' = 50$ psf, $\phi' = 37$ degrees (see Plates 34b and 35b)
 $c' = 500$ psf, $\phi' = 37$ degrees (see Plates 34a and 35a)

ii) Tailings

a) Elastic Silts

S_u (static) = 50 psf at 0 feet depth
 1900 psf at 100 feet depth

Su (dynamic) = 35 psf at 0 feet depth
 1330 psf at 100 feet depth

b) Sands and Silty Sands

ϕ' (static) = 30 degrees
 Su (dynamic) = 100 psf

iii) Foundation Material

$\phi' \approx 45$ degrees

The results of the analyses are presented in the following table.

| Case | Seismic Coefficient, k_s | Minimum Factor of Safety F.S | Yield Seismic Coefficient, k_y |
|------------|----------------------------|------------------------------|----------------------------------|
| I and II | 0 | 1.83 - 2.28 | -- |
| | 0.10 | 1.44 - 1.79 | |
| | 0.15 | 1.29 - 1.61 | 0.28 - 0.42 |
| | 0.20 | 1.17 - 1.46 | |
| III and IV | 0 | 1.74 | -- |
| | 0.10 | 1.30 | |
| | 0.15 | 1.16 | 0.22 |
| | 0.20 | 1.05 | |

It should be noted that the slip surface shown on Plate 35b was not considered critical in our analyses because of the future installation of a new chimney or blanket drain. Either drain system would reduce the seepage and ravelling forces that would produce localized instability associated with the slip surface on Plate 35b.

The results of our stability analysis indicate that the dam is stable during both static and dynamic loading conditions. According to recommendations by Seed (1979), earth dams of similar construction are expected to experience limited deformations and remain stable during and after a magnitude 7 earthquake provided that 1) the build-up of pore water pressure does not significantly reduce the static strength

of embankment material and 2) a minimum factor of safety of 1.15 is computed from a pseudo-static analysis using a seismic coefficient of 0.10g. The pseudo-static factors of safety computed for various phreatic surface locations and soil properties are well above the minimum required value. In addition, the embankment material is dense to very dense and is not susceptible to an appreciable loss of shear strength. Therefore, the dam is expected to remain stable during and following the design earthquake.

4. Deformation Analysis

To estimate the magnitude of permanent displacement of the embankment during the design earthquake, we performed studies using a simplified response and deformation analysis based on methods developed by Makdisi and Seed (1978, 1979).

First, the intensity of shaking within the embankment was estimated based on the estimated natural frequency of the embankment, anticipated frequency content of the input base motion, and dynamic soil properties of similar dam embankment material. The response spectra for rock sites by Idriss (1987) scaled to a PBA of 0.3g was used in our analysis. A maximum crest acceleration of about 0.8g was computed.

Next, based on the geometry and location of the critical slip surface, and a yield coefficient of 0.22 to 0.42g (see Plates 34 and 35), we calculated permanent deformations to be insignificant, which confirms conclusions by Seed (1979).

V CONCLUSIONS AND RECOMMENDATIONS

The results of field investigation and laboratory testing performed on the tailings material indicate that during a hypothetical embankment failure, the potential for a tailings material flow and contamination of the downstream area is very low because of the strength of the tailings as they now exist. We judge that the consistency of the tailings material is such that if a section of the embankment were removed, the tailings would fail but would maintain approximately a 4:1 (horizontal to vertical) slope.

On the basis of 1) the results of our 1971 studies, 2) geotechnical data obtained during our construction observation services, 3) piezometric data collected during about 20 years of operation, and 4) results of our present studies, we conclude that the embankment, in its present condition, is adequately safe during both static and maximum credible seismic loading conditions. We also judge that if the water were allowed to come in contact with the embankment, the dam would be safe under static and seismic loading conditions. However, due to potential problems discussed below, we strongly recommend that the long-term performance of the dam be carefully monitored and mitigation measures be immediately implemented should the monitoring program indicate potential instability.

If, as part of restoration of the Rainy Creek, water is allowed to flood the tailings reservoir area and is maintained at the present tailings level, it could potentially emerge from the downstream face of the embankment causing erosion of soil and eventually, localized slope instability problems.

For the past 20 years, the drain pipe beneath embankment has successfully collected water at the dam foundation level and discharged it into the creek at the downstream side. This system is expected to operate effectively in the future. However, it is possible that the pipe may corrode or clog during long-term operation. If

so, water could be released from the pipe within the embankment, and, if not absorbed by previous natural drainage material upon exit, erode the downstream face, eventually causing localized instability of the embankment. Although unlikely, the same problems could arise from clogging of the natural gravel drainage system.


An acceptable monitoring program would consist of the installation of new piezometers at locations shown on Plate 36 to detect the presence of water and the location of the phreatic surface inside the embankment. The piezometric data should be regularly reviewed and conditions of the dam be periodically inspected. Mitigating measures such as installation of a blanket drain, chimney drain, or other acceptable drainage system (see Plate 36) near the downstream toe should be adopted if and when water approaches the downstream face of the embankment.

If water is kept at Elevation +2910 feet about 500 feet upstream of the dam and a channel is constructed to collect Rainy Creek and flood water, nonuniform settlement of the tailings should be anticipated. Since a total long-term settlement of about 5 feet is anticipated as water drains out of the tailings material, the channel and its lining system should be flexible enough to tolerate the potentially large differential settlement. To minimize anticipated differential settlement, we recommend that the channel be constructed as close as possible to the left abutment at a starting elevation of about +2910 feet.

VI REFERENCES

- Idriss, I. M., 1987. Earthquake Ground Motions, Lecture Notes, Course on Strong Ground Motions, Earthquake Engineering Research Institute, Pasadena, California, April 10-11, 1987.
- Pardee, J.T., 1950, Late Cenozoic Block Faulting in Western Montana, GSA Volume 61, pages 359-406.
- Pardee, J.T. and Larsen, E.S., 1928, Deposits of Vermiculite and other Minerals in the Rainy Creek District near Libby, Montana. Economic Geology Part I, pages 17-29.
- Ross, Clyde P. and Nelson, Willis H., 1959, Regional Seismicity and Brief History of Montana Earthquakes, U.S. Geological Survey Professional paper No. 435-E. pages 25-30.
- Seed, H. B., 1979. Considerations in the Earthquake Resistant Design of Earth and Rockfill Dams, Geotechnique 29, No. 3, p. 215-263.
- Seed, H.B. and Harder, L.F., Jr., 1990. SPT-Based Analysis of Cyclic Pore Pressure Generation and Undrained Residual Strength, H.B. Seed Memorial Symposium, v.II. pages 351-376.

VII ILLUSTRATIONS



EXPLANATION

A-1 Boring Number and Location

P-1 Piezometer Number and Location

0 200
Approximate Scale in Feet

Reference: Topographic Map prepared by Walker and Associates, Inc.
untitled, undated.



Harding Lawson Associates
Engineering and
Environmental Services

Site Plan
W.R. Grace Dam
Rainy Creek, Montana

PLATE

1

DRAWN
AM

JOB NUMBER
5891,053.03

APPROVED
GLW

DATE
11/91

REVISED DATE

Laboratory Tests

-200=7.7%
MA, Sec Plate 15
TxUU 312(450)
LL=60, PI=8
-200=75.9%

-200=45.7
MA, See Plate 16

*Blow counts converted to
pseudo-standard penetration
blow counts using a
conversion factor of 0.6.

**Elevation referenced to
National Geodetic Vertical
Datum.

Moisture
Content (%)
Dry
Density (pcf)

71.1 56

59.7 67

Blows/foot

14*

4*

Push

4

4*

6

7*

Depth (ft)
Sample

Equipment 4" dia. Rotary

Elevation 2912.9 ft** Date 06/27/91

GRAY-BROWN SILTY GRAVEL WITH
SAND (GM)
moist

ACCESS
FILL

OLIVE GREEN ELASTIC SILT (MH)
soft to medium stiff, saturated,
abundant fine grained platy minerals
(diesel odor)

color changes to blue-green with interbedded
sandy silt and silty sand stringers
(diesel odor)

GREEN POORLY GRADED SAND (SP)
loose, saturated, fine grained
(diesel odor)

OLIVE GREEN SILTY SAND (SM)
loose, saturated
(diesel odor)

OLIVE GREEN ELASTIC SILT (MH)
medium stiff, saturated, abundant fine
pyrite flakes (diesel odor)

OLIVE-GREEN SILTY SAND (SM)
loose, saturated, fine-grained, abundant mica

OLIVE GREEN ELASTIC SILT (MH)
medium stiff, saturated, moderately plastic



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 1
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 2)

PLATE

2a

DRAWN

JOB NUMBER

5891,053.03

APPROVED

FILE

11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture Content (%)
Dry Density (pcf)

Blows/foot
Depth (ft)
Sample

Equipment 4" dia. Rotary

Elevation 2912.9 ft** Date 06/27/91

-200=6.4%
MA, See Plate 17

12.9 132

30/5.6**

30/5**

OLIVE GREEN POORLY GRADED SAND (SP)
loose, saturated, fine-grained, angular to platy,
trace silt and gravel (diesel odor)

becoming medium dense

MOTTLED GRAY-GREEN WELL GRADED SAND
WITH SILT AND GRAVEL (SW-SM)
very dense, saturated, fine to coarse grained sand
angular to subrounded gravel, with abundant
platy minerals

(Embankment Material)

Boring was terminated at 56.0 feet.
No free groundwater was encountered.



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 1
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 2 of 2)

PLATE

2b

| | | | | | |
|-------|-------------|----------|----------|------|--------------|
| DRAWN | JOB NUMBER | APPROVED | FILE | DATE | REVISED DATE |
| | 5891,053.03 | | 11529G19 | | |

Laboratory Tests

Moisture
Content (%)

Dry
Density (pcf)

Blows/foot

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2911.4 ft** Date 06/26/91

ACCESS
FILL

GRAY-BROWN SILTY GRAVEL WITH SAND (GM)
moist (auger cuttings)

DARK GRAY-GREEN SILTY SAND (SM)
very loose, saturated, fine-grained,
platey grains, with abundant pyrite

GRAY-GREEN ELASTIC SILT (MH)
soft, saturated, trace fine-grained sand,
moderate to high plasticity

DARK GREEN SILTY SAND (SM)
very loose, saturated, fine-grained,
platey grains

OLIVE GREEN ELASTIC SILT (MH)
soft, saturated, trace fine pyrite flakes,
with occasional thin stringers of silty sand

becoming medium stiff, with interbedded
brown silty sand stringers

BROWN AND OLIVE GREEN SILTY SAND (SM)
loose, saturated, fine platey grained

OLIVE GREEN ELASTIC SILT (MH)
stiff, saturated, high plasticity,
trace platey pyrite

TxUU 3S3(500),
See Plate 28
LL=51, PI=10,
See Plate 26
-200=71.3%

63.2 62

Push

-200=75.3%

67.8 64

5*

PLATE

3a



Harding Lawsoo Associates
Engineering and
Environmental Services

Log of Boring A- 2
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 2)

DRAWN

JOB NUMBER

5891,053.03

APPROVED

FILE

11529G19

DATE

REVISED DATE

Laboratory Tests

TxUU 946(800),
See Plate 29
LL=71, PI=27,
See Plate 26
-200=84.5%
CC=0.75

-200=33.5%
MA, See Plate 18

Moisture
Content (%)
Dry
Density (pcf)

60.4 64

47.4 77

Blows/foot

Push

12*

14

13

23

21

75

Depth (ft)
Sample

Equipment 4" dia. Rotary

Elevation 2911.4 ft** Date 06/26/91

OLIVE GREEN SANDY ELASTIC SILT (MH)
stiff, saturated, with abundant fine
platey minerals, fine-grained sand with
interbedded silty sand seams

DARK GREEN SILTY SAND (SM)
medium dense, saturated
abundant platey minerals

DARK GREEN POORLY GRADED SAND WITH
SILT (SP-SM)
medium dense, saturated, fine to medium
grained, angular to platey grains, with
occasional sandy silt stringers

OLIVE GREEN ELASTIC SILT (MH)
stiff, saturated, abundant platey minerals,
moderately plastic

GREEN SILTY SAND (SM)
medium dense, saturated, pockets of sandy silt

DARK GREEN POORLY GRADED SAND WITH
SILT (SP-SM)
medium dense, saturated, fine grained sand,
platey grains

(Embankment Material)

Boring was terminated at 77.0 feet.
No free groundwater was encountered.



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 2
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 2 of 2)

PLATE

3b

| DRAWN | JOB NUMBER | APPROVED | FILE | DATE | REVISED DATE |
|-------|-------------|----------|----------|------|--------------|
| | 5891,053.03 | | 11529G19 | | |

Laboratory Tests

-200=9.7%
MA, See Plate 19

-200=76%

TxUU 1006(750),
Sec Plate S0
LL=69, PI=2S,
Sec Plate 26
-200=82.6%

Moisture
Content (%)
Dry
Density (pcf)

64.0 62

Blows/foot

Push

9

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2913.5 ft** Date 06/28/91

ACCESS
FILL

GREEN WELL GRADED SAND
WITH GRAVEL (SW)
moist (auger cuttings)

GREEN WELL GRADED SAND WITH SILT
AND GRAVEL (SW-SM)
loose, saturated, coarse grained sand,
angular to platy grains, angular gravel

OLIVE GREEN ELASTIC SILT WITH SAND (MH)
very soft, saturated, moderate to high plasticity

SILTY SAND (SM)
loose, saturated, fine to medium grained
OLIVE GREEN ELASTIC SILT (MH)
very soft, saturated, trace fine grained sand

OLIVE GREEN SILTY SAND (SM)
very loose, saturated, fine grained, platy

BLUE-GREEN ELASTIC SILT (MH)
soft to stiff, saturated,
trace pyrite, occasional thin stringers of
sandy silt



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 3
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 2)

PLATE

4a

DRAWN

JOS NUMBER
5891,053.03

APPROVED

FILE
11529G19

DATE

REVISED DATE

Laboratory Tests

-200=6.0%
MA, See Plate 20

Moisture
Content (%)
Dry
Density (pcf)

14.0 128

Blows/foot

18*

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2913.5 ft** Date 06/28/91

40
45
50
55
60
65
70
75
80

GREEN WELL GRADED SAND WITH GRAVEL
(SW)
dense, saturated, fine to coarse
grained sand, gravel to 1 inch diameter

Boring was terminated at 46.5 feet.
No free groundwater was encountered.



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 3
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 2 of 2)

PLATE

4b

DRAWN

JOB NUMBER
5891,053.03

APPROVED

FILE
11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture
Content (%)
Dry
Density (pcf)

Blows/foot

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2913.6 ft** Date 06/27/91

-200=1.7
MA, See Plate 21
-200=6.1
MA, See Plate 22

31.7 84

9"

5

5"

10

1

7"

15

16

20

25

30

35

40

BROWN GRAY POORLY GRADED GRAVEL
WITH SAND (CP)
moist

ACCESS
FILL

OLIVE BLUE-GREEN ELASTIC SILT (MH)
soft to medium stiff, saturated, interbedded with
silty sand stringers

OLIVE GREEN ELASTIC SILT (MH)
soft, saturated, abundant fine
platey minerals, with interbedded sand stringers
(diesel odor)

GREEN POORLY GRADED SAND WITH GRAVEL
(SP) loose, saturated, fine to coarse grained
subangular to platy sand, trace subrounded
gravel (diesel odor)

GREEN WELL GRADED SAND (SW)
medium dense, moist, fine to coarse grained
sand,
syenite and pyroxinite up to 1" diameter
(Embankment Material)

Boring terminated at 21.5 feet
No free groundwater was encountered.



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 4 (Sheet 1 of 1)
W. R. Grace Dam
Rainy Creek, Montana

PLATE

5

DRAWN

JOB NUMBER

5891,053.03

APPROVED

FILE

11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture
Content (%)
Dry
Density (pcf)

Blows/foot

Depth (ft)

Sample


Equipment 4" dia. Rotary

Elevation 2910.1 ft** Date 06/28/91

-200=5E.3
MA, See Plate 23

-200=76.6%

67.5 61



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 5
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 2)

PLATE

6a

| | | | | | |
|-------|-------------|----------|----------|------|--------------|
| DRAWN | JOB NUMBER | APPROVED | FILE | DATE | REVISED DATE |
| | 5891,053.03 | | 11529G19 | | |

Laboratory Tests

-200=60.2%
MA, See Plate 24

Moisture
Content (%)
Dry
Density (pcf)

Blows/foot
Depth (ft)
Sample
Push

Equipment 4" dia. Rotary

Elevation 2910.1 ft** Date 06/28/91

BROWN AND GREEN SILTY SAND (SM)
loose, saturated, with interbedded layers
of medium stiff elastic silt

Boring was terminated at 50.0 feet.
No groundwater was encountered.



Harding Lawson Associates
Engineering and
EnVironmental Services

Log of Boring A- 5
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 2 of 2)

PLATE

6b

| DRAWN | JOB NUMBER | APPROVED | FILE | DATE | REVISED DATE |
|-------|-------------|----------|----------|------|--------------|
| | 5891,053.03 | | 11529G19 | | |

Laboratory Tests


Moisture
Content (%)
Dry
Density (pcf)

Blows/foot

Depth (ft)
Sample

Equipment 4" dia. Rotary

Elevation 2836.5 ft** Date 06/24/91



GRAY AND BROWN POORLY GRADED GRAVEL
WITH SAND (GP)
dense, moist, cobbles up to 2' dia.
with trace silt, subrounded to subangular

occasional seams of syenite, tremolite, and
quartz in boulders



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 6
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 2)

PLATE

7a

DRAWN

JOB NUMBER
5891,053.03

APPROVED

FILE
11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture
Content (%)
Dry
Density (pcf)

Blows/foot
Depth (ft)
Sample

60/3" 40
Core 45
50/2" 50
50/2" 55
60
65
70
75
80

Equipment 4" dia. Rotary

Elevation 2836.5 ft** Date 06/24/91

GRAY-BROWN SANDY SILT (ML)
very stiff, saturated, fine to
medium-grained sand, with stringers of silty sand
GRAY-GREEN POORLY GRADED SAND (SP)
very dense, saturated, medium to coarse grained,
abundant gravel, magnetite
GRAY POORLY GRADED GRAVEL
WITH SAND (SP)
very dense, saturated,
coarse sand with boulders up to 2' dia.
GRAY-GREEN POORLY GRADED SAND (SP)
very dense, saturated, with abundant magnetite
(weathered pyroxenite)
GRAY-GREEN PYROXENITE
moderately hard, friable, with abundant magnetite

Boring was terminated at 56.0 feet.
No free groundwater was encountered.



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 6
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 2 of 2)

PLATE

7b

DRAWN

JOS NUMBER
5891,053.03

APPROVED

FILE
11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture
Content (%)
Dry
Density (pcf)


Blows/foot

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2816.0 ft** Date 06/25/91



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 7
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 1)

PLATE

8

| | | | | | |
|-------|-------------|----------|----------|------|--------------|
| DRAWN | JOB NUMBER | APPROVED | FILE | DATE | REVISED DATE |
| | 5891,053.03 | | 11529G19 | | |

Laboratory Tests


Moisture
Content (%)
Dry
Density (pcf)

Blows/foot

Depth (ft)
Sample

Equipment 4" dia. Rotary

Elevation 2791.3 ft** Date 06/29/91



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 8
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 1)

PLATE

9

DRAWN

JOS NUMBER

5891,053.03

APPROVED

FILE

11529G19

DATE

REVISED DATE

Laboratory Tests

-200=28.3%
MA, See Plate 25

Moisture
Content (%)
Dry
Density (pcf)

12.5 133


Blows/foot

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2828.1 ft** Date 06/30/91



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A- 9
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 1)

PLATE

10

DRAWN

JOB NUMBER
5891,053.03

APPROVED

FILE
11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture
Content (%)
Dry
Density (pcf)


Blows/foot

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2828.5 ft** Date 06/30/91



BROWN SANDY SILT WITH GRAVEL (ML)
soft to stiff, saturated, cobbles up to 6",
occasional thin stringers of silty
sand up to 1/2" thick (auger cuttings)

BROWN-GRAY POORLY GRADED GRAVEL
WITH SILT (GP)
dense, saturated



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A-10
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 1 of 2)

PLATE

11a

DRAWN

JOB NUMBER

5891,053.03

APPROVED

FILE

11529G19

DATE

REVISED DATE

Laboratory Tests

Moisture
Content (%)
Dry
Density (pcf)

Blows/foot

Depth (ft)

Sample

Equipment 4" dia. Rotary

Elevation 2828.5 ft** Date 06/30/91

40
45
50
55
60
65
70
75
80

GRAY-BROWN WELL GRADED GRAVEL
WITH SAND AND SILT (GW-GM)

GREEN PYROXENITE
moderately hard, friable

Boring was terminated at 57.6 feet.
No free groundwater was encountered.



Harding Lawson Associates
Engineering and
Environmental Services

Log of Boring A-10
W. R. Grace Dam
Rainy Creek, Montana

(Sheet 2 of 2)

PLATE

11b

DRAWN

JOB NUMBER
5891.053.03















APPROVED

FILE
11529G19

DATE

REVISED DATE

UNIFIED SOIL CLASSIFICATION SYSTEM - ASTM D2487-85

| MAJOR DIVISIONS | | | | | GROUP NAMES |
|--|--|--|---|--|---|
| COARSE-GRAINED SOILS More than 50% retained on the No. 200 sieve | GRAVELS More than 50% of coarse fraction retained on No. 4 sieve | Clean gravels less than 5% fines | GW |  | WELL-GRADED GRAVEL, WELL-GRADED GRAVEL WITH SAND |
| | | | GP |  | POORLY-GRADED GRAVEL, POORLY-GRADED GRAVEL WITH SAND |
| | | Gravels with more than 12% fines | GM |  | SILTY GRAVEL, SILTY GRAVEL WITH SAND |
| | | | GC |  | CLAYEY GRAVEL, CLAYEY GRAVEL WITH SAND |
| | SANDS 50% or more of coarse fraction passes No. 4 sieve | Clean sand less than 5% fines | SW |  | WELL-GRADED SAND, WELL-GRADED SAND WITH GRAVEL |
| | | | SP |  | POORLY-GRADED SAND, POORLY-GRADED SAND WITH GRAVEL |
| | | Sands with more than 12% fines | SM |  | SILTY SAND, SILTY SAND WITH GRAVEL |
| | | | SC |  | CLAYEY SAND, CLAYEY SAND WITH GRAVEL |
| FINE-GRAINED SOILS 50% or more passes the No. 200 sieve | SILTS AND CLAYS Liquid limit less than 50% | ML |  | SILT, SILT WITH SAND OR GRAVEL, SANDY OR GRAVELLY SILT | |
| | | CL |  | LEAN CLAY, LEAN CLAY WITH SAND OR GRAVEL, SANDY OR GRAVELLY LEAN CLAY | |
| | | OL |  | ORGANIC SILT OR CLAY, ORGANIC SILT OR CLAY WITH SAND OR GRAVEL, SANDY OR GRAVELLY ORGANIC SILT OR CLAY | |
| | SILTS AND CLAYS Liquid limit 50% or more | MH |  | ELASTIC SILT, ELASTIC SILT WITH SAND OR GRAVEL, SANDY OR GRAVELLY ELASTIC SILT | |
| | | CH |  | FAT CLAY, FAT CLAY WITH SAND OR GRAVEL, SANDY OR GRAVELLY FAT CLAY | |
| | | OH |  | ORGANIC SILT OR CLAY, ORGANIC SILT OR CLAY WITH SAND OR GRAVEL, SANDY OR GRAVELLY ORGANIC SILT OR CLAY | |
| HIGHLY ORGANIC SOILS | | Pt | | PEAT | |

For definition of dual and borderline symbols, see ASTM D2487-85.

KEY TO TEST DATA

| | | Shear Strength (psf) | Confining Pressure |
|--------|---------------------------------|----------------------|---|
| Perm | - Permeability | TxUU 3200 (2600) | - Unconsolidated-Undrained Triaxial Shear |
| Consol | - Consolidation | (FM) or (S) | (field moisture or saturated) |
| LL | - Liquid Limit (%) | TxCU 3200 (2600) | - Consolidated-Undrained Triaxial Shear |
| Pi | - Plasticity Index (%) | (P) | (with or without pore pressure measurement) |
| Gs | - Specific Gravity | TxCD 3200 (2600) | - Consolidated Drained Triaxial Shear |
| MA | - Particle Size Analysis | SSCU 3200 (2600) | - Simple Shear Consolidated Undrained |
| ■ | - "Undisturbed" Sample | (P) | (with or without pore pressure measurement) |
| ☒ | - Bulk or Classification Sample | SSCD 3200 (2600) | - Simple Shear Consolidated Drained |
| ☐ | - Lost Sample | DSCD 2700 (2000) | - Consolidated Drained Direct Shear |
| | | UC 470 | - Unconfined Compression |
| | | LVS 700 | - Laboratory Vane Shear |
| | | TV 800 | - Torvane Shear |
| | | PP 400 | - Pocket Penetrometer |
| | | | (actual reading divided by 2) |



Harding Lawson Associates
Engineering and
Environmental Services

**Soil Classification Chart
and Key to Test Data**
W.R. Grace Dam
Rainy Creek, Montana

PLATE

12

DRAWN AM
JOB NUMBER 5891,053.03

APPROVED

DATE

REVISED DATE

12/91

Relative Density of Coarse-Grained Soils

| Relative Density | Standard Penetration Test Blow Count (blows per foot) |
|---------------------|--|
| very loose | <4 |
| loose | 4 - 10 |
| medium dense | 10 - 30 |
| dense | 30 - 50 |
| very dense | >50 |

Consistency of Fine-Grained Soils

| Consistency | Identification Procedure | Approximate Shear Strength (psf) |
|--------------|---|--|
| Vary soft | Easily penetrated several inches with fist | less than 250 |
| Soft | Easily penetrated several inches with thumb | 250-500 |
| Medium stiff | Penetrated several inches by thumb with moderate effort | 500 - 1000 |
| Stiff | Readily indented by thumb, but penetrated only with great effort | 1000 - 2000 |
| Very Stiff | Readily indented by thumb nail | 2000 - 4000 |
| Hard | Indented with difficulty by thumb nail | greater than 4000 |

Natural Moisture Content *

| | |
|-------------|---|
| Dry - | Requires considerable moisture to obtain optimum moisture content* for compaction |
| Moist - | Near the optimum moisture content for compaction |
| Wet - | Requires drying to obtain optimum moisture content for compaction |
| Saturated - | Near or below the water table, from capillarity, or from perched or ponded water |

* Optimum moisture content as determined in accordance with ASTM Test Method D1557-78.

Where laboratory data are not available, the above field classifications provide a general indication of material properties; the classifications may require modification if laboratory tests are subsequently conducted.



Harding Lawson Associates
Engineering and
Environmental Services

**Physical Properties Criteria
for Soil Classifications**
W.R. Grace Dam
Rainy Creek, Montana

PLATE

13

DRAWN AM JOB NUMBER 5891,053.03

APPROVED *GLW*

DATE 11/91

REVISED DATE

I CONSOLIDATION OF SEDIMENTARY ROCKS; usually determined from unweathered samples. Largely dependent on cementation.

U = unconsolidated
P = poorly consolidated
M = moderately consolidated
W = well consolidated

II BEDDING OF SEDIMENTARY ROCKS

| <u>Splitting Property</u> | <u>Thickness (feet)</u> | <u>Stratification</u> |
|---------------------------|-------------------------|-----------------------|
| Massive | Greater than 4.0 | Vary thick bedded |
| Blocky | 2.0 to 4.0 | Thick bedded |
| Slabby | 0.3 to 2.0 | Thin bedded |
| Flaggy | 0.05 to 0.2 | Very thin bedded |
| Shaly or platy | 0.01 to 0.05 | Laminated |
| Papery | Less than 0.01 | Thinly laminated |

III FRACTURING

| <u>Intensity</u> | <u>Size of Pieces (Feet)</u> |
|------------------------|------------------------------|
| Very little fractured | Greater than 4.0 |
| Occasionally fractured | 1.0 to 4.0 |
| Moderately fractured | 0.5 to 1.0 |
| Closely fractured | 0.1 to 0.5 |
| Intensely fractured | 0.05 to 0.1 |
| Crushed | Less than 0.05 |

IV HARDNESS

1. Soft - Reserves for plastic material alone.
2. Low hardness - Can be gouged deeply or carved easily with a knife blade.
3. Moderately hard - Can be readily scratched by a knife blade; scratch leaves a heavy trace of dust and is readily visible after the powder has been blown away.
4. Hard - Can be scratched with difficulty; scratch produces little powder and is often faintly visible.
5. Very hard - Cannot be scratched with knife blade; leaves a metallic streak.

V STRENGTH

1. Plastic or very low strength.
2. Friable - Crumbles easily by rubbing with fingers.
3. Weak - An unfractured specimen of such material will crumble under light hammer blows.
4. Moderately strong - Specimen will withstand a few heavy hammer blows before breaking.
5. Strong - Specimen will withstand a few heavy ringing hammer blows and will yield with difficulty only dust and small flying fragments.
6. Very strong - Specimen will resist heavy ringing hammer blows and will yield with difficulty only dust and small flying fragments.

VI WEATHERING - The physical and chemical disintegration and decomposition of rocks and minerals by natural processes such as oxidation, reduction, hydration, solution, carbonation, and freezing and thawing.

- D. Deep - Moderate to complete mineral decomposition; extensive disintegration; deep and thorough discoloration; many fractures, all extensively coated or filled with oxides, carbonates, and/or clay or silt.
- M. Moderate - Slight changes or partial decomposition of minerals; little disintegration; cementation little to unaffected; moderate to occasionally intense discoloration; moderately coated fractures.
- L. Little - No megascopic decomposition of minerals; little or no effect on normal cementation; slight and intermittent, or localized discoloration; few stains on fracture surfaces.
- F. Fresh - Unaffected by weathering agents; no disintegration or discoloration; fractures usually less numerous than joints.



ANDESITE,
BASALT,
RHYOLITE



GRAYWACKE



SCHIST



SILTSTONE, MUDSTONE
CLAYSTONE



CHERT



LIMESTONE,
CORAL



SERPENTINE



TUFF



CONGLOMERATE



SANDSTONE



SHALE



PYROXENITE



Harding Lawson Associates
Engineering and
Environmental Services

**Physical Properties Criteria
for Rock Classifications**
W.R. Grace Dam
Rainy Creek, Montana

PLATE

14

DRAWN
AM

JOB NUMBER
5891,053.03

APPROVED
GLW


DATE
11/91

REVISED DATE

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer

3 1 1/2 3/4 3/8 4 8 16 30 40 50 100 200

Reference ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|---------------------------|
| ■ | A-1 • 15.0 FT | GRAY SAND W/ SILT (SW-SM) |




Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

15

| | | | | | |
|-------|-------------|----------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | | 07-15-1991 | | 11/91 |



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|-----------------------------|
| 10 | A-1 @ 25.0 FT | OLIVE-GREEN SILTY SAND (SM) |




Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

16

| | | | | | |
|-------|-------------|----------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | HL | 07-15-1991 | | 11/91 |



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|---|
| □ | A-1 @ 55.0 FT | MOTTLED GRAY-GREEN SAND W/ SILT (SW-SM) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

17

DRAWN

JOB NUMBER
5891.053.03

APPROVED

[Signature]


DATE
07-15-1991

REVISED

DATE
11/91

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer

Reference ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|----------------------------|
| ■ | A-2 @ 50.5 FT | DARK GREEN SILTY SAND (SM) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists


Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

18

| | | | | | |
|-------|-------------|-----------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | <i>EM</i> | 07-15-1991 | | 11/91 |

U.S. Standard Sieve Size (in.) ——— U.S. Standard Sieve Numbers ——— Hydrometer



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|---------------------------------------|
| ■ | A-3 @ 5.0 FT | GREEN SAND W/ SILT AND GRAVEL (SW-SM) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

19

DRAWN

JOB NUMBER
5691.053.03

APPROVED


DATE
07-15-1991

REVISED

DATE
11/91

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer

Reference: ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|--------------------------|
| ■ | A-3 @ 45.5 FT | GRAY SAND W/ GRAVEL (SW) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana


PLATE

20

| | | | | | |
|-------|-------------|--------------------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | <i>[Signature]</i> | 07-15-1991 | | 11/91 |

U.S. Standard Sieve Size (in.) ——— U.S. Standard Sieve Numbers ——— Hydrometer

Reference: ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|-----------------|
| ■ | A-4 • 10.5 FT | BROWN SAND (SP) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE


21

| | | | | | |
|-------|-------------|--------------------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | <i>[Signature]</i> | 07-15-1991 | | 11/91 |

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer

3 1½ ¾ ⅜ 4 8 16 30 40 50 100 200

Reference ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|---------------------------|
| ■ | A-4 @ 11.0 FT | GRAY SAND W/ SILT (SP-SM) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana


PLATE

22

| | | | | | |
|-------|-------------|--------------------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | <i>[Signature]</i> | 07-15-1991 | | 11/91 |

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer

Reference: ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|----------------------|
| ■ | A-5 9 20.5 FT | GRAY SANDY SILT (ML) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists


Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

23

| | | | | | |
|-------|-------------|--------------------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | <i>[Signature]</i> | 07-15-1991 | | 11/91 |

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|------------------------------|
| ■ | A-5 @ 45.7 FT | GRAY SANDY ELASTIC SILT (MH) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

24

DRAWN

JOB NUMBER
5891.053.03

APPROVED

HLA

DATE
07-17-1991


REVISED

DATE
11/91

U.S. Standard Sieve Size (in.) U.S. Standard Sieve Numbers Hydrometer

3 1½ ¾ ⅜ 4 8 16 30 40 50 100 200

Reference: ASTM D 422



| | | | | | | |
|---------|--------|------|--------|--------|------|--------------|
| COBBLES | COARSE | FINE | COARSE | MEDIUM | FINE | SILT OR CLAY |
| | GRAVEL | | SAND | | | |

| Symbol | Sample Source | Classification |
|--------|---------------|---------------------------------|
| A | A-9 @ 9.0 FT | BROWN SILTY SAND W/ GRAVEL (SM) |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Particle Size Analysis
W.R. Grace Dam
Rainy Creek, Montana

PLATE

25

DRAWN

JOB NUMBER
5891.053.03


APPROVED

[Signature]

DATE
07-15-1991

REVISED

DATE
11/91



| SYMBOL | BORING NUMBER | DEPTH (feet) | CLASSIFICATION | LL (%) | PL (%) | PI (%) | MOISTURE CONTENT (%) |
|------------------------------------|---------------|--------------|---------------------------------------|--------|--------|--------|----------------------|
| □ | A-1 | 16.7 | GRAY ELASTIC SILT W/ SAND (MH) | 60 | 52 | 8 | 71.1 |
| | A-1 | 35.5 | OLIVE-GREEN SILTY SAND (SM) | NP* | NP | NP | |
| ▽ | A-2 | 25.2 | OLIVE-GREEN ELASTIC SILT W/ SAND (MH) | 51 | 41 | 10 | 63.2 |
| ◇ | A-2 | 46.0 | OLIVE-GREEN SANDY ELASTIC SILT (MH) | 71 | 44 | 27 | 60.4 |
| + | A-3 | 36.5 | BLUE-GREEN ELASTIC SILT (MH) | 69 | 44 | 25 | 64.0 |
| * NGN PLASTIC - NOT SHOWN ON CHART | | | | | | | |



Harding Lawson Associates
Engineering and
Environmental Services

Plasticity Chart
W.R. Grace Dam
Rainy Creek, Montana

PLATE

26

DRAWN

JOB NUMBER
5B91.053.03

APPROVED


[Signature]

DATE
07-15-1991

REVISED

DATE
11/91

DEVIATOR STRESS (ksf)



AXIAL STRAIN (percent)

| | | | |
|---|------------------|----------------------------|-------------------|
| SPECIMEN TYPE UNDISTURBED | | SHEAR STRENGTH 312 paf | |
| DIAMETER (in) 2.67 | HEIGHT (in) 6.00 | STRAIN AT FAILURE 7.0 % | |
| MOISTURE CONTENT 71.1 % | | CONFINING PRESSURE 450 psf | |
| DRY DENSITY 56 pcf | | STRAIN RATE 0.60 %/min | |
| CLASSIFICATION GRAY ELASTIC SILT W/ SAND (MH) | | | SOURCEA-1 @ 16.7' |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Unconsolidated - Undrained
Triaxial Compression Test Report
W.R. Grace Dam
Rainy Creek, Montana

PLATE

27

DRAWN

JOB NUMBER
5891.053.03

APPROVED


[Signature]

DATE
07-12-1991

REVISED

DATE
11/91

DEVIATOR STRESS (ksf)



AXIAL STRAIN (percent)

| | | | |
|--|------------------|------------------------|-------------------|
| SPECIMEN TYPE UNDISTURBED | | SHEAR STRENGTH 382 psf | |
| DIAMETER (in) 2.87 | HEIGHT (in) 6.00 | STRAIN AT FAILURE 10.3 | % |
| MOISTURE CONTENT 63.2 | % | CONFINING PRESSURE 500 | psf |
| DRY DENSITY 62 | pcf | STRAIN RATE 0.60 | %/min |
| CLASSIFICATION OLIVE-GREEN ELASTIC SILT W/ SAND (MH) | | | SOURCEA-S 9 25.2' |




Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Unconsolidated - Undrained
Triaxial Compression Test Report
W.R. Grace Dam
Rainy Creek, Montana

PLATE

28

| | | | | | |
|-------|-------------|----------|------------|---------|-------|
| DRAWN | JOB NUMBER | APPROVED | DATE | REVISED | DATE |
| | 5891.053.03 | EM | 07-12-1991 | | 11/91 |



| | | | |
|--|------------------|----------------------------|-------------------|
| SPECIMEN TYPE UNDISTURBED | | SHEAR STRENGTH 946 psf | |
| DIAMETER (in) 2.87 | HEIGHT (in) 5.70 | STRAIN AT FAILURE 8.6 % | |
| MOISTURE CONTENT 60.4 % | | CONFINING PRESSURE 800 psf | |
| DRY DENSITY 64 pcf | | STRAIN RATE 0.60 %/min | |
| CLASSIFICATION OLIVE-GREEN SANDY ELASTIC SILT (MH) | | | SOURCEA-S @ 46.0' |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Unconsolidated - Undrained
Triaxial Compression Test Report
W.R. Grace Dam
Rainy Creek, Montana

PLATE

29

DRAWN


JOB NUMBER
5691.053.03

APPROVED
EHL

DATE
07-12-1991

REVISED

DATE
11/91



| | | | | | |
|------------------|------------------------------|-------------|--------------------|-------------------|-------|
| SPECIMEN TYPE | UNDISTURBED | | SHEAR STRENGTH | 1005 | psf |
| DIAMETER (in) | 2.85 | HEIGHT (in) | 6.00 | STRAIN AT FAILURE | 7.3 % |
| MOISTURE CONTENT | 64.0 | % | CONFINING PRESSURE | 750 | psf |
| DRY DENSITY | 62 | pcf | STRAIN RATE | 0.50 | %/min |
| CLASSIFICATION | BLUE-GREEN ELASTIC SILT (MH) | | | SOURCEA-S @ | 36.8' |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Unconsolidated - Undrained
Triaxial Compression Test Report
W.R. Grace Dam
Rainy Creek, Montana

PLATE

30

DRAWN

JOB NUMBER
8681.069.03

APPROVED

RM

DATE
07-12-1991


REVISED

DATE
11/91

PRESSURE (ksf)

VOID RATIO, e

O_v
 $cm^2/sec \times 10^{-3}$



Reference: ABTN D-2420

| SPECIMEN TYPE | | | | BEFORE TEST | | | | AFTER TEST | |
|---|------|---------------|------|------------------|------------|--------|------------------|------------|--|
| TRIMMED | | | | | | | | | |
| DIAMETER (in) | 2.43 | HEIGHT (in) | 0.00 | MOISTURE CONTENT | w_o | 67.1 % | w_f | 49.0 % | |
| OVERBURDEN PRESSURE, O_{vo}' | | | | VOID RATIO | e_o | 1.68 | e_f | 1.27 | |
| PRECONSOL PRESSURE, $(d_{vo}')_{max}$ | | | | SATURATION | S_o | 100 % | S_f | 100 % | |
| COMPRESSION INDEX, C_c | | | | DRY DENSITY | γ_d | 89 pcf | γ_d | 81 pcf | |
| LIQUID LIMIT | --- | PLASTIC LIMIT | --- | PLASTICITY INDEX | --- | | SPECIFIC GRAVITY | 2.06 | |
| CLASSIFICATION OLIVE GREEN SANDY ELASTIC SILT (MH) SOURCE A-2 @ 48.7 FT | | | | | | | | | |



Harding Lawson Associates
Engineers, Geologists
& Geophysicists

Consolidation Test Report
W.R. Grace Dam
Rainy Creek, Montana

PLATE

31

DRAWN

JOB NUMBER
8891.069.03

APPROVED

ETH

DATE


07-24-1991

REVISED

DATE

11/91

| | |
|-------------------------------------|-----|
| MAXIMUM DRY DENSITY (pcf) | 144 |
| CORRECTED MAXIMUM DRY DENSITY (pcf) | 144 |
| OPTIMUM WATER CONTENT (%) | 7.9 |



Reference: ASTM D-1557

| | 1 | 2 | 3 | 4 |
|---|------------------------------|-----|--------------------|-----|
| MOISTURE CONTENT (%) | 4.1 | 6.2 | 7.9 | 9.8 |
| DRY DENSITY (pcf) | 143 | 143 | 144 | 139 |
| % PASSING #100 100.0 | SPECIFIC GRAVITY (g/cc) 2.70 | | MOLD DIAMETER 6.00 | |
| CLASSIFICATION BRN SAND W/ SILT & GRVL (SP-SM) SOURCE BULK @ 0.0 FT | | | | |



Harding Lawson Associates
Engineers and Geoscientists

Compaction Test Report
W.R. Grace Dam
Rainy Creek, Montana

PLATE

32

DRAWN

JOB NUMBER
5691.053.03


APPROVED

PS

DATE
07-17-1991

REVISED


DATE
11/91



EXPLANATION

- Qal - Mainly valley fill consisting of silt, sand and gravel
- Qg - Glacial drift; morainal and outwash plain deposits of mountain glaciers (Quaternary)
- pCm - Missoula Group, chiefly red, maroon or purple argillite, sandy or quartzitic argillite, and generally impure quartzite and limestone (Pre-Cambrian)
- pCw - Wallace Formation; dark gray argillite, arenaceous and argillaceous limestone and gray limy quartzite with shale and sandstone in large areas (Pre-Cambrian)

- Geologic boundary
Dashed where approximately located
- Geologic boundary indicated by the compilers on the basis of incomplete data
- Fault, character not designated
Dashed where approximately located
- Concealed fault
- Thrust fault
T, upper plate
- Fault indicated by the compilers on the basis of incomplete data



Reference: Geologic Map of Montana prepared by Ross, Andrews and Wilkind (in cooperation with Montana Bureau of Mines and Geology), dated 1955.





Harding Lawson Associates
Engineering and
Environmental Services

Geologic Map of Site and Vicinity
W.R. Grace Dam
Rainy Creek, Montana

PLATE
33

DRAWN AM
JOB NUMBER 5891,053.03

APPROVED DATE 2/92
REVISED DATE



Case I, II: Stability Analysis - Water at 500 feet from Embankment ($C' = 500$ psf)

Sheet 1 of 2



Harding Lawson Associates
Engineering and
Environmental Services

Analytical Model and
Soil Properties
W.R. Grace Dam
Rainy Creek, Montana

PLATE



34a

DRAWN AM JOB NUMBER 5891,053.03

APPROVED GLW

DATE 11/91

REVISED DATE



Case I, II: Stability Analysis - Water at 500 feet from Embankment ($C' = 50 \text{ psf}$)

Sheet 2 of 2



Harding Lawson Associates
 Engineering and
 Environmental Services

Analytical Model and
 Soil Properties
 W.R. Grace Dam
 Rainy Creek, Montana

PLATE



34b

DRAWN AM JOB NUMBER 5891.053.03

APPROVED GLW

DATE 11/91

REVISED DATE



Case III, IV: Stability Analysis - Water at Face of Embankment ($C' = 500$ psf)

Sheet 1 of 2

PLATE



Harding Lawson Associates
Engineering and
Environmental Services

Analytical Model and
Soil Properties
W.R. Grace Dam
Rainy Creek, Montana

DRAWN
AM



JOB NUMBER
5891,053.03

APPROVED
GLW

DATE
11/91

REVISED DATE

35a



0 70
Scale in Feet

Case III, IV: Stability Analysis - Water at Face of Embankment ($C' = 50$ psf)

Sheet 2 of 2



Harding Lawson Associates
Engineering and
Environmental Services

Analytical Model and
Soil Properties
W.R. Grace Dam
Rainy Creek, Montana

PLATE


35b

DRAWN AM JOB NUMBER 5891.053.03

APPROVED GLW

DATE 11/91

REVISED DATE



135398



Herdling Lawson Associates
Engineering and
Environmental Services

DRAWN
AM

JOB NUMBER
5891.053.03

**Schematic Section of
Proposed Drainage/Monitoring System
W.R. Grace Dam
Rainy Creek, Montana**

APPROVED
GLW

DATE
11/91

REVISED DATE

PLATE
36

DISTRIBUTION

3 copies: W. R. Grace & Company
 Construction Products Division
 P.O. Box 609
 Libby Montana 59923
 Attention: Mr. Alan Stringer

GLW/mfb/Bi2703-R71

QUALITY CONTROL REVIEWER

Donald Bruggers for
Keith H. Bergman
Geotechnical Engineer



Schafer & Associates
P.O. Box 6186
Bozeman, MT 59715
(406) 587-3478

Waste Management
Land Reclamation
Resource Inventory
Agricultural Consulting

May 22, 1992

Mr. Alan R. Stringer
General Manager
Construction Products Division
W.R. Grace & Co.
P.O. Box 609
Libby, MT 59923-0609

RE: Responses to W.R. Grace Closure Plan - First Review

Dear Mr. Stringer:

The following are responses to questions regarding the tailings impoundment closure plan put forth in DSL's letter to you dated May 8, 1992 (Certified Mail No. P 676 686 599). They also incorporate some of the discussion on these items which took place in a meeting conducted in DSL's offices on May 19, 1992. Responses to Items 13 and 14 were provided by Harding Lawson Associates and relate to issues in their report on the stability of the tailings impoundment dam. All others relate to the conceptual flood routing design in the report prepared by Schafer and Associates.

Item 1. The percent of ground cover does not affect the runoff calculations for the PMF event, which is the primary concern for this site. The proposed system is designed to handle flows in excess of 0.5 PMF which is an order of magnitude greater than a 100 year event.

Changing the percent of ground cover from >75% to something less (60 to 70%) will have only a minor effect on the peak flows for 100 year events, which are expected to remain less than the designed control structure outflows.

Item 2. The excavated material referred to on page 4-13 of the Schafer and Associates report is for the emergency spillway construction only. Approximately 2,400 cubic yards of material will be excavated to construct the emergency spillway on the west abutment. The excavated material is proposed to be placed in the groin of the west abutment to provide additional protection. The material will

be placed with standard earthmoving equipment and compacted. The existing dam face in this area will be prepared by stripping existing vegetation and keying new material into the existing materials in the dam face to improve stability. Should concerns over placement and stability remain, an alternate location will be selected to spoil the excavated material.

In the meeting with DSL on May 19th, it was determined that this question related to materials excavated from the outlet channel (hence, the reference to Plate 15). Materials excavated from this area will be used to construct the downhill slope of the outlet channel and to reinforce the area of the outlet channel where water is turned to cascade down to the valley floor.

Item 3. The decant tower pipeline will be plugged with concrete during closure. W.R. Grace has previously plugged a decant tower pipeline by pumping grout into the discharge end of the pipeline until the entire line is filled. This procedure was effective and will be used again.

Item 4. To maintain the water surface away from the face of the dam, it is necessary to construct the inlet channel as shown on Plate 8, with an inflow elevation of (approximately) 2904', and a gradient of 0.38%. To steepen the gradient would require a shorter channel which in turn would cause the water surface to be maintained closer to the face of the dam.

An alternative to lower the elevation of the control structure (within the dam) was reviewed and discarded due to the increased excavation required to construct the inflow channel, control structure, and outflow channel.

Sedimentation of material in the inlet channel is not anticipated to pose a significant problem. Initially, the majority of stream sedimentation is expected to occur in the wetland system upstream of the inflow channel where flow velocities are negligible. Should a minor amount of material settle in the inlet channel during periods of low flows, increased flow velocities during peak events will most likely clean the channel because these will be relatively fine materials. Over the years, the wetland may begin to accumulate sediment at the upper end of the impoundment (See also Items 11 and 15). Under these conditions the sedimentation may, over geologic time, extend into the upper portion of inlet channel but the result will be for the stream to establish a naturally stable gradient in materials washed out of Upper Rainy Creek and Fleetwood Creek leading to the outlet structure at 2900' through the constructed inlet channel.

The model used to calculate the inlet channel velocity of 5.5 fps is located toward the end of Appendix D.

Item 5. Fleetwood Creek will be restored to a channel constructed in natural material adjacent to the toe of the coarse tailings dump. This channel will be built to

handle a 100 year storm event in accordance with DSL's reclamation guidelines. We anticipate using existing streambed materials, which are quite coarse materials, to armor the toe of the coarse tailings. Two or three small ponds currently exist along this stretch of Fleetwood Creek. We would leave these ponds as they are. Details of the channel will be forthcoming with the final design.

Item 6. We do not anticipate that infiltration from a localized area near the toe of the impoundment would produce significant stability problems for the dam. However, an impermeable channel liner constructed of either HDPE or clay, extending to a suitable distance from the face of the dam (approximately 500 feet) could be incorporated into the final design. W.R. Grace is amenable to this as an element of the final inlet channel design.

Item 7. The interface between the inlet channel and the control structure will be heavily armored with a layer of rock rip-rap. We also intend to incorporate design features in the outlet structure to protect against the possibility of channeling between the structure itself and the soil materials next to it. Details will be forthcoming with the final design.

Item 8. Following excavation, the control structure will be placed, properly bedded, and the excavation backfilled with the original material. The backfill will be placed in proper lifts (12" maximum) and compacted to a density that meets or exceeds the original specifications used during the construction of the dam. A primary concern for the design of the outlet structure will be to protect against differential settlement. We will need to characterize the underlying materials carefully to do this. Ideally, it will be possible to construct the outlet control structure in such a way that it rests entirely on bedrock. If this is not possible, a suitable design can be made with the structure resting entirely on the compacted dam materials. Details, sections, and specifications will be provided with the final design.

Item 9. The drop structures will be constructed (and anchored) to the specifications recommended by the SCS. This may include keying into bedrock, doweling, or other methods deemed necessary to provide a long-term structure. Details, sections, and specifications will be provided with the final design.

Item 10. The outlet channel will be designed for long-term geotechnical stability and we will give serious attention to the concern addressed by this question during final design. Our intent is to utilize bedrock foundation to the extent possible without creating unnecessarily large sidehill cuts. The bottom of the channel will be slightly sloped to the inside of the cut to keep the normal stream flow on bedrock materials thereby preventing infiltration losses.

It is not uncommon to construct sidehill access roads on soil materials. The existing roadway which can be seen on Plate 15 (but is not identified as a

road) is constructed on soils. The new road will not receive heavy traffic and is amply protected against erosion by the large channel between it and the sidehill. Also, excavated materials will be placed on the sidehill in benches which are keyed into existing materials in order to promote stability. These are factors which will help to maintain its integrity over the years.

Item 11.

It is not likely that the impoundment will ever fill entirely with sediment. The outlet at 2900' elevation will be maintained as the only outlet for stream flow. Because of this, as sedimentation begins to fill the wetland area, the tendency will be for Rainy Creek to cut a natural stream channel in the sediment materials at the upper end of the impoundment and flow into the inlet channel which we are constructing in the tailings materials. The question raised in Item 4 and our response to it are pertinent to this situation.

Also, we do not feel that a full PMF design criteria is appropriate. For example, in the Record of Decision for the impoundment dams at the Wann Springs Pond Operable Unit for the Silver Bow Creek/Butte Area NPL Site, the dam is designed and permitted for a 0.5 PMF event. We consider this to be an even more critical situation since this impoundment contains materials which are classified as hazardous. The criteria for this facility design were apparently set by EPA and DNRC. Comments by the Dam Safety Bureau on this issue would be appropriate.

Item 12.

A system to control trash and debris will be included in the final design. It is anticipated that the general design approach will incorporate two sets of "pile fences" set across the inlet channel, one being immediately upstream of the inlet to the control structure and the other being a distance upstream. The pile fences are expected to intercept and divert the larger debris, while allowing the smaller pieces to pass. The control structure and drop structures are expected to pass the smaller pieces without problems arising.

It is not recommended to install a grate or other "smaller" debris capturing device over the entrance to the control structure. These tend to plug easily and are difficult (or impossible when inundated) to clean.

Debris collection devices are not considered necessary for the drop structures, and are not proposed.

Maintenance of the debris control devices will be part of the proposed maintenance plan.

Item 13.

We concur with DSL's conclusion that the actual distance of the O'Brien Creek fault from the mine site is 13 miles (21 km) and not 13 km. We also agree that this error in our analysis resulted in a conservative estimate of ground motion associated with a magnitude 7 event on the O'Brien Creek fault. We will correct this error and revise the report accordingly.


With regard to the potential for seismic activity on the Rainy Creek fault, according to our conversation with Mr. Mike Stickney of the Montana Bureau of Mines and Geology (MBMG), there is insufficient evidence of either Holocene (last 11,000 years) or Quaternary (last 2 to 3 million years) activity on this fault in our seismic analysis. Our seismic design criteria considers the occurrence of a magnitude 5.5 event at a very close distance to the site, resulting in a peak ground acceleration (PGA) of 0.30 gravity (g). We believe that a PGA of 0.30g conservatively envelopes expected seismic activity at this site under the presently known tectonic framework.

~~Item 14.~~ We propose to monitor the location of the phreatic surface within the embankment by installing six additional piezometers in the downstream face of the dam. Three piezometers will be installed near the toe of the dam, with one lined-up against the existing piezometer P-2 (please refer to the Harding Lawson Associates report for the location of the six existing piezometers); two piezometers will be installed near the existing drainage pipe to monitor possible long-term leakage from this system; and one piezometer will be installed near the proposed outlet channel. We judge that a periodic monitoring of these twelve piezometers will enable us to detect any change in the phreatic surface. Remedial actions such as those presented in our geotechnical report dated February 3, 1992 will be taken, should the phreatic surface approach unacceptable levels.

Item 15. Again, we do not feel that a full PMF is appropriate as a design basis within the criteria set forth by the Dam Safety Bureau (See Item 11). A spillway to accommodate a full PMF is technically feasible; however, it would entail large sidehill cuts on the west side of the tailings dam and relocation of the Forest Service road.

If we can be of further assistance in addressing these issues, please call.

Sincerely,

A handwritten signature in dark ink, appearing to read "T. J. Hudson", written over a horizontal line.

Thomas J. Hudson
Project Manager

A3-Reference 6

GRACE

Construction Products Division

TO: R. M. Vining

DATE: December 1, 1981

FROM: J. W. Wolter

SUBJECT: Libby Impoundment Dam

cc: O. M. Favorito

W. J. McCaid ~~Libby~~

R. E. Schneider

E. S. Wood

Under the authority of Public Law 92-367, an engineering firm, Morrison-Maierle, Inc., inspected our impoundment dam on July 25, 1980 and again on August 13, 1981. A report titled "Rainy Creek Basin - Zonolite Tailings Dam" was issued by Morrison-Maierle in September 1981 and approved by the Corps of Engineers, Department of the Army.

The comprehensive engineering report was based on events resulting from a "100-year flood". This hypothetical event is considered as the probable maximum flood (PMF) and is the resultant from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The PMF is based on a July to August thunderstorm that produces 6" of rain in one hour and 8" of rain in six hours. This flood is also based on a 100-year, 24-hour antecedent storm of 3.4" as outlined from the National Oceanic and Atmospheric Administration (NOAA). This antecedent storm produced .3" of run-off prior to the PMF storm. Further conservatism assumes that the diversion structure on Rainy Creek had failed, allowing the entire run-off from Rainy Creek to join Fleetwood Creek and enter the reservoir.

This combination of events would result in the dam overtopping during the PMF when approximately 55% total flood volume enters the reservoir. The flood subsequently would occur downstream as a result of overtopping of the dam. The aforementioned PMF produces an estimated 3,770 acre feet of water. Since the reservoir is 68.5 acres in size and contains less than five (5) feet of water, the total water normally behind the dam is less than nine percent of postulated PMF.

This PMF essentially generates 43,400 cubic feet per second (cfs) of flow from the 9.7 sq. mile basin. To put this in perspective, the average uncontrolled water flow in the Kootenai River for 52 years (prior to construction of the Libby dam) on record is for July at 30,000 cfs, August for 13,000 cfs and September at 17,000 cfs. Or looking at it in another way, this flood would be 45% greater than the average uncontrolled flow

during the month of July in the Kootenai River. The maximum flow of water on record at Libby in the Kootenai River was 121,000 cfs in the year 1916. This flow was generated from 9,900 sq. miles of drainage in the U.S. and Canada.

Findings and conclusions included in the report which is based on criteria developed for the U.S. Army Corps of Engineers under their "guidelines for safety inspection of dams" results in the dam being classified as Category I, having a "high downstream hazard potential". Their findings state "the dam is located such that its failure could endanger more than a few lives and cause excessive economic loss".

We disagree with these findings and have included in our objections to the Corps a letter from Lyle Lewis, a professional engineer with the engineering firm of Harding and Lawson Associates, stating the following: "It is our opinion that the downstream hazard should be classified as low or moderate". Further statements from Mr. Lewis include: "For three miles below the dam, in Rainy Creek Valley, there is nothing but the oiled roadway".

In a draft document sent to the Mine Safety and Health Administration (MSHA), indications were given that "failure could endanger many lives and cause excessive economic loss". This draft document resulted in a critical response from MSHA and is included as an exhibit in the Corps of Engineers final report. In order to mitigate this unreasonable interpretation, the Corps of Engineers has prepared a memo for MSHA indicating that the only potential damage referred to in the report was to the facilities owned by Grace and that an acceptable monitoring and evacuation plan of the Grace facilities would prevent severe losses or risks to Grace personnel. A copy of this clarification memo from Colonel Leon K. Morashi, the District Engineer for the Corps of Engineers, is attached as Exhibit 2.

Recommendations from this report and our implementation plans are as follows:

1. Immediately develop, implement and periodically test an emergency warning plan for use in the event of impending embankment overtopping for structural failure.
 - This emergency warning plan is being implemented. A copy of the first draft of this plan is attached as Exhibit 1.
2. Periodically test the decant line in the section which passes through the embankment for possible leaks which could threaten the embankment.

This procedure has been in effect and we have retained the services of Harding and Lawson as our consultant engineering firm for both construction and maintenance on this facility.

3. Conduct more detailed hydrologic and hydraulic routings to better determine the downstream hazard potential and to establish a safe minimum flood storage volume and spill requirement.

Lyle Lewis, consulting engineer for Harding and Lawson, has been given the assignment to work with Libby Engineering and develop the details requested.

4. Continue to conduct inspections of the dam on an annual basis by engineers experienced in dam design and construction, continue to monitor and evaluate piezometers, foundations, toe drains and maintain construction log of all additions and modifications to the project.

This procedure has been in effect and utilizes the engineering services of Harding and Lawson.

The PMF as stipulated by the Corps of Engineers utilizing their computer program HEC-1 would result in the dam overtopping after 55% of the flood water entered the ponded area. Since the probable maximum precipitation (PMP) would generate a peak flow of 43,400 cfs and a volume of 3,770 acre feet, the present spillway is inadequate to withstand this surge. The resultant would possibly lead to a breach in the dam that could wash up to 125,000 cu. yds. of dam, slimes and coarse tailings from the impoundment area. This is about 6.6% of the total 1,880,000 cu. yds. of material presently stored above the dam. While the majority of this material will form a delta immediately below the dam, the slimes and finest fractions would continue down stream. It is postulated that 25,000-30,000 cu. yds. could reach the Kootenai River or about 1.5% of the stored material.

Harding and Lawson concurs with our local management that an antecedent storm followed by a 6" storm in one hour is unreasonably conservative for the Libby area. We will, therefore, attempt to persuade the Corps of Engineers to revise the PMF based on reliable meteorologic and hydrologic data. This data will be gathered and presented to the Corps of Engineers by Harding and Lawson under the supervision of CPD.

In the event that Harding and Lawson determines, after thoroughly evaluating hydrologic and meteorologic data, that conditions leading to a PMF are realistic or if they are unable to convince the Corps of Engineers that conditions leading to a PMF are unreasonable, the following actions will be taken:

1. A decision will be made to determine the most economic and technologically safe method to control a PMF.
2. The Corps of Engineers will be consulted to their concurrence as to the method or methods recommended.


December 1, 1981

3. A schedule for implementation will be presented to CPD and Grace management for spending authorization.

At this time it would appear that a concrete spillway costing approximately \$150,000 would adequately handle a PMF. Alternative controls considered for a PMF included:

1. Constructing an aquaduct capable of diverting all water around the dam and costing \$2.4 million.
2. Maintaining the dam at levels capable of holding the full 3,770 acre feet of water behind the dam at a cost of \$1.7 million.

If the Harding and Lawson studies support a lesser PMF (and the Corps of Engineers concurs), it is likely that the existing spillway will prove adequate or, at most, a modestly improved spillway will be sufficient at costs of less than \$20,000.



Jack W. Wolter

JWW:dlc
Attachments

A3-Reference 7

DEPARTMENT OF NATURAL RESOURCES
AND CONSERVATION

WATER RESOURCES DIVISION • 1424 Ninth Avenue, Helena, MT 59601
(406) 444-6601 Telefax (406) 444-0533

BRIAN SCHWEITZER, GOVERNOR



STATE OF MONTANA

DIRECTOR'S OFFICE (406) 444-2074
FAX: (406) 444-2684

FO BOX 201601
HELENA, MONTANA 59620-1601

MEMO

To: Tim Davis, WRD Administrator; Laurence Siroky, WOB Bureau Chief

From: Michele Lemieux, P.E. Montana Dam Safety Program Manager

Date: Tuesday, February 01, 2011

Re: Seismic Hazard Assessment – Flower Creek Dam

The purpose of this memo is to provide a cursory assessment of the seismic hazard at Flower Creek Dam. This assessment includes an estimate of ground shaking that could occur from hypothetical earthquakes in the area, as well as a determination of the probability of these various seismic events occurring.

Estimate of Ground Shaking from Hypothetical Earthquakes

Figure #1 shows distribution and magnitude of recent earthquakes and mapped faults in the vicinity of Libby, Mt (Source: Wong, et al, 2005). Figure #1 also shows the estimated peak ground acceleration at the base of Flower Creek Dam from various hypothetical events calculated using the DNRC MTShake Ground Shaking Estimation Program (Wong, 2008). Peak ground acceleration (PGA) is a seismic parameter commonly used to assess severity of ground shaking. PGA is reported as a fraction of the gravitational constant g . For reference, 0.01 g could cause broken dishes and windows; 0.15 g can cause heavy furniture to be overturned; 0.32 g can cause buildings to shift off of their foundation while 0.7 g can destroy well built wooden structures (Richter, 1958). Hypothetical events were divided into two categories: Those that may occur along regional mapped faults with geologically recent activity and those on unmapped or "blind faults" in the vicinity of Libby.

Large events on the *Savage Lake*, *Bull Lake*, *Swan* or *Nyack* faults cause only *minimal* ground shaking at Flower Creek Dam (PGA = 0.08 g). To verify results calculated by the MTShake program, a check was run by Ivan Wong of URS Corporation using the latest methodology for the closest fault (Savage Lake Fault, 18km distance). The average peak ground acceleration at the dam site using the new methods was calculated to be 0.11 g . The URS calculations and related technical information are included in Appendix A.

Not all faults are mapped. Glaciation during the last ice age and dense forest cover tends to obscure surface manifestations of fault movement. Conventional thinking is that blind fault earthquakes do not have magnitudes that exceed 6.5. The logic behind this assumption is that if a fault is capable of producing a magnitude 7 or greater earthquake, there is generally some surface manifestation of the fault. That said, it is possible that unmapped faults capable of generating a magnitude 7 or greater earthquake could be present. The magnitude 7.0 earthquake in Haiti occurred on a fault which had minimal surface expression. Assuming that the maximum magnitude of a blind fault earthquake in close proximity to the dam is 6.5, the peak horizontal acceleration at the dam would be 0.23g.

For reference, the DNRC seismic response procedure (DNRC, 2008) takes seriously any event over 0.2g. Immediate inspection is required for *any* dam that experiences ground accelerations at this level. Damage (cracking, foundation movement) can occur. However, historically, much higher accelerations are needed to cause catastrophic failure of a dam.

As discussed in the recent coring report on Flower Creek Dam (NTL Engineering, 2010), the poor condition of the concrete could result in damage and/or failure at accelerations of 0.16g or higher. Thus, it can be concluded that a magnitude 6.5 earthquake on a blind fault in the vicinity of Libby could cause ground shaking sufficient to damage or fail Flower Creek dam. Note that it is typical for accelerations at the top of the dam to be significantly amplified as compared to the dam foundation. Evaluating the amplification effects of a structure requires a complex analysis.

Seismic Event Probability

Figure#2 illustrates the 2% probability of exceedance in 50 years for the peak ground acceleration in the Libby area (Wong et al, 2005). This is equivalent to a 2500 year return period. The range in acceleration values in the Libby area is partially attributed to the presence of alluvium along the major river valleys, which can amplify ground motions. Flower Creek dam is located on Precambrian bedrock. Bedrock does not amplify ground motions in the same manner as alluvium. Available data indicate that there is a 2% probability in 50 years that Flower Creek Dam will see a seismic event that causes ground motions of 0.1g.

Figure #3 illustrates the 1% probability of exceedance in 50 years for the peak ground acceleration in the Libby area. This is equivalent to the 5000 year return period. Figure 3 shows that there is a 1% probability in 50 years that Flower Creek Dam will see a seismic event that causes ground motions of 0.2g. As mentioned above, preliminary studies indicate that ground motions of 0.2g can damage or fail the dam. Thus, it can be concluded that there is a 1% probability in 50 years that Flower Creek Dam will experience a seismic event that will damage or fail the dam.

For reference, the State of Utah standard is the 5000 year return period for high hazard dams and the 2500 year return period for significant hazard dams. Large federal dams are required to design their structures to withstand much larger quakes (10,000 year to 50,000 year return intervals).

The DNRC Dam Safety Program is in the process of adopting a seismic standard. For dams with significant downstream hazards (such as Flower Creek Dam), the 5000 year return period will likely be

the standard. For dams with lower levels of risk, the 2500 year return period will apply. The Flower Creek Dam should be designed at a minimum to withstand an earthquake that generates a ground shaking of 0.2g (the 5000 year event). As mentioned above, recent engineering analysis questions the dam's ability to withstand a ground shaking of 0.2g. Thus it can be assumed with the knowledge we have to date that Flower Creek Dam does not meet the proposed Montana dam seismic standard.

Mike Stickney with the earthquake studies office conducted an independent assessment of the average return period of earthquakes in the Libby area according to magnitude. Mike concluded that that an earthquake with a magnitude of 5.0 might occur within 65 km of Libby once in a 49-year period and that a magnitude 6.0 earthquake might occur once in a 226-year period. Details of Mike's analysis and a discussion on the assumptions involved are contained in Appendix A.

Summary

- A large earthquake (magnitude 7+) on nearby mapped faults will likely not generate high enough ground shaking at Flower Creek Dam to cause damage or failure. The likelihood of experiencing an earthquake of this magnitude on these nearby faults is extremely remote.
- A magnitude 6.5 earthquake on a blind fault in the vicinity of Libby could cause ground shaking sufficient to damage or fail Flower Creek dam. There is a 1% chance in 50 years that Flower Creek Dam will experience this level of ground shaking.
- Flower Creek Dam does not appear to meet the State's proposed seismic design standard.
- Based on recent earthquake records, it can be concluded that a magnitude 6.0 earthquake might occur within 65km of Libby once in a 226-year period.

References


Wong, et al., 2005, Probabilistic Earthquake Hazard Maps for the State of Montana, MBMG Publication 117

NTL Engineering, 2010, Geotechnical Engineering Report, Phase II Geotechnical Investigation of Flower Creek Dam

Wong and Wright, (2008) MTShake Users Manual

DNRC Earthquake Response Guidelines (2008)


Seismicity Near Flower Creek Dam



2% Probability of Exceedance in 50 Years
Peak Horizontal Acceleration (g) at the Ground Surface

~ 2500 year Return
Interval

Peak Horizontal Acceleration (g)



MBMG Publication XXX


Probabilistic Earthquake Ground Shaking Maps for the State of Montana

by
Ivan Wong, Susan Olig, Mark Dober,
Douglas Wright, Eliza Nemser, David Lageson,
Walter Silva, Michael Stickney, Michele Lemieux
and Larry Anderson

2005

**1% Probability of Exceedance in 50 Years
Peak Horizontal Acceleration (g) at the Ground Surface**

~ 5000 year Return
Interval



Appendix A

Technical Data and Discussions

Hello Ivan:

I have been getting quite a few inquiries about seismic hazards in NW Montana and their relationship to the Flower Creek Dam. I know that Michele has been receiving information from you on this topic and has been copying me with your replies.

I was surprised to hear that a M 7 earthquake only 18 km from the dam site would produce only 0.11 g. This must be at a specific period. The curves on the graphs you have sent certainly peak at values above 0.2 g. I presume that a concrete arch dam would have a fairly low natural period (several seconds?). Can you clarify what spectral frequency your values apply to. I guess the fundamental question is: would an M 7 earthquake on the Savage Lake fault generate more than 0.16 g in the frequency range of importance to the dam?

Thank you so much for any clarification.

-Mike

Michael Stickney, Director
Earthquake Studies Office
Montana Bureau of Mines and Geology
Montana Tech of the University of Montana
1300 W Park St
Butte, MT 59701

(406) 496-4332 Voice
(406) 496-4451 Fax
mstickney@mtech.edu
<http://mbmgquake.mtech.edu>

From: Ivan_Wong@URSCorp.com
To: [Stickney, Mike](#)
Cc: [Lemieux, Michele](#)
Subject: Re: PGA at Flower Creek Dam, Montana
Date: Thursday, January 20, 2011 11:44:58 AM

Howdy Mike, hope you're doing well! Yup it is surprising that the PGA is that low but there are several factors going on. First the spectra were computed using the new NGA ground motion models which as you've heard, have lowered the ground motions for events of $M > 7$ particularly at short periods i.e., PGA. So if you look at the plot that I think Michele sent you, the average PGA is 0.11 g. PGA is defined at 0.01 sec period (100 Hz) so its the value on the far left. The site is reportedly hard rock so we have used a high Vs30 of 1500 m/sec. The NGA models are capped at this value. This Vs30 was a guess on our part. It could be lower but we don't have any data. The damsite is in the footwall in contrast to the hanging wall so most of the radiated energy is going away from the damsite. Finally all the NGA developers have normal faulting giving lower ground motions than strike-slip and reverse by about 20%.

I don't know what the natural period of Flower Creek Dam is but if its a concrete arch, then I would expect is rather stiff and its period is a few tenths of second. Don't know.

Hope this helps. Get back to me with more questions. Michele says she's hired one of dam engineers in Denver to help evaluate the dam. We'll know more. I'm sure I'll get roped into the evaluation.

ivan

Ivan G. Wong
Principal Seismologist/Vice-President
Manager, Seismic Hazards Group
URS Corporation
1333 Broadway, Suite 800
Oakland, CA 946123
Direct: (510) 874-3014
Fax: (510) 874-3268
Email: ivan_wong@urscorp.com

This e-mail and any attachments contain URS Corporation confidential information that may be proprietary or privileged. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.


"Stickney, Mike" <MSickney@mttech.edu>

01/20/2011 09:20 AM

To "Ivan_Wong@URSCorp.com"
<Ivan_Wong@URSCorp.com>

cc

Subject PGA at Flower Creek Dam, Montana



- Abrahamson & Silva (2008)
- - - Boore & Atkinson (2008)
- - - Campbell & Bozorgnia (2008)
- - - Chiou and Youngs (2008)
- Average

Mag = 7.0
 Normal faulting
 Dip = 55.0
 $R_{rup} = 18.0$ km, $R_{jb} = 18.0$ km
 In FootWall
 $V_{s30} = 1500$ m/s

URS

Project No. 00000000

Flower Creek Dam
Montana

MEDIAN
 HORIZONTAL SPECTRA
 FOR THE SAVAGE LAKE FAULT

Figure
#

From: [Stickney, Mike](#)
To: lcema@libby.org; [Lemieux, Michele](#)
Cc: [Deal, Edmond](#); [Miller, Marvin](#)
Subject: Libby area earthquake recurrence information
Date: Thursday, January 13, 2011 9:23:57 AM
Attachments: [Libby.pdf](#)
[LibbyQks.txt](#)

Hello Vic and Michele:

I went ahead and repeated the search of the Montana Bureau of Mines and Geology earthquake catalog for all earthquakes that we have located within a 65 km radius of Libby (taken as 48.388 N, 115.556 W) since January 1982. This search produced 163 earthquakes with magnitudes ranging from 0 to 4.7 (attached as LibbyQks.txt), the majority (87%) of which occurred since 2000 when seismic monitoring capabilities dramatically improved in northwestern Montana. I sorted these earthquakes according to magnitude and created a cumulative-number-of-earthquakes versus magnitude plot (attached as Libby.pdf). A linear regression of the larger magnitude earthquakes ($M \geq 2.6$) is shown as a line on the plot and results in the equation: $\log N = 3.07 - 0.66 M$, where N is the number of earthquakes greater than or equal to magnitude M . The correlation coefficient for this regression is 0.992 (1.00 would be a perfect fit). I selected magnitude 2.6 as the minimum magnitude for this analysis because the data points for lower magnitude events begin to diverge systematically from a straight line, indicating incomplete detection and location of earthquakes with magnitudes less than 2.6 (particularly for the 1982-1999 time period).

Solving the above equation for various magnitudes and dividing by the 28-year catalog period gives the annual number of earthquakes of magnitude M . The inverse of the annual number of earthquakes is the average return period of an earthquake of magnitude M . These results are summarized in the following table.

| Magnitude | Number / Year | Return Time (Years) |
|-----------|---------------|---------------------|
| 3.5 | 0.202 | 4.9 |
| 4.0 | 0.094 | 10.6 |
| 4.5 | 0.044 | 22.9 |
| 5.0 | 0.020 | 49.0 |
| 5.5 | 0.010 | 105. |
| 6.0 | 0.0044 | 226. |
| 6.5 | 0.0021 | 485. |

The above results for earthquakes of magnitude 5.0 and larger extrapolates beyond both the time and magnitude range for which we have data and should be viewed with extreme caution. Furthermore, no attempt was made to remove dependent earthquakes, examples of which are aftershocks or swarm events that are clearly related to each other in time and space. This simplistic analysis assumes that the past 28 years of seismicity is characteristic of longer term earthquake behavior in the Libby region. These earthquake return times are similar to the concept of a 100-year flood. That is, knowing the size of the 100-year flood does not in any way help one predict

when a flood that big will occur; only that, given enough historic data, that a flood of this size is likely to occur once in a 100-year period. With consideration of these limitations, this analysis suggests that an earthquake of magnitude 5.0 might occur within 65 km of Libby once in a 49-year period, and that a magnitude 6.0 earthquake might occur once in a 226-year period.

I hope that this information may in some way assist your efforts. If you have any questions or need additional information, please do not hesitate to contact me.

-Mike

Michael Stickney, Director
Earthquake Studies Office
Montana Bureau of Mines and Geology
Montana Tech of the University of Montana
1300 W Park St
Butte, MT 59701

(406) 496-4332 Voice
(406) 496-4451 Fax
mstickney@mtech.edu
<http://mbmgquake.mtech.edu>

